SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	12/11/2018 12:15

Date Of Accident 12/11/2018 10:40

Exact Location Of Accident CHANGI AIRPORT T1 - TAXI QUEUE

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD1801H

Insured/Policyholder

Name Of Registered Owner PREMIER TAXIS PTE LTD

Co Reg No 200304975H
Email Address NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-62148880

Vehicle Particulars

Manufacturer HYUNDAI Model I30-1.6 (M)

Exact Purpose for which vehicle was being used at

time of accident

HIRED & REWARDS

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage THIRD PARTY

Fleet Policy YES

Policy Number 5095103893

Cover Note Number

Driver

 Name of Driver
 TAN SUAN AIK

 NRIC No
 \$0709723I

 Date Of Birth
 02/03/1946

 Occupation
 OUTDOOR

 Date Of Driving Pass
 14/08/1970

Driving Experience 48 YEARS AND 2 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98559723

Fax Number

Contact Number

EMail Address NOEMAIL

Address BLK 632B #05-127 SENJA ROAD

Postcode 672632

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTH

Vehicle Registration Number of Driver's Own

Vehicle

OTHER - HIRER

Insurance Company of Driver's Own Vehicle

-

NO

YES

NO

YES

NO

1

NO

NO

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

VEH. A - NO PAX VEH. B - 1 PAX

Attachment(s)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

...

Was there any audio recorded?

YES NO

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD3284L

Vehicle Make/Model/Colour COMFORT TAXI/HY I40

Details Of Properties VEH. B
Vehicle Category TAXI

Name of Driver MALE CHINESE

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN SUAN AIK - DRIVER OF VEH. A

Approximate Age Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

WILL SEEK FOR MEDICAL

SHD1801H

YES

NO

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Driver's Signature

1 2 NOV 2018

Reporting Centre Personnel's Signature

e & Time:

Date & Time:


(If driver is not the policyholder)
Date & Time:

N:

Name: NRIC/FIN No.:

A AC Vicardo Dian Consu. 373

Sketch Plan Pg. 2



Page 5 of 14

Describe Circumstance of the Accident.

ON 12/11/2018 @ 1040 HRS, I WAS DRIVING MY TAXI (SHD 1801 H), TRAVELLING ALONG THE TAXI QUEUE DRIVEWAY @ CHANGI AIRPORT T1.

WHILE I WAS MOVING AHEAD, SUDDENLY VEHICLE B (SHD 3284 L – COMFORT TAXI) WHICH WAS MOVING OFF FROM THE TAXI BAY (ON MY RIGHT) – FAILED TO KEEP FOR PROPER LOOK OUT, HAD ENCROACHED ONTO MY PATH ON MY RIGHT FRONT.

AS SUCH, THE LEFT FRONT OF VEHICLE B COLLIDED ONTO THE RIGHT FRONT OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE RIGHT FRONT PORTION AND VEHICLE B HAD DAMAGES ON THE LEFT FRONT PORTION.

AS A RESULT, I FELT SOME DISCOMFORT & WILL SEEK FOR MEDICAL TREATMENT SOON. NO AMBULANCE AT SCENE.

NO PASSENGERS ONBOARD MY TAXI & VEHICLE B HAD A PASSENGER ONBOARD.

*VIDEO FOOTAGE CAPTURED.

