SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	13/11/2018 18:20
Date Of Accident	13/11/2018 07:25
Exact Location Of Accident	ALONG UPPER BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SLK9500P
Insured/Policyholder	
Name Of Registered Owner	ONG HONG HOCK
NRIC No	S1386314H
Email Address	JACKSON.ONGHH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81232322
Alternative Phone No	OTHERS-81232322
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE

Vehicle Category	PRIVATE CAR	
Insurance Company		
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD	
Type Of Coverage	COMPREHENSIVE	
Fleet Policy	NO	
Policy Number	5087647028-01	
Cover Note Number		

Cover Note Number	
Driver	
Name of Driver	ONG HONG HOCK
NRIC No	S1386314H
Date Of Birth	27/07/1959
Occupation	INDOOR
Date Of Driving Pass	14/06/1977
Driving Experience	41 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81232322
Fax Number	
Contact Number	OTHERS-81232322

EMail Address JACKSON.ONGHH@GMAIL.COM

162 VERDE VIEW Address

Postcode 688738

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured **OWNER**

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident **COLLISION - HEAD TO REAR**

Weather Conditions **CLEAR** Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? YES

Foreign Vehicle Registration Number JRA743 (MOTORCYCLE)

Number of vehicles involved in the accident 2 NO Was any body injured in the Accident? Was any injured conveyed to hospital by NO

ambulance?

2

Was any other material or property damaged? YES I have been approached by unknown person(s) NO soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1 NAME: : DAUGHTER

> GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes.Please state which Police Station

Police Station Name TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY: Police Station Address

SINGAPORE

Police Station Contact TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given?

If Yes, against whom?

NO

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN, ATTACHMENT AND POLICE REPORT T/20181113/7009

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number **JRA743** Vehicle Make/Model/Colour **HONDA**

Details Of Properties

MOTORCYCLE Vehicle Category

Name of Driver MR GAN CHENG HAI

NRIC/Passport Number 5 11117925

Contact Number

Address

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan



ATTACHMENT

Accident along Upper Bukit Timah Road opposite former 'Ford' factory involving SLK9500P and JRA743 (Malaysian Motorbike)

Date: 13 Nov 2018

Time of Accident: 7.27am, Weather: Clear

Location of Accident: Upper Bukit Timah Road (towards City) Opposite former Ford factory

Statement

On 13 Nov 2018 at about 7.27am when I stopped my vehicle, SLK9500P behind other cars stopping at red traffic light ahead along Upper Bukit Timah Road towards city at junction of Upper Bukit Timah Road/ Old Jurong Road. Suddenly I heard a 'bang' at the back of my car and then saw a Malaysian registered motorbike, JRA 743 lying on the left of my car.

The rider, Mr Gan Cheng Hai of Work Permit No. 5/11117925 suffered a minor cut on his wrist. I offered to call an ambulance but he rejected it. Other than the minor cut, he told me he is fine and was able to ride off with his bike.

ga 13/11/20CP Rosl hattors

My car had bad scratches and broken tail light.

UPPER BUKIT TIMAH ROAD

CITY

JRA743

SLK9500P

ONG HONG HOCK

(DRIVER OF SLK9500P)

S1386314H





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 1 of 4 Report No. T/20181113/7009

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/11/2018 15:04		Made:	Vide Report No.:	Station Diary No.:
Informa	nt's Partic	ulars		
	Informant: ONG HOCK		Address: 162 VERDE VIEW SINGAPO	RE 688738
	/ ID No.: D / S13863	14H	Contact No.: Home/Office:	Mobile: 81232322
National SINGAP	ity: ORE CITIZ	EN	Email: jackson.onghh@gmail.com	
Sex: Male	Age: 59	Date of Birth: 27/07/1959	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Electrical engineer (general)		(general)	Driving Licence Information: Class: 3	Date of Expiry:

Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 13/11/2018 07:25	Type of Location Straight Road
UPPER BUK	T TIMAH ROAD			
		Road Surface: Dry		Road Speed Limit: 70 Km/h
Weather: Clear Traffic Flow: One Way				COLD TO SERVICE STATE OF THE S

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
JRA743	Motorcycle	HONDA		Red	Slightly Damaged	0
SLK9500P	Car	TOYOTA	COROLLA+ ALTIS+1.6+ CVT	Grey	Slightly Damaged	1

Details of V	ehicle Insurance		What is to be	
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 2 of 4 Report No. T/20181113/7009

CONTINUATION OF REPORT

Details of V	ehicle Insurance			
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLK9500P	NTUC Income Insurance Co-Operative Limited	5087647028-01	08/02/2018	07/02/2019
Details of P	erson Involved	No. of the last		
Any Pedestr	an Involved: No			
No. of Pedes	strians Injured: NIL	Use of Pedestrian Cr	rossing: NA	
Rider				
Name	MR GAN CHENG HAL	ID No.	E 44447000	

No. of Pedestrian	s Injured: NIL	Use of Pe	destriar	Cross	sing: NA
Rider		000 0110	deotria	101000	ang. ren
Name	MR GAN CHENG HAI		ID No.		5 11117925
Related Vehicle	JRA743 (Motorcycle)		Conta	ect No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disc	charge	NIL	
	ted Medical Leave NIL	Degree o		Slight	t
Driver					
Name	ONG HONG HOCK		ID No	•((S1386314H
Related Vehicle	SLK9500P (Car)		Conta	ict No.	81232322
Hospital/Clinic	NIL		Class Drivin Licent Expiry	g	Class: 3 Date of Expiry: NIL
Date Treatment	NIL Date Disc		harge	NIL	
No. of Days gran	ted Medical Leave NIL	Degree of		NIL	

Brief Details

On 13 Nov 2018 at about 7.27am when I stopped my vehicle, SLK9500P behind other cars stopping at red traffic light ahead along Upper Bukit Timah Road towards city at junction of Upper Bukit Timah Road/ Old Jurong Road. Suddenly I heard a 'bang' at the back of my car and then saw a Malaysian registered motorbike, JRA 743 lying on the left of my car.

The rider, Mr Gan Cheng Hai of Work Permit No. 5/11117925 suffered a minor cut on his wrist. I offered to call an ambulance but he rejected it. Other than the minor cut, he told me he is fine and was able to ride off with his bike.

My car had bad scratches and broken tail light.

- 1. File attachment with photos less than 2MB
- 2. Landmarks Opposite former 'FORD' factory
- 3. Traveling along Upper Bukit Timah Road towards City
- 4. The accident did not take place at pedestrian crossing

ONG HONG HOCK



T/20181113/7009

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 4 Report No. T/20181113/7009

CONTINUATION OF REPORT

S1386314H 81232322





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 4 of 4 Report No. T/20181113/7009

CONTINUATION OF REPORT

Sketch Plan		
Informant is	not able to provide sketch	nla


NP168

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 13/11/2018 15:04
Officer In Charge Of Case: TP / TPIB / ANG YI TING, STEPHANIE Contact No.: 65476414	Classification Of Case:
Contact No.: 65476414 Authentication Stamp	

ATTACHMENT

Accident Along Upper Bukit Timah Road (opp former Ford factory) involving SLK9500P and JRA743 on 13 Nov 2018 at 7.27am

SLK9500P Driver Details





JRA743, Motorbike Rider Details



























