15/5/2010	1 CC 4, UPC 180	2086 / K pa 5/12 LARE :DAC:
* DAS CASE OF FREE	ASSIS	13)"/2018
Surveyot:	V8V DOI: 1	Lete / Time: 15 11 12918 Registered in Merimen:
Pre-assign / CCU /)	FTE GN8180X	Claim No. : (8/18/18/ VP OS/07/069
Insured Vehicle No.		Claim No. : (8/18/10)
Name of Itisured	Ope construction fil	Policy No. :
Insured Tel No.	: HP:	Make / Model :
Excess Sec II :SS	D.O.A: W /18/20/8	Place of Accident: Wordlans AVE 2
Is driver the owner?		
		OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
If NO, Driver Nam Driver Tel N		Insured Liability: % Final? Yes / No
Mushs	<u> </u>	
INSRS: WSP: Tel: North Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS: INSRS: WSP: Tel: Liability: RMKS:
Date/ Time		ANALYSIS CONTRACTOR CO
15/1	8/48/80 X - c23/4x4 120 13320/119	STAGE DATE / PIC Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call CI:
Midia	tite I ture monetate.	After call ity to OI:
8 4 19 -	the I type monetose.	Documentation Check List: Handler Typist
2/12/15	FILE PASS TO HIMLE TO LLOSSO	Notification itr (if non-pickup)
4.511	The transfer of the territory	After call ltr to OI:
		Authorisation To Act:
		Release Voucher: Final Repair Bill:
		Car Rental Invoice:
		Towing Invoice
2		
		LTA / GIA : Medical Bill:
		PIR: Mandate/Reject Instruction:
		LOD Payment Breakdown Form:
		AND DESCRIPTION OF THE PROPERTY OF THE PROPERT
RELIMINARY ADVIC	E Date/Time: Sent By:	Post-Repair Photos: Others:
- Indiana - Alaka - Al	A STATE OF THE STA	Confirm by:
INALIZATION	Date/Time: Confirm with:	20000000 100000000000000000000000000000
epair Cost:	S\$ (days) Reduction:	
INAL SETTLEMENT	Date/Time: 2/11/9 Confirm with Jeff	
final Liability:	% (Agreed / Astessed) BOLA S/N No	11 NO 01 B 48, ASS. LIB:
Repair Cost: (w/637)	55 449.40	
Loss of Rental (LOR):(w		SOLDY SERVICE
Loss of Use (LOU):	SS - (\$ x days)	11-11-11-11
Loss of Income (LOI):	S\$ (S x days)	U HT
LOU c	11117	only one]
GIA/LTA Search	\$\$ 2.00	1) Claim status: Normal/Reject/Private Settle
Medical:	S\$ -	
Disbursement:	S\$ (e.g. Tow/ Inc	dependent) 2) Report Format: 3) Survey fee: 9450
Legal Cost	SS -	13) Survey tee. 14430
Total:	SS 547.70 Global Sum SS:	Email Call
FINAL PAYMENT	Date/Time: Confirm with:	
Payce 1:	Name 1: Marie 1: Marie 1: Marie 1:	lage Enterprises Pte Ltd
Payee 2: (Strike if N.A.)		
Payee 3: (Strike if N.A.)	S\$ Name 3:	CONTRACTOR OF THE PROPERTY OF

East John John John John John John John John		A531	GNMENT	0
Truck Trailer or 1945 19		Date: 301/110\8	97911.170	
To inspect Vehicle No At Workshop mile Mile Ting Of 19 lipsing 8 Tox Pough Colour 19 lipsing 8 Tox Pough Sp. Reading 1059 TRadic Insured 15td IN I NA Sp. Reading 1059 TRadic Insured 15td IN I NA Sp. Reading 1059 TRadic Insured 15td IN I NA Sp. Reading 1059 TRadic Insured 15td IN I NA Sp. Reading 1059 TRadic Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td OF Sho Gen. Cond. Good) Fair I Poor I Bush of Insured Insured 15td OF Sho Toyo I York Or The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame				
To inspect Vehicle No At Workshop mile Mile Ting Of 19 lipsing 8 Tox Pough Colour 19 lipsing 8 Tox Pough Sp. Reading 1059 TRadic Insured 15td IN I NA Sp. Reading 1059 TRadic Insured 15td IN I NA Sp. Reading 1059 TRadic Insured 15td IN I NA Sp. Reading 1059 TRadic Insured 15td IN I NA Sp. Reading 1059 TRadic Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td IN I NA Sp. Reading 1059 TRACE Insured 15td OF Sho Gen. Cond. Good) Fair I Poor I Bush of Insured Insured 15td OF Sho Toyo I York Or The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame 1 Body Structure affected the to collision. The URL I Chassis Irame	OD TP I WS I TP RES I OD R		0 (1)	XIV as thou
of 19 Linning Tod Rugh. Insured 19 Linning Tod Rugh. Insured 19 Linning Tod Rugh. Insured 19 Linning Tod Rugh. Sp. Reading 1059 TiRado: Insured 15td 11 1 1 A Sp. Reading 1059 TiRado: Insured 15td 11 1 I I I I I I I I I I I I I I I I I	To Inspect Vehicle No:	Description of the Control of the Co	The state of the s	7-6
Insured Policy No. Claims No. Som Insured (Clearis Record) Make of Veh: (Policy Condition) Make of Veh: (Policy I Fee I Leaked / Burnt or Modi: NII / SIRTING or (Policy I Fee I Leaked / Burnt or Modi: NII / SIRTING or (Policy I Fee I Leaked / Burnt or Modi: NII / SIRTING or (Policy I Fee I Leaked / Burnt or Modi: NII / SIRTING or (Policy I Fee I Leaked / Burnt or Modi: NII / SIRTING or (Policy I Fee I Leaked / Burnt or Modi: NII / SIRTING or (Policy I Fee I Leaked / Burnt or Modi: NII / SIRTING or (Policy I Fee I Leaked / Burnt or Modi: NII / SIRTING or (Policy I Fee I Leaked / Burnt or Modi: NII / SIRTING or (Policy I Fee I Leaked / Burnt or Modi: NII / SIRTING	at Workshop m/s	Motor Image	1110	
Colored Record) Make of Veh (Clearit's Record) Make of Veh (Policy Condition) Make of Veh Made: Indied Jammed / Leaked / Burnt or Made: Nill / SIR All more of Instruction Tyre Size: F: 225/55R16 Size Indied Jammed / Leaked / Burnt or Made: Nill / SIR Indied Jammed / Leaked / Burnt or Made: Nill / SIR Indied Jammed / Leaked / Burnt or Made: Nill / SIR Indied / Jammed / Leaked / Burnt or Made: Nill / SIR Indied / Jammed / Leaked / Burnt or Made: Nill / SIR Indied / Jammed / Leaked / Burnt or Made: Nill / SIR Indied / Jammed / Leaked / Burnt or Tyre Size: F: 225/55R16 Size Indied / Jammed / Leaked / Burnt or Record / Jammed / Leaked / Burnt or Made: Nill / SIR Indied / Jammed / Leaked / Burnt or Made: Nill / SIR Indied / Jammed / Leaked / Burnt or Made: Nill / SIR Indied / Jammed / Leaked / Burnt or Record / Size Indied / Jammed / Leaked / Burnt or Made: Nill / SIR Indied / Jammed / Leaked / Burnt or Record / Size Indied / Jammed / Leaked / Burnt or Made: Nill / SIR Indied / Jammed / Leaked / Burnt or Record / Size Indied / Jammed / Leaked / Burnt or Made: Nill / SIR Indied / Jammed / Leaked / Burnt or Record / Size Indied / Jammed / Leaked / Burnt or Made: Nill / SIR Indied / Jammed / Leaked / Burnt or Record / Size Indied / Jammed / Leaked / Burnt or Record / Size Indied / Jammed / Leaked / Burnt or Record / Size Indied / Size In	of 19 1	Lorong 8 Toa Payon.	Sp Reading 703 /	THERIO, HISSIAGO
Claims No. Claims No. Sum Insured: (Client's Record) Make of Veh: (Policy Condition) Make of Veh: (Policy Condition) (Po) 0	Eng/No:	14. 21/16/5/
Clears No. Sum insured: (Clear's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its preparate the time of inspection. Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No. Est. Repairs: Of days Res.: Yes or No. Est. Repairs: Of Adys Res.: Yes or No. CA / REV / REP. / 24 HRS Date / Time Action / Instruction Date / Time Action / Instruction Date / Time Action / Instruction Consistent Report: Date / Time Action / Instruction Consistent Report: Date / Time Action / Instruction Consistent Report: Consistent	Policy No.			
Sum insured: (Client's Record) Make of Veh: (Pokey Condition) Make of Veh: (Pokey Condition) Modiff Insurance Insura	CONTRACTOR OF THE PROPERTY OF			1 .
(Client's Record) Make of Veh: (Policy Condition) June Com (Policy Con (Policy		Excess		
Made of Veh:	40.54000 VIAA4008 9024			
Consistent Con			Modi: Nil / S/Rim / ST A/Rim	or
Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No Est. Repairs: Consistent?: Yes or No Lum Sum: CA / REV / REP. / 24 HRS Date: Person Contacted: Date / Time Action / Instruction Date / Time Action / Instruction Contacted: Date / Time Action / Instruction Contacted: Contacted: Days Of Repair: Resurvey No. of Trip: Contacted: Con		u ancom		
Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: C/ days Res.: Yes or No Lum Sum: L/B / % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Vehicle: IN / OUT Date: Person Contacted: Date / Time Action / Instruction CF / CF			R:	225/55R18
repair at the time of inspection. Bal or Market Value: IDAC Accident Rport: Consistent? Yes or No Est. Repairs: Consistent? Yes or No Est. Repairs: Consistent? Yes or No Est. Repairs: Consistent? Yes or No Consistent? Yes or No Est. Repairs: Consistent? Yes or No Est. Repairs: Consistent? Yes or No Consistent? Yes or No Est. Repairs: Consistent? Yes or No Consistent Yes or Yes or No Consistent Yes or Ye			SIDUN / EXNOVA / GY / FS / LIZ	A / MIC / OHTSU / PIR / SUMI /
Bal or Market Value: IDAC Accident Rport: Consistent? Yes or No GIA / PR Seen: Consistent? Yes or No Est. Repairs: O/ days Res.: Yes or No Lum Sum: /-B/1% 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: N/OUT Date / Time: Action / Instruction U//// Bib ASN C Code Determine File Pass to? Preli. Report Date Time: File Return to? Add Fee: Stite Insp (\$ 1.5 - PS 6) Interview (\$ 1.5 - PS 6) Report Format: Front Ribal 9 mm			TOYO/YOKO or	
Date/Time: File Pass to? Date/Time: File Return to? Date/Time: File Return to? Date/Time: File Return to? Add Fee: Site Inspect Survey No. of Trip: Date/Time: File Return to? Add Fee: Site Inspect Survey No. of Trip: Consistent?: Yes or No LUBal. 9 mm LU	M.		Front	Rear
GIA / PR Seen: Consistent?: Yes or No Est. Repairs: C/ days Res.: Yes or No L/Bal. D.O.A. 25/10/18 D.O.J. 20/11/19 Survey held at Des. of Damages: Frt Report Des. of Damages: Frt D		Consistent? : Yes or No	R/Bal. 9 mm	R/Bal. 7 mm
Est. Repairs: Color Color			L/Bal. 9 mm	
Lum Sum: /-B/% 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT Date / Time Action / Instruction VI/II Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction VI/II Chassis frame / Body Structure affected due to collision. Date / Time Ple Pass to? Preli. Report Days Of Repair: Resurvey No. of Trip: Survey Fee. Transportation Add Fee: Site Insp. (\$) 5-PS SI Interview (\$) 5-PS SI Report Format:	61		D.O.A. 25/10/18	D.O.L. 20/11/19
Date: Person Contacted: Note:	A 100 March 1 100			
Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date/Time Action / Instruction		7."	Des. of Damages Frt Rear 0	S / N/S / U/C / Rooftop or
Date / Time Action / Instruction Date / Time Action / Instruction Date / Time Action / Instruction Order / Time Action	CA / REV / REP. /	24 HRS Vehicle: IN / O	IT.	
Duto/Time: File Pass to? Preli. Report Days Of Repair: Preli. Report Resurvey No. of Trip: Survey Fee Transportation Add Fee: Site Insp (\$) _ S - PS _ SI Interview (\$) Photos Report Format: Tech. Invs (\$) Others	Date: Pers		The U/C / Chassis frame / B	ody Structure affected due to collision.
Transportation Add Fee: Site Insp (\$) _8 + PS _ Si Photos Report Format: Tech Invs (\$) Others	21/1 Cil	ACUT Cotherin	7894.16J 90b)	
Date/Time, File Return to?	i i		SOCIES ALEGERIA DE HECCESOR	
Report Format : Interview (\$) Photos Tech Inva (\$) Others				indiana de la companya de la company
Report Format : Interview (\$) Photos Tech Invs (\$) Others	2)	Add	L) _S+RS(SI
Report Format.		~	Account of the Control of the Contro) Photos
4 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Report Format :	127	Tech Inva (5)	(i) Others
	and the second s		Weekend (\$	

Date: 22.11.2018

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

18/18/18/VP05/021069

Our ref:

CC4/LPC18020567/Kpa3

The Motor Claims Department M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJM 7474H

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20.11.2018 at the premises of M/s Motor Image Enterprises Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	4,314.16
Revised Estimate Amount	: S\$	420.00
"Check" Items Amount	: S\$	
Total (Including Check Items)	: S\$	420.00
Market Value	: S\$	(est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	(est.)

Description of Damage:

The vehicle sustained damages at the

Rear Portion

nearside front

Comments/Present Status:

Damages Consistent

Estimated normal period for repairs:

1.0 days

Yours faithfully,

KENNETH KONG

Licensed Appraiser

MOTORIMAGE ENTERPRISES PTE. LTD. 19 LORONG 8, TOA PAYOH SINGAPORE 319255

ESTIMATE

: ACCIDENT/BODY REPAIRS

WORKSHOP

: TOA PAYOH

CONTACT NO : 64730333

REFERENCE : INS/IC/CHI/1023/2018

DATE

: 10-NOV-2018

LONPAC INSURANCE BHD.

100 BEACH ROAD

#19-00 SHAW TOWER

\$(189702)

TEL: 62507388 FAX: 62963767

OWNER'S NAME : KOK FOOK KEE (GUO FUJI)

ADDRESS

: APT BLK 158 CANBERRA DRIVE #09-36

\$(768083)

TELEPHONE NO : 98373285

TYPE OF CLAIM : THIRD PARTY CLAIM

POLICY NO : PNPV2018-00012960

VEHICLE NO : SJM7474H

MODEL CODE : GT7BKVL

MODEL/YEAR : XV 2.0I-S EYESIGHT AWD CVT
ENGINE NO : FB20YE33510
CHASSIS NO : JF1GT7KL5JG046580

MILEAGE : 1 KM

DATE IN : 10/11/2018

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : DANIEL A JUDE** ACCIDENT DATE : 25/10/2018

Print Date

: 10/11/2018

Print Time

: 12:11:04

MOTORIMAGE ENTERPRISES PTE. LTD. 19 LORONG 8, TOA PAYOH SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJM7474H

S/NO JOB CODE	DIRECTOR OF LINE				SURVEYOR'S RECOMMENDATION
2 ZZ/001	CONDUCT TP CLAIM LONPAC LOCATION:WOODLANDS A TIME:1900HRS DATE:25/10/2018	AVE 2			
3 ZZ/002	REPAIR/REPLACE RR BUMPER AND PANEL	NN	1	120.00	X
4 22/003	RESPRAY RR BUMPER AND PANEL			840.00	4201
5 22/004	TO CONDUCT PROTECTANT COATING	nn	9	500.00	X
6 22/005	TO CONDUCT ANTI-RUST COATING	N	L	580.00	X
7 ZZ/006	TO_SUPPLY AND INSTALL REVERSE SENSOR - 2 E	YES 4	R	300.00	X4RJVC
8 ZZ/007	SUNDRIES		**	100.00	X
9 ZZ/008	TO CONDUCT REAR LIGHTING TEST ON FOG LAMP	•	un	50.00) X
			223		2 0
	TOTAL LABOUR CHARGES			3490.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJM7474H

DAMAG	ED	2	AK	R)	à	r	K.	J	L	0		
										-	-	-	-

S/NO PARTS DESCRIPTION	PARTS NUMBER				S/NETT	S/LIST REMARKS
1 BUMPER FACE R XV	57704FL250	n	401.10	(
2 BRKT SD R XV RH	57707FL400	14	12.10	X		
3 BRKT SD R XV LH	57707FL410	Sn	12.10	X		
4 BRKT CORNER R 5D RH	57707FL460	SL	21.60	×		
5 BRKT CORNER R 5D LH	57707FL470	sn.	21.60	×		
6 BRKT LWR R	57707FL510	n	50.40	×		
7 BEAM COMPL R EU	57711FL0419P	M	203.00	X		
8 COVER HOOK R XV	57731FL570NN	50	6.50	X		
9 WSTR DR R G	63516FL000	ړ√	108.00	X		
10 LENS & BODY COMPLREH	84913AL120	Sz	129.60	X		
11 LENS & BODY COMPLELE	84913AL140	5	64.20	X		
			1030.20	0.0	0.00	
SUB TOTAL LESS DISCOUNT (NETT-20 %)			206.04		0.0	
					0.0	
GRAND TOTAL		9				÷.
OFFICE TOTAL			824.16	6		
OVERALL TOTAL						

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD. 19 LORONG 8, TOA PAYOH SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJM7474H

TOTAL LABOUR CHARGES

3490.00

TOTAL SPARE PARTS CHARGES

824.16

GRAND TOTAL

4314.16 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME

SURVEYED DATE

AUTHORIZED DATE : EXCESS CLAUSE : LIABILITY :

0.00 0.00

REMARKS

130

Not Nothank Iday Renny After Pains

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

> LKK Auto Consultants Fence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged partist during resurvey
- Parts prices are subject to confirmation
- Trust party survey is on a "Without Prejudice" basis
- * No :liegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Nivitha (LKK Auto)

GERALD POH WEE BIN <geraldpoh@lonpac.com> From: Tuesday, 13 November 2018 9:38 AM Sent: Admin-D (LKKAuto) To: MT_Claim_SG; danieljude@motorimage.net FW: SJM7474H - 3RD PARTY CLAIM - (TP) - (GY8180X) - (LONPAC INSURED) -Cc: Subject: LIABILITY STATUS SJM7474H ESTIMATE.PDF; SJM7474H GIA REPORT.PDF; 2018Year10Month25Day_ Attachments: 19Hour01Minute19.232Sec_Rear-camera (online-video-c....mp4 10.07am @ 13/11/18 High Importance: person® Daniel : 18/18/18/VP05/021069 Our Ref Dear Catherine, Kindly proceed to survey and revert to them on liability. Our insured has already lodged the report. Best Regards Gerald Poh Senior Claims Executive | Lonpac Insurance Bhd 300 Beach Road, #17-04/07 The Concourse, Singapore 199555 Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706 From: Daniel Jude [mailto:danieljude@motorimage.net] Sent: Tuesday, 13 November, 2018 9:28 AM To: MT_Claim_SG Subject: RE: SJM7474H - 3RD PARTY CLAIM - (TP) - (GY8180X) - (LONPAC INSURED) - LIABILITY STATUS Importance: High Hi Claims Team, Any update on this case? Has your insured reported the case? Kindly advise liability status as at current. Attached is the GIA report and Estimate for repair. 2nd attempt. Thank You.

Best Regards

Daniel A Jude

Service Executive

Motor Image Enterprises Pte Ltd


19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net











Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

From: Daniel Jude

Sent: Monday, November 12, 2018 12:37 PM

To: 'mt_claims@lonpac.com' <mt_claims@lonpac.com>
Cc: TPY Insurance Team <tpyinsteam@tanchong.org>

Subject: FW: SJM7474H - 3RD PARTY CLAIM - (TP) - (GY8180X) - (LONPAC INSURED) - LIABILITY STATUS

Importance: High

Hi Claims Team,

Any update on this case?

Has your insured reported the case?

Kindly advise liability status as at current.

Attached is the GIA report and Estimate for repair.

2nd attempt.

Thank You.

Best Regards
Daniel A Jude
Service Executive
Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net











Disclaimer. This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

From: Daniel Jude

Sent: Saturday, November 10, 2018 12:16 PM

To: mt_claims@lonpac.com

Cc: TPY Insurance Team < tpyinsteam@tanchong.org>

Subject: FW: SJM7474H - 3RD PARTY CLAIM - (TP) - (GY8180X) - (LONPAC INSURED) - LIABILITY STATUS

Importance: High

Hi Claims Team,

Any update on this case?

Has your insured reported the case?

Kindly advise liability status as at current.

Attached is the GIA report and Estimate for repair.

Thank You.

Best Regards Daniel A Jude Service Executive Motor Image Enterprises Pte Ltd 19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net















Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

From: Daniel Jude

Sent: Thursday, November 1, 2018 3:02 PM

To: 'mt_claims@lonpac.com' <mt_claims@lonpac.com>
Cc: TPY Insurance Team <tpyinsteam@tanchong.org>

Subject: SJM7474H - 3RD PARTY CLAIM - (TP) - (GY8180X) - (LONPAC INSURED) - LIABILITY STATUS

Importance: High

Hi Claims Team,

Kindly advise liability status of the above mentioned.

Estimate will be attached later.

Thank You.

Best Regards

Daniel A Jude

Service Executive

Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net

















Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the

vications cannot be guarantee	to be timely, secure, error-free or virus-free. The
sender immediately by return e-mail. Internet communications cannot be guarantee sender does not accept liability for any errors or omissions.	
数	
5	
19.1	

Mei Kwan (LKKAuto)

From:

GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent:

Wednesday, 14 November, 2018 9:50 AM

To:

Mei Kwan (LKKAuto)

Cc:

MT_Claim_SG RE: SJM7474H - 3RD PARTY CLAIM - (TP) - (GY8180X) - (LONPAC INSURED) -

Subject:

LIABILITY STATUS

Attachments:

14112018094751.pdf

Follow Up Flag:

Follow up

Flag Status:

Completed

Categories:

HMK

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Wednesday, 14 November, 2018 9:45 AM

To: GERALD POH WEE BIN

Cc: MT_Claim_SG; Admin A; Hsiao Tong (LKKAuto); CS A Team

Subject: RE: SJM7474H - 3RD PARTY CLAIM - (TP) - (GY8180X) - (LONPAC INSURED) - LIABILITY STATUS

WITHOUT PREJUDICE

LPC ref: 18/18/18/VP05/021069 LKK REF: CC4/LPC18020567/pa3

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Has your insured reported the case?

Kindly advise liability status as at current.

Attached is the GIA report and Estimate for repair.

2nd attempt.

Thank You.

Best Regards

Daniel A Jude

Service Executive


Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net



Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

From: Daniel Jude

Sent: Monday, November 12, 2018 12:37 PM

To: 'mt_claims@lonpac.com' <mt_claims@lonpac.com>
Cc: TPY Insurance Team <tpyinsteam@tanchong.org>

Subject: FW: SJM7474H - 3RD PARTY CLAIM - (TP) - (GY8180X) - (LONPAC INSURED) - LIABILITY STATUS

Importance: High

Hi Claims Team,

Any update on this case?

Has your insured reported the case?

Kindly advise liability status as at current.

Attached is the GIA report and Estimate for repair.

Service Executive Motor Image Enterprises Pte Ltd 19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net

×		
×××××		

Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

From: Daniel Jude

Sent: Thursday, November 1, 2018 3:02 PM

To: 'mt_claims@lonpac.com' <mt_claims@lonpac.com>
Cc: TPY Insurance Team <tpyinsteam@tanchong.org>

Subject: SJM7474H - 3RD PARTY CLAIM - (TP) - (GY8180X) - (LONPAC INSURED) - LIABILITY STATUS

Importance: High

Hi Claims Team,

Kindly advise liability status of the above mentioned.

Estimate will be attached later.

Thank You.

Best Regards

Daniel A Jude

Service Executive

Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Friday, 16 November 2018 8:56 AM

To:

'danieljude@motorimage.net'

Cc: Subject: Admin A; assignments RE: SJM7474H - 3RD PARTY CLAIM - (TP) - (GY8180X) - (LONPAC INSURED) -

LIABILITY STATUS *LKK REF: CC4/LPC18020567/pa3

Without Prejudice

Dear Sirs/ Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]

Sent: Tuesday, 13 November 2018 9:38 AM To: Admin-D (LKKAuto) admin-d@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>; danieljude@motorimage.net

Subject: FW: SJM7474H - 3RD PARTY CLAIM - (TP) - (GY8180X) - (LONPAC INSURED) - LIABILITY STATUS

Importance: High

Our Ref

: 18/18/18/VP05/021069

Dear Catherine,

Kindly proceed to survey and revert to them on liability.

Our insured has already lodged the report.

Best Regards Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd 300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Daniel Jude [mailto:danieljude@motorimage.net]

Sent: Tuesday, 13 November, 2018 9:28 AM

To: MT_Claim_SG

Subject: RE: SJM7474H - 3RD PARTY CLAIM - (TP) - (GY8180X) - (LONPAC INSURED) - LIABILITY STATUS

Importance: High

Hi Claims Team,

Any update on this case?

Has your insured reported the case?

Kindly advise liability status as at current.

Attached is the GIA report and Estimate for repair.

2nd attempt.

Thank You.

Best Regards Daniel A Jude Service Executive Motor Image Enterprises Pte Ltd 19 Lorong 8 Toa Payoh Singapore 319255 HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net















Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the

sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

From: Daniel Jude

Sent: Monday, November 12, 2018 12:37 PM

To: 'mt_claims@lonpac.com' <mt_claims@lonpac.com>
Cc: TPY Insurance Team <tpyinsteam@tanchong.org>

Subject: FW: SJM7474H - 3RD PARTY CLAIM - (TP) - (GY8180X) - (LONPAC INSURED) - LIABILITY STATUS

Importance: High

Hi Claims Team,

Any update on this case?

Has your insured reported the case?

Kindly advise liability status as at current.

Attached is the GIA report and Estimate for repair.

2nd attempt.

Thank You.

Best Regards

Daniel A Jude

Service Executive

Motor Image Enterprises Pte Ltd


19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net











Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

From: Daniel Jude

Sent: Saturday, November 10, 2018 12:16 PM

To: mt claims@lonpac.com

Cc: TPY Insurance Team < tpyinsteam@tanchong.org>

Subject: FW: SJM7474H - 3RD PARTY CLAIM - (TP) - (GY8180X) - (LONPAC INSURED) - LIABILITY STATUS

Importance: High

Hi Claims Team,

Any update on this case?

Has your insured reported the case?

Kindly advise liability status as at current.

Attached is the GIA report and Estimate for repair.


Thank You.

Best Regards Daniel A Jude Service Executive Motor Image Enterprises Pte Ltd 19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net





Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

From: Daniel Jude

Sent: Thursday, November 1, 2018 3:02 PM

To: 'mt_claims@lonpac.com' <mt_claims@lonpac.com> Cc: TPY Insurance Team < tpyinsteam@tanchong.org>

Subject: SJM7474H - 3RD PARTY CLAIM - (TP) - (GY8180X) - (LONPAC INSURED) - LIABILITY STATUS

Importance: High

Hi Claims Team,

Kindly advise liability status of the above mentioned.

Estimate will be attached later.

Thank You.

Best Regards

Daniel A Jude

Service Executive

Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com : www.motorimage.net











Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.



This email has been checked for viruses by AVG antivirus software. www.avg.com



Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255 T (65) 6417 0333 F (65) 6252 5655 W www.motorimage.net

Co Reg No: 198702032R

DISCHARGE VOUCHER

Name of Insured:	KOK FOOK KEE			14
Address of Insured:	BLK 158 CANBERRA	DRIVE #09-36 S(7680	83))	
Name of Repairs:	MOTOR IMAGE ENTERP	PRISES PTE LTD / WOR	RKSHOP	
Address of Repairs:	NO. 19 LORONG 8 TOA	PAYOH SINGAPORE 3	19225	
Place of Accident:	WOODLANDS AVENU	E 2		
Date of Accident:	25/10/2018	Vehicle No: _	SJM7474	Н
Policy No: PNP	V2018-00012960	Claim No:		
settling the repair costs all further obligations at vehicle on or about the I/We agree that by virtu Vehicle are subrogated I/We hereby grant the all or any of such rights I/We further agree to fuexercising such rights charges and expenses	at I/vve have received from the a ired to my/our entire satisfaction is stated above with the said repaind liabilities under the aforesaid abovementioned date and place ue of such payment, all my/our read to the said Insurers in accordance said insurers the authority to use and remedies including the rigurnish the said Insurers with any and remedies whilst on their pains arising in connection with any parts.	ipolicy in respect on and acce. ights and remedies in respect on a some or in the laws governing the my/our name to the extent that to give discharge and recovers they agree to indemnify rest they agree to indemnify rests.	ct of the damage such matters. necessary to effeipts therefore. easonably required to the such matter such matters.	my/our said motor es to the said Motor fectively exercise e of me/us when bility for costs
exercise of such rights REPAIRERS:	and remedies.	INSURED:	2009	S7126589G
Company's Chop 8	& Signature	IC No. & Sign	ature/Compar	
SAY	EDINAH ALI		KOK FOOI	K KEE
Name		Name		
04/1	12/2018		04/12/201	8
Date	- 1/A/41 (18)	Date		

Motor Image Enterprises Pte Ltd

Request For Car Rental
Date: 03 12 2016.
Department: SERVICE ING Request By: 88001 WAT AND
Invoice To: MIE SVC TP MIE SVC - LK
Reason: 3rd party car rental for SIM 74744.
MR KOIL FOOK KEE
98373205
9007326
Owner's Car Plate No: STM 7 H744 . Authorized No. of days:
Owner's Car Model: XV
Date Required: 3/12/2016 Date Returned: 04/12/2016.
Model of Vehicle Required: (Auto / Manual):
Authorized By: (Name & Signature of Dept Mgr)
To Be Completed by Downtown Travel Service P L Staff:
Vehicle Number Assigned: SKG 6884J Car Model: NISIW SYGN
Rental Date: 3/12/16 Date Returned: 4 Dec 2018
Process by: ICAMR

ar	KS		
Rem	arks		
A	dd	Ву	On
	Remarks 1	нмк	14/11/2018 9:33:39 AM
	SJM 7474H; GY 8180X EST: \$4314.16 SUR: KSC WKSP: MOTOR IMAGE ENTERPRISES PTE LTD	нмк	21/11/2018 4:21:49 PM
		нмк	15/11/2018 9:56:32 AM
_	FILE PASS TO CHT 161118 OID rear-ended TP*100%	СНТ	16/11/2018 8:45:44 AM
	161118 OID rear-ended TP 100% 161118 Email to TP:DS	СНТ	16/11/2018 8:45:50 AM
	Rec'd sur assign & TP est	СНТ	10/12/2018 10:15:37 AM
Verior	ATANTO HOLD BUY & ATANTO PASS TO HISIAO TONG	STU	2/4/2019 11:14:51 AM
	TO HEIAO TONG	STU	2/4/2019 11:18:06 AM
100	TO MUNICIPAL PROPERTY AND	CHT	6/4/2019 1:21:45 PM
		LKM	22/4/2019 3:45:31 PM
60	TO OFFICIAL STATE & HANDLE	СНТ	24/4/2019 8:11:28 AM
-	REC'D DV *** PASS TO JIA LE	LSL1	28/11/2019 9:33:01 AM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internation	nale Des Experts En Automo	Dille
NPAC INSURANCE		Ref : CC4/LPC180205	567/Kpa3n2
= + 011 BOAD	DURSESINGAPORE 199555	Date: 03-12-2019 Code: LPC2	
	Policy Particulars	:- THIRD PARTY CLAI	M
Insured Veh.	GY 8180X	Veh. Inspected	SJM /4/4⊓
Policy No.	Z18VC05000313	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/021069	Excess (\$)	0.00
Assign From	GERALD	Assign Date	13/11/2018
	Vehicle Part	iculars & Condition	
Make & Model	SUBARU XV (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JF1GT7KL5JG046580	Colour	METALLIC RED
Odometer	1659	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
		itions of Tyres	
3. 19. 19. 19. 19. 19. 19. 19. 19. 19. 19	Size	Make	Balance
R/H Front Tyre	27 0 3 00 24 POPULA	BRIDGESTONE	9 mm
L/H Front Tyre		BRIDGESTONE	9 mm
R/H Rear Tyre	225/55 R18	BRIDGESTONE	9 mm
L/H Rear Tyre	225/55 R18	BRIDGESTONE	9 mm
		otion of Damages	
THE VEHICLE S	USTAINED DAMAGES AT THE	REAR PORTION.	
DAMAGES SEE			
5.	Gene	eral Information	国际基础代码的
Accident Date	25/10/2018	Inspection Date	20/11/2018
Survey held a		SES PTE LTD	
	19 TOA PAYOH LORONG 8 SINGAPORE 319255		
5a.		Remarks	4.010
STATE OF THE PARTY	TION WAS CONDUCTED ON A'	WITHOUT PREJUDICE" B	RISED REPAIRS.
	NOT TO VOLID INSTRUCTION		

1 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 7474H

aty	STMENT ON REPAIR COST FOR VEHICLE NO. SJ Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
200	REPLACEMENT OF PARTS			
- 1	BUMPER FACE R XV (N)	TO REPAIR SEE LABOUR	401.10	
200	2000	SERVICEABLE	12.10	
	BRKT SD R XV RH (N)	SERVICEABLE	12.10	-
	BRKT SD R XV LH (N)	SERVICEABLE	21.60	
	BRKT CORNER R 5D RH (N)	SERVICEABLE	21.60	2
	BRKT CORNER R 5D LH (N) BRKT LWR R (N)	TO REPAIR SEE	50.40	
	BEAM COMPL R EU (N)	TO REPAIR SEE	203.00	
		SERVICEABLE	6.50	
	COVER HOOK R XV (N)	SERVICEABLE	108.00	
	WSTR DR R G (N)	SERVICEABLE	129.60	9
	LENS & BODY COMPLRRH (N)	SERVICEABLE	64.20	0
	1 LENS & BODY COMPLRLH (N)		-206.0	4
	LESS 20% DISCOUNT		824.1	6
	SPECIAL NETT ITEMS	NOT NECESSARY	100.0	0
	1 SUNDRIES (SN)		300.0	
	2 EYES REVERSE SENSOR (SN)	SERVICEABLE	400.0	200
	Commence of the Commence of th		400.0	
	LABOUR	NOT NECESSARY	1,120.0	
	REPAIR /REPLACE RR BUMPER AND PANEL.	1 (50,000,000,000)	840.0	00 420.
	RESPRAY RR BUMPER AND PANEL .	NOT NECESSARY	500.0	00
	TO CONDUCT PROTECTANT COATING.	NOT NECESSARY	1,400,500	00
	TO CONDUCT ANTI-RUST COATING.	NOT NECESSARY	and the second	00
	TO CONDUCT REAR LIGHTING ON FOG LAMP.			-
	-			-
	*		3,090	
	GRAND TOTAL		4,314	.16 420

Report Ref No. CC4/LPC18020567/Kpa3n2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 420.00

Report Ref No. CC4/LPC18020567/Kpa3n2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.