

SLS REC. BY:

REF:

CS/CT118020572/T11bhz

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Irene Tay of CIL Date/Time: 13-11-2018 532pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 3941G Insured: GBH 3897H

at Workshop m/s Volkswagen Tel:

of 1 Kumpung Ampel off Macpherson Rd

Policy No: Claim No: SNM18D05304C02

Sum Insured: Excess:

Make of Veh: D.O.A. 08/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 14/11/2018 10am Person Contacted: Steven Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLC 3941G - x
	Part by Part \$9388.55. 4day working
	(Red: 2531.12, 21%)

DATE

Taufik

REF:

CTI

ASSIGNMENT

From

Date:

15/12/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLC 3941G

at Workshop m/s:

Volkswagen

of

1 Kampong Ampat off Maghassen Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

10-30am
owner waiting



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SLC 3941G.

Yr Regn

2016 May

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Polo GP

C.C

1197

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

13125

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZ6KZG4023935

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

15/11/15P1030

Survey held at

Willy Ampat

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 15 FEB 2019

Date/Time: File Pass to?

1) 15/2 Typist

Date/Time: File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

TP
9388.55

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation

) \$ - PS \$

) Photos

) Others

TOTAL

220

Catherine Chong (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 13 November, 2018 5:32 PM
To: steven.chee@vw.com.sg
Cc: assignments@lkkauto.com
Subject: CTP REF NO. SNM18D05304C02 VW REF NO. SLC3941G - ACCIDENT INVOLVING SLC3941G AND GBH3897H ON 08 NOVEMBER 2018
Attachments: 13112018172944.pdf

WITHOUT PREJUDICE

Dear Sir/Mdm (Steven),

We refer to the above matter.

As spoken, you have requested for LKK.

Aside to LKK:

Please liaise with Volkswagen.

Thank you.

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/11/2018 16:25
Date Of Accident	08/11/2018 11:30
Exact Location Of Accident	BLK 114 ALJUNIED CRESCENT OPEN SPACE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC3941G
Insured/Policyholder	
Name Of Registered Owner	NG HUI HIA
NRIC No	S1245840A
Email Address	HSQUARENG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96785673
Alternative Phone No	OFFICE-96785673

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	POLO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10743047
Cover Note Number	

Driver

Name of Driver	NG HUI HIA
NRIC No	S1245840A
Date Of Birth	26/02/1957
Occupation	INDOOR
Date Of Driving Pass	24/02/1983
Driving Experience	35 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96785673
Fax Number	
Contact Number	OFFICE-96785673
E Mail Address	HSQUARENG@HOTMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was at Blk 114 Aljunied Crescent open space carpark. I was in my car. My car was in stationary position when vehicle GBH3897T reversed and its rear collided onto my car front portion. Damages to my car were on the front portion. No injuries were involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH3897T
Vehicle Make/Model/Colour	TOYOTA / DYNA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	YEW FOOK WENG
NRIC/Passport Number	
Contact Number	84978372
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

VERIFIED BY AJAX MARS


REPORTING OFFICER

Muhammad Faizal

Bin Pablia

Witnessed by Reporting Centre Personnel

Sketch Plan

	<p>B/114 AL-SUNICO CRESCENT ARRECK</p>
<p>A: SLC 39416 B: GSH 30475 (REVERSED)</p>	

Common Statement Pg. 1

ACCIDENT STATEMENT (2000 characters)

I was at Blk 114 Aljunied Crescent open space carpark. I was in my car. My car was in stationary position when vehicle GBH3897T reversed and its rear collided onto my car front portion. Damages to my car were on the front portion. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD FAIZAL BIN PABILA

MARS Officer:



Registered Owner or Driver's Signature

Job Complete Date/Time

8 November 2018 at 3:11 PM

Date/Time:

8 November 2018 at 3:11 PM

REPUBLIC OF SINGAPORE / DRIVING LICENCE

Licensee's Name NG HUI HIA

Birth Date: 26 Feb 1957

Issue Date: 28 Mar 2003

000324228C

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1245840A

Name NG HUI HIA

黄慧霞

Race CHINESE

Date of Birth 26-02-1957

Sex F

Country of Birth SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE 24 Feb 1983

NP 428A

Licence No: S1245840A

0961168

NRIC No: S1245840A

AB+

Date of Issue 17-05-1993

APT BLK 122 GEYLANG EAST CENTRAL #07-78

SINGAPORE 380122

NRIC No: S1245840A

Date: 24/12/2012

No: 7320210



VGS Singapore, 247, 159934 Singapore

NG HUI HIA
122 GEYLANG EAST CENTRAL
#07-76
Singapore, 380122
Singapore

Tanjik 97495749
WP
15/11/18 1030
sure like auto.com
Resurvey before paint
4 days.

VGS Singapore
247
Alexandra Road
159934 Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV033664
Quote No. SER/QUO/18C00048
QuoteDate 12/11/18
Salesperson Anthony Yong
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make Volkswagen Passeng	Model Description Polo GP 1.2 BMT DSG SR LED	Mileage 11,096	Service Advisor STEVEN CHEE
License No. SLC3941G	VIN WVWZZZ6RZGU023935	Initial Registration 12/05/16	Sales Advisor Anthony Yong
Engine Code	Labor Type 1L	Engine No. CJZ 757637	Model Code 6C13EZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P MACP LABOUR	LABOUR	4	UNIT	3360 ✓	3,360.00
P B&P MACP PAINT	SPRAY PAINT	4	Labor	✓ 1600	3,200.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un	✓ 480	480.00
P B&P MECH	COMPULSORY TO DO AFTER AC CHECK WIRE HARNESS, ECU, S	1	Time Un	✓ ✓	280.00
	Nett				
	Sum Labor				7,320.00
P 6C0807217B GRU	FRT BUMPER	1	Pieces	876.20	876.20
P 6C0807693	FRT BUMPER CTR BRACKET	1	Pieces	54.92	54.92
P 6C0853651 RYP	RADIATOR GRILLE	1	Pieces	319.41	319.41
P 6R0823031G	FRT BONNET	1	Pieces	1,040.36	1,040.36
	Use Predecessor 6R0823031E				
	Sum Item				2,290.89

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Explanations

P = Proportionately Charged

Payment Terms No Credit

Sum Labor	7,320.00
Sum Item	2,290.89
Total SGD	9,610.89
7% GST	672.76
Total SGD Incl. GST	10,283.65

Payments to: - BBN: - Acc.-No.:

11919.64

Service Order Confirmation

SERVICE ORDER NO: 18IP3032

CUSTOMER NO.: CV033664

CUSTOMER NAME: NG HUI HIA

TELEPHONE NO.:

ADDRESS: 122 GEYLANG EAST CENTRAL #07-76

Singapore

VEH No.: SLC3941G

Order Date: 20/11/18

Reg Date: 12/05/16

KM: 11,096

VIN NO.: WVVZZZ6RZGU023935

ENGINE NO:

SA: STEVEN CHEE

MODEL: Polo GP 1.2 BMT DSG SR LED

MODEL NO.: 6C13EZ

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P MECH CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1	TU	280		280
2	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	480		480
3	B&P SUNDRIES AIR CON GAS	48	TU	1.25		60 (A)
4	B&P AIRCON VACUUM & REGAS AIRCON-NETT	1	TU	420		420 (A)
5	B&P MACP LABOUR LABOUR + LOCK CARRIER	4	UNIT	840		3,360
6	B&P MACP PAINT SPRAY PAINT	2	LAB	800		1,600
7	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
8	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
Item						
9	6R0823031G FRT BONNET	1	PCS	1,040.36		1,040.36
10	6C0853651 RYP RADIATOR GRILLE	1	PCS	319.41		319.41
11	6C0853671A RYP CENTRE LOWER GRILLE	1	PCS	272.61		272.61 (A)
12	6R0805588AF LOCK CARRIER	1	PCS	682.30		682.30 (A)
13	6C0818411B A/C CONDENSER	1	PCS	827.07		827.07 (A)
14	G 013040M2 COOLANT ADD 1.5 Ltr Ready Mix	2	PCS	23.40		46.80 (A)

Remarks : CHINA TAIPING DIRECT SETTLEMENT

DOA : 08/11/2018

T/P VECH : GBH3897H

SURVEY BY : TAUFIK (LKK)

Service Order Confirmation

SERVICE ORDER NO: 18IP3032

CUSTOMER NO.: CV033664

CUSTOMER NAME: NG HUI HIA

TELEPHONE NO.:

ADDRESS: 122 GEYLANG EAST CENTRAL #07-76

Singapore

VEH No.: SLC3941G

Order Date: 20/11/18

Reg Date: 12/05/16

KM: 11,096

VIN NO.: WVVZZZ6RZGU023935

ENGINE NO:

SA: STEVEN CHEE

MODEL: Polo GP 1.2 BMT DSG SR LED

MODEL NO.: 6C13EZ

<u>No.</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>UOM</u>	<u>UNIT PRICE</u>	<u>DISC %</u>	<u>AMOUNT</u>
------------	--------------------	------------	------------	-------------------	---------------	---------------

TOTAL	9,388.55
GST AMOUNT	657.20
TOTAL AMOUNT	10,045.75

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

Supplementary or Omitted List



VEHICLE NUMBER: SLC3941G

MODEL POLO 1.2

CLAIMS DETAILS

	LABOUR DESCRIPTION	AMOUNT		
		Qty	Unit	Amount
1	B&P AIR CON GAS	48	\$ 1.25	\$ 60.00
2	VACUUM & REGAS AIRCON - NETT	1	\$ 420.00	\$ 420.00
3				
4				
5				
Total				\$480.00

No.	Item No.	Description	Qty	Unit Pricing	Discount	Amount
1	6C0853671A RYP	CENTRE LOWER GRILLE		\$272.61		\$272.61
2	6R0805588AF	LOCK CARRIER		\$682.30		\$682.30
3	6C0816411B	A/C CONDENSER		\$827.07		\$827.07
4	G 013040M2	COOLANT ADD 1.5 Ltr Ready Mix	2	\$23.40		\$46.80
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
TOTAL:						\$1,828.78

Total Labour & Parts

\$2,308.78

Survey By

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18020572/T1TBN2

Date: 15/02/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3035051800
Claimant Vehicle No :	SLC3941G	Insured Vehicle No :	GBH3897H
Date of Loss:	08/11/2018	Nature of Claim:	TP
		Claim No:	SNM18D05304C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC3941G	Engine No:	CJZ757637
Make & Model:	VOLKSWAGEN POLO, 1.2 A05 (A)	Chassis No:	WVWZZZ6RZGU023935
Reg. Date:	12/05/2016 (Man. Year: 2015)	Odometer:	13125 km
Colour:	Blue		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45R16	Rear Tyre Size:	215/45R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,119.67	3,188.55	931.12	22.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,800.00	6,200.00	1,600.00	20.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	11,919.67	9,388.55	2,531.12	21.23
+ GST 7.00/7.00% (\$\$)	834.38	657.20	177.18	21.23
Nett Amount (\$\$)	12,754.05	10,045.75	2,708.30	21.23

INSPECTION

Date of Assignment:	16/11/2018	
Date Inspected:	15/11/2018	Inspected At: Volkswagen Centre Singapore (MacPherson) 1 KAMPONG AMPAT Singapore 368314

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Feb 2019)
Parts: 144	VOLKSWAGEN POLO 1.2 A05 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLC3941G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Repair	876.20 FS	*- FS
2	1		*FRT BUMPER CTR BRACKET	Not Necessary	54.92 FS	*- FS
3	1		*RADIATOR GRILLE	Cut	319.41 FS	*319.41 FS
4	1		*FRT BONNET	Bent	1,040.36 FS	*1,040.36 FS
5	1		*CENTRE LOWER GRILLE	Cut	272.61 FS	*272.61 FS
6	1		*LOCK CARRIER	Cracked	682.30 FS	*682.30 FS
7	1		*A/C CONDENSER	Dented	827.07 FS	*827.07 FS
8	2		*COOLANT ADD 1.5 LTR READY MIX	Necessary	46.80 FS	*46.80 FS
Total Parts (S\$)					4,119.67	3,188.55

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	3,360.00	3,360.00
2	SPRAY PAINT	New	3,200.00	1,600.00
3	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	New	480.00	480.00
4	CHECK WIRE HARNESS ECU,S	New	280.00	280.00
5	B&P AIR CON GAS	New	60.00	60.00
6	VACUUM & REGAS AIRCON	New	420.00	420.00
Gross Labour Cost (\$\$)			7,800.00	6,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >