

ASS. REC. BY:

REF: CS/III18020577/Ksd36 Special Instruction:

Surveyor:

Kenneth

Menimen

From (Person):

Gabriel Wee

ASSIGNMENT (Office)

of

III

Date/Time:

14/11/18 @ 10:31 am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKN 8547H

Insured:

SHD 3464J

at Workshop m/s

Trust Autoworks

Tel:

9108 2728

of

BLK 5035 # 01-345 Amk Ind. Park 2

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

7/11/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:38 am @ 14/11/18

Person Contacted:

Anthony

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKN 8547H - NA / INC18020282 / 24

DOA: 7/11/2018

SHD 3464J - NA / INC18020282 / 24

DOA: 7/11/2018

11/11/18 8:48 am email
 01/12/18 8:52 am confirm Anthony

ASS. REC. BY:

REF: TH 1Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 814,800

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 10 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKN 85471Yr Regn: 03, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Toy Wishc.c. 1.794Colour: N. Black

A/C: Insured / Std / NI / NA

Sp. Reading: 163511

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDER12W 403003209Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size: King Long 1P5/65R15R: Newton

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear


R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 7/11/18D.O.I. 12/11/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time

Action / Instruction

11/11 File pass to Catherine, est not ready
 07/12/18 Confirmed HS \$ 5,200/- @ 10 days with Kenneth.
 (\$ 5,693.80 Red - 52%)

RECEIVED 07 DEC 2018

Date/Time, File Pass to?

07/12/18



: Prell. Report



: Final Report

Date/Time, File Return to?

Days Of Repair: 10

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee: 350

Transportation: _____

S + RS. SI

Fixtars

Others

TOTAL

360

Report Format :

Lump Sum / I.B.I. (\$

5,200/- HS

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 14 November 2018 10:31 AM
To: 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Subject: FW: PRS Notice for SKN 8547H
Attachments: 20181109111502107.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKN8547H and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Kelley Choong [<mailto:kelley@chiaarul.com>]

Sent: 09 November, 2018 5:33 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Re: PRS Notice for SKN 8547H

Our client proposes LKK Auto.

Thank you

Sent from my iPhone

On 9 Nov 2018, at 15:27, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Joel Nah

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 206 Fax: 6224 4174

From: Kelley Choong [<mailto:kelley@chiaarul.com>]

Sent: Friday, 9 November, 2018 11:17 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: jerone@chiaarul.com

Subject: PRS Notice for SKN 8547H

O/Ref: SKN 8547H (kc/jr)

Y/Ref: TBA

Dear Sirs,

We refer to the above matter.

Kindly find enclosed herewith the PRS Notice for your attention.

Please do not hesitate to contact us should you have any queries thereof.

Regards,

Ms Kelley Choong

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached

you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

<20181109111502107.pdf>

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S • A. RAVIDASS

Our Ref : SKN 8547H (Kc / Jr)

Your Ref :

9 November 2018

India International Insurance Pte Ltd
64 Cecil Street
#04/#05-00, IOB Building
Singapore 049711

BY EMAIL

Dear Sir,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : BETHLEHEM AUTO
ACCIDENT INVOLVING SKN 8547H & SHD 3464J ALONG WOODLANDS
TERRACE ON 7 NOVEMBER 2018
PRE-REPAIR INSPECTION NOTICE

1. We act for Bethlehem Auto, the owner of motor vehicle SKN 8547H, which was involved in the aforesaid accident.
2. We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. SHD 3464J damages, costs and disbursements as a result of your insured driver's negligence.
3. Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Trust Autoworks at Blk 5035 #01-345 Ang Mo Kio Industrial Pk 2 Singapore 569538 and kindly arrange with Mr Anthony Cheong at T: 9108 2728.
4. If we do not hear from you within the next **two (2) working days**, we shall advise our client to proceed with their own inspection and repairs.
5. Please reply either by fax at 6733 8183 or by email to kelly@chiaarul.com.

Yours faithfully,

MR ARULCHELVAN S

cc: Client (email)

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7232J
Vehicle Details	
Vehicle No.:	SKN8547H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 AUTO
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	1ZZ3237109
Chassis No.:	JTDER12W403003209
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,662.00
Original Registration Date:	25 Mar 2009
First Registration Date:	25 Mar 2009
Transfer Count:	3
Actual ARF Paid:	\$18,662.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Mar 2019
PARF Rebate Amount:	\$9,331.00
Intended COE Rebate Details	
COE Expiry Date:	24 Mar 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$4,889.00
COE Rebate Amount:	\$177.00
Total Rebate Amount:	\$9,508.00

The information contained herein is correct as at 13 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/11/2018 11:14
Date Of Accident	07/11/2018 16:40
Exact Location Of Accident	WOODLANDS TERRACE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN8547H
Insured/Policyholder	
Name Of Registered Owner	BETHLEHEM AUTO
Co Reg No	53347232J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90927202
Alternative Phone No	OFFICE-90927202

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH 1.8 AUTO
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5084781498-02
Cover Note Number	

Driver

Name of Driver	NIZAM BIN NOH
NRIC No	S6908035I
Date Of Birth	08/03/1969
Occupation	OUTDOOR
Date Of Driving Pass	09/10/1991
Driving Experience	27 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96335116
Fax Number	
Contact Number	OFFICE-96335116
Email Address	NOEMAIL

Address	BLK 536 WOODLANDS DRIVE 14
	#06-617
Postcode	730536
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY PARKED ON THE PARKING LOT OF WOODLANDS TERRACE FOR ABOUT 10 MIN FOR WAITING MY WIFE. SUDDENLY I FELT AN IMPACT OF MY VEHICLE. I ALIGHT FROM MY VEHICLE AND REALIZE THAT VEHICLE B HIT ONTO MY VEHICLE REAR RIGHT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD3464J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	KO HONG KWAN (GAO HONGGUANG)
NRIC/Passport Number	S7303261Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to statement.

DECLARATION

(/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trust Autoworks

Blk 5035 #01-369 Ang Mo Kio Industrial Pk 2 Singapore 569538
H/P 91082728

Bethlehem Auto
Blk 536 Woodlands Dr 14
#06-617
Singapore 730536

Vehicle No : SKN8547H
Make : Toyota Wish
Year : 2009

Not Authorized
1st Day 8 Days
Resurvey After Paint
8 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy	✓
1 pc	Rear tail-gate emblem " Logo "	✓
1 pc	Rear tail-gate inner trim board	? refer photo
1 pc	Rear tail-gate inner lock	✓
1 pc	Rear boot rubber	✓
1 pc	Rear o/s tail-lamp assy	✓
1 pc	Rear o/s fender	✓
1 pc	Rear o/s fender inner trim board	? refer photo
1 pc	Rear o/s fender air duct	✓
1 pc	Rear end panel	✓
1 pc	Rear end panel inner garnish	✓
1 pc	Rear bumper	✓
1 pc	Rear o/s bumper side retainer	✓
1 pc	Rear o/s bumper bracket	✓
1 pc	Rear o/s bumper reflector	✓
1 pc	Rear windscreen moulding	✓
1 pc	Rear exhaust silencer	? refer photo
1 pc	Rear exhaust silencer heat shield	? refer photo
1 pc	Rear o/s shock absorber	?
1 pc	Rear o/s hub assy	?

B ₁	\$1,096.50	—
RM	\$45.78	—
RM	\$395.10	✓
RM	\$425.94	✓
RM	\$291.61	50% ✓
B ₂₀	\$491.60	—
B ₂₀	\$1,025.60	—
B ₂₀	\$552.30	✓
CM	\$205.10	✓
B ₁	\$537.90	✓
RM	\$284.90	✓
B ₁	\$497.10	✓
CM	\$55.10	✓
B ₁	\$47.50	✓
RM	\$52.90	✓
RM	\$68.74	✓
RM	\$855.60	✓
B ₁	\$105.10	✓
RM	\$325.60	✓
RM	\$305.10	✓
	\$7,665.07	
Less 25 %	\$1,916.27	
	\$5,748.80	

S. Nett Item

1 pc	Rear reverse sensor
1 pc	Rear windscreen sealant
1 pc	Rear o/s tyre rim
1 pc	Rear o/s tyre

RM	\$200.00	✓
RM	\$55.00	40% ✓
RM	\$400.00	✓
RM	\$280.00	70% ✓
	\$935.00	
balance c/f	\$6,683.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SKN 8547 H

balance b/f \$6,683.80

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,500.00 1200l

To putty & spray paint on rear accident affected portion.

\$1,500.00 1200l

Check/reconnect wiring.

\$45.00 20l

To spray anti rust on accident affected portion.

\$120.00 90l

Remove/renew rear windscreen glass

\$100.00 ✓

Remove/refit rear boot lid lock mechanism, inner trim to new lid..

\$100.00 60l

Remove/renew exhaust silencer

\$200.00 60l

Remove/refit rear boot upholstery to facilitate repair

\$120.00 ✓

Four wheel towing (Troller)

(B711) \$120.00 700l

Remove/renew rear o/s undercarriages

~ \$350.00 X

Check and realign wheel alignment

\$60.00 ✓

Total \$10,898.80

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2018 11:58 Edit Reg		14 Nov 2018 00:00 Edit Adj Rpt	S\$5,200.00 Edit Estimates	S\$5,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: ~, Co. Reg. No.: -									
Main Claimant: -									
Vehicle Reg. No.: SKN8547H		Date of Loss: 07/11/2018 00:00 - :59 [115 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SHD3464J		Policy No. (Claimant):							
		Excess:							
Repairer: Trust Autoworks (HQ) BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541, 569541 Ang Mo Kio - Tel:									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 23/11/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKN8547H

[SHD3464J]

TP

-

Nov 7 2018 12:00AM

[-]

Trust Autoworks

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
2	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
3	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
4	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
5	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
6	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
7	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
8	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
9	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
10	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
11	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
12	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
13	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
14	07/12/18 09:44	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
15	07/12/18 09:44	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
16	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
17	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
18	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
19	07/12/18 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
20	07/12/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
21	07/12/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
22	07/12/18 09:46	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
23	07/12/18 09:46	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
24	07/12/18 09:46	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
25	07/12/18 09:46	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
26	07/12/18 09:46	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	15/11/18 09:15	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III18020577/KSD3E2

Date: 26/12/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SKN8547H

Insured Vehicle No : SHD3464J

Date of Loss: 07/11/2018

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKN8547H

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ3237109

Reg. Date: 25/03/2009 (Man. Year: 2009)

Chassis No: JTDER12W403003209

Colour: Metallic Black

Odometer: 163511 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Linglong 8 mm

Rear Left Side: Neuton 8 mm

Front Right Side: Linglong 8 mm

Rear Right Side: Neuton 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,683.80	4,997.17	1,686.63	25.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,215.00	3,010.00	1,205.00	28.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,898.80	8,007.17	2,891.63	26.53
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	10,898.80	5,200.00	5,698.80	52.29

INSPECTION

Date of Assignment: 14/11/2018

Date Inspected: 12/11/2018 Inspected At:

BLK 5035 # 01-345 AMK IND.PARK 2

Repairer : Trust Autoworks (HQ)

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Dec 2018)
Parts: M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKN8547H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL-GATE ASSY	Bent	1,096.50 FL	*1,096.50 FL
2	1		*REAR TAIL-GATE EMBLEM LOGO	Necessary	45.78 FL	*45.78 FL
3	1		*REAR TAIL-GATE INNER TRIM BOARD	Mtg Cracked	395.10 FL	*395.10 FL
4	1		*REAR TAIL-GATE INNER LOCK	Dented	425.94 FL	*425.94 FL
5	1		*REAR BOOT RUBBER (\$291.61) (50%)	Cut	218.71 FS	*145.80 FS
6	1		*REAR O/S TAIL-LAMP ASSY	Broken	491.60 FL	*491.60 FL
7	1		*REAR O/S FENDER	Buckled	1,025.60 FL	*1,025.60 FL
8	1		*REAR O/S FENDER INNER TRIM BOARD	Buckled	552.30 FL	*552.30 FL
9	1		*REAR O/S FENDER AIR DUCT	Cracked	205.10 FL	*205.10 FL
10	1		*REAR END PANEL	Bent	537.90 FL	*537.90 FL
11	1		*REAR END PANEL INNER GARNISH	Distorted	284.90 FL	*284.90 FL
12	1		*REAR BUMPER	Bent	497.10 FL	*497.10 FL
13	1		*REAR O/S BUMPER SIDE RETAINER	Cracked	55.10 FL	*55.10 FL
14	1		*REAR O/S BUMPER BRACKET	Bent	47.50 FL	*47.50 FL
15	1		*REAR O/S BUMPER REFLECTOR	Broken	52.90 FL	*52.90 FL
16	1		*REAR WINDSCREEN MOULDING	Necessary	68.74 FL	*68.74 FL
17	1		*REAR EXHAUST SILENCER	Repair	855.60 FL	*- FL
18	1		*REAR EXHAUST SILENCER HEAT SHIELD	Bent	105.10 FL	*105.10 FL
19	1		*REAR O/S SHOCK ABSORBER	Serviceable	325.60 FL	*- FL
20	1		*REAR O/S HUB ASSY	Serviceable	305.10 FL	*- FL
21	1		*REAR REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	55.00 FS	*40.00 FS
23	1		*REAR O/S TYRE RIM	Serviceable	400.00 FS	*- FS
24	1		*REAR O/S TYRE (70%)	Punctured	280.00 FS	*196.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,527.17	6,468.96
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,843.37	1,471.79
Total Parts (\$\$)	6,683.80	4,997.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING	New	1,500.00	1,200.00
2	TO PUTTY & SPRAY PAINT ON REAR ACCIDENT AFFECTED PORTION	New	1,500.00	1,200.00
3	CHECK / RECONNECT WIRING	New	45.00	20.00
4	REMOVE / RENEW REAR WINDSCREEN GLASS	New	100.00	100.00
5	REMOVE / REFIT REAR BOOT LID LOCK MECHANISM, INNER TRIM TO NEW LID	New	100.00	60.00
6	REMOVE / RENEW EXHAUST SILENCER	New	200.00	60.00
7	REMOVE / REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	120.00	120.00
8	FOUR WHEEL TOWING (TROLLER)	New	120.00	100.00
9	REMOVE / RENEW REAR O/S UNDERCARRIAGES	New	350.00	0.00
10	CHECK AND REALIGN WHEEL ALIGNMENT	New	60.00	60.00
11	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	120.00	90.00
Gross Labour Cost (S\$)			4,215.00	3,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >