

ASS. REC. BY:

REF:

REF: CS/CTU18020578/Jsber

Special Instruction:

Surveyor

Մոհամեդ

ASSIGNMENT (Office)

From (Person):

Ung Chin Kiat

of

CTL

Date/Time:

14.11.2018 11:14am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 5053T

Insured:

GBH 4780P

at Workshop m/s

Triple H Automotive

Tel:

of

14 Defu Lure 10 #01-398

Policy No:

DM CVS 141819 U51800

Claim No:

SNM18D05142C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29.103018

(Client's Record)

CA / REV / REP. / REV 24 HRS' WP'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle **IN/OUT**

Date/Time

Action/Instruction	(✓) Estimate
--------------------	----------------

Hwee Jie

REF: CTL

ASSIGNMENT

LOE till 26 May 2023

From Date: 07.11.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKV 5053T
at Workshop n/s Triple H Automotive
of 14 Detu Lane 10 #01-398

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKV 5053T Yr Regn: 27 May 2008

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios C/C 1497

Colour: Black A/C Insured / Std / NI / NA

Sp. Reading: 243753 T/Radio: Insured / Std / NI / NA

Eng/No: 1N2X756491

C/No: MR053HY9305064543

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 29/10/18

Survey held at

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 7/11/18

@ 1400

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 26,000

PV - 17,381

NV - 8619

3/12 Confirmed L/S \$5,400/- with 7 days repair

03/12/18 Confirmed L/S \$5,400/- @ 7 days with Hwee Jie.
(\$10,388.70 Red - 66%)

RECEIVED 04 DEC 2018

Date/Time: File Pass to?

04/12/18



Preli. Report

1) Typist



Final Report

Date/Time: File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 2

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Report Format:

Lump Sum / I.B.I: \$ 5,400/- 4/s

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Oct 2018		14 Nov 2018 11:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SHUN HONG PTE LTD , Co. Reg. No.: 201414931C		
Main Claimant:	TAY AUTO , Co. Reg. No.: 53382969X		
Vehicle Reg. No.:	SKV5053T	Date of Loss:	29/10/2018 16:00 - :59 [125 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D05142C02	Policy/Cover Note No.:	DMCVSN1819051800 (Comprehensive) Coverage: 18/06/2018 - 17/06/2019
Vehicle Reg. No. (Insured):	GBH4780P	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Triple H Automotive Service (HQ) BLK 1065 EUNOS AVE 4 #01-156 SINGAPORE 409799, 409799 Eunos - Tel: 6842 5883		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/11/2018]		
Driver/Custodian (Insured):	RANA MD SALIM (26 / Male), NRIC: G2353301X		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	2969X
Vehicle Details	
Vehicle No.:	SKV5053T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	1NZX756491
Chassis No.:	MR053HY9305064543
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,344.00
Original Registration Date:	27 May 2008
First Registration Date:	27 May 2008
Transfer Count:	2
Actual ARF Paid:	\$12,344.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 May 2023 ✓
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,096.00
COE Rebate Amount:	\$17,381.00
Total Rebate Amount:	\$17,381.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 Nov 2018

OK

Bal = 4yrs 7mths



Village Hotel Bugis
\$136

[Learn more](#)



Furama RiverFront
\$182

[Learn more](#)



Hotel Je Orchard
\$200

[Learn more](#)

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)

[Advertiser Login](#)

[Ways of Selling](#)

Classic Offer! Best Deal! Fast Selling! Hurry Down Now!



Selling Cheap! Come And Get It
Fast! Low Depre Yrly! Lots Of
New COE Cars Avail.
Classic Credit [StarAd](#)

Lake View Credit Pte Ltd

[view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category ▾

« Back (1 2) Next »

Sort by Date Posted ▾

40 results/page ▾

78 vehicles

toyota vios e

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota vios e		Any	Any	2008	Any	Any	Any	Available
	Toyota Vios	1.5A E (New 5-yr COE)	\$27,800	\$5,560 /yr	17-Oct-2008	1,497 cc	-	Sedan	Available
2.88% P.a Nett By GV Cars Financing At \$2000 Downpayment From \$488 Lowest Monthly With 100% Loan Approval. 2 Years Warranty By GV In House Workshop. New \$2k Metallic Paint/6 Months Road Tax. Extra Add... 2.88%P.A Lowest Interest@Gv Cars Financing \$2000 Downpayment Monthly From \$488 GV Credit Pte Ltd Posted: 08-Nov-2018 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota									
	Toyota Vios	1.5M E Sports (COE till 01/2023)	\$26,500	\$6,270 /yr	29-Jan-2008	1,497 cc	86,800 km	Sedan	Available
Schedule A Test Drive Today. Viewing Is Strictly By Appointment Only. Carro Posted: 26-Oct-2018 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota									
	Toyota Vios	1.5A E (COE till 04/2023)	\$29,800	\$6,760 /yr	07-Apr-2008	1,497 cc	138,000 km	Sedan	Available
Low Down Payment Of 4\$K For Sporty Toyota Vios, Very Fuel Efficient! A Practical, Stylish And Comfortable Car That You Wouldn't Want To Miss! Buy It From Us With A Peace Of Mind, Trade In Welcome. Be ... Tay Motor & Credit Pte Ltd Posted: 28-Oct-2018 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota									
	Toyota Vios	1.5A E (COE till 05/2023)	\$27,000	\$5,990 /yr	13-May-2008	1,497 cc	-	Sedan	Available
Elegant Beige, Low Fuel Consumption, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-House Loan Packages Available. Prime Motor & Leasing Posted: 31-Oct-2018 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota									
	Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	Toyota Vios	1.5A E (New 5-yr COE)	\$29,800	\$5,960 /yr	25-Jul-2008	1,497 cc	178,000 km	Sedan	Available
\$0 Down, 100% Loan Available! New Paintwork New Leather Seats, Best For Grab And Transportation Usages! Call Now! ABWIN (1994) Pte Ltd Posted: 31-Oct-2018 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota									
	Toyota Vios	1.5A G (New 5-yr COE)	\$28,800	\$5,760 /yr	12-Aug-2008	1,497 cc	-	Sedan	Available
Excellent Condition G Model, Very Well Maintained By Previous Owner. Fuel Efficient And Responsive Engine! Call Now To Arrange For Viewing And Test Drive! Posted: 09-Sep-2018 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota									

[Compare](#)

Shirley Hiew (LKK Auto)

From: Jh G <gjh-wjh@hotmail.com>
Sent: Monday, 3 December 2018 4:50 PM
To: Admin-D (LKKAuto)
Subject: Re: SKV 5053T
Attachments: Frt View 2.JPG; Frt View 3.JPG; Frt View.JPG; Inner boot.JPG; Rear Full View.JPG; Rear Left Side View.JPG; Rear Left View.JPG; Rear Lid Cargo.JPG; Rear Lid.JPG; Rear right view.JPG; Rear View 2.JPG; Rear View 3.JPG; Rear View.JPG; Finalisation Invoice for (SKV5053T).pdf; Invoice For Rental (SKV5053T).pdf; LTA Search (SKV5053T).pdf

Hi,

Confirmed with acceptance.

Please proceed on you end.

Please refer to the attached for the final repair bill, rental invoice and after paint photos.

Anything i missed out, please call me at 97718731. (Mr Hui)

Thank You.

Best Regards,
Mr Hui

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, December 3, 2018 4:29 PM
To: gjh-wjh@hotmail.com
Cc: assignments; SUR
Subject: SKV 5053T

Dear Mr Hui,

Kindly refer to the attachment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/10/2018 16:06
Date Of Accident	29/10/2018 16:10
Exact Location Of Accident	SELETAR CLUB ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV5053T
Insured/Policyholder	
Name Of Registered Owner	TAY AUTO
Co Reg No	53382969X
Email Address	TAYZW@LIVE.COM
Mobile Phone No	
Alternative Phone No	OFFICE-92376232

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 E (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V05932/VPL/R00
Cover Note Number	14/06/2018 TO 13/06/2019

Driver

Name of Driver	TAY ZHI WEI
NRIC No	S8928256Z
Date Of Birth	22/08/1989
Occupation	OUTDOOR
Date Of Driving Pass	13/12/2013
Driving Experience	4 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92376232
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 137 LORONG AH SOO #09-528 (S) 530137
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH4780P
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAY ZHI WEI
Approximate Age	

Injuries Sustain

KHOO TECK PUAT HOSPITAL - 1DAYS OF MC

Injured person in which vehicle?

SKV5053T

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

Accident Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along the straight road. The car in front slow down, so I slow down, the lorry came from behind at a very high speed from quite a distance and ran into me. The impact is so hard I hit my head. I called for an ambulance and police came shortly after.

Insurance Co.	Liberty Insurance PLC
Vehicle No.	SKV5053T
Date of Accident	30/10/2018
<input type="checkbox"/> Reporting Unit	
<input type="checkbox"/> Own Damage Claim	
<input type="checkbox"/> Third Party Claim	
<input checked="" type="checkbox"/> Other Workshop	


DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Liberty Insurance Pte Ltd
 Registration no. 199002791D
 51 Club Street
 #03-00 Liberty House
 Singapore 069428
 Tel: (65) 6221 8611 Fax: (65) 6226 3360

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No	SD18V05932 /VPL /R00
From	MZ400B
Date Of Issue	14-JUN-2018
1.Index Mark and Registration No. of Vehicle:	SKV5053T
2.Chassis number of Vehicle:	MR053HY9305064543
3.Name of Policyholder:	TAY AUTO
4.Effective date of Commencement of Insurance for the purpose of the Act:	14-JUN-2018 00:00 AM
5.Date of Expiry of Insurance:	13-JUN-2019 23:59 PM
6.Persons or Classes of Persons entitled to drive*:	TAY ZHI WEI
For Uber/Grabcar Usage :	
For Social, domestic & pleasure purposes : Any Authorised Drivers driving with the permission of the Policyholder.	
<p>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.</p> <p>And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.</p>	
7.Limitations as to use*:	
A) Use for carriage of passengers or goods in connection with the Policyholder's business.	
B) Use for social, domestic and pleasure purposes.	
8.Policy does not cover:	
A) Use for racing, pace-making, reliability trials or speed-testing.	
B) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.	
*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.	
We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).	
For and on behalf of LIBERTY INSURANCE PTE LTD Approved Insurers  Authorised Signature	
For Information only	Comprehensive, Unlimited Windscreen, Uber/Grabcar Extension (Geographical Area: Singapore only)
COVERAGE :	MARKET VALUE AT THE TIME OF LOSS
SUM INSURED:	Section I (Singapore) S\$2000, Section I (Outside Singapore) S\$4000, Section II (Singapore) S\$1500, Section II (Outside Singapore) S\$3000, Windscreen Excess S\$100
EXCESS	
FINANCE COMPANY:	THIAM HENG AUTO (S) PTE LTD
PRODUCER NAME	TWH CONSULTANCY PTE LTD

PLYW 20180614

Ver.1.260705



Khoo Teck Puat Hospital
90 Yishun Central
Singapore 768828
Tel: (65) 6555 8000
Fax: (65) 6602 3700
Website: www.ktph.com.sg

MEDICAL CERTIFICATE

ORIGINAL

KHANE181462909

NAME : TAY ZHI WEI
NRIC : S8928256Z

Type of Medical Leave granted : **OUTPATIENT SICK LEAVE**

The above named attended Examination/Treatment from **29 Oct 2018 17:30** to **29 Oct 2018 18:55**

The above named is unfit for duty for a period of **1** day(s), from **30 Oct 2018** to **30 Oct 2018** inclusive.

The Certificate is **not valid** for absence from court attendance.

Remarks :

29 Oct 2018
Date Issuing Doctor **Dr Chia, Hooi Tzing (62864F)**

A&E
Location

Doctor's Signature

Reg No. : 200717564H

----- Tear Along Here -----



Khoo Teck Puat Hospital
90 Yishun Central
Singapore 768828
Tel: (65) 6555 8000
Fax: (65) 6602 3700
Website: www.ktph.com.sg

MEDICAL CERTIFICATE

DUPLICATE

KHANE181462909

NAME : TAY ZHI WEI
NRIC : S8928256Z

Type of Medical Leave granted : **OUTPATIENT SICK LEAVE**

The above named attended Examination/Treatment from **29 Oct 2018 17:30** to **29 Oct 2018 18:55**

The above named is unfit for duty for a period of **1** day(s), from **30 Oct 2018** to **30 Oct 2018** inclusive.

The Certificate is **not valid** for absence from court attendance.

Remarks :

29 Oct 2018
Date Issuing Doctor **Dr Chia, Hooi Tzing (62864F)**

A&E
Location

Doctor's Signature

Reg No. : 200717564H

Triple H Auto Pte Ltd

Blk 14 Defu Lane 10

#01-398

Singapore 539195

H/P: 9771 8731 / 9054 5425

Email: gjh-wjh@hotmail.com

Business Registration : 201818087Z

CASH SALE

Invoice Date: 01/11/18

Vehicle No: SKV5053T

Make/Model: Toyota Vios

Chassis No:

Mileage:

To: 3rd Party Claim

S/N	QUANTITY	PARTICULARS	UNIT PRICE	AMOUNT (\$)	
01	01	Rear Bumper DD		\$235.40	/
02	01	Rear Boot DD		\$513.60	/
03	01	Rear Inner Panel DD		\$620.60	/
04	01	Rear Windscreen CRA		\$480.00	/
05	02	Windscreen Gums NEC	50	\$80.00	/
06		Windscreen Labour	120	\$150.00	/
07	1 Set	Rear Brake Pads NN		\$96.30	X
08	02	Rear Wheel Bearing NN	\$192.60	\$385.20	X
09	02	Exhaust Mounting NN	\$38.00	\$76.00	X
10	02	Rear Tail Lamp CRA	\$192.60	\$385.20	/
11	02	Rear Bumper Retainer (Small) NN	\$40.60	\$81.20	X
12	02	Rear Bumper Retainer (Big) CRA	\$42.80	\$85.60	/
13		Rear Boot Moulding DD		\$117.70	/
14		Private Hire Sticker NEC (SN)		\$20.00	/
15		Computerise Wheel Alignment		\$150.00	X
16	1 Set	Reverse Sensor MIS		\$180.00	/
17		Reverse Sensor Labour	50	\$120.00	/
18	1 Set	Rear Boot Lock DM		\$124.00	/
19		Rear Bumper Plastic Garnish CRA	120	\$192.60	/
20		Tow Hook NN		\$64.20	X
21		Exhaust NN		\$380.00	X
22	02	Rear Boot Hinges DD BT	\$68.00	\$136.00	/
23		Windscreen Moulding NEC		\$117.70	/
24	LH	Tail Lamp Panel DD	249.6	\$706.20	/
25	LH	Rear Fender DD BUC		\$770.00	/
26	2	Rear Disc Rotor NN	\$180.00	\$360.00	X
27		Rear Axle NN		\$1600.00	X

28		Rear Axle Dismantle & Installation Labour	NN		\$800.00	X
29	1 Set	Rear Suspension	NN	\$81.00	\$162.00	X
30	2	Brake Calipers	NN	\$53.50	\$107.00	X
31		Petrol Tank Pipe	NN		\$55.00	X
32		Number Plate	NN		\$60.00	X
33		Number Plate Lamp	CRA		\$55.00	/
34		Toyota Emblem, Vios Emblem	NEC	90	\$120.00	/
01	Labour For Accident Area & Above Parts Installation			1400	\$2600.00	
02	Spray Painting For Accident Area			1200	\$1800.00	
Total:					\$13,986.50	

Subject parts will ~~deduct~~
25% discount.

15,788.70

NET-\$5400

7 days

L/S


15/11/18.

Qty Hwee Die - 91803151

7/11/18

after

Re-survey, Dismantle & After paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after painting
- To display damaged part(s) on resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Triple H Auto Pte Ltd

Blk 14 Defu Lane 10

#01-398

Singapore 539195

H/P: 9771 8731 / 9054 5425

Email: gjh-wjh@hotmail.com

Business Registration : 201818087Z

CASH SALE

Invoice Date: 12/11/18

Vehicle No: SKV5053T

Make/Model: Toyota Vios

Chassis No:

Mileage:

To: 3rd Party Claim

S/N	QUANTITY	PARTICULARS	UNIT PRICE	AMOUNT (\$\$)
01	01	Spare Tyre Sponge CRA	195	\$385.20 ✓
02		Spare Tyre Panel DD Buc	580	\$727.60 ✓
03		Number Plate Garnish CRA	20	\$160.50 ✓
04		Duct Assy Quarter Vent (Left Side) CRA	89.6	\$171.20 ✓
05	2	Rear Bumper Reflector CRA	\$53.50	\$107.00 ✓
06	1 Set	Rear Brake Light NN		\$117.70 X
07	35 pcs	Clips NEC	\$3.80	\$133.00 ✓
				60
			Total:	\$1802.20

25% Discount to Subject Parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Oct 2018		14 Nov 2018 11:14 Edit Adj Rpt	S\$5,400.00 Edit Estimates	S\$5,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

SHUN HONG PTE LTD, Co. Reg. No.: 201414931C

Main Claimant:

TAY AUTO, Co. Reg. No.: 53382969X

Vehicle Reg. No.:

SKV5053T

Claim Type:

TP / SNM18D05142C02

Vehicle Reg. No. (Insured):

GBH4780P

Repairer:

Triple H Automotive Service (HQ) BLK 1065 EUNOS AVE 4 #01-156 SINGAPORE 409799, 409799 Eunos - Tel: 6842 5883

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 23/11/2018]

Driver/Custodian (Insured):

RANA MD SALIM (26 / Male), NRIC: G2353301X

Date of Loss:

29/10/2018 16:00 - :59
[125 Months and 2 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

DMCVSN1819051800 (Comprehensive)
Coverage: 18/06/2018 - 17/06/2019

Policy No. (Claimant):

Excess:

S\$0.00

[Created by insurer]

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS





































[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKV5053T (SNM18D05142C02)
 [GBH4780P]
 TP
 TAY AUTO
 Oct 29 2018 4:00PM
 [SHUN HONG PTE LTD]
 Triple H Automotive Service

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
2	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
3	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
4	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
5	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
6	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
7	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
8	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
9	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
10	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
11	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
12	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
13	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
14	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
15	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
16	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
17	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
18	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
19	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
20	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
21	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
22	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
23	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
24	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
25	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
26	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
27	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
28	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
29	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
30	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
31	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
32	03/12/18 17:21	General View						Load JPG	<input checked="" type="checkbox"/>	
33	03/12/18 17:22	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
34	03/12/18 17:22	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
35	03/12/18 17:22	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
36	03/12/18 17:22	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
37	03/12/18 17:22	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	03/12/18 17:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	03/12/18 17:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	03/12/18 17:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	03/12/18 17:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	03/12/18 17:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	03/12/18 17:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	03/12/18 17:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	03/12/18 17:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	03/12/18 17:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	03/12/18 17:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	03/12/18 17:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	03/12/18 17:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	03/12/18 17:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	03/12/18 17:23	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/11/18 11:14	insd gia report	 Load PDF	
2	14/11/18 11:14	tp gia report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/18 14:59	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118020578/JSBE2

Date: 05/12/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1819051800

Claimant Vehicle
No: SKV5053TInsured Vehicle
No: GBH4780P

Date of Loss: 29/10/2018

Nature of Claim: TP

Claim
No: SNM18D05142C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV5053T

Make & Model: TOYOTA VIOS, 1.5 E (A)

Reg. Date: 27/05/2008 (Man. Year: 2008)

Colour: Black

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 1NZX756491

Chassis No: MR053HY9305064543

Odometer: 243753 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,168.70	4,056.50	6,112.20	60.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,620.00	2,770.00	2,850.00	50.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,788.70	6,826.50	8,962.20	56.76
Approved Total (Overridden) (S\$)		5,400.00		
Nett Amount (S\$)	15,788.70	5,400.00	10,388.70	65.80

INSPECTION

Date of Assignment: 14/11/2018

Date Inspected: 07/11/2018 Inspected At:

14 DEFU LANE 10 #01-398
Repairer : Triple H Automotive Service
(HQ)

Estimated Period of Repair: 7.0 days

Adjuster: ONG HWEE JIE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2018)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV5053T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	235.40 F	*235.40 FL
2	1		*REAR BOOT	Dented	513.60 F	*513.60 FL
3	1		*REAR INNER PANEL	Dented	620.60 F	*620.60 FL
4	1		*REAR WINDSCREEN	Cracked	480.00 F	*480.00 FL
5	2		*WINDSCREEN GUMS	Necessary	80.00 F	*50.00 FL
6	1		*SET REAR BRAKE PADS	Not Necessary	96.30 F	*- FL
7	2		*REAR WHEEL BEARING	Not Necessary	385.20 F	*- FL
8	2		*EXHAUST MOUNTING	Not Necessary	76.00 F	*- FL
9	2		*REAR TAIL LAMP	Cracked	385.20 F	*385.20 FL
10	2		*REAR BUMPER RETAINER (SMALL)	Not Necessary	81.20 F	*- FL
11	2		*REAR BUMPER RETAINER (BIG)	Cracked	85.60 F	*85.60 FL
12	1		*REAR BOOT MOULDING	Dented	117.70 F	*117.70 FL
13	1		*PRIVATE HIRE STICKER	Necessary	20.00 FS	*20.00 FS
14	1		*SET REVERSE SENSOR	Missing	180.00 F	*180.00 FL
15	1		*SET REAR BOOT LOCK	Damaged	124.00 F	*124.00 FL
16	1		*REAR BUMPER PLASTIC GARNISH	Cracked	192.60 F	*120.00 FL
17	1		*TOW HOOK	Not Necessary	64.20 F	*- FL
18	1		*EXHAUST	Not Necessary	380.00 F	*- FL
19	2		*REAR BOOT HINGES	Dented / Bent	136.00 F	*136.00 FL
20	1		*WINDSCREEN MOULDING	Necessary	117.70 F	*117.70 FL
21	1		*LH TAILLAMP PANEL	Dented	706.20 F	*249.60 FL
22	1		*LH REAR FENDER	Dented / Buckled	770.00 F	*770.00 FL
23	2		*REAR DISC ROTOR	Not Necessary	360.00 F	*- FL
24	1		*REAR AXLE	Not Necessary	1,600.00 F	*- FL
25	2		*SET REAR SUSPENSION	Not Necessary	162.00 F	*- FL
26	2		*BRAKE CALIPERS	Not Necessary	107.00 F	*- FL
27	1		*PETROL TANK PIPE	Not Necessary	55.00 F	*- FL
28	1		*NUMBER PLATE	Not Necessary	60.00 F	*- FL
29	1		*NUMBER PLATE LAMP	Cracked	55.00 F	*55.00 FL
30	1		*TOYOTA EMBLEM, VIOS EMBLEM	Necessary	120.00 F	*90.00 FL
31	1		*SPARE TYRE SPONGE	Cracked	385.20 F	*195.00 FL
32	1		*SPARE TYRE PANEL	Dented / Buckled	727.60 F	*580.00 FL
33	1		*NUMBER PLATE GARNISH	Cracked	160.50 F	*20.00 FL
34	1		*DUCT ASSY QUARTER VENT (LEFT SIDE)	Cracked	171.20 F	*89.60 FL
35	2		*REAR BUMPER REFLECTOR	Cracked	107.00 F	*107.00 FL
36	1		*SET REAR BRAKE LIGHT	Not Necessary	117.70 F	*- FL
37	1		*CLIPS (35PCS)	Necessary	133.00 F	*60.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 10,168.70 5,402.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 0.00/25.00% (S\$)					0.00	1,345.50
Total Parts (S\$)					10,168.70	4,056.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WINDSCREEN LABOUR	New	150.00	120.00
2	COMPUTERISE WHEEL ALIGNMENT	New	150.00	0.00
3	REVERSE SENSOR LABOUR	New	120.00	50.00
4	REAR AXLE DISMANTLE & INSTALLATION LABOUR	New	800.00	0.00
5	LABOUR FOR ACCIDENT AREA & ABOVE PARTS INSTALLATION	New	2,600.00	1,400.00
6	SPRAY PAINTING FOR ACCIDENT AREA	New	1,800.00	1,200.00
Gross Labour Cost (S\$)			5,620.00	2,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >