

25/10/2018

ASS. REC. BY: REF: CS3/ III 18013910/ Nsb²⁷ Special Instruction: /

Surveyor: AlaZ ASSIGNMENT (Office)

From (Person): Jou Nah of III Date/Time: 14/11/2018

Estimated Cost: Bill to:

OD TP / VS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBF 2734 Y Insured: SHB 10734

at Workshop in: Ong Motor Tel: 8380 2233

of 464 Macpherson Rd

Policy No: Claim No: MCT18070837

Sum Insured: Excess:

Make of Veh: D.O.A. 28/07/2018
(Client's Record) 01/08/2018

CA / REV / REP. / REV 24 HRS rup H.O.D. Endorsement:


Date/Time: 4:20pm 03/7/18 Person Contacted: Jacley Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>FBF 2734 Y - NA / INC 18013854 / K4</u> <u>D.O.A. 28/7/2018</u>
	<u>SHB 10734 - NA / INC 18013854 / K4</u> <u>D.O.A. 28/07/2018</u>

19/11/18 Clear photograph in Mui men.
Submit LRs \$4,400/- @ 5' days
(\$9,000/- Red - 67%)

RECEIVED 19 NOV 2018

Repair days 5


16/11/2018

Termin lin

350-20=270

15/11/18

ASSIGNMENT

From:

Date: 01/08/18

Estimated Cost:

ON ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBF 2734Y

at Workshop m/s

of

Only Motor
464 Macpherson Rd

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Jaaky @ 8380 2233

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

cup

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBF 2734Y

Yr Regn: ATR 12013

Type: M.Car / ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA FZ1

c.c 998

Colour:

BLACK

A/C: Insured / Std / NI / ☒ NA

Sp. Reading:

133,920

T/Radio: Insured / Std / NI / ☒ NA

Eng/No:

C/No:

JYARN16R000000345

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size:

F: 120 / 70 2R17

R: 190 / 55 2R17

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / CHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

mm

L/Bal:

mm

D.O.A.

D.O.I.

Survey held at

only motor

Des. of Damages: Frt / Rear / ☒ O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/8/18

Submitted the report

Date/Time, File Pass to?

19/11/12

1)

typist

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 4,400/- 45)

80

10

90

Catherine Chong (LKK Auto)

From: Joel Nah Shern Ern <JoelNah@iii.com.sg>
Sent: Wednesday, 14 November, 2018 11:15 AM
To: 'Catherine Chong (LKK Auto)'
Cc: Sundari Nagarajan - III
Subject: rights have been granted for this case MCT18070837

Dear all,

Rights have been granted for this LOD.

Kindly conduct a reappraisal for this claim.

Thanks.

Joel Nah
Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street #04-02 IOB Building
Singapore 049711
Tel: 6347 6100 Ext 206 Fax: 6224 4174

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Catherine Chong (LKK Auto)

From: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Sent: Monday, 29 October, 2018 2:19 PM
To: Hsiao Tong (LKKAuto); assignments; Admin A
Subject: FW: MCT18070837

From: Mekavathanan Sarangapani
Sent: Monday, 29 October 2018 2:19:34 PM (UTC+08:00) Kuala Lumpur, Singapore
To: Olivia Lau (LKKAuto); KKLau
Cc: Sundari Nagarajan - III; Natalia Lim
Subject: MCT18070837

Very Urgent

Dear Olivia and team

We have recd LOD for TPPD claim (costs of repairs) thru Chia S Arul. However Ong Motors is an ARC :

Ong motor is an ARC

HPH Auto Service	HQ	Blok 900B Tampines Street 93	#01-246/254	3288
Ong Motors	HQ	454 Macpherson		3681

And it is a breach of the ARC aggt to engage TP Lawyers for which we are now considering action thru GIA .

Please confirm if PRI was carried out at Ong Motors and repairs too were duly carried out there, as repair bill is from Moto 51 Pte Ltd and are they relatd ?

Natalia will provide rights for you to access docts .

Sundari – Please view CCTV footage (see below excerpt) traffic held up at both sides of the yellow box junction and yet M/bike proceeded forward – Is this assessment correct ??

Please carry out Paper survey please on a w/ admission of liability basis .


Main	Offer Processing	Claim Details	Adjuster's Details	De
CLAIM SUBFOLDER DETAILS				[Created by adjuster]
Insured:	-, Co. Reg. No.: -			
Main Claimant:	-			
Vehicle Reg. No.:	FBF2734Y	Date of Loss:	28/07/2018 00:00 - :59 [87 Months and 13 Days f	
Claim Type:	TP / MCT18070837	Policy/Cover Note No.:	MCOM0015	
Vehicle Reg. No. (Insured):	SHB4073H	Policy No. (Claimant):		
		Excess:		
Repairer:	Ong Motors (HQ) PROFILE 464 Macpherson, 368182 Macpherson - Tel:			
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] 15/08/2018]			
CLAIM REGISTERED				
Cim. No (Cim Reg Date)	MCT18070837 (14/08/2018)		Intimation (Notify Date)	From TP C
Registration Type	[Manually registered]		Claim Status	OPEN
Incurred	TP			
St	0.00			

TP's nature and extent of damage :



TP's version – vehicles stopped at yellow junction:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 28/07/18 at @ 2030hrs, I was riding my motorcycle (CBF 2734Y) along Tampines Central 1 towards the direction Tampines Ave 4 on the right. I saw the vehicle ahead start to move off and I proceed to move forward. Suddenly a taxi (3HB 403H) from opposite direction make a right turn and collided onto the right front portion of my

Insured's version :

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 20 June 2018 (A) 20:30 hrs. I was waiting at central 1 to turn Right to Century Square. The traffic was heavy. I was a stop before Box Junction. I was a notice. Both on coming vehicle stop due to intent. When I was a just move. Suddenly, Veh B. in-between. Both vehicle to go through. I was a cannot see him coming and hit him. at the point of accident. Veh A. carry 4 passengers. 1 was injured.

DECLARATION

I/We declare the foregoing particulars are true to my best knowledge.

UNIFCITY TRANSPORTATION PTE LTD
CO. REG. NO. 189003321H

Policyholder's Signature
Date & Time:

000000000000000000

Driver's Signature
Date & Time:

Reporting Officer's Signature
Name:
Date & Time:

Page 2 of 2

Accident Photo



COST OF CLAIMS	Repairer's	Adjuster
Parts	0.00	0.0
Miscellaneous Items	0.00	0.0
Labour	0.00	0.0
Paintwork Labour	0.00	0.0
Towing	0.00	0.0
Nett Amount (S\$)	0.00	0.0

INSPECTION

Date of Assignment: 31/07/2018
Date Inspected: 01/08/2018
Inspected At: Ong Motors (HQ)
464 Macpherson
Singapore 36818
Estimated Period of Repair: 0.0 days

Adjuster: Muhammad Nazril Bin Abdullah
Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

Printing Options

- ☐ Hide Company Header - Leave lines blank
- ☐ Print continuously - Do not break pages

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com,assignments@lkkauto

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Claimant Vehicle No : FBF2734Y

Date of Loss: 26/07/2018

Policy No:

Insured Vehicle No :

Nature of Claim:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBF2734Y
 Make & Model: YAMAHA FZ1-N, 998cc
 Reg. Date: 15/04/2011 (Man. Year: 2010)
 Colour: Black
 Engine Capacity: 998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Foot
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-s

CONDITION OF TYRES

Front Tyre Size:	120/70Z R17	Rear Tyre Size:
Front Left Side:	Michelin 5 mm	Rear Left Side:
Front Right Side:	0 mm	Rear Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's
Parts	0.00	0.0
Miscellaneous Items	0.00	0.0
<		

28/07/2018

Best Regards,

Mekavathanan

HOD

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

DID: 6347 6105 Fax: 6224 4174



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

No	Subject Matter	Current	Revised	Remarks
1	Reserves			
	TPPD	PRESERVE	511	
	TPPI	PRESERVE		
	UNINSURED LOSS	PRESERVE		
	SUBRO	PRESERVE		
	LPPN			
	Investigation Fees			
	Survey Fees		3000	
	Legal Fees			
	Others			
2	Fraud Check			
3	Upload to merimen			
4	Grant Rights			
5	Payment			

*** FAX TX REPORT ***

TRANSMISSION OK

JOB NO. 3638
 DESTINATION ADDRESS 967338183
 SUBADDRESS
 DESTINATION ID
 ST. TIME 29/10 18:54
 TX/RX TIME 00:20
 PGS. 1
 RESULT OK



*on Motors
 Doc*

CHIA S ARUL LLC
 ADVOCATES & SOLICITORS
 UEN 201330709H

ARULCHELVAN S

Your Ref : To be advised
 Our Ref : AS.182037-PD.dt(mq)



23 October 2018

COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 GAS BUILDING
 SINGAPORE 575717

BY CERTIFICATE OF POSTING

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL STREET
 #04/06-00 IOB BUILDING
 SINGAPORE 049711

BY PDX
 We are in receipt of your letter, which is enclosing our attention.
 We shall accept liability. Kindly note that we are preserving our
 rights to conduct a medical examination on your client where
 necessary.

Our Ref:

Name :

Date :

India International Insurance Co. Ltd.

Dear Sirs,

**ACCIDENT INVOLVING FBF 2734Y & SHB 4073H ALONG TAMPINES CENTRAL 1 ON
 28 JULY 2018**

We refer to the above matter.

We act for MOHAMED REZA BIN AMIRUDIN, the owner of motor vehicle **FBF 2734Y**
 involved in the captioned accident.

We were instructed by our client to claim damages against you in connection with a road
 traffic accident **ALONG TAMPINES CENTRAL 1 ON 28 JULY 2018** involving our client's
 motor vehicle **FBF 2734Y** and your motor vehicle driven by you at the material time

29/10/2018

on Motor
Acc

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Your Ref : To be advised
Our Ref : AS.182037-PD.dt(mq)



23 October 2018

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
GAS BUILDING
SINGAPORE 575717

BY CERTIFICATE OF POSTING

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/06-00 IOB BUILDING
SINGAPORE 049711

BY PDX

Dear Sirs,

ACCIDENT INVOLVING FBF 2734Y & SHB 4073H ALONG TAMPINES CENTRAL 1 ON 28 JULY 2018

We refer to the above matter.

We act for MOHAMED REZA BIN AMIRUDIN, the owner of motor vehicle FBF 2734Y involved in the captioned accident.

We were instructed by our client to claim damages against you in connection with a road traffic accident ALONG TAMPINES CENTRAL 1 ON 28 JULY 2018 involving our client's motor vehicle FBF 2734Y and your motor vehicle driven by you at the material time.

We are instructed that the accident was caused by your negligent driving and/or management of your vehicle SHB 4073. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

a)	Costs of Repair		S\$13,400.00
b)	Loss of Use (12 days x \$50)		S\$ 600.00
c)	Survey Report fee		S\$ 938.00
d)	LTA		S\$ 7.49
e)	GIA		S\$ 29.00
f)	Costs		S\$ 2,000.00
g)	Towing		S\$ 80.00
	Total		S\$17,054.49

A copy of each of the following supporting documents is enclosed.

- a) A copy of our client's GIA and police report;
- b) A copy of Final Repair Bill;
- c) A copy of the LTA search;
- d) A copy of the towing invoice; and
- e) A copy of the survey report, invoice and photographs of our client's motor vehicle.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully,

MR ARULCHELVAN S

Enclosure(s)





**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-118064

Date of Request: 01/08/2018

Your Ref No: WALK IN TAN CY

MOTO 51 PTE LTD
2 KAKI BUKIT AVENUE 2, #01-17, KAKI BUKIT AUTOHUB
SINGAPORE 417921

Dear Sir/Madam,

Your Vehicle No: FBF2734Y

Date of Accident: 28/07/2018

Place of Accident: TAMPINES CENTRAL

Involving Vehicle No: SHB4073H

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-118065

Date of Request: 01/08/2018

Your Ref No: WALK IN TAN CY

MOTO 51 PTE LTD
2 KAKI BUKIT AVENUE 2, #01-17, KAKI BUKIT AUTOHUB
SINGAPORE 417921

Dear Sir/Madam,

Date of Accident: 28/07/2018

Vehicle No: FBF2734Y

Place of Accident: TAMPINES CENTRAL 1 B4 JUNC TAMPINES AVE 4

Involving Vehicle No: SHB4073H

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHB4073H	TAMPINES CENTRAL 1 B4 JUNC TAMPINES AVE 4	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/07/2018 10:17
Date Of Accident	28/07/2018 20:20
Exact Location Of Accident	TAMPINES AVE 4 TURN TO CENTRAL 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB4073H
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	LIM KWEE HUAT
NRIC No	S0175555B
Address	BLK 113 CLEMENTI STREET 13 #07-25

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	5

Circumstances of Accident

PLS REFER TO ATTACHED /Type Of Accident : HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303321R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIA/IMC SketchPlanForm_V3



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



MOTO 51 PTE LTD

Kaki Bukit Autohub, 2 Kaki Bukit Ave 2, #01-18
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : moto51@n51.com.sg
Company Reg. No. : 201536417C

MOHAMED REZA BIN AMIRUDIN
13 PASIR RIS RISE #04-25
SINGAPORE 518086

Contact : 92703849

TAX INVOICE

Date : 04/10/2018

Date in : 28/07/2018

Vehicle Num. : FBF2734Y

Make/Model : YAMAHA FZ1-N-2010

Chassis/Eng# : JYARN16R000000345/N513E052713

Accident Date : 28/07/2018

Claim No : CLM13302

Reference : JULY-03/2018

Policy No. : 5087929570-01 (07/05/2019)

LUMPSUM REPAIR BILL
AS PER SURVEYOR REPORT
REF : CAS/18-09/053 DATED 31/07/2018
BY CONSTANT APPRAISER SERVICES

Amount S\$

13,400.00

E. & O.E. Sub S\$: 13,400.00

Total Amount S\$: 13,400.00



for MOTO 51 PTE LTD



BIKEBULANCE

9D, Yuan Ching Road #03-38 S(618646)
Tel: 6425-5332 96880928
Email: bikebulance@yahoo.com
MOTORCYCLE/SCOOTER Haulage Company

- ☐ DELIVERY ORDER
☐ CASH SALE
☐ INVOICE

CR/S

Motor S1

NO : 16546

RE :

DATE: 30.07.18

ITEM	QTY	DESCRIPTION	UNIT PRICE	AMOUNT
1	1	Towing FBF 0724Y P21	\$	\$ 80 00
2		92703849	\$	\$
3		From AS Changi - Paya Ubi	\$	\$
4		IDAC to 464 mapherson	\$	\$
5			\$	\$
Total			\$	\$ 80 00

50% of quoted Price or min \$20 (which ever is higher) is liable for cancellation of booking (Not For Contract Basis)

注意: 本公司對所拖的電單車, 在拖運中如有任何損壞, 一概由車主自行負責

NOTE: Vehicle is hauled at owner's risk. The Company accepts no responsibility for damages or other misdeemeanor to your vehicle whilst being towed.

YM 2E ☐ YM 2C ☐ GY 2E ☐ GBB 2K ☐ GZ 2320T ☐ GBB4376E ☐ Other ☒

E & O E

Issued By

Customer's Signature & Chop

Bikebulance Is The Solution To Your Motorcycle / Scooter Conveying Needs (Local & West Malaysia)

Enquire Vehicle & Owner Information (Vehicle No. SHB4073H As At 28 Jul 2018 / 20:30:00)

Legal Firm Search Details:

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: FBF2734Y

Enquirer's Ownership No.:

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

Current Vehicle Details:

Vehicle No.: SHB4073H

Make Description/Model: HYUNDAI / I40 1.7 CRDI F/LAT ABS AIRBAG 4DR

Insurance Company Name: INDIA INT'L INS PTE LTD



Chia See Kim Angela Sharon has successfully logged out.

Your last login date and time was 22 Oct 2018, 11:27:49.

To return to ONE MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

Sl No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type
1	Vehicle	5HB4073H	-	18.19 Enquire Veh Owner Info (Others) by Law Firm
• Log Date/Time 22 Oct 2018 / 11:35:59				
2	Vehicle	GBF4925A	-	18.19 Enquire Veh Owner Info (Others) by Law Firm
• Log Date/Time 22 Oct 2018 / 11:34:29				
3	Vehicle	SKN9728X	-	18.19 Enquire Veh Owner Info (Others) by Law Firm
• Log Date/Time 22 Oct 2018 / 11:32:29				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/07/2018 17:28
Date Of Accident	28/07/2018 20:30
Exact Location Of Accident	TAMPINES CENTRAL 1 B4 JUNC TAMPINES AVE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBF2734Y
Insured/Policyholder	
Name Of Registered Owner	MOHAMED REZA BIN AMIRUDIN
NRIC No	S9247595F
Email Address	RAZA_AMZR@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92703849
Alternative Phone No	OTHERS-92703849
Vehicle Particulars	
Manufacturer	YAMAHA
Model	FZ1-N
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5087929570-01
Cover Note Number	
Driver	
Name of Driver	MOHAMED REZA BIN AMIRUDIN
NRIC No	S9247595F
Date Of Birth	29/12/1992
Occupation	INDOOR
Date Of Driving Pass	23/07/2014
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92703849
Fax Number	
Contact Number	OTHERS-92703849
Email Address	RAZA_AMZR@GMAIL.COM

Address 13 PASIR RIS RISE
#04-25
Postcode 518086
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB4073H
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **renege policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available to all interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the publishing of this report as the content and to copies of the report being made available if/when said.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I, the policyholder, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me be processed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (to "insurers") who have insured vehicle(s) involved in this accident shall be collected (by referred to as the "insurers"), the insurers' lawyer/law firm, the Ministry of Transport of Singapore and any relevant government department/authority (such as the police) for the purpose of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and/or my claims investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) handling but unpaid dealing with my insurance claim, processing and/or payment;
 - (iv) administering my claims including the issuing of correspondence, statements, and/or issuing any documents which could involve disclosure of certain personal data (such as me bringing about delivery of the documents to my personal owner of envelope/mail parcel(s)); and/or
 - (v) complying with applicable law in order to the insurers' interest and/or dealing with my claims for other purposes.
 - (ii) all insurers who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firm are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes; and
 - (iii) my Personal Information may/are be disclosed by any of the insurers and/or the insurer's third party service providers (agents) including the lawyer/law firm which may be based outside of Singapore, for one or more of the above purposes;
 - (iv) my Personal Information will also be collected and used to compile my claims history for the purpose of fraud detection, investigations and management in current and all future claims;
 - (v) the information so collected under (a) above may be used / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or handling my claims;
 - (ii) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or handling my claims;
 - (iii) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or handling my claims;
 - (iv) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or handling my claims;
 - (v) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or handling my claims;
 - (vi) for any purpose which is required under any regulatory law or court orders;


Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/ID No.

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/15/18 at 10:00 AM I was riding my motorcycle
 (2734) on the highway when I noticed the driver of
 a car (2/15/18 T-4) in the right lane of traffic
 going to the right. I was in the left lane of traffic
 and I noticed the car was going to make a right
 turn and collided with the right front portion of my bike.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Yellow Box
 Date & Time

Temporary Central 1
 If driver is not the possessor
 Date & Time

Reporting Officer's Signature
 Name
 (10-H) FBF 2734

2/15/2018

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

INVOICE

To: Mohamed Reza Bin Amirudin
13 Pasir Ris Rise
#04-25
Singapore 518086

Date : 25/09/2018

Invoice No : IV18-09053/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle FBF 2734Y (Inclusive Of Photographs And Transport Charges) Our reference : CAS/18-09/053	\$938.00
Total	\$938.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

Automobile Inspection Report

To: Mohamed Reza Bin Amirudin 13 Pasir Ris Rise #04-25 Singapore 518086		Date : 25/09/2018 Reference No : CAS/18-09/053	
<u>General Information</u>			
Registration No. : FBF 2734Y Accident Date : 28/07/2018			
<u>Particulars of Damaged Vehicle</u>			
Colour : Black	Engine Capacity : 998 cc	Make & Model : Yamaha RZ1-N	Pre-Accident Condition : Good
Mileage (KM) : 133920	Chassis No. : JYARN16R000000345	Engine No. : N513E052713	Steering : Affected
Registration Date : 15/04/2011		Brake : In Order	
<u>Tyre Condition</u>			
Front Tyre	Size 120/70R17	Make MICHELIN	Balance 90%
Rear Tyre	190/55R17	MICHELIN	90%
<u>Inspection</u>			
Repairer : Moto 51 Pte Ltd 2 Kaki Bukit Ave 2, #01-17 Kaki Bukit Autohub, Singapore 417921			
<u>Adjustment And Recommendation Cost Of Repair</u>			
Repairer's Estimate : \$18,604.80			
Revised Amount : \$13,400.00			
Less Excess : -			
Nett Total : \$13,400.00			
<u>Remarks</u>			
(A) Survey was done on 31/07/2018 (B) Re-survey was done on 03/08/2018 (C) Re-survey after repair was done on 12/09/2018 (D) The survey was conducted entirely on WITHOUT PREJUDICE basis. (E) We have NOT given any instruction to authorize the repair of the vehicle.			

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Constant Appraiser Services

Vehicle No : FBF 2734Y

Our ref : CAS/18-09/053

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
		<u>PARTS REPLACEMENT – LIST ITEMS</u>				
1	2pcs	Brake disc R/L @ \$420.00	Bent/Warped	840.00	840.00	NNX
2	2pcs	Fork assy R/L @ \$1,200.00	Bent/Twisted	2,400.00	2,400.00	RX
3	1pc	Fork lower bracket	Bent	550.00	550.00	NN
4	1pc	Front fender	Dented/Grazed	190.00	190.00	AT
5	2pcs	Front signal R/L @ \$65.00	O/S Grazed	130.00	65.00	NN
6	1pc	Front wheel rim	Dented/Warped	950.00	950.00	RX
7	1pc	Front wheel rim shaft	Bent	78.00	78.00	BT
8	1pc	Fuel tank assy	Serviceable	950.00	-	
9	1pc	Fuel tank front cover	Grazed/Broken	115.00	115.00	BR
10	2pcs	Fuel tank front cover sticker R/L @ \$34.00	Necessary	68.00	68.00	NE
11	1pc	Gear pedal	Serviceable	115.00	-	
12	1pc	Handle bar	Bent	240.00	240.00	BT
13	1pc	Headlamp assy	Serviceable	550.00	-	
14	1pc	Ignition coil	Dented/Grazed	371.00	371.00	NN
15	2pcs	Mirror R/L @ \$95.00	Grazed/Bent	190.00	190.00	NN
16	1pc	Radiator assy	Dented/Bent	780.00	✓ 780.00	DD
17	2pcs	Radiator fan assy @ \$226.00	Damaged/Jammed	452.00	✓ 452.00	DD
18	1pc	Radiator grille	Deformed	132.00	132.00	DD
19	2pcs	Radiator side cover R/L @ \$95.00	Grazed/Broken	190.00	190.00	CR
20	1pc	Radiator top hose	Bent	16.00	16.00	BT
21	2pcs	Rear footrest bracket R/L @ \$165.00	O/S Bent	330.00	165.00	BT
22	2pcs	Rear footrst R/L @ \$48.00	O/S Grazed	96.00	48.00	AT
23	2pcs	Rear signal R/L @ \$65.00	O/S Grazed	130.00	65.00	AT
24	1pc	Rear tailboard	Repair	350.00	-	
25	1pc	Rectifier	Dented/Damaged	441.00	441.00	NN
26	1pc	Rectifier bracket RH	Bent	78.00	78.00	BT
27	1pc	Steering stem	Bent	410.00	410.00	BT
				11,142.00	8,834.00	
		Less 10%		(1,114.20)	(883.40)	
		Sub total		10,027.80	7,950.60	

Constant Appraiser Services

Vehicle No : FBF 2734Y

Our ref : CAS/18-09/053

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
		<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>				
1	1set	Body slider set	Grazed	320.00	320.00	CUT
2	1set	Brake pedal set	Grazed/Bent	550.00	550.00	CUT
3	1pc	Exhaust muffler	Dented/Grazed	2,800.00	2,800.00	NN
4	1pc	Exhaust muffler holder	Grazed	146.00	146.00	SCR ✓
5	2pcs	Fork oil seal R/L @ \$60.00	Cut/Necessary	120.00	120.00	ME
6	1set	Front footrest set	Grazed/Bent	320.00	240.00 320.00	SCR ✓
7	1pc	Front no plate	Serviceable	15.00	-	
8	1pc	Front tyre	Serviceable	280.00	-	
9	1set	Front wheel bearing set	Necessary	65.00	65.00	NE
10	1set	Front wheel rim slider set	Grazed	220.00	120.00 220.00	CUT
11	1set	Handle bar balancer set	Grazed	180.00	180.00	CUT
12	1set	Handle bar grip set	Torn	85.00	85.00	SCR
13	1set	Lever set (brembo racing)	Grazed	680.00	680.00	RJ
14	1pc	Rear box	Dented/Grazed	780.00	780.00	RX
15	1pc	Rear box bracket	Twisted	160.00	160.00	RX
16	1pc	Steering corn/bearing	Necessary	96.00	96.00	NEC ✓
		Sub total		16,844.80	14,472.60	
		<u>LABOUR & MISC. CHARGES</u>				
1		To remove, reinstall electrical wiring harness, check lighting. (to FR)		60.00	30.00	
2		To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident		500.00	200.00 350.00	
3		To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident		800.00	400.00 600.00	
4		To Straighten body frame to the original position		400.00	200.00 300.00	
		Grand total		18,604.80	15,752.60	
Recommended cost of lump sum repair (To its pre-accident condition)					13,400.00	

Repair days 8

TGLIN

lin

15/11/18

Constant Appraiser Services

Vehicle No : FBF 2734Y

Our ref : CAS/18-09/053

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$13,400.00** on a contractual basis. Under normal circumstances, the repair period would be about **12 (Twelve)** working days.

Yours faithfully,

Constant Appraiser Services

A handwritten signature in black ink, appearing to read 'Lim Yong Tian', is written over a circular stamp. The stamp contains the text 'CONSTANT APPRAISER SERVICES' around the perimeter and 'CAS' in the center.

Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III18013910/Nsbe2-1		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 21-11-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4073H	Veh. Inspected	FBF 2734Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	MCT18070837	Excess (\$)	0.00	
Assign From	JOEL NAH	Assign Date	14/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA FZ1	c.c	998	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	JYARN16R000000345	Colour	BLACK	
Odometer	133920	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70Z R17	MICHELIN	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	190/55Z R17	MICHELIN	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/07/2018	Inspection Date	01/08/2018	
Survey held at	ONG MOTOR - 464 MACPHERSON ROAD.			
Repairer	MOTO 51 PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 2734Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	BRAKE DISC R/L @\$420.00	NOT NECESSARY	840.00	-
2	FORK ASSY R/L @\$1200.00	TO REPAIR SEE LABOUR	2,400.00	-
1	FORK LOWER BRACKET	NOT NECESSARY	550.00	-
1	FRONT FENDER	CUT	190.00	190.00
2	FRONT SIGNAL R/L @\$65.00	NOT NECESSARY	130.00	-
1	FRONT WHEEL RIM	TO REPAIR SEE LABOUR	950.00	-
1	FRONT WHEEL RIM SHAFT	BENT	78.00	78.00
1	FUEL TANK ASSY	SERVICEABLE	950.00	-
1	FUEL TANK FRONT COVER	BROKEN	115.00	115.00
2	FUEL TANK FRONT COVER STICKER R/L @\$34.00	NECESSARY	68.00	68.00
1	GEAR PEDAL	SERVICEABLE	115.00	-
1	HANDLE BAR	BENT	240.00	240.00
1	HEADLAMP ASSY	SERVICEABLE	550.00	-
1	IGNITION COIL	NOT NECESSARY	371.00	-
2	MIRROR R/L @\$95.00	NOT NECESSARY	190.00	-
1	RADIATOR ASSY	DENTED	780.00	780.00
2	RADIATOR FAN ASSY @\$226.00	DENTED	452.00	452.00
1	RADIATOR GRILLE	DENTED	132.00	132.00
2	RADIATOR SIDE COVER R/L @\$95.00	CRACKED	190.00	190.00
1	RADIATOR TOP HOSE	BENT	16.00	16.00
2	REAR FOOTREST BRACKET R/L @\$165.00	O/S BENT	330.00	165.00
2	REAR FOOTREST R/L @\$48.00	O/S CUT	96.00	48.00
2	REAR SIGNAL R/L @\$65.00	O/S CUT	130.00	65.00
1	REAR TAILBOARD	TO REPAIR SEE LABOUR	350.00	-
1	RECTIFIER	NOT NECESSARY	441.00	-
1	RECTIFIER BRACKET RH	BENT	78.00	78.00
1	STEERING STEM	BENT	410.00	410.00

Report Ref No. CS3/III18013910/Nsbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,114.20	-302.70
			10,027.80	2,724.30
	<u>SPECIAL NETT ITEMS</u>			
1	SET BODY SLIDER (SN)	CUT	320.00	320.00
1	SET BRAKE PEDAL (SN)	CUT	550.00	550.00
1	EXHAUST MUFFLER (SN)	NOT NECESSARY	2,800.00	-
1	EXHAUST MUFFLER HOLDER (SN)	SCRATCHED	146.00	146.00
2	FORK OIL SEAL R/L @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SET FORK FOOTREST (SN)	SCRATCHED	320.00	240.00
1	FRONT NO PLATE (SN)	SERVICEABLE	15.00	-
1	FRONT TYRE (SN)	SERVICEABLE	280.00	-
1	SET FRONT WHEEL BEARING (SN)	NECESSARY	65.00	65.00
1	SET FRONT WHEEL RIM SLIDER (SN)	CUT	220.00	120.00
1	SET HANDLE BAR BALANCER (SN)	CUT	180.00	180.00
1	SET HANDLE BAR GRIP (SN)	SCRATCHED	85.00	85.00
1	SET LEVER SET (BREMBO RACING) (SN)	TO REPAIR SEE LABOUR	680.00	-
1	REAR BOX (SN)	TO REPAIR SEE LABOUR	780.00	-
1	REAR BOX BRACKET (SN)	TO REPAIR SEE LABOUR	160.00	-
1	STEERING CORN / BEARING (SN)	NECESSARY	96.00	96.00
			6,817.00	1,922.00
	<u>LABOUR</u>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING. (TO FR)		60.00	30.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		500.00	200.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FORK ASSY R/L, FRONT WHEEL RIM, REAR TAILBOARD, SET LEVER SET (BREMBO RACING), REAR BOX AND REAR BOX BRACKET.		800.00	400.00

Report Ref No. CS3/III18013910/Nsbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION.		400.00	200.00
			1,760.00	830.00
GRAND TOTAL			18,604.80	5,476.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,400.00

Report Ref No. CS3/III18013910/Nsbe2-1

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.