

INS. CASE OWNER

CC 0 /CTI1802

LKK:
IDAC:

ASSIGNMENT

Surveyor:

DOE

Date / Time :

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.

Name of Insured

Insured Tel No. _____

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident :

If **NO**, Driver Name / Age :

Driver Tel No. :

(VA) YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : ☐ Final ? Yes / No

INSRS:
WSP:
Tel :
Liability
RMKS:



INRS:
WSP:
Tel :
Liability :
RMKS:



INSRS;
WSP;
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time		STAGE	DATE/ PIC
1/12/18	SHOUGBY 2 - X	Non-Reporting ltr (1st):	
1/12/18	SHOUGBY 2 - X	Non-Reporting ltr (2nd):	
1/12/18	SHOUGBY 2 - X	Non-Reporting ltr (Final):	
1/12/18	SHOUGBY 2 - X	Notification ltr (if non-pickup):	
1/12/18	SHOUGBY 2 - X	Call OI:	20/12/18 - vic
1/12/18	SHOUGBY 2 - X	After call ltr to OI:	1/12/18 - vic
20/12/18 @ 1:50PM	SHOUGBY 2 - X	Documentation Check List:	Handler Typist
21/01/19	SHOUGBY 2 - X	Notification ltr (if non-pickup)	☐
21/01/19	SHOUGBY 2 - X	After call ltr to OI:	☒
21/01/19	SHOUGBY 2 - X	Authorisation To Act:	☒
21/01/19	SHOUGBY 2 - X	Release Voucher:	☒
21/01/19	SHOUGBY 2 - X	Final Repair Bill:	☒
21/01/19	SHOUGBY 2 - X	Car Rental Invoice:	☒
21/01/19	SHOUGBY 2 - X	Towing Invoice	☐
21/01/19	SHOUGBY 2 - X	LTA/GIA:	☒
21/01/19	SHOUGBY 2 - X	Medical Bill:	☐
21/01/19	SHOUGBY 2 - X	PIR:	☐
21/01/19	SHOUGBY 2 - X	Mandate/Reject Instruction:	☐
21/01/19	SHOUGBY 2 - X	LOD	☒
21/01/19	SHOUGBY 2 - X	Payment Breakdown Form:	☐
21/01/19	SHOUGBY 2 - X	Post-Repair Photos:	☐
21/01/19	SHOUGBY 2 - X	Others:	☐

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: P/P	SS 1,424.60 (2 days)	Reduction: 4 %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 2/10/19	Confirm with: William	Email ☐ Call ☐
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No. : 269	If NO or B 28, Ass. Lia :
Repair Cost: (outdoor)	SS 1,524.32		(COB OPEN BOOK)
Loss of Rental (LOR):	SS 250.80 (2 days) x \$ 125.40		
Loss of Use (LOU):	SS 100.00 (\$ 50 x 2 days)		
Loss of Income (LOI):	SS - (\$ x days)		
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☒	[Tick only one]	
GIA/TA Search	SS 7.19		
Medical:	SS -		1) Claim status: Normal/Reject/Private Settle
Disbursement:	SS -	(e.g. Tow/ Independent)	2) Report Format:
Legal Cost:	SS -		3) Survey fee: \$ 400.00
Total:	SS 1,882.61	Global Sum SS: 1,880.00	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	SS 1,880.00	Name 1: COMPENOTBLARO	ENGINEERING PTE LTD
Payee 2: (Strike if N.A.)	SS -	Name 2:	-
Payee 3: (Strike if N.A.)	SS -	Name 3:	-

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspected Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No _____
Claims No _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 2 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD48672 Yr Regn: 7 Oct, 2016
Type: M.Car / M.Cycle / Bus / Van / Lorry / T/B / Prime Mover /
Truck / Trailer or
Make: Toyota Prius cc 1798
Colour: Blue A/C: Ins 6 / Std / NI / NA
Sp. Reading: 259783 T/Radio: Ins 6 / Std / NI / NA
Eng/No: _____
C/No: JTDKB3F4X0J533499
Gen. Cond: Good / 6 / Poor / Burnt
Steering: In order / 6 / Jammed / Leaked / Burnt or
Brake: In order / 6 / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/65R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Went / d4
Front Rear
R/Bal. 7 mm R/Bal. 7 mm
L/Bal. 7 mm L/Bal. 7 mm
D.O.A. 12/11/18 D.O.I. 13/11/18
Survey held at CDGE (Loyang)
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Rear.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	CTI
	PIR @ 1,424.60
	CRMD: @ 60.00 / 4%
cond (w/ot)	@ 1,524.32
LOK	@ 250.00 (125.40 x 2)
LOI	@ 100.00 (50.00 x 2)
	@ 1,674.32
200%	@ 984.16

Date/Time, File Pass to? 7.10 Prel. Report
1) 9.11.18 Final Report
Date/Time, File Return to?

Days Of Repair: _____
Resurvey No. of Trip: _____

Report Format: _____
Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:	
Transportation:	\$ + RS. \$ _____
Photos	
Others	
TOTAL	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18020588/K1hb3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 14-11-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKT 8988L	Veh. Inspected	SHD 4867Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	14/11/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/11/2018	Inspection Date	13/11/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18020588/K1hb3

Date: 14.11.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD4867Z

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13.11.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	1,484.60
Revised Estimate Amount	: S\$	1,424.60
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

REPAIR ESTIMATE

China Taping
CPIP

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305238478
 REGN NO : SHD4867Z
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 07.10.2016
 DATE/TIME IN : 13.11.2018 10:45
 ACCIDENT DATE : 12.11.2018

LKK - Kalvin

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0302-0596-G	REAR DOOR LH	1	1,232.80 25.00 924.60
0002	28-01-0302-2013-A	REAR DOOR APPS LH	1	80.00 2.50 80.00

SUB-TOTAL : 1,004.60

JOB NATURE

0000 L	PANEL BEATING	220.00	200
0001 23-502	SPRAYPAINT ON AFFECTED AREA	220.00	200
0002 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	20

SUB-TOTAL : 480.00

TOTAL : 1,484.60

MVA NAME & SIGNATURE
 DATE :

SURVEYOR NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for pricing resurvey
- Parts prices are subject to information
- Third party survey is on "without prejudice" basis
- No illegal means shall be used
- Survey report shall be submitted to the relevant and is subject to approval from the relevant Company.

Acknowledged by Repairer
 Signature:
 Date:

Kalvin LKK
 13/11/18 1505hr
 2 Pgs.
 PIP
 Before Paint photo

COMFORTDELGRO ENGINEERING PTE LTD

Date: 13.11.2018

Time: 14:46:49

REPAIR ESTIMATE

Page: 1

China Taping
CPIP

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305238478
 REGN NO : SHD4867Z
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 07.10.2016
 DATE/TIME IN : 13.11.2018 10:45
 ACCIDENT DATE : 12.11.2018

LKK - Kalvin

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0302-0596-G	REAR DOOR LH	1	1,232.80 25.00 924.60
0002	28-01-0302-2013-A	REAR DOOR APPS LH	1	80.00 2.50 80.00

SUB-TOTAL : 1,004.60

JOB NATURE

0000 L	PANEL BEATING	220.00	200
0001 23-502	SPRAYPAINT ON AFFECTED AREA	220.00	200
0002 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	20

SUB-TOTAL : 480.00

TOTAL : 1,484.60

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

Kalvin 11/11/18
 13/11/18 15:05h
 2 Pys
 PIP
 Before Paint photo

Auto Cons
 Repairer of the
 • To resurvey before
 • To display damaged
 • Parts prices are subject
 • Third party survey is on "no
 • No illegal modifications
 • Supplementary items are
 is subject to final approval of the Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305238478
REGN NO : SHD4867Z
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 07.10.2016
DATE/TIME IN : 13.11.2018 10:45
ACCIDENT DATE : 12.11.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-0596-G	REAR DOOR LH	1	1,232.80	25.00	924.60
0002 28-01-0302-2013-A	REAR DOOR APPS LH	1	80.00		80.00

SUB-TOTAL : 1,004.60

JOB NATURE

0000 L	PANEL BEATING				200.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA				200.00
0002 20-00	TUFF COAT ON AFFECTED PARTS.				20.00

SUB-TOTAL : 420.00

TOTAL : 1,424.60


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :
AUTHORISED : YES / NO

COMFORTDELGRO
ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 8280 Facsimile + 65 6280 9755
Workshops
69 Loyang Drive Singapore 508965 24 Serangoon Singapore 758156
383 Sin Ming Drive Singapore 575717 7 Sungai Kadut Way Singapore 728791
45 Pandan Road Singapore 609286 501 Yishun Industrial Park A Singapore 758732
623 Ubi Road 3 Singapore 758999

Date/Time: 19.11.2018 14:46 Page : 1

Team: ARC Repair TP(CLSO)1 JOB CARD Sales Order: 3873058 JC NO.: 305238478


OMER	REGN NO.: SHD4867Z	MILEAGE
IS COMFORT TRANSPORTATION PTE LTD	MAKE : TOYOTA	FUEL
OMER NO. 7010045	MODEL PRIUS HYBRID(G4)	E.....1/2.....F
IESS 383 SIN MING DRIVE	DATE/TIME IN 13.11.2018 10:45	
65508755	YR OF MANU 07.10.2016	TARGET DATE
(R) (O)	CHASSIS CODE JTDKB3FUX03533499	COMPLETION DATE/TIME:
JOINT CARD NO.		

JOB DESCRIPTION

Accident Date: 12.11.2018
NATURE: 3P 12.11.18

S/NO	LABOR CODE
000030	L
000040	23-502
000050	20-00

DESCRIPTION
PANEL BEATING
SPRAYPAINT ON AFFECTED AREA
TUFF COAT ON AFFECTED PARTS.



KED & PASSED OUT BY: _____

SERVICE ADVISOR CUSTOMER'S SIGNATURE

edgement Slip	Exit Pass
No.: SHD4867Z	Vehicle No.: SHD4867Z
LIMITS	
Service Advisor	Signature/Date
Name of Service Advisor	Date

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Date : 15/11/18

Fax:

Date of Accident : 12-Nov-18

Final Lumpsum Repair cost _____

We confirm the estimates and finalized amount

Fax : 65468156

Date : 15/11/18

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Shu Pei (LKKAUTO)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Tuesday, 27 November 2018 2:36 PM
To: Shu Pei (LKKAUTO)
Cc: Lucas Lee; Admin A; Vic (LKKAUTO); Claims Dept of CTI
Subject: RE: Direct Settlement - Accident Involving SKT8988L (OI : CTI - SNM18D05369C02/8) and SHD4867Z (TP : LKK REF - CC3/CTI18020588/K1hb3)on 13.11.2018
Attachments: MCC418147025-SKT8988L.pdf

Dear Shu Pei,

As requested, attached a copy of our insured's GIA report for your perusal.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com



From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 27 November, 2018 12:43 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Lucas Lee <lucas.lee@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving SKT8988L (OI : CTI - TBA) and SHD4867Z (TP : LKK REF - CC3/CTI18020588/K1hb3)on 13.11.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Tuesday, 20 November 2018 7:10 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Lucas Lee <lucas.lee@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving SKT8988L (OI : CTI - TBA) and SHD4867Z (TP : LKK REF - CC3/CTI18020588/K1hb3)on 13.11.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Wednesday, 14 November 2018 4:33 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Lucas Lee <lucas.lee@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>

Subject: Direct Settlement - Accident Involving SKT8988L (OI : CTI - TBA) and SHD4867Z (TP : LKK REF - CC3/CTI18020588/K1hb3)on 13.11.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHD 4867Z at M/s ComfortDelGro Engineering Pte Ltd (Loyang) on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2360.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Vic (LKKAuto)

From: Vic (LKKAuto)
Sent: Tuesday, 29 January, 2019 12:02 PM
To: Elaine Cheong
Cc: Lucas Lee; Admin A; Claims Dept of CTI; Vic (LKKAuto); Alfred Toh
Subject: RE: Direct Settlement - Accident Involving SKT8988L (OI : CTI - SNM18D05369C02/8) and SHD4867Z (TP : LKK REF - CC3/CTI18020588/K1hb3)on 13.11.2018

Dear Elaine,

We refer further to the below email.

Please be informed that we had settled the matter with TP repairer at a global sum of **\$1,880.00** (all in) with breakdown as below:

Cost of Repair (w/gst)	\$ 1,524.32
Loss of Rental (\$125.40 x 2 days)	\$ 250.80
Loss of Income (\$50.00 x 2 days)	\$ 100.00
LTA Search Fee	\$ 7.49
TOTAL	\$ 1,882.61

Relevant documents will be forwarded to your good office in due course.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Elaine Cheong [<mailto:elaine.cheong@sg.cntaiping.com>]
Sent: Tuesday, 27 November, 2018 2:36 PM
To: Shu Pei (LKKAuto)
Cc: Lucas Lee; Admin A; Vic (LKKAuto); Claims Dept of CTI
Subject: RE: Direct Settlement - Accident Involving SKT8988L (OI : CTI - SNM18D05369C02/8) and SHD4867Z (TP : LKK REF - CC3/CTI18020588/K1hb3)on 13.11.2018

Dear Shu Pei,



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18020588/K1hb3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 31-01-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKT 8988L	Veh. Inspected	SHD 4867Z
Policy No.		Coverage (\$)	0.00
Claim No.	SNM18D05369C02/8	Excess (\$)	0.00
Assign From		Assign Date	13/11/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDKB3FUX03533499	Colour	BLUE
Odometer	259783	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	7 mm
L/H Front Tyre	195/65 R15	WEST LAKE	7 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	7 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/11/2018	Inspection Date	13/11/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4867Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR LH	DENTED	1,232.80	1,232.80
	LESS 25% DISCOUNT		-308.20	-308.20
			924.60	924.60
<u>SPECIAL NETT ITEMS</u>				
1	REAR DOOR APPS LH (SN)	NECESSARY	80.00	80.00
			80.00	80.00
<u>LABOUR</u>				
	PANEL BEATING.		220.00	200.00
	SPRAYPAINT ON AFFECTED AREA.		220.00	200.00
	TUFF COAT ON AFFECTED AREA.		40.00	20.00
			480.00	420.00
GRAND TOTAL			1,484.60	1,424.60
RECOMMENDED COST OF REPAIRS				1,424.60

Report Ref No. CC3/CT118020588/K1hb3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.