

COMFORTDELGRO ENGINEERING PTE LTD

Date: 13.11.2018

REPAIR ESTIMATE

Time: 14:46:49

Page: 1

China Tai ping
CPIP)

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305238478
 REGN NO : SHD4867Z
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 07.10.2016
 DATE/TIME IN : 13.11.2018 10:45
 ACCIDENT DATE : 12.11.2018

LKK - kalvin

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0302-0596-G	REAR DOOR LH	1	1,232.80 25.00 924.60
0002	28-01-0302-2013-A	REAR DOOR APPS LH	1	80.00 2.50 80.00

SUB-TOTAL : 1,004.60

JOB NATURE

0000 L	PANEL BEATING	220.00	200
0001 23-502	SPRAYPAINT ON AFFECTED AREA	220.00	200
0002 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	20

SUB-TOTAL : 480.00

TOTAL : 1,484.60

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

Kalvin 11/11/18
 13/11/18 1505h
 2 Pgs.
 PIP
 Before Paint photo

< Auto Consultancy & Survey
 Repairer of the following:
 • To resurvey before/after surveying
 • To display damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modifications allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date: