

206201 TI has - (5)

CoE 2020 Nov-

ASSIGNMENT

Veh No: 6E 3119 Yr Regn: 205 / 100

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna C.C. 2986

Colour Silver A/C: Insured / Std / NI / NA

Sp. Reading 437019 T/Radio: Insured / Std / NI / NA

Eng/No:

C7No: ST F4F 349 803011271

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: (Nil) S/Rim / STD A/Rim or

Tyre Size: F: 185/R14
R: 155/R12 (D)

N/S	O/S

Front 6 mm Rear 6/4 mm

R/Bal. 8 mm R/Bal. 67 mm

L/Bal. 6 mm L/Bal. 6/6 mm

D.O.A. D.O.I. 26/4/18

Survey held at McKean Is. 4 Kander Pl

@ 1 pm

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

w/s will pass estimate to later

☐ : Preli. Report
☐ : Final Report

Resurvey No. of Trip:

Transportation.

Add Fee: : Site Insp (\$
$$) \quad S + RS \rightarrow SI$$

☐ Interview (\$

) Photos

Tech. Invs (\$)

) Others

☐ Weekend (\$)

TOTAL