

22/03/2002

ASS REC. BY:

REF:

CS3/CT118020666/Gcb02

Special Instruction:

Surveyor:

GB

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTL

Date/Time:

14/12/018 520pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FV 9376U

Insured:

GBC 2807L

at Workshop m/s

Foo Soon Heng

Tel:

64846033

of

Blk 10 Amk Ind Park 2A #05-11

Policy No:

DMCVSN3030351800

Claim No:

SNM1800535602

Sum Insured:

Excess:

Make of Veh:

D.O.A.

20072018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

15/12/018 939am

Person Contacted:

Mr. Foo

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

FV9376U-X.

GBC 2807L-X.

Surveyor: ValREF: Gi

8503:

ASSIGNMENT

(-2022)

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Too Soon Henry

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$9000

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SV 9376UYr Regn: 11 Dec 2002

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda ST1100PY c.c. 1085Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 219255

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: IH25C26C05M100303Gen. Cond: Good / Fair / Poor / BurntSteering: Insider / Jammed / Leaked / Burnt orBrake: Insider / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 110/80ZR18R: 160/70ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mmR/Bal. 4 mmL/Bal. 4 mmL/Bal. 4 mm

D.O.A. _____

D.O.I. 15-11-18Survey held at w/s4:25pmDes. of Damages: Frt / Rear / D/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$3000 - \$4000

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 150

Transportation:

S + RS, SI

Photos

Others

TOTAL

150Report Format : PRE

Lump Sum / I.B.I. (\$) _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Nov 2018		14 Nov 2018 18:22 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:									
Main Claimant: NORFIFI BIN MAHAT									
Vehicle Reg. No.:		FV9376U	Date of Loss:	20/07/2018 22:00 - :59					
Claim Type:		TP / SNM18D05356C02	Policy/Cover Note No.:	DMCVSN3030351800					
Vehicle Reg. No. (Insured):		GBC2807L	Policy No. (Claimant):						
		Excess:	S\$0.00						
Repairer: Foo Soon Heng Motor Repair (HQ) 10 Ang Mo Kio Industrial Park 2A, #05-11, Ang Mo Kio Autopoint, 560047 Ang Mo Kio - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/11/2018]									
Adj Asg. Remarks: PLEASE SURVEY AND REVERT									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
<div> </div> ALL ASSOCIATED TASKS									
<div> View All Search Tasks Create New Task Complete </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Wednesday, 14 November, 2018 5:20 PM
To: Jacqueline Tan
Cc: assignments@lkkauto.com
Subject: CTP REF NO. GBC2807L VL REF NO. AM.JT.INS.F20.FV9376U.18 - ACCIDENT INVOLVING GBC2807L AND FV9376U ON 20 JULY 2018
Attachments: ANR(GBC2807L).pdf

Dear LKK (Catherine),

Please liaise with JAC from Vision LLC at 6534-2811.

Thank you.

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8503I
Vehicle Details	
Vehicle No.:	FV9376U
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	ST1100PY
Primary Colour:	White
Manufacturing Year:	2001
Engine No.:	SC26E3007509
Chassis No.:	JH2SC26C0YM100303
Maximum Power Output:	-
Open Market Value:	\$13,322.00
Original Registration Date:	11 Dec 2002
First Registration Date:	11 Dec 2002
Transfer Count:	7
Actual ARF Paid:	\$1,999.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Dec 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,856.00
COE Rebate Amount:	\$760.00
Total Rebate Amount:	\$760.00
Message	

Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.

This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.

Honda ST1100


Price S\$9000.00



1995



197000km



FN-****-J



Class 2



CHAT

--	--

(MESSAGES/U/43200) **Singapore**
BIKES.



Description

(<https://www.singaporebikes.com/bikemart/sg/>)

Specifications

General Info.

Bike Make Honda

Bike Model ST1100


Bike Class Class 2

Bike Type Cruiser

Transmission Manual

Engine
Capacity 1100 cc

Under Hire
Purchase No



Additional

First Owner No

Effective Date
Ownership 14-06-1995

Original Reg.
Date 13-06-2000

Bike Color

COE Expiry
Date 13-06-2022

Additional

Quota
Premium (QP) 0.00

Road Tax
Expiry Date 31-12-2016

Mileage 197000km

Instalment
Details N/A

Accessories

Seller Information

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/07/2018 10:15
Date Of Accident	20/07/2018 22:00
Exact Location Of Accident	BTW BLK 615 & 617 CARPARK LOT 516D @ YISHUN RING
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FV9376U
Insured/Policyholder	
Name Of Registered Owner	NORFIFI BIN MAHAT
NRIC No	S7238503I
Email Address	NORFIFIMAHAT@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82020568
Alternative Phone No	OFFICE-82020568
Vehicle Particulars	
Manufacturer	HONDA
Model	ST1100PY
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MC/00492443
Cover Note Number	05/06/2018-04/06/2019
Driver	
Name of Driver	NORFIFI BIN MAHAT
NRIC No	S7238503I
Date Of Birth	24/10/1972
Occupation	INDOOR
Date Of Driving Pass	16/04/2002
Driving Experience	16 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82020568
Fax Number	
Contact Number	OFFICE-82020568
Email Address	NORFIFIMAHAT@GMAIL.COM

Address 266 TAMPINES ST 21
02-14
Postcode 520266
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 32 YISHUN ST 81 , POSTCODE: 768456 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-8522999 - FAX NO: 68522239
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Nov 2018		14 Nov 2018 18:22 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: NORFIFI BIN MAHAT									
Vehicle Reg. No.: FV9376U		Date of Loss: 20/07/2018 22:00 - :59 [187 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D05356C02		Policy/Cover Note No.: DMCVSN3030351800							
Vehicle Reg. No. (Insured): GBC2807L		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Foo Soon Heng Motor Repair (HQ) 10 Ang Mo Kio Industrial Park 2A, #05-11, Ang Mo Kio Autopoint, 560047 Ang Mo Kio - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 23/11/2018]									
Adj Asg. Remarks: PLEASE SURVEY AND REVERT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FV9376U (SNM18D05356C02)**
[GBC2807L]
TP
NORFIFI BIN MAHAT
Jul 20 2018 10:00PM
[-]
Foo Soon Heng Motor Repair

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View [View in Browser](#)

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/11/18 09:26	General View	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) | [Save](#) | [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18020666/GCBE2

Date: 26/11/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3030351800

Claimant Vehicle
No: FV9376UInsured Vehicle
No: GBC2807L

Date of Loss: 20/07/2018

Nature of Claim: TP

Claim
No: SNM18D05356C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FV9376U

Make & Model: HONDA TA200, 197cc PHANTOM (M)

Engine No: SC26E3007509

Reg. Date: 11/12/2002 (Man. Year: 2001)

Chassis No: JH2SC26C0YM100303

Colour: White

Odometer: 219255 km

Engine Capacity: 1085 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80Z R18

Rear Tyre Size: 160/70Z R17

Front Left Side: Bridgestone 4 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/11/2018

Date Inspected: 15/11/2018 Inspected At:

Foo Soon Heng Motor Repair (HQ)
10 Ang Mo Kio Industrial Park 2A, #05-11,
Ang Mo Kio Autopoint
Singapore 560047

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Nov 2018)	
Parts:	N/A	HONDA TA200 197cc PHANTOM (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FV9376U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >