7.31038.7003 -	
ASS, REC. BY	CONCINED IN MARKET TO A 1 A Special Instruction
Surveyor:	ASSIGNMENT (Office)
From (Person	rere tay of CTI Date/Time: 14/11/188 5.52pm
Estimated Co.	st. Dille.
OD (TP) W	STTP RES / OD RES / EVA / INV / MV / CS
To Inspect Ve	chicle No: SLT 1751L Insured: GBC 7697D
at Workshop i	m/s EM Solution Tel: 6466 0226
of	160 8in Ming Drive # 03-18/19
Policy No:	DMCVEN 1437981702
Sum Insured:	DMCVSN 1437981703 Claim No: SNM18D05357CO2
-	Excess:
Make of Veh: (Client's Record	
CA / REV /	REP. / REV 24 HRS (up)
Date/Time: 9	H.O.D. Endorsement:
-	Person Contacted: Bernound Vehicle IN OUT
Date/Time	Action/Instruction ( > ) Estimate
	SLT 17511-X
	GBC 7697D -X
-	

REF: CT1

ASSIGNMENT

From: Date: 15/11/2018	Veh No: SUTINSIL	Yr Regn: 20 (	octeo17
Estimated Cost:	Type: MCas/ M.Cycle / Bus / Van / Lo	orry / raxi / Prime Mov	e1 /
OD (TP) WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or	1	100 C
To Inspect Vehicle No: SLT 1751 L	Make: Subaru F		
at Workshop m/s EM Solution	Colour Jud	A/C: Insured / S	The same of the sa
of 160 Sin Ming Drive #03-18/19	Sp.Reading 160 60	T/Radio: Insured / S	otd / NI / NA
Insured:	Eng/No:	Clata	e ([NI
Policy No.		85JG 09	1434
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt		
Sum Insured: Excess:	Steering: Ino@er / Jammed / Leaked		
(Client's Record)	Brake: In order / Jammed / Leaked	/ Burnt or	
Make of Veh: Before 12pm	Modi: Nil / SIRim / STD A/Rim o		
$\mathcal{O}_{t}$	Tyre Size: F: 215/	SSRIS	
(Policy Condition)	R:	()	
Remark: The veh had commenced its N/S O/S	BS DUN / EXNOVA / GY / FS / LIZA	/ MIC / OHTSU / PIR L	SUMI /
repair at the time of inspection.	TOYO / YOKO or		
Bal. or Market Value:	Front	Rear	^
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm	R/Bal.	mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm	L/Bal.	mm
Est. Repairs:	D.O.A.	D.O.I. 15-1	1-18
Lum Sum: % 3 Val.: Yes or No	Survey held at	5 (	L: YOUBAN
	Des. of Damages : Frt / Rear / O/S	/ N/S, / U/C / Roofto	op or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	WA	N/S	
Date: Person Contacted:	The U/C / Chassis frame / Bod	y Structure affected d	ue to collision.
Date / Time Action / Instruction & Socoo	•		
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 片		
: Final Report	Resurvey No. of Trip: 2	Survey Fee:	150
Date/Time, File Return to?		Transportation:	
2) Add Fee	The second secon	)S+RSSI	
	: Interview (\$	) Photos	
Report Format: PRS.	- : Tech. Invs (\$	) Others	
Lump Sum / I.B.I: (\$	: Weekend (\$	)	
		- L	150

## Nivitha (LKK Auto)

From:

Irene Tay <irene.tay@sg.cntaiping.com>

Sent:

Wednesday, 14 November 2018 5:52 PM

To:

Sally Chong; assignments@lkkauto.com

Cc:

EM Solution Pte Ltd; judysoh@visionlawllc.com

Subject:

RE: OUR REF.: E21.108696.18 (SLT 1751L @ 13.11.2018)

// CHINA

TAIPING REF NO: GBC 7697D

#### WITHOUT PREJUDICE

Dear LKK (Catherine),

Please liasie with Sally from Vision LLC at 6534-2811.

Thank you.

Regards,

#### Irene Tay

Executive

Claims Department (Motor Division)

## China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6192

Fax (65) 62247478/62247175

Email: claimsdept@sg.cntaiping.com

www.sg.cntaiping.com



#### Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Sally Chong [mailto:sallychong@visionlawllc.com]

Sent: Wednesday, 14 November, 2018 5:27 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Angie Foo <angie.foo@sg.cntaiping.com>; Lucas Lee

<lucas.lee@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>

Cc: EM Solution Pte Ltd <emautosolution@singnet.com.sg>; judysoh@visionlawllc.com

Subject: OUR REF.: E21.108696.18 (SLT 1751L @ 13.11.2018) // CHINA TAIPING REF NO : GBC 7697D

URGENT

Dear Irene.

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: LIN MIN

ACCIDENT INVOLVING SLT 1751L & GBC 7697D ON 13 NOV 2018 ALONG CTE TOWARDS ANG MO KIO AFTER JALAN BAHAGIA AB ABOUT 23:00 HRS

We refer to our tele-con a moment ago where you proposed LKK as your proposed SJE.

TAKE NOTICE that we object to your surveyor stated aforesaid, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following List of Motor Surveyors for your consideration:-

Name of Surveyor	Company Name
Dennis Yap	Pal's Appraiser Pte Ltd
Michael Yap	Mc-coy Appraiser Pte Ltd
Andy Yap	LCW Appraiser Pte Ltd
B J Loi	Par Automotive Consultancy
Sebastian Lim	Constant Appraiser Services
Lee Yew Hok	Constant Appraiser Services
Alan Cheong	CL Appraiser Pte Ltd

## Please be informed that the said vehicle can be inspected at:-

Venue

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity,

Singapore 575722

Contact

Mr. Bernard (Tel.: 6456-0226 / 9101-8302)

If you fail to conduct the pre-repair inspection within the next 2 working days, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

# Sally Chong

(Secretary) VISION LAW LLC 133 NEW BRIDGE ROAD, #18-01/02, CHINATOWN POINT,

SINGAPORE 059413 TEL.: 6534-2811 (ext 115)

FAX: 6535-6802

From: Sally Chong [mailto:sallychong@visionlawllc.com]

Sent: Wednesday, 14 November, 2018 11:01 AM

To: 'claimsdept@sg.cntaiping.com'; 'Angie Foo'; 'Lucas Lee'; 'Irene Tay'

Cc: EM Solution Pte Ltd (emautosolution@singnet.com.sg); 'judysoh@visionlawllc.com'

Subject: OUR REF.: E21.MISC.18 (SLT 1751L @ 13.11.2018) // CHINA TAIPING REF NO: GBC 7697D

Importance: High

Dear Sir.

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: LIN MIN

ACCIDENT INVOLVING SLT 1751L & GBC 7697D ON 13 NOV 2018 ALONG CTE TOWARDS ANG MO KIO AFTER JALAN BAHAGIA AB ABOUT 23:00 HRS

We are instructed by LIN MIN to notify you of a road traffic accident ON 13 NOV 2018 ALONG CTE TOWARDS ANG MO KIO AFTER JALAN BAHAGIA AB ABOUT 23:00 HRS involving our client's vehicle registration number SLT 1751L and vehicle registration number GBC 7697D driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

# Sally Chong

(Secretary)
VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413
TEL.: 6534-2811 (ext 115)

FAX: 6535-6802

# C.c.: VEHICLE OWNER OF GBC 7697D

AEROMAC ENGINEERING PTE LTD 6 Yishun Industrial Street 1, #05-07/08, North View Bizhub,

Singapore 768090

#### VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413 Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

#### DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any

person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any

errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.	
This email has been scanned by the Symantec Email Security.cloud service. For more information please visit <a href="http://www.symanteccloud.com">http://www.symanteccloud.com</a>	

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	10931
Vehicle Details	AND THE RESIDENCE OF THE PROPERTY OF THE PARTY.
Vehicle No.:	SLT1751L
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Nov 2018
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0XT CVT AWD SR
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	FA20CB14118
Chassis No.:	JF1SJGK85JG099454
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$16,462.00
Original Registration Date:	20 Oct 2017
First Registration Date:	20 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$16,462.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Oct 2027
PARF Rebate Amount:	\$12,346.00
Intended COE Rebate Details	10.0-+ 2027
COE Expiry Date:	19 Oct 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,109.00
COE Rebate Amount:	\$42,897.00
Total Rebate Amount:	\$55,243.00

The information contained herein is correct as at 19 Nov 2018

ОК

E-FILE

(Draft)

MLHM18147296 / Lai Huat (Meng Kee) Motor Pte Ltd - Sin Ming ENTRY DATE & TIME: 14/11/2018 11:23 SUBMITTED BY: [To Be Confirmed]

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 14/11/2018 11:23 Date Of Accident 13/11/2018 23:00

**Exact Location Of Accident** CTE TOWARDS ANG MO KIO

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLT1751L

Insured/Policyholder

Name Of Registered Owner LIN MIN NRIC No S7881093I

Email Address MINMIN082002@YAHOO.COM

Mobile Phone No (LOCAL) +65-93654218

Alternative Phone No Others-96895955

Vehicle Particulars

Manufacturer SUBARU

Model FORESTER 2.0XT

Exact Purpose for which vehicle was being used at time of

accident

PRIVATE USE

Are you claiming under your own insurance policy for

repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

170008163-01

Cover Note Number

Driver

Name of Driver LIM WEI YANG (LIN WEIYANG)

NRIC No S7821222E Date Of Birth 21/07/1978 Occupation **INDOOR** Date Of Driving Pass 22/05/1999

**Driving Experience** 19 YEARS AND 5 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96895955

Fax Number

Contact Number

**EMail Address** NOEMAIL

Address 3 COUNTRYSIDE VIEW

Postcode 789719

## SKETCH PLAN

## IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)


Date & Time:

11.2310

Reporting Centre Personnel's Signature

Poh Kwee Choo Name:

S6840583A NRIC/FIN No .:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT
13/11/2018@2300 hrs, I was driving along CTE towards
In Mo Kion After passing Idan Bahayia exist there was an accident on lane 1. I am a doctor
So I slowed down and stopped my vehicle to check
is help regular from those accident victims.
Suddenly a lorry on my left lane cut into
my lane and cottided Ento the left Brown side
portion al my vehicle
, 33
Repair at EM solution Ptc Ltd.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

14 MAY 2018

Driver's Signature

(If driver is not the policyholder) Date & Time  $\frac{1}{4}$   $\frac{1101}{2018}$ 

Reporting Centre Personnel's Signature

NRIC/FIN No.: Poh Kwee Choo S6840583A

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sul	bmitted	Ins Auth'ed	Status	
Main	14 Nov 2018		18 Dec 2018 12:40 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00			Pending for Report Cancel Cas	
	Main	R	eference	Claim De	tails		Documents		Show All
CLAIM SU	BFOLDER DE	TAILS			[	Created I	by insurer]		
Insured:	-, Co. Re	g. No.: -							
Main Claimant:	LIN MIN								
Vehicle Reg No.:	SLT175	1L		Date of		13/11/2018 23:00 - :59 [12 Months and 24 Days From LTA Reg Date (Man Yr)]			
Claim Type	: TP / SN	M18D05357C02	2	Policy/0 Note No		DMCVSN1437981703			
Vehicle Reg No. (Insured):	GBC7697	D		Policy N (Claima					
				Excess:	S	\$0.00			
Repairer:	Em Soluti	on Pte Ltd (HQ)	BLK 17 SIN MING I	ND EST SECTOR A,	575675 S	Sin Ming -	Tel: 64560226		
Handling Insurer:	China Tai	ping Insurance	(Singapore) Pte. L	.td. (HQ) - Tel: 638	9 6111	[Handled	by <b>Irene Tay Hu</b>	i Ping - 6389	36192]
Adjuster:	LKK Auto	<b>Consultants Pte</b>	Ltd (HQ) - Tel: 62	56-3561 [Handle	d by XIN	IG GUO Q	IANG] [Final	Rpt due 28/	12/2018]
Adj Asg. Remarks:	PLEASE SU	JRVEY AND REVER	RT						
ASSOCIA	TED MAIL RE	CEIVED					View	All Comp	ose Case Mail
There are r	o mail for this	case.							
ALL ASSO	CIATED TAS	SKS <sup>□</sup>			Vie	w All   S	Search Tasks   Cre	eate New Task	Complete
Due Dat			Group Subjec	t Handler	Assigned		Completed On	Created (	

### **Claim Documents**

Up	load Documents Up	load Photos   Compose New Letter	View View in Browser	er 🗸
Pho	Photos/Images		3 per page	<b>✓</b>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail F	Print
1	18/12/18 14:46	General View	1 Load PDF	
2	18/12/18 14:46	Photographs of Damaged Parts	Load PDF	
3	18/12/18 14:46	Photo After Spray	1 Load PDF	

## **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/CTI18020667/GCD3E2

Date:

18/12/2018

REFERENCE

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

DMCVSN1437981703

Claimant Vehicle

SLT1751L No:

Insured Vehicle No:

GBC7697D

Date of Loss:

13/11/2018

Nature of Claim: TP

Claim No:

SNM18D05357C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SLT1751L

Make & Model:

SUBARU FORESTER, 2.0 (A)

Engine No:

FA20CB14118

Reg. Date:

20/10/2017 (Man. Year: 2017)

Chassis No: Odometer:

JF1SJGK85JG099454 16060 km

Colour: **Engine Capacity:** 

1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification:

Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size:

225/55 R18

Rear Tyre Size:

225/55 R18

Front Left Side:

Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

18/12/2018

Date Inspected:

15/11/2018

Inspected At:

Em Solution Pte Ltd (HQ)

160 SIN MING DRIVE #03-18/19

SIN MING AUTOCITY SINGAPORE 575722

Estimated Period of Repair:

4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

## REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 18 Dec 2018)

Parts:

M1-SUV

SUBARU FORESTER 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLT1751L)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >