

ASS. REC. BY:

REF: CS/AIG18020669/Kvd3⁹² Special Instruction:Surveyor:
Menhen

Kenneth

ASSIGNMENT (Office)

From (Person):

Abu Kassim

of

AIG

Date/Time:

15/11/18 @ 9:42am

Estimated Cost:

Bill to:

OD ☒ TP ☐ WS / TP RES / OD RES / EYA / INV / MV / CS

To Inspect Vehicle No:

SDT 1818Z

Insured:

SME 42755

at Workshop m/s

RC Auto

Tel:

9761 9383

of

160 Sin Ming Drive #06-20

Policy No:

1800113142

Claim No:

0821651910 SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/11/2018

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

9:57am @ 15/11/18

Person Contacted:

Mr. Tan

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

REF: AIG

ASSIGNMENT

From:

Date: 15/11/2018

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SDT 1818Z

at Workshop m/s

RC Auto

of

160 Sin Ming Drive # 06-20

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SDT 1818Z

Yr Regn:

03 09

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Proton A) Saga

c.c

1332

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

204222

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

PL1BT3SRA-93063236

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/60R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

2

mm

R/Bal.

7

mm

L/Bal.

2

mm

L/Bal.

7

mm

D.O.A.

13/11/18

D.O.I.

15/11/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/11/18 19:12h Costum, car not ready

22/11 11:00 & 2300h Car back (Red 350.40, 60%)

RECEIVED 22 NOV 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 22/11 - typist

Days Of Repair:

10

Resurvey No. of Trip:

-

Survey Fee:

Transportation:

250

20

) S+RS SI

) Photos

) Others

TOTAL

270

Report Format:

merimen

Lump Sum / I.B.I: (\$

2300/-)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Nov 2018 Edit Reg		15 Nov 2018 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LIN SHENGXIN, ID: S8414979I		
Main Claimant:	V360PROPERTY (STNGAPORE) PTE. LTD., Co. Reg. No.: 201704745C		
Vehicle Reg. No.:	SDT1818Z	Date of Loss:	13/11/2018 00:00 - :59
Claim Type:	TP / 0821651910SG	Policy/Cover Note No.:	1800113142 (Comprehensive)
Vehicle Reg. No. (Insured):	SME4275S	Policy No. (Claimant):	
		Excess:	
Repairer:	RC AUTO (HQ) 18 Sin Ming Industrial Estate Sector A, #01-43, 575676 Sin Ming - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 26/11/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

- Pre repair inspection request - SDT1818Z VS SME4275S (OI) DOA 13/11/2018

From: Abu Kassim, Noor Mariesa
To:
Cc: Fong, Andy-SY, Chin, Lee-Ying, Md Ishak, Mohd Imran, Lim, Sheng Yang, Chan, Yoke Shi, Azlan, Syazairdina, Mithoosingh, Aashweenjeetkaur
Sent: 15/11/2018 9:42:06 AM
Attachments:  temp4495.tif

Hi,

Please refer to the enclosed request from **Legal Options LLC**

Claim no : 08216519105G003
Case Owner : Foo Chit Yan

If you have any queries/concerns, please let us know.
Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Regards,

Mariesa Abu Kassim (Mariesa)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

NoorMariesa.AbuKassim@aig.com | www.aig.com

IMPORTANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: pinky@legaloptions.biz
To: Syazairdina.Azlan@aig.com, lyna@legaloptions.biz
Cc: Andy-SY Fong@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, yokeshi.chan@aig.com, Baljit.Kaur@aig.com
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SME4275S AND SDT1818Z ON 13/11/2018
Date: Wed, 14 Nov 2018 09:59:21 +0000

Dear Sirs,

Our client is agreeable to Kenneth Kong from LKK.

The said surveyor may contact Mr Tan at 9761 9383, M/s RC Auto at 160 Sin Ming Drive #06-20, Sin Ming Autocity, Singapore 575722

*If we do not hear from you within 2 days of this email, our clients shall deem that you have agree that the surveyor appointed by our clients shall be our single joint expert for this matter.

Thank you,

Pinky
M/s Legal Options LLC

From: Azlan, Syazairdina
Sent: Wed, 14 Nov 2018 08:44:27 +0000
To: pinky@legaloptions.biz, lyna@legaloptions.biz
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Kaur, Baljit
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SME4275S AND SDT1818Z ON 13/11/2018

Without Prejudice

Your Reference : 18-A18-MISC218-O2-VL.jp.sb
Our Reference : SME4275S

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Chin, Ann

Sent: Wednesday, November 14, 2018 2:37 PM

To: PRDSG.FNOL

Cc: Chan, Yoke Shi; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina; Md Ishak, Mohd Imran; Tan, Lily (AIG); Zhou, Aiping; Ho, Choon-Poh; Quek, Joyceline-CH

Subject: 05#SME42755#002,002#DEFAULT

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

LEGAL OPTIONS LLC

ADVOCATES & SOLICITORS
Mediators - Commissioners for Oaths - Notary Public
法商律師事務所

Motor Accident & Personal Injuries
Tel: (65) 6513 2800 Fax: (65) 6438 8275

Commercial, Litigation, Property, Trust & Estate, Family
Tel: (65) 6438 8039 Fax: (65) 6734 8230

We do not accept service of Court Documents by fax

Directors
Joan Lim Phock Hoon LL.B (Hons)
Victor Leong Wai Meng LL.B (Hons)
Teo Lip Hua Benedict LL.B (Hons) LL.M

Junior Secretary's DID: 6513 2803
Direct Fax: 6438 8275
(Email: hwa@legoptions.biz)

Mailing Address for Accident Claims
Documents Support:
23 Kaki Bukit Avenue 4 #01-01 South Wing
Singapore 415933

Your Ref : SME 4275S

Our Ref : 18-A18-MISC218-02-VL.jp.sb

14th November 2018

M/S AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way #07-16

AIG Building

Singapore 079120

(Attn: Motor Claims Department)

Dear Sirs,

CLAIMANT : V360PROPERTY (SINGAPORE) PTE LTD
ACCIDENT INVOLVING VEHICLE SDT 1818Z, SME 4275S AND OTHERS ALONG TPE
TOWARDS SLE AFTER TAMPINES AVENUE 10 EXIT ON 13/11/2018

We are instructed by M/S V360PROPERTY (SINGAPORE) PTE LTD to notify you of a road traffic accident on 13th NOVEMBER 2018 at about 18:00 HOURS ALONG TPE TOWARDS SLE AFTER TAMPINES AVENUE 10 EXIT involving our client's vehicle registration number SDT 1818Z and vehicle registration number SME 4275S driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully


cc: Clients (SDT 1818Z)

IMMEDIATE ATTENTION

BY FAX: 6835 7416/POST

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4745C
Vehicle Details	
Vehicle No.:	SDT1818Z
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Nov 2018
Vehicle Make:	PROTON
Vehicle Model:	SAGA 1.3L AT M-LINE AIRBAG 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	54PEPL4361
Chassis No.:	PL1BT3SRR9B063236
Maximum Power Output:	70.0 kW (93 bhp)
Open Market Value:	\$9,592.00
Original Registration Date:	10 Mar 2009
First Registration Date:	10 Mar 2009
Transfer Count:	3
Actual ARF Paid:	\$9,592.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Mar 2019
PARF Rebate Amount:	\$4,796.00
Intended COE Rebate Details	
COE Expiry Date:	09 Mar 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$4,460.00
COE Rebate Amount:	\$130.00
Total Rebate Amount:	\$4,926.00

The information contained herein is correct as at 22 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/11/2018 13:09
Date Of Accident	13/11/2018 18:00
Exact Location Of Accident	TPE TOWARDS SLE AFTER TAMPINES AVE 10 EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDT1818Z
Insured/Policyholder	
Name Of Registered Owner	V360PROPERTY (SINGAPORE) PTE. LTD.
Co Reg No	201704745C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67146717
Vehicle Particulars	
Manufacturer	PROTON
Model	SAGA-1.3 (A)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091687076
Cover Note Number	
Driver	
Name of Driver	ISKANDAR BIN AZIZ
NRIC No	S9410503Z
Date Of Birth	31/03/1994
Occupation	OUTDOOR
Date Of Driving Pass	01/06/2016
Driving Experience	2 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87423929
Fax Number	
Contact Number	
EMail Address	ISKANDAR@V360PROPERTY.COM

Address	BLK 485B CHOA CHU KANG AVE 5 #11-116 SINGAPORE
Postcode	682485
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME4275S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIN SHENG XIN
NRIC/Passport Number	S8414979I
Contact Number	97668979
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHD395U
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

TAN KOON LAM

NRIC/Passport Number

Contact Number

97972595

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Not Anthonie
11 Lys 82³00h
Presmy After Point
10 days

Reg. No. 53199168K

Date : 20-Nov-2018

[illegible]

Acknowledged by Repairer

Received by

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18020669/KVD3N2
Date: 27/11/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800113142
Claimant Vehicle No :	SDT1818Z	Insured Vehicle No :	SME4275S
Date of Loss:	13/11/2018	Nature of Claim:	TP
		Claim No:	0821651910SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDT1818Z	Engine No:	S4PEPL4361
Make & Model:	PROTON SAGA, 1.3 (A)	Chassis No:	PL1BT3SRR9B063236
Reg. Date:	10/03/2009 (Man. Year: 2009)	Odometer:	204222 km
Colour:	Metallic Silver		
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R14	Rear Tyre Size:	185/60R14
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,842.40	3,362.00	480.40	12.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,860.00	100.00	5.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,802.40	5,222.00	580.40	10.00
Approved Total (Overridden) (\$\$)		2,300.00		
Nett Amount (\$\$)	5,802.40	2,300.00	3,502.40	60.36

INSPECTION

Date of Assignment:	15/11/2018	Inspected At:	160 SIN MING DRIVE# 06-20 SIN MING AUTOCITY SINGAPORE 575722 REPAIRER: RC AUTO (HQ)
Date Inspected:	15/11/2018		
Estimated Period of Repair:	10.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	580.00 FL	*580.00 FL
2	1		*FRONT BUMPER BEAM	Bent	290.00 FL	*290.00 FL
3	1		*FRONT HEADLAMP	O/s Mtg Cracked	840.00 FL	*420.00 FL
4	1		*REAR BOOTLID	Buckled	640.00 FL	*640.00 FL
5	1		*REAR BOOTLID LOCK	Distorted	120.00 FL	*120.00 FL
6	1		*REAR LAMP (RH)	Cracked	240.00 FL	*240.00 FL
7	1		*REAR BUMPER SPONGE	Cracked	95.00 FL	*95.00 FL
8	2		*REAR BUMPER BRACKET	Bent	150.00 FL	*150.00 FL
9	1		*REAR PANEL	Bent	285.00 FL	*285.00 FL
10	2		*REAR BUMPER RETAINER	Serviceable	76.00 FL	*- FL
11	1		*REAR BUMPER	Bent	480.00 FL	*480.00 FL
12	1		*REAR PANEL GARNISH	Mtg Distorted	180.00 FL	*180.00 FL
13	1		*SET REVERSE SENSOR	Shorted	234.00 FS	*200.00 FS
14	1		*SET FRONT NO PLATE	Cracked	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,240.00	3,710.00
- List Item Discount on L Items 10.00/10.00% (S\$)	397.60	348.00
Total Parts (S\$)	3,842.40	3,362.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RESPRAY FRONT AND REAR PORTION	New	800.00	800.00
2	TO KNOCK AND REPLACE FRONT AND REAR PORTION	New	1,100.00	1,000.00
3	ANTI-RUST	New	60.00	60.00
Gross Labour Cost (\$\$)			1,960.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >