

Surveyor

Tanpin

REF: ASM(CAXA)

Robert Tan

@

### ASSIGNMENT

From: \_\_\_\_\_ Date: 3/12/18

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKC6648X

at Workshop m/s

of performance  
303 Alexandra Rd

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Chua

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 974K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>1up</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKC6648X Yr Regn: 2011 / April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 730Li

C.C 2996

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 58619

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

UK AKB 22 0206W 74784

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

245/50R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 3/12/18 320pm

Survey held at

pmc.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

\_\_\_\_ \$ + RS. \_\_\_\_ SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee: ☐ Site Insp (\$ \_\_\_\_\_)

☐ Interview (\$ \_\_\_\_\_)

☐ Tech. Invs (\$ \_\_\_\_\_)

☐ Weekend (\$ \_\_\_\_\_)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	6457H
<b>Vehicle Details</b>	
Vehicle No.:	SKC6648X
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2018
Vehicle Make:	B.M.W.
Vehicle Model:	730LI AT ABS D/AB 2WD 4DR NAV HID SR
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	12117666N52B30AF
Chassis No.:	WBAKB22020CN74784
Maximum Power Output:	190.0 kW (254 bhp)
Open Market Value:	\$73,443.00
Original Registration Date:	28 Apr 2011
First Registration Date:	28 Apr 2011
Transfer Count:	1
Actual ARF Paid:	\$73,443.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Apr 2021
PARF Rebate Amount:	\$44,065.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	27 Apr 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$62,001.00
COE Rebate Amount:	\$14,862.00
<b>Total Rebate Amount:</b>	<b>\$58,927.00</b>

The information contained herein is correct as at 04 Dec 2018

OK