

Surveyor: SMR

REF:

NS/INC18020687/Gsb52

C5369K

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s SMRT

of _____

Insured: SJW 857TK

Policy No. 5044594313-08 160718-150719

Claims No. MT/1019389-002


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 6425C

Yr Regn: 01 Nov 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ~~Toyota~~ Toyota Prius c.c 1798

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 123279 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTOK B3F U903573380

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. B-11-18

Survey held at w/s 433cpm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>SHD 6425C - NS/INC14403552 / Highw2</u>
	<u>SJW 857TK - X</u>
	<u>1069.98</u>
<u>28/11/18</u>	<u>Confirmed P/P \$ 1,069.98 @ 2 days with XGA</u>
	<u>(\$ 1,836.75 Red - 63%)</u>
	<u>RECEIVED 28 NOV 2018</u>

Date/Time, File Pass to?

28/11/18

1) Typ. 3

Date/Time, File Return to?

2) _____

☐

: Preli. Report

☒

: Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

1 S + RS 1 SI

: Photos

: Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 1,069.98 r/p)

TP Claims against NTUC Income: Follow-Through Survey

Date: 28/11/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1019389-002	SMRT TAXIS PTE LTD	SHD 6425C	SJW 8577K	11/11/2018	17:50	\$ 2,906.73
2	MT/1021736-001	SMRT TAXIS PTE LTD	SHD 6355X	SJQ 6887K	15/11/2018	12:20	\$ 3,594.95

Claim received from LKK Auto

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No. (For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5044594313-08		CAMPUS SUPPLIES PTE LTD	199100692K	GPC	drive CLASSIC	SJW8577K	SJW8577K	16/07/2018	15/07/2019

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
<YeoPohsuan@smrt.com.sg>
Sent: Wednesday, 28 November 2018 1:24 PM
To: Shirley Hiew (LKK Auto); Guo Qiang (LKKAuto)
Cc: SUR; CS A Team
Subject: RE: SHD6425C

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, 28 November 2018 10:06 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Guo Qiang (LKKAuto)
Cc: SUR; CS A Team
Subject: RE: SHD6425C

Dear Poh Suan,

Confirmed final fig \$1,069.98 @ 2 working days of repairs .

Thank you.

Best Regards,

Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, 26 November 2018 11:19 AM
To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHD6425C

Hi Guo Qiang,

Attached herewith the repair estimate of SHD 6425C having Case No:
TAX/11/18/2049.

There is no change to the approved amount of \$1,069.98 @ 2 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))

Sent: Monday, 26 November 2018 11:11 AM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))

Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/11/2018 12:34
Date Of Accident	11/11/2018 17:50
Exact Location Of Accident	SLIP ROAD FROM ALEXANDRA ROAD TOWARDS TELOK BLANGA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6425C
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	
Driver	
Name of Driver	CHUA WEE LOON
NRIC No	S7925678A
Date Of Birth	08/08/1979
Occupation	OUTDOOR
Date Of Driving Pass	04/12/2009
Driving Experience	8 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STATIONARY ALONG THE SLIP ROAD FROM ALEXANDRA ROAD TOWARDS TELOK BLANGAH ROAD AS I WAS LOOKING OUT FOR THE ONCOMING TRAFFIC. WHILST I WAS STATIONARY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SJW8577K HAD COLLIDED ONTO THE REAR OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW8577K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

A- SHD6425C
B- SJW8577K

Alexandra Road

[illegible]

I/We declare the foregoing particulars are true in every respect.



AAJ Ans 12/1/18
Driver's Signature

12/11/2018

Page 4 of 10

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5369K

Vehicle Details

Vehicle No.:	SHD6425C
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS100502
Chassis No.:	JTDKB3FU903573380
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	01 Nov 2017
First Registration Date:	01 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2025
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	31 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$29,227.00
Total Rebate Amount:	\$32,977.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Nov 2018

OK



Case Details

Case Reference Number :

TAX/11/18/2049

Type of Repair : Accident Repair

Vehicle Registration Number :

SHD6425C

Company Type : SMRT Taxi Pte

Ltd

Estimation ID : EST-4495-ID the Rep

Assigned By : Kok Wah Wong

Insurance Company Name : NTUC Income Insurance Co-

Ltd LKK Automotive Ltd is hence notify

Accident Date and Time : 11/11/2018 09:50 AM

Vehicle Age(In Months) : 12

- To resurvey be after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main	Repair X		COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair	
One Time Key In	Main	MC /		CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00 /	25.00	11.25	Replace	10	11.25 /	Replace	
One Time Key In	Main	NN X		PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60 /	25.00	5.70	Replace	0	0	Not Give	
One Time Key In	Main	NN {	X	PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60 /	25.00	5.70	Replace	0	0	Not Give	
One Time Key In	Main		X	PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60 /	25.00	5.70	Replace	0	0	Not Give	
One Time Key In	Main		X	SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00 /	25.00	16.50	Replace	0	0	Not Give	
One Time Key In	Main	NN X		REAR BUMPER REINFORCEMENT	1	318.80	318.80 /	25.00	239.10	Replace	0	0	Check	

Total Spare Part Cost 1,594.73

Lump Sum Discount (%) 0.00

Final Spare Part Cost 1,594.73

Surveyor Total 549.97

Lump Sum Dis (%) 0

Final Sur Total 549.97

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00 ✓	0.00	180.00	Replace	0	0	Check ▾
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00 ✓	0.00	120.00	Replace	2	120.00 ✓	Replace ▾
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50 ✓	25.00	83.63	Replace	0	0	Check ▾
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70 ✓	25.00	84.53	Replace	0	0	Check ▾
One Time Key In	Main			FILLER, RR BUMPER, LH	1	119.90	119.90 ✓	25.00	89.93	Replace	1	0	Repair ▾
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30 ✓	25.00	418.72	Replace	1	418.72 ✓	Replace ▾
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Not Give ▾
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	0	0	Not Give ▾

Total Spare Part Cost 1,594.73

Surveyor Total 549.97

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 1,594.73

Final Sur Total 549.97

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION	338.00	200	
Total:		338.00	200.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		738.00	280.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY BUMPER BEAM	180.00	0	
3	TO RESPRAY FILLER RR BUMPER LH	180.00	80	
Total:		738.00	280.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TOWING CHARGE	56.00	0	
2	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40	
3	TO WASH AND VACUUM	60.00	0	
Total:		236.00	40.00	

3338.30

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,594.73	549.97
Total Labour Cost	338.00	200.00
Total Spray Painting	738.00	280.00
Other	236.00	40.00
Overall Total	2,906.73	1,069.97
Lump Sum Repair Option		
Lump Sum Total	0.00	1,069.97
Surveyor Approved Amount		1,069.97
No of Repair Days*	3	2
Remarks		part by part before paint photos
Surveyor Name		GuoQiang

Estimator Assesment(\$)

Surveyor Assesment(\$)

Signature



Guo Qiang

Save



Clear

Survey Date



13/11/2018

Section A - Accident Details

Registration Number	SHD6425C
Case Reference Number	TAX/11/18/2049
Registration Date	01/11/17
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHUA WEE LOON (CAI WEILUN)
Type of Accident	Head to Rear
Accident Date and Time	11/11/18 5:50 PM
Accident Reported Date and Time	12/11/18 12:23 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098714
Special Instruction to ARC, if any	TOWED \$40
Prepared Date and Time	12/11/18 6:09 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$738.00	\$280.00
Total Spare Part Cost	\$1,594.73	\$549.98
Total Other Cost	\$236.00	\$40.00
TOTAL COST	\$2,906.73	\$1,069.98 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Tuck Foo Kok	GUO QIANG (LKK) / NTUC
ARC / Surveyor Sign Off Date	12/11/2018 6:48 PM	13/11/2018 4:59 PM
Signature		
Remarks		part by part before paint photos

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1811-0315	Invoice Number	
Quotation Date	20.11.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$338.00	\$200.00
Total Labour	\$338.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$80.00
Total Spray Painting & Panel Beating	\$738.00	\$280.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$236.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		5246247030	PAD, RR BUMPER, RH & LH, 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5246247020	PAD, RR BUMPER, RH & LH, 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5246247010	PAD, RR BUMPER, RH & LH, 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5219147030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given
		5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Check
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Check
		5256647900	FILLER, RR BUMPER, LH	1.00	\$119.90	100.00	\$0.00	Replace	Repair
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace
		5216947020	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Not Given
		5246147010	PAD, RR BUMPER, CTR	0.00	\$2.20	0.00	\$0.00	Replace	Not Given
Total					\$1,926.00		\$549.98		

549.98
+ 200.00
+ 320.00
1069.98



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18020687/Gsbs2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 05-12-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJW 8577K	Veh. Inspected	SHD 6425C
Policy No.	5044594313-08	Coverage (\$)	0.00
Claim No.	MT/1019389-002	Excess (\$)	0.00
Assign From		Assign Date	13/11/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU903573380	Colour	MAROON
Odometer	123279	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	FALKEN	6 mm
L/H Front Tyre	195/65R15	FALKEN	6 mm
R/H Rear Tyre	195/65R15	FALKEN	6 mm
L/H Rear Tyre	195/65R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/11/2018	Inspection Date	13/11/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6425C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
10	CLIPS PIECE, FRT & RR BUMPER @ \$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	GUARD, RR BUMPER, LOWER (DISC 25%)	CUT	558.30	418.73
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
2	PAD, RR BUMPER, RH & LH, 1 @ \$3.80	NOT NECESSARY	7.60	-
2	PAD, RR BUMPER, RH & LH, 2 @ \$3.80	NOT NECESSARY	7.60	-
2	PAD, RR BUMPER, RH & LH, 3 @ \$3.80	NOT NECESSARY	7.60	-
2	SEAL, RR BUMPER ARM, RH & LH @ \$11.00	NOT NECESSARY	22.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	RETAINER, RR BUMPER, LH	NOT NECESSARY	111.50	-
1	RETAINER, RR BUMPER, RH	NOT NECESSARY	112.70	-
1	COVER, GUARD RR BUMPER LOWER	NOT NECESSARY	14.80	-
3	PAD, RR BUMPER, CTR @ \$2.20	NOT NECESSARY	6.60	-
1	COVER, RR BUMPER ASSY	TO REPAIR SEE LABOUR	423.90	-
1	FILLER, RR BUMPER, LH	TO REPAIR SEE LABOUR	119.90	-
			2,026.30	549.98
LABOUR				
PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF COVER, RR BUMPER ASSY AND FILLER, RR BUMPER, LH.			338.00	200.00
SPRAY PAINT.			738.00	280.00
TOWING CHARGE.			56.00	-
TO TEST AND REFIX REVERSE SENSOR SYSTEM.			120.00	40.00
TO WASH AND VACUUM.		NOT NECESSARY	60.00	-
			1,312.00	520.00
GRAND TOTAL			3,338.30	1,069.98
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,069.98

Report Ref No. NS/INC18020687/Gsbs2

Report Ref No. NS/INC18020687/Gsbs2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

A handwritten signature in black ink, appearing to be "K.K.LAU".

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.