

REF: CSI /SPF18020719 / Klvb sz

Special Instruction:

45: ₹ 1500.00

*Third Parties:*

Claimant:

Surveyor: Vicom Ltd

Workshop: Comfort Delcro

From (Person): Frankie Thuy of SPF Date/Time: 15-11-2018  
Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD/TP Re-inspection (Evaluation)

To Inspect Vehicle No: SH 7438H

Insured: QX228H

at Workshop m/s Comfort Delgado  
of 59 Loyang Drive

Tel:

Policy No:

Claim No: AEMP/105/001/2018/155

Sum Insured:

Excess:

Make of Veh:

D.O.A. 05-10-2018


(Client's Record)

H.O.D. Enrolment/Date: \_\_\_\_\_

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT \_\_\_\_\_

Date/Time: 10/1/16 Confirmed with 10/1/16 Final Fig 10/1/16, 10/1/16 days (Red \$ 10/1/16 / 10/1/16 %; Original 3 days)

Date/Time: 16/11/18 Submit Final Fig LS 1200, 2 days (Red \$ 300 / 30 %; Original 2 days)

Date/Time	Action/Instruction
	SH 7438.H - CP3 / TML/6075584 / Hlvbn2
	Range \$1.2K - \$1.5K
	<div style="text-align: center;"> RECEIVED 20 NOV 2018 </div> <div style="text-align: right;">   20/11/2018 </div>

RECEIVED 20 NOV 2018

✓ 20/11/2018

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)
--

**Para(3) : Nett Value**

Market Value :

Salvage Value :

Nett Value :

Inspected/  
Evaluated by:

*Fee Charged:*

Basic & Add	
Transport	
Photos	
Others	
Total	

Date: \_\_\_\_\_

1) Date/Time 20/11- typist File Pass to

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

2) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

4) Date/Time File Return to

6) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

## Veron Chen (LKKAUTO)

---

**From:** Frankie THAY (SPF) <Frankie\_THAY@spf.gov.sg>  
**Sent:** Tuesday, 20 November 2018 10:37 AM  
**To:** Admin-D (LKKAUTO)  
**Cc:** Abdul Rahman MOHAMAD SALIM (SPF); Rosalyn TAN (SPF)  
**Subject:** RE: AEMD/105/009/2018/155 Post Survey for SH7438H  
**Attachments:** 2018-155 GIA for SH7438H.pdf

Catherine,  
Please find GIA report in attachment.

Thanks.

Frankie Thay (Mr)  
Safe Driving Manager  
Automotive Engineering & Management Division  
Police Logistics Department  
Singapore Police Force  
DID: (65) 6478 4841 | FAX: (65) 6478 4848



**WARNING** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

---

**From:** Admin-D (LKKAUTO) <admin-d@lkkauto.com>  
**Sent:** Friday, 16 November 2018 9:53 AM  
**To:** Frankie THAY (SPF) <Frankie\_THAY@spf.gov.sg>  
**Cc:** Abdul Rahman MOHAMAD SALIM (SPF) <Abdul\_Rahman\_Mohamad\_Salim@spf.gov.sg>  
**Subject:** RE: AEMD/105/009/2018/155 Post Survey for SH7438H

Dear Mr Frankie,

Kindly assist provide us the full set GIA report.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Frankie THAY (SPF) [[mailto:Frankie\\_THAY@spf.gov.sg](mailto:Frankie_THAY@spf.gov.sg)]  
**Sent:** Thursday, 15 November, 2018 4:47 PM  
**To:** Admin-D (LKKAUTO) <admin-d@lkkauto.com>  
**Cc:** Abdul Rahman MOHAMAD SALIM (SPF) <[Abdul\\_Rahman\\_Mohamad\\_Salim@spf.gov.sg](mailto:Abdul_Rahman_Mohamad_Salim@spf.gov.sg)>  
**Subject:** RE: AEMD/105/009/2018/155 Post Survey for SH7438H

Catherine,  
Please find GIA for SH7438H in attachment.

Thanks.

Frankie Thay (Mr)  
Safe Driving Manager  
Automotive Engineering & Management Division  
Police Logistics Department  
Singapore Police Force  
DID: (65) 6478 4841 | FAX: (65) 6478 4848



**HOME TEAM**  
TRANSFORMATION 2025  
One Home, One Team  
Building Our Future Together

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

---

**From:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Thursday, 15 November 2018 4:12 PM  
**To:** Frankie THAY (SPF) <[Frankie\\_THAY@spf.gov.sg](mailto:Frankie_THAY@spf.gov.sg)>  
**Cc:** Abdul Rahman MOHAMAD SALIM (SPF) <[Abdul\\_Rahman\\_Mohamad\\_Salim@spf.gov.sg](mailto:Abdul_Rahman_Mohamad_Salim@spf.gov.sg)>  
**Subject:** RE: AEMD/105/009/2018/155 Post Survey for SH7438H

Dear Mr Frankie,

Kindly assist provide us the both party GIA report.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) [<mailto:admin-d@lkkauto.com>]  
**Sent:** Thursday, 15 November, 2018 4:08 PM  
**To:** 'Frankie THAY (SPF)' <[Frankie\\_THAY@spf.gov.sg](mailto:Frankie_THAY@spf.gov.sg)>; Olivia Lau (LKKAuto) <[olivialau@lkkauto.com](mailto:olivialau@lkkauto.com)>  
**Cc:** 'Abdul Rahman MOHAMAD SALIM (SPF)' <[Abdul\\_Rahman\\_Mohamad\\_Salim@spf.gov.sg](mailto:Abdul_Rahman_Mohamad_Salim@spf.gov.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: AEMD/105/009/2018/155 Post Survey for SH7438H

Dear Mr Frankie,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Frankie THAY (SPF) [mailto:Frankie\_THAY@spf.gov.sg]

**Sent:** Thursday, 15 November, 2018 3:55 PM

**To:** Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>

**Cc:** Catherine Chong <catherinechong90.cc@gmail.com>; Abdul Rahman MOHAMAD SALIM (SPF) <Abdul Rahman Mohamad Salim@spf.gov.sg>

**Subject:** RE : AEMD/105/009/2018/155 Post Survey for SH7438H

Your reference : SH 7438H

Our reference : AEMD/105/009/2018/155

Olivia,

Please conduct a post survey for SH7438H and probed with upper range repair cost.

Thanks.

Frankie Thay (Mr)  
Safe Driving Manager  
Automotive Engineering & Management Division  
Police Logistics Department  
Singapore Police Force  
DID: (65) 6478 4841 | FAX: (65) 6478 4848



**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

## Catherine Chong (LKK Auto)

---

**From:** Frankie THAY (SPF) <Frankie\_THAY@spf.gov.sg>  
**Sent:** Thursday, 15 November, 2018 3:55 PM  
**To:** Olivia Lau (LKKAuto); Admin-D (LKKAuto)  
**Cc:** Catherine Chong; Abdul Rahman MOHAMAD SALIM (SPF)  
**Subject:** RE : AEMD/105/009/2018/155 Post Survey for SH7438H  
**Attachments:** 2018-155 Survey for SH7438H.pdf

Your reference : SH 7438H

Our reference : AEMD/105/009/2018/155

Olivia,

Please conduct a post survey for SH7438H and probed with upper range repair cost.

Thanks.

Frankie Thay (Mr)  
Safe Driving Manager  
Automotive Engineering & Management Division  
Police Logistics Department  
Singapore Police Force  
DID: (65) 6478 4841 | FAX: (65) 6478 4848



**HOME TEAM**  
TRANSFORMATION 2025  
One Home, One Team  
Building Our Future Together

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/10/2018 16:10
Date Of Accident	05/10/2018 12:40
Exact Location Of Accident	YISHUN ST 61 OPEN CAR PARK B/635
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH7438H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	YAP HIAN CHUAN
NRIC No	S1566675G
Date Of Birth	08/11/1962
Occupation	OUTDOOR
Date Of Driving Pass	23/12/1982
Driving Experience	35 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93395735
Fax Number	
Contact Number	
EMAIL Address	NOEMAIL



Address	BLK 222 YISHUN STREET 21 #10-443
Postcode	760222
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	PASIR RIS N.P.C
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO ATTACHED / POLICE REPORT : T/20181005/2071

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX228H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	LEFT FRT
No. Of Passenger (Including Driver)	

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO REG. NO. 192202321R


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Kindly refer to police case @ T/20181005/2071

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 100002221R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20181005/2071

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

1 of 3

Report No. T/20181005/2071

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/10/2018 15:15	Vide Report No.: F/20181005/0104	Station Diary No.: 61
--	-------------------------------------	--------------------------

## Informant's Particulars

Name of Informant: YAP HIAN CHUAN			Address: APT BLK 222 YISHUN STREET 21 #10-443 SINGAPORE 760222		
ID Type / ID No.: NRIC NO / S1566675G			Contact No.: Home/Office: Mobile: 93395735		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 55	Date of Birth: 08/11/1962	Type of Informant: Driver		
Race: Chinese			Language: Mandarin		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:		

## General Information of the Accident

Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 05/10/2018 12:40	Type of Location: Car Park
Location: Along Road 1 YISHUN STREET 61 open space carpark near to B/635 Yishun St 61.				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX228H	Car	TOYOTA	Altis	White	Slightly Damaged	1
SH7438H	Car	HYUNDAI	i40	Blue	Slightly Damaged	0

## Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20181005/2071

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

2 of 3

Report No. T/20181005/2071

## CONTINUATION OF REPORT

Driver			
Name	YAP HIAN CHUAN		ID No. S1566675G
Related Vehicle	SH7438H (Car)		Contact No. 93395735
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

**Brief Details.**

On the 05/10/2018 at 12.40pm, I was driving my Comfort Taxi inside the open space carpark near to B/635 Yishun St 61. As I was driving, suddenly a Police Car QX228H came out of the Parking Lot 107, and hit onto my left front side of my Taxi. The left side of my Taxi was scratched on the front passenger door portion. While the Police car front bumper on the left side was dented and scratches with the front number plate dropped off. No one was injured. The Traffic Police came down and took my In-car camera memory card for their investigations.

I have a witness who is the driver of CityCab SHC7072K.



**SINGAPORE  
POLICE FORCE**



T/20181005/2071

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

3 of 3

Report No. T/20181005/2071

## CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
G /  
Sr Staff Sgt WONG TING CHIEN

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
05/10/2018 15:15

Officer In Charge Of Case:  
TP / GIA /  
Staff Sgt WONG SIEU LUI  
Contact No.: 65476151

Classification Of Case:









**SINGAPORE  
POLICE FORCE**

Authentication Stamp  
NP168

SIGNATURE











**VICOM LTD**

385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555  
Facsimile (65) 6458 1040

www.vicom.com.sg  
Company Registration No: 198100320R

## TAX INVOICE

COMFORTDELGRO ENGINEERING PTE LTD  
#205 Braddell Road  
Blk C Ext 1 3rd Level  
Singapore 579701

ATTN : MOTOR CLAIMS DEPT.

VEHICLE No. : SH7438H  
ACCIDENT DATE : 05/10/2018  
AIM No. : 305222363  
INSURED VEH.No: QX228H

GST REG No. : M9-0000652-A  
CUSTOMER ID : VACC0013  
INVOICE No. : LY011539  
INVOICE DATE : 19/10/2018  
PAYMENT TERM : 30 Days Credit

DESCRIPTION	QTY	UNIT PRICE (SG\$)	AMOUNT (SG\$)
Photographs	14	1.00	\$ 14.00
Transportation	1	50.00	\$ 50.00
VAC Assessment Fee	1	135.00	\$ 135.00

REMARKS	GROSS AMOUNT	\$	199.00
CTPL	GST @ 7%	\$	13.93
	INVOICE AMOUNT	\$	212.93

This is a computer generated TAX INVOICE

No signature required

Cheque should be made payable to 'VICOM LTD'.

**Sin Ming**

385 Sin Ming Drive Singapore 575718  
Tel: (65) 6455 5358 Fax: (65) 6455 8638

**Bukit Batok**

511 Bukit Batok Ct 23 Singapore 659545  
Tel: (65) 6560 3312 Fax: (65) 6569 0722

**Kaki Bukit**

23 Kaki Bukit Ave 4 Singapore 415933  
Tel: (65) 6741 6697 Fax: (65) 6749 2305

COMFORTDELGRO ENGINEERING PTE LTD

#205 Braddell Road

Blk C Ext 1 3rd Level

Singapore 579701



VICOM LTD

385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555

Facsimile (65) 6458 1040

www.vicom.com.sg

Company Registration No. 190100300P

## SURVEY REPORT

### GENERAL INFORMATION

VAC Ref. No.	: 533486	Claim No.	: 305222363
Accident Date	: 05/10/2018	Claim Type	: THIRD PARTY
Assignment Date	: 08/10/2018	Policy No.	:
Survey Date	: 08/10/2018	Finalised Dt.:	
Survey Report Date	: 19/10/2018		

### VEHICLE PARTICULARS

Vehicle No.	: SH7438H	Chassis No.	: KMHLB41UMFU065829
Registration Date	: 24/03/2015	Engine No.	: OBSCURED
Make	: HYUNDAI	Engine Cap.	: 1685 CC
Model	: I-40	Transmission	: AUTO
		Colour	: BLUE

### CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)

Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	: 436692KM		

<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	205/60R16	HANKOOK	6
FRONT LH	205/60R16	HANKOOK	6
REAR RH	205/60R16	HANKOOK	6
REAR LH	205/60R16	HANKOOK	6

### SURVEY CONDUCTED AT

ComfortDelGro Engineering Pte Ltd,  
59 Loyang Drive Singapore 508969.  
Assignment given by: MVA Limts (C.D.G.E.)

### REMARKS

[1] Workshop Estimate : S\$ 2,214.96  
[2] Our Adjustment : S\$ 1,500.00  
[3] Repair Period : 3 days  
[4] We have not authorised repairs. This survey was carried out on without prejudice basis.

Sin Ming

385 Sin Ming Drive Singapore 575718

Bukit Batok

511 Bukit Batok St 23 Singapore 659545

Kaki Bukit

23 Kaki Bukit Ave 4 Singapore 415933

## VICOM LTD

## SURVEY REPORT

## Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (\$\$)	VAC Adjustment (\$\$)
1	1	Front Bumper	Deformed	1052.20	1052.20
2	1	Front Bumper Bracket Top Lh	Distorted	22.40	22.40 X
3	1	Front Bumper Bracket Lh	Distorted	24.60	24.60 X
4	1	Front Fender Shield Lh	Deformed	174.90	174.90 X
5	1	Front Wheel Hub Cap Lh	Not In Use	107.10	0.00
<b>Subtotal</b>				: 1381.20	1274.10
Less 20 %				276.24	254.82
<b>TOTAL</b>				: 1104.96	1019.28

## SPECIAL NETT ITEM

1	1	Front Fender Advertisement Logo (Lh)	Necessary	100.00	100.00
<b>TOTAL</b>				: 100.00	100.00

**TOTAL FOR SPARE PARTS** : 1204.96 1119.28

**VICOM LTD**  
**SURVEY REPORT**

SH7438H @ 05/10/2018

**Annex B: Adjustment on Labour and Spray Painting**

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Labour charges	440.00	<del>300.00</del> 200
2	Spray painting	440.00	400.00
3	Wiring charges	50.00	<del>20.00</del> 30
4	Front wheel alignment	80.00	60.00
<b>TOTAL FOR LABOUR AND SPRAY PAINTING</b>		<b>1010.00</b>	<b>780.00</b>

**Summary**

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
<b>TOTAL FOR SPARE PARTS</b>	<b>1204.96</b>	<b>1119.28</b>
<b>TOTAL FOR LABOUR AND SPRAY PAINTING</b>	<b>1010.00</b>	<b>780.00</b>
<b>TOTAL REPAIR COST</b>	<b>2214.96</b>	<b>1899.28</b>

**VICOM LTD****SURVEY REPORT****Annex C: Conclusion****ASSESSOR'S REPORT**

At the place of inspection, we saw this vehicle sustained front nearside damage.

The damages seen during our survey were at front bumper, front n/s fender and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

**ASSESSOR'S RECOMMENDATION**

Comfortdelgro Engineering Pte Ltd (Loyang) estimated a repair cost of S\$2,214.96. We adjusted it to S\$1,899.28 on a part-by-part basis.

As this vehicle was more than 3 years old during the accident, we assess repairs on a lumpsum basis is appropriate. By applying the market discount of 20% from the part-by-part repairs, the re-adjusted repair cost on lumpsum basis is S\$1,519.42, round upto S\$1,510.00.

Accordingly, we recommend repairs to this vehicle be carried out on a lumpsum basis at S\$1,500.00.

The repairs would require a period of 3 working days.



Kamarudin Abdul Kadir  
for VICOM Ltd

C/S \$1200 / 2 days



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: AEMD/105/009/2018/155

Date: 23<sup>rd</sup> November 2018

Our Ref: CS1/SPF18020719/K1vbs2

**M/s Automotive Engineering & MGT Divison**

Accident Claim Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Frankie Thay

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
SH 7438H INSURED VEHICLE: QX 228H ACCIDENT DATE: 05/10/2018**

We thank you for your instruction on 15/11/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SH 7438H from M/s Vicom Ltd.
- b) Singapore Accident Statement of Vehicles SH 7438H.
- c) Colour damaged vehicle photographs of SH 7438H.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SH 7438H
Make & Model	: Hyundai I40
Year of Registration	: 2015
Chassis Number	: KMHLB41UMFU065829
Engine Capacity	: 1685 cc

2. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7438H**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEFORMED	1,052.20	1,052.20
1	FRONT BUMPER BRACKET TOP LH	NO DAMAGED	22.40	-
1	FRONT BUMPER BRACKET LH	NO DAMAGED	24.60	-
1	FRONT FENDER SHIELD LH	NO DAMAGED	174.90	-
1	FRONT WHEEL HUB CAP LH	NOT IN USE	107.10	-
	LESS 20% DISCOUNT		-276.24	-210.44
			1,104.96	841.76
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT FENDER ADVERTISEMENT LOGO (LH) (SN)	NECESSARY	100.00	100.00
			100.00	100.00
<b><u>LABOUR</u></b>				
	LABOUR CHARGES.		440.00	200.00
	SPRAY PAINTING.		440.00	400.00
	WIRING CHARGES.	NOT NECESSARY	50.00	-
	FRONT WHEEL ALIGNMENT.		80.00	60.00
			1,010.00	660.00
<b>GRAND TOTAL</b>			<b>2,214.96</b>	<b>1,601.76</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,200.00</b>

Report Ref No. CS1/SPF18020719/K1vbs2

**THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,200.00 - \$1,500.00****KALVIN ANG WEI KUN**

Automotive Assessor / Investigator

**K.K. LAU CPT(RET)****BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE****REGD Auto Consultant-SAE, Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.