

Your Ref: AEMD/105/009/2018/155

Date: 23<sup>rd</sup> November 2018

Our Ref: CS1/SPF18020719/K1vbs2

**M/s Automotive Engineering & MGT Divison**

Accident Claim Section  
(Singapore Police Force)  
1 Mount Pleasant Road  
Blk 8 Old Police Academy  
Singapore 298333  
(The Motor Claims Department)

Attn: Frankie Thay

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
SH 7438H INSURED VEHICLE: QX 228H ACCIDENT DATE: 05/10/2018**

We thank you for your instruction on 15/11/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SH 7438H from M/s Vicom Ltd.
- b) Singapore Accident Statement of Vehicles SH 7438H.
- c) Colour damaged vehicle photographs of SH 7438H.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SH 7438H
Make & Model	: Hyundai I40
Year of Registration	: 2015
Chassis Number	: KMHLB41UMFU065829
Engine Capacity	: 1685 cc

2. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.