



SMRT Automotive Services Pte Ltd  
251 North Bridge Road Singapore 179102  
Tel: 65 63311000 Fax: 65 63340247

## Tax Invoice

GST Reg No. : MR-8500001-7  
CRN : 199004280Z  
Invoice No. : IV190100160  
Date : 10.01.2019  
Vehicle No. : SMB5081T  
Your Ref No. : BUS/11/18/1004  
Our Ref No. : 24098787  
Terms : 30 Days

Customer Code: 3000066

SMRT BUSES LTD

Block Unit  
STREET 62  
6 ANG MO KIO  
SINGAPORE 569140



Description	Qty	Unit Cost	Add %	/ (Discount) Amount	Amount
Labour					
TO REPAIR LH PORTION CENTER	1.00	\$ 800.00	0.00	\$ 0.00	\$ 800.00
Others					
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1.00	\$ 700.00	0.00	\$ 0.00	\$ 700.00
PIXEL STENCIL LHS MID	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
GRAND TOTAL				\$	1,700.00

Remark :

Make/Model : ENVIRO 500  
Accident Date : 01.11.2018

N.B. Payment by cheque should be crossed and made payable to 'SMRT Automotive Services Pte Ltd'.  
No receipt will be issued unless requested.

Authorised Signature  
for SMRT Automotive Services Pte Ltd

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/11/2018 15:28
Date Of Accident	01/11/2018 16:00
Exact Location Of Accident	AYE AFTER BS 17141
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB5081T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81111111

### Vehicle Particulars

Manufacturer	ALEXANDER DENNIS
Model	DOUBLE DECKER

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-II027592MFBP
Cover Note Number	

### Driver

Name of Driver	ZAINUDDIN BIN ABU BAKAR
NRIC No	S1385141G
Date Of Birth	20/11/1959
Occupation	OUTDOOR
Date Of Driving Pass	03/07/1996
Driving Experience	22 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 6 ANG MO KIO ST62

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

### General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR

Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 11

### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

I WAS TRAVELLING ALONG AYE ON THE LEFT MOST LANE. AHEAD I OF MY BUS, THERE WAS A PTE BUS (PH9559H) IN STATIONARY POSITION WITH HAZARD LIGHTS. I'M NOT SURE IF IT HAD BROKEN DOWN OR WAS INVOLVED IN ACCIDENT. I COULD SEVERAL PTE CARS AHEAD OF MY BUS FOLLOWING THE PTE BUS OVERTAKING THE PTE BUS AS SUCH I FOLLOWED. WHILE I WAS PREPARING TO OVERTAKE THE PTE BUS, I REALISED MY BUS CAN'T PASS THRU HENCE THE PTE BUS BUS DRIVER, WHILE INSIDE THE BUS, GUIDED ME SLOWLY. I DROVE FORWARD WITHIN MY LANE, SUDDENLY THE PTE SWERVED A SHARPE RIGHT AND IT'S RIGHT VIEW MIRROR COLLIDED ONTO MY BUS LEFT CENTRE PORTION. THE BUS DRIVER ADMITTED HIS FAULT AND WE EXCHANGE PARTICULARS.

### Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PEND DOWNLOAD

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PH9559H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category BUS

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Hand-drawn sketch of a river bend. Two points are marked: (A) SMB5081 and (B) PH9559H. The river is labeled 'AYE' and 'Clement Stadium'.

# Clement's Stadium

[illegible]

7

## Enquire Transaction History

### Transaction History Details

Log Date/Time:	02 Nov 2018 / 15:55:33		
Asset Type:	Vehicle	Transaction Amount:	\$7.49
Asset ID:	PH9559P		
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)	Channel:	External Agency
User ID:	ESASBAH0 - BALQISH BINTE ABDUL HALIL	Business Transaction Reference No.:	20181102155533162552

Search Date / Time: 01 Nov 2018 16:00:00

Insurance Company: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Information displayed is correct as at the log date and time.

[Enquire Related Logs](#)

[Back to List](#)