

ASS. REC. BY:

REF: CS3/AIG18020758/Jcd31²

Special Instruction:

Surveyor:

Hwee Jee

ASSIGNMENT (Office)

From (Person):

Chin lee Ying

of

AIG

Date/Time: 16/11/18 @ 11:15am

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJM 6627R

Insured:

SLU 1397X

at Workshop m/s

Hup Lay Huat

Tel:

9677 3832

of

1 kaki Bukit Ave 6 #01-35

Policy No:

1700082184

Claim No:

9843966329SG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:45am @ 16/11/18

Person Contacted:

Mr. Tan

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SJM 6627R - X
	SLU 1397X - CS/FCI 18018751 / 71rd3 DOA: 11/10/2018
	Dismantle: 19/11/2018.
	After repair: 20/11/2018.

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 16/11/2018 11:15:27 AM
Attachments:  81035.LTR.pdf  NEW PRI - SLU1397X AND SJM6627R.PDF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Cheonghoh Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply please quote our Reference Number

Our Ref: LCH.ct/2KB02-61035.18

13.11.18

BY FAX NO. 66367416 AND BY HAND
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120

BY CERTIFICATE OF POSTING TO ALL DEFENDANTS
Ong Sin Yee
68 Joo Chiat Lane #01-06
Singapore 429109

BY FAX NO. 66367416 AND BY HAND
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120

Tan Yon Joo (chen Yongyu)
BLK 107A Edgetfield Plains #03-104
Singapore 821107

Dear Sirs

We are instructed by Kallio Rentals to notify both of you of a road traffic accident on 11.11.18 at about 11:30 am at CTE towards city involving our client's vehicle registration number SJM 6627 R and vehicles registration number SLU 1397 X and SLG 5604 X driven by your respective insured driver/you/your driver at the material time. A copy of the Singapore accident statement filed is available.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

For the avoidance of doubt, our client will be claiming for compensation for loss of use/rental of a replacement vehicle in the instances enumerated in the State Courts Practice Direction Amendment No. 1 of 2016 paragraphs 7.1 and 7.2 of the Appendix C of the Pre-action Protocol for Non-Injury Motor Accident Cases which compensation is additional to any other claim for loss of use/rental of a replacement vehicle which our client may make against your insured and/or your insured's driver and or you/your driver.

Yours faithfully

Cheonghoh Law Corporation

encs:

This is a computer-generated document and requires no signature

cc: client (via e-mail/fax only) - SJM 6627 R

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/11/2018 12:39
Date Of Accident	11/11/2018 11:30
Exact Location Of Accident	CTE TWDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM6627R
Insured/Policyholder	
Name Of Registered Owner	KAJIO RENTALS
Co Reg No	53387434C
Email Address	KAJIORENTALS@HOTMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-97295873

Vehicle Particulars

Manufacturer	TOYOTA
Model	PICNIC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5104625411
Cover Note Number	

Driver

Name of Driver	TIANG ZHANG YONG ALEX
NRIC No	S9017673J
Date Of Birth	18/05/1990
Occupation	INDOOR
Date Of Driving Pass	21/07/2015
Driving Experience	3 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90256351
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 114 LORONG 3 GEYLANG #04-63
Postcode	381114
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : ASTON TIANG ZHANG HAO GENDER: : MALE
Passenger 2	NAME: : SIEW ZHU JUN GENDER: : FEMALE
Passenger 3	NAME: : ENGEL FANG LAVIANI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KOLAM AYER NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 72 GEYLANG BAHRU #01-3038 , POSTCODE: 330072 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2969999 - FAX NO: 62937659
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20181111/2075.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU1397X
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B

Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLS4619Y
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	ENGEL FANG LAVIANI
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJM6627R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:



Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #3 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20181111/2075

1 of 5

Police Station Of Origin:
Kolam Ayer NPP
72 Geylang Bahru #01-3038 SINGAPORE
330072
Tel No: 1800-2969999

Report No. T/20181111/2075

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/11/2018 18:04	Vide Report No.:	Station Diary No.: 38
--	------------------	--------------------------

Informant's Particulars

Name of Informant: TIANG ZHANG YONG, ALEX	Address: APT BLK 114 LORONG 3 GEYLANG #04-63 SINGAPORE 381114		
ID Type / ID No.: NRIC NO / S9017673J	Contact No.:	Mobile: 90256351	
Nationality: SINGAPORE CITIZEN	Home/Office:		
	Email:		
Sex: Male	Age: 28	Date of Birth: 18/05/1990	Type of Informant: Driver
Race: Chinese	Language:	Institution / School Name:	
Occupation: MINDEF OFFICER	Driving Licence Information: Class: 3	Date of Expiry:	

General Information of the Accident

General Information: 07-27-2018					Type of Location: Straight Road
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 11/11/2018 11:30		
Location: Along Road 1 CENTRAL EXPRESSWAY					
CTE towards City before 6.5km Mark					
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJM6627R	Car	TOYOTA	PICNIC AUTO W/O ROOF RACK	Black	Seriously Damaged	3
SKZ3572D	Car	VOLVO	V40 T2 (A)	Black	Slightly Damaged	1
SLG5604X	Car	NISSAN	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR	White	Slightly Damaged	3

Sketch Plan #4 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20181111/2075

Police Station Of Origin:
Kolam Ayer NPP
72 Geylang Bahru #01-3038 SINGAPORE
330072
Tel No: 1800-2969999

2 of 5

Report No. T/20181111/2075

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLS4619Y	Car	VOLKSWAGO N	POLO GP 1.2 TSI AT 6C13EZ SR LED	Grey	Slightly Damaged	2
SLU1397X	Car	VOLVO	V40 T2 (A)		Slightly Damaged	1

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	FANG ENGELIA LAVIANI		ID No. G8367025N
Related Vehicle	SJM6627R (Car)		Contact No. 98895563
Hospital/Clinic	TAN TOCK SENG HOSPITAL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	11/11/2018		Date Discharge 11/11/2018
No. of Days granted Medical Leave	03		Degree of Injury Slight
Driver			
Name	TIANG ZHANG YONG, ALEX		ID No. S9017673J
Related Vehicle	SJM6627R (Car)		Contact No. 90256351
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL
Driver			
Name	LAW YI HENG		ID No. S9226774A
Related Vehicle	SKZ3572D (Car)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

Sketch Plan #5 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20161111/2075

Police Station Of Origin:
Kolam Ayer NPP
72 Geylang Bahru #01-3038 SINGAPORE
330072
Tel No: 1800-2969999

3 of 5

Report No. T/20161111/2075

CONTINUATION OF REPORT

Driver			
Name	TAN YON FOO	ID No.	S7127869G
Related Vehicle	SLG5604X (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LOW JIANYING	ID No.	S8412007C
Related Vehicle	SLS4619Y (Car)	Contact No.	NIL
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	11/11/2018	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious
Driver			
Name	ONG SIN YEE	ID No.	S7115237E
Related Vehicle	SLU1397X (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 11/11/2018, at about 1130hrs, I was driving my car (Registration Number: SJM6627R) along CTE towards City. I was travelling along lane 2 and wanted to change lane into lane 1. I signaled right and checked the traffic before filtering right.

Out of the sudden, the car in front of me (Registration Number: SLS4619Y) suddenly jam break. I did not manage to break in time and as a result, I collided into the said car. Another car behind me (Registration Number: SLU1397X) almost collided into me however, the driver managed to avoid the collision. However, the said car brushed against my car. I alighted from my car to make a check and discovered that there were 5 cars involved in this accident. SLS4619Y had actually collided into another car in front of it (Registration number: SKZ3572D). This caused the back bumper of SKZ3572D and front bumper of SLS4619Y to be slightly dented. There were also scratches on both vehicle. My front of my car was



**SINGAPORE
POLICE FORCE**



T/20181111/2075

Police Station Of Origin:
Kolam Ayer NPP
72 Geylang Bahru #01-3038 SINGAPORE
330072
Tel No: 1800-2969999

4 of 5

Report No. T/20181111/2075

CONTINUATION OF REPORT

seriously crashed. The right side of my rear bumper had some scratches due to the brush against SLU1397X. Behind SLU1397X was another car (Registration number: SLG5604X) which had collided into the rear of SLU1397X. This caused the front bumper and bonnet cover of SLG5604X to be dented. I am unsure of the damages at the rear of SLU1397X however the front seems to be fine.

One of my Passenger namely Fang Engelia Laviani went for medical treatment at Tan Tock Seng Hospital due to swelling on both her shin. She was granted three days Medical Leave from 11/11/2018 to 13/11/2018. The driver of SLS4619Y namely Low JianYing went to Tan Tock Seng Hospital as well and he had spine fracture as a result of this accident.

I wish to state that there is no in-vehicular camera in my car. I am unsure whether other cars have in-vehicular cameras. I am lodging this report as required.

Accident Sketch Plan Pg. 1



SINGAPORE
POLICE FORCE



T/20181111/2075

Police Station Of Origin:
Kolam Ayer NPP
72 Geylang Bahru #01-3038 SINGAPORE
330072
Tel No: 1800-2969999

5 of 5

Report No. T/20181111/2075

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

A /
Sgt 2 LEE ZHAN RUI XAVIER

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /
SSI 2 YEO GEAK ENG CECILIA
Contact No.: 65476404

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:

11/11/2018 18:04

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7434C
Vehicle Details	
Vehicle No.:	SJM6627R
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PICNIC AUTO W/O ROOF RACK
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	1AZ5848095
Chassis No.:	JTEGH23B300026300
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$23,511.00
Original Registration Date:	13 Jan 2009
First Registration Date:	13 Jan 2009
Transfer Count:	1
Actual ARF Paid:	\$23,511.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jan 2019
PARF Rebate Amount:	\$11,755.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jan 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$3,089.00
COE Rebate Amount:	\$45.00
Total Rebate Amount:	\$11,800.00

The information contained herein is correct as at 19 Nov 2018

OK

MOTORCAR (Rear)

Rear Portion

Vehicle No: **SJM6627R**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	/	1
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NFE	G	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	RH DIS	/	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish	CRG	/	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender	DD	R	
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield	CRG	/	
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items:

Assessor:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Nov 2018 Edit Reg		16 Nov 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	ONG SIN YEE, ID: S7115237E		
Main Claimant:	KAJIO RENTALS, Co. Reg. No.: 53387434C		
Vehicle Reg. No.:	SJM6627R	Date of Loss:	11/11/2018 11:00 - :59 [117 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9843966329SG	Policy/Cover Note No.:	1700082184 (Comprehensive)
Vehicle Reg. No. (Insured):	SLU1397X	Policy No. (Claimant):	
		Excess:	
Repairer:	Hup Ley Huat Motor Spray Painting Services () BLK 1 KAKI BUKIT AVE 6 #01-35, 409793 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 27/11/2018]		
Claimant's Solicitor:	CHEONGHOH LAW CORPORATION - Tel: 63378700		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (19/11/2018): Request to upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJM6627R (9843966329SG)**
[SLU1397X]

TP

KAJIO RENTALS

Nov 11 2018 11:00AM

[ONG SIN YEE]

Hup Ley Huat Motor Spray Painting Services

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
2	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
3	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
4	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
5	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
6	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
7	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
8	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
9	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
10	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
11	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
12	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
13	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
14	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
15	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
16	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
17	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
18	19/11/18 19:27	General View														Load JPG	<input checked="" type="checkbox"/>			
19	19/11/18 19:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>			
20	19/11/18 19:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>			
21	19/11/18 19:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>			
22	19/11/18 19:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>			
23	19/11/18 19:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>			
24	19/11/18 19:28	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>			
25	21/11/18 11:20	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>			
26	21/11/18 11:20	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>			
27	21/11/18 11:20	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>			
28	21/11/18 11:20	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>			
29	21/11/18 11:20	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>			
30	21/11/18 11:20	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>			
Documentation															1 per page			<input checked="" type="checkbox"/>		
No.	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)														Thumbnail	Print			
1	19/11/18 11:21	OI GIA REPORT														Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18020758/JCD3S2

Date: 26/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1700082184

Claimant Vehicle No : SJM6627R

Insured Vehicle No : SLU1397X

Date of Loss: 11/11/2018

Nature of Claim: TP

Claim No: 9843966329SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM6627R**

Make & Model: TOYOTA PICNIC, 2.0 (A)

Reg. Date: 13/01/2009 (Man. Year: 2008)

Colour: Black

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1AZ5848095

Chassis No: JTEGH23B300026300

Odometer: 151343 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size:

215/60R16

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/11/2018

Date Inspected: 16/11/2018 Inspected At:

Hup Ley Huat Motor Spray Painting Services
BLK 1 KAKI BUKIT AVE 6 #01-35
Singapore 409793

Estimated Period of Repair: 2.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER RH	Distorted	0.00 F	*- F
4	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
5	1		*REAR RH FENDER	Repair	0.00 F	*- F
6	1		*REAR RH FENDER INNER SHIELD	Cut	0.00 F	*- F
F=Franchise part.				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >