

REF: CS3/MSG18020775/Rcd3 Special Instruction:

ASS. REC. BY:

Surveyor: Rasul
Munim

ASSIGNMENT (Office)

From (Person): Christina Wong of MSIG Date/Time: 16/11/18 @ 9:32am

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKF 6863A Insured: PC 2997E

at Workshop m/s: Sin Heng Long Tel: 90681801 / 6481 6078

of BK 5032 AMK Ind. park 2 # 01-305

Policy No: B28623691 MKC Claim No: 575821

Sum Insured: Excess:

Make of Veh: D.O.A. 12/11/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS (up) H.O.D. Endorsement:

Date/Time: 16/11/18 @ 9:57am Person Contacted: Ian Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SKF 6863A - NBA / MSG18020460 / Y D.O.A: 12/11/2018
	PC 2997E - NBA / MSG18020460 / Y D.O.A: 12/11/2018
	After repair: 27/11/2018

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Nov 2018		16 Nov 2018 09:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MARITEAM TRANSPORT SERVICES PTE LTD, Co. Reg. No.: -		
Main Claimant:	LEW KWANG PING, ID: S6817503H		
Vehicle Reg. No.:	SKF6863A	Date of Loss:	12/11/2018 14:00 - :59 [105 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 575821	Policy/Cover Note No.:	B28623691MKC (Comprehensive) Coverage: 23/10/2018 - 22/10/2019
Vehicle Reg. No. (Insured):	PC2997E	Policy No. (Claimant):	
		Excess:	
Repairer:	Sin Heng Long Motor Work (Ang Mo Kio) Blk 5032 Ang Mo Kio Industrial Park 2, #01-305, 569535 Ang Mo Kio - Tel: 9068 1801 / 6481 6078		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/11/2018]		
Driver/Custodian (Insured):	ALVIN TAN YEONG HWEE (), NRIC: S1533563G, Tel: +6592301270		
Adj Asg. Remarks:	Liability unclear. TP disagree with our SJE list. Proceed to appoint LKK Auto Consultants. Contact Person: Mr Ian Chan / 9068 1801 / 6481 6078.		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Report: 12/11/2018 18:23
 Date of Accident: 12/11/2018 14:30
 Exact Location Of Accident: ALONG VICTORIA STREET
 Country/Area of Loss: SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number: SKF6863A
 Insurance Policyholder:
 Name Of Registered Owner: LEW KWANG PING
 Identification No: S6817503H
 E-mail Address: IVANKPLEW@GMAIL.COM
 Telephone No: (LOCAL) +65-91996600
 Alternative No: OTHERS-91996600
 Vehicle Category:
 Make/Model: ALFA ROMEO
 Year: 159
 Purpose for which vehicle was being used at time of accident: PRIVATE USE
 Is the vehicle insured under your own insurance policy? NO
 Preferred mode of action to be taken: THIRD PARTY
 Vehicle Category: PRIVATE CAR
 Insurance Company: MSIG INSURANCE (SINGAPORE) PTE. LTD.
 Type of Policy: COMPREHENSIVE
 Excess: NO
 Policy No: A 80435342 QMX
 Claimant Name:
 Name: LEW KWANG PING
 Identification No: S6817503H
 Date of Birth: 07/04/1968
 Claimant Address: INDOOR
 Date of Birth of Parents: 07/10/1986
 Date of Marriage: 32 YEARS AND 1 MONTH
 Gender: MALE
 Telephone No: (LOCAL) +65-91996600
 Alternative No: OTHERS-91996600
 E-mail Address: IVANKPLEW@GMAIL.COM

BLK 535 SERANGOON NORTH AVENUE 4
#02-179

P 550535
W Is the driver an employee of the Insured's Company? NO
If Yes, State the relationship of the Driver with the Insured: OWNER
V Registration Number of Driver's Own Vehicle: -
V -
V -
Is the Driver's Own Vehicle Insured by the Company of Driver's Own Vehicle? -
-
-

Circumstances of the Accident

T Direction of Movement: SIDE SWIPE
V Road Conditions: CLEAR
F Weather: DRY

Accident Details

V Was the vehicle involved in this accident? NO
F How many vehicles involved in the accident? 2
V Were any persons injured in the Accident? YES
V How many injured persons conveyed to hospital by ambulance? NO
V Was any personal or property damaged? YES
I How many persons involved by unknown person(s) in the accident? NO
S How many persons requiring accident claims assistance? NO
F How many witnesses (Including Driver)? 3
F Name of Witness 1: NAME: WANG JIAN (GUEST)
GENDER: MALE
F Name of Witness 2: NAME: GUEST
GENDER: MALE

Police Action

V Was the accident reported to the police? YES
F Please state which Police Station: TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
F State the address: ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
F State the contact number: TEL NO: 65470000 - FAX NO:
V Was a Police Prosecution given? NO
F Was a Police Report given?

Copies of Documents

F State the Police Report Number: POLICE REPORT T/20181112/7014

V Was the Police Report available for attachment? YES
V Was the Police Report captured by Car Camera? YES
V Was the Police Report recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

V Registration Number: PC2997E
V Make/Model/Colour: NISSAN
F Classification:
V Vehicle Type: COMMERCIAL VEHICLE
F

Police Report Number:

Case Number:

Area:

File:

Insurance Company Name:

Policy Number:

Name of Injured Person (Including Driver):

DETAILS OF INJURED PERSON 1

Name: WANG JIAN (GUEST)

Date of Birth:

Severity of Injury: SLIGHT INJURY

Was the person in a vehicle? SKF6863A

Was the person wearing a seat belt? YES

Was the person taken to hospital by ambulance? NO

Date:

Time:

File:

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The use and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any crime reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. My judgment of this report to the insurers; you hereby consent to the archiving of this report at the centre and to copies of this report being made available aforesaid.
8. I consent under the Personal Data Protection Act (PDPA)

to stand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) administering, processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) My insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) My Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) My Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) My Personal Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: *Kepli W...*
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



CIRCUMSTANCES OF THE ACCIDENT

*PLS REFER TO POLICE REPORT
1/2018/112/2014*

DECLARATION

The foregoing particulars are true in every respect.

[Signature]

Signature

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 12/11/2018

Reporting Centre Personnel's Signature
Name: *Rashid Walters*
NRIC/FIN No.:

POLICE REPORT



T/20181112/7014

1 of 3

Report No. T/20181112/7014

**SINGAPORE
POLICE FORCE**

Region Of Origin:
District 3 SINGAPORE 408865
70000

TRAFFIC ACCIDENT

Report Made: 16:24	Vide Report No.:	Station Diary No.:
-----------------------	------------------	--------------------

Particulars

Informant NG PING		Address: APT BLK 535 SERANGOON NORTH AVENUE 4 #02-179 SINGAPORE 550535	
ID No. S6817503H		Contact No.:	Mobile: 91996600
HOME CITIZEN		Email: ivankplew@gmail.com	
Age 50	Date of Birth: 07/04/1968	Type of Informant: Driver	
		Language: English	Institution / School Name:
Occupation: Tractor		Driving Licence Information: Class: 3 Date of Expiry:	

Information of the Accident

Injury Others	Drink Drive: No	Date/Time of Accident: 12/11/2018 14:30	Type of Location: Straight Road
------------------	-----------------------	---	------------------------------------

STREET

Road Surface: Dry	Road Speed Limit: 60 Km/h
Traffic Control: Not Controlled	Traffic Volume: Light
Collision: Moving Vehicles - Side Swipe - Same Direction	Anyone conveyed by ambulance: No

Vehicle Involved

No.	Type	Make	Model	Color	Condition	No of Passenger
	Bus/Coach/Minibus	NISSAN	Nissan	White	Slightly Damaged	0
1A	Car	ALFA ROMEO	159	Silver	Seriously Damaged	3

Vehicle Insurance

No.	Insurance Company	Insurance No	Effective	Expiry Date

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20181112/7014

Police Station Of Origin:
Singapore Police
100, Cross Street, Singapore 408865
Tel: 670000

2 of 3
Report No. T/20181112/7014

CONTINUATION OF REPORT

Details of Person Involved			
Pedestrian Involved: No			
Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	Wang Jian	ID No.	G53637086
Vehicle	SKF6863A (Car)	Contact No.	08618789701989
License	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Treatment	NIL	Date Discharge	NIL
Days granted Medical Leave	NIL	Degree of Injury	Slight
Witness			
Name	LEW KWANG PING	ID No.	S6817503H
Vehicle	SKF6863A (Car)	Contact No.	91996600
License	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Treatment	NIL	Date Discharge	NIL
Days granted Medical Leave	NIL	Degree of Injury	NIL

On 12/11/2018, at or about 1432 hrs, I was driving SKF 6863A traveling along Victor street towards the junction at the Junction of Jalan Sultan Road, heading to Hotel Boss with my 2 foreign guests I was driving in Lane 3 (red line Bus Lane 4 is beside me), I was following the traffic in front. I was filtering to the left into Jalan Sultan Road for Hotel Boss when PC 2997E, a passenger van cuts into my lane, I was alerted by hitting my brakes and moved into the red line bus lane and collided into his left rear wheel hitting my right front fender. I have also kerb the left side of my car and wheels. There was a slight injury to one of my guest. The witness explains the full scenario.

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20181112/7014

Station Of Origin:
Police
1000 3 SINGAPORE 408865
170000

3 of 3


Report No. T/20181112/7014

CONTINUATION OF REPORT

1
not able to provide sketch plan

Signature Of Officer Recording The Report: Not available
Signature Of Interpreter: Not available
Charge Of Case: G, STEPHANIE 65476414
Stamp

Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Date/Time: 12/11/2018 16:24
Classification Of Case:



> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details	
Vehicle No.:	SKF6863A
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	ALFA ROMEO
Vehicle Model:	ALFA 159 2.2JTS.SELESPEED
Chassis No.:	ZAR93900007255811
Propellant:	Petrol
Engine No.:	939A50006331254
Engine Capacity:	2198 cc
Maximum Power Output:	136.0 kW (182 bhp)
Maximum Laden Weight:	2010 kg
Unladen Weight:	1490 kg
Year Of Manufacture:	2009
Original Registration Date:	19 Jan 2010
Lifespan Expiry Date:	-
COE Category:	B - Car (1601cc & above)
Quota Premium:	\$19,190.00
COE Expiry Date:	18 Jan 2020
Road Tax Expiry Date:	18 Jan 2019
PARF Eligibility Expiry Date:	18 Jan 2020
Inspection Due Date:	18 Jan 2019
Intended Transfer Date:	19 Nov 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 18 Jan 2019. You may renew the road tax from 19 Oct 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 18 Jan 2019, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 19 Jan 2019 to 18 Jul 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	723.00	-	723.00
Total Amount Payable:			748.00

Amount Payable (From 19 Jan 2019 to 18 Jan 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	1,446.00	-	1,446.00
Total Amount Payable:			1,471.00

You may print this page for reference.

OK

Print

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7503H
Vehicle Details	
Vehicle No.:	SKF6863A
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Nov 2018
Vehicle Make:	ALFA ROMEO
Vehicle Model:	ALFA 159 2.2JTS.SELESPEED
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	939A50006331254
Chassis No.:	ZAR93900007255811
Maximum Power Output:	136.0 kW (182 bhp)
Open Market Value:	\$26,681.00
Original Registration Date:	19 Jan 2010
First Registration Date:	19 Jan 2010
Transfer Count:	3
Actual ARF Paid:	\$26,681.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jan 2020
PARF Rebate Amount:	\$14,674.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jan 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,190.00
COE Rebate Amount:	\$2,233.00
Total Rebate Amount:	\$16,907.00

The information contained herein is correct as at 19 Nov 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Nov 2018		16 Nov 2018 09:32 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	MARITEAM TRANSPORT SERVICES PTE LTD, Co. Reg. No.: -		
Main Claimant:	LEW KWANG PING, ID: S6817503H		
Vehicle Reg. No.:	SKF6863A	Date of Loss:	12/11/2018 14:00 - :59 [105 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 575821	Policy/Cover Note No.:	B28623691MKC (Comprehensive) Coverage: 23/10/2018 - 22/10/2019
Vehicle Reg. No. (Insured):	PC2997E	Policy No. (Claimant):	
		Excess:	
Repairer:	Sin Heng Long Motor Work (Ang Mo Kio) Blk 5032 Ang Mo Kio Industrial Park 2, #01-305, 569535 Ang Mo Kio - Tel: 9068 1801 / 6481 6078		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 17/11/2018]		
Driver/Custodian (Insured):	ALVIN TAN YEONG HWEE (), NRIC: S1533563G, Tel: +6592301270		
Adj Asg. Remarks:	Liability unclear. TP disagree with our SJE list. Proceed to appoint LKK Auto Consultants. Contact Person: Mr Ian Chan / 9068 1801 / 6481 6078.		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

***SKF6863A (575821)**
[PC2997E]
TP
LEW KWANG PING
Nov 12 2018 2:00PM
[MARITEAM TRANSPORT SERVICES PTE LTD]
Sin Heng Long Motor Work

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View View in Browser ▾

Video			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/11/18 17:30	Video - Other Video frm TP	Load MP4	<input type="checkbox"/>
Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/11/18 17:28	Accident Statement From: SC - Reg. No: PC2997E, Claimant: MARITEAM TRANSPORT SERVICES PTE LTD	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
2	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
3	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
4	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
5	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
6	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
7	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
8	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
9	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
10	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
11	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
12	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
13	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
14	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
15	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
16	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
17	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
18	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
19	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
20	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
21	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
22	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
23	19/11/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
24	04/12/18 15:25	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
25	04/12/18 15:25	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
26	04/12/18 15:25	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
27	04/12/18 15:25	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
28	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
29	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
30	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
31	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
32	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
33	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
34	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
35	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
36	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
37	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
38	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
39	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
40	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
41	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
42	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
43	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
44	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
45	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
46	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
47	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
48	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
49	04/12/18 15:25	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/11/18 17:28	Notice of PRI		<input type="checkbox"/>
2	13/11/18 17:28	SKF6863A GIA Rpt From: SC - Reg. No: PC2997E, Claimant: MARITEAM TRANSPORT SERVICES PTE LTD		<input type="checkbox"/>
3	15/11/18 17:37	TP Details of workshop		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18020775/R1CD3S2
Date: 06/12/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B28623691MKC
Claimant Vehicle No :	SKF6863A	Insured Vehicle No :	PC2997E
Date of Loss:	12/11/2018	Nature of Claim:	TP
		Claim No:	575821

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF6863A	Engine No:	939A50006331254
Make & Model:	ALFA ROMEO 159, 2.2 Selespeed (A)	Chassis No:	ZAR93900007255811
Reg. Date:	19/01/2010 (Man. Year: 2009)	Odometer:	116902 km
Colour:	Grey		
Engine Capacity:	2198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	16/11/2018		
Date Inspected:	16/11/2018	Inspected At:	Sin Heng Long Motor Work (Ang Mo Kio) Blk 5032 Ang Mo Kio Industrial Park 2, #01-305 Singapore 569535
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$7,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Dec 2018)

Parts: N/A ALFA ROMEO 159 2.2 Selespeed (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKF6863A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >