

ASS. REC. BY:

REF:

REF: CS3/MSG18020781/R/cd30

Special Instruction:

• Surveyor :

Rasul

### ASSIGNMENT (Office)

From (Person)

Christina Wong

of

MSIG

Date/Time:

16/11/2020 9:51am

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 752T

Insured:

SJN6537L

at Workshop m/s

Kuo Li Auto

Tel:

9694 3328 / 64826314

of

BLK 5035, AMK Ind. park 2 #01-363

Policy No:

29071659 QMX

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13/11/2018

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

10:7am @ 16/11/18

Person Contacted:

Ah hweo.

Vehicle IN OUT

Date/Time

Action/Instruction ( X )	Estimate
1. Review the project scope and objectives.	
2. Identify the key stakeholders and their roles.	
3. Develop a detailed project plan and timeline.	
4. Allocate resources and assign tasks to team members.	
5. Monitor progress and communicate regularly with stakeholders.	
6. Address any issues or risks that arise during the project.	
7. Evaluate the project's success and gather feedback for future projects.	

GBD 752T-X

81N6537L-X

## ASSIGNMENT

From: \_\_\_\_\_ Date: 16/11/2018

Estimated Cost: \_\_\_\_\_

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐

To Inspect Vehicle No: GBD 752 Y

at Workshop m/s Kuo Li Auto

of BIK 5035, AMK Ind. Park 2 #01-363

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (Cap)

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBD 752 Y Yr Regn: Jun / 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN CABSTAR C.C. 2953

Colour: GRN A/C: Insured / Std / NI / NA

Sp. Reading: 76154 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JN18C 2F 2420855768

Gen. Cond: Good ☒ Fair ☐ Poor ☐ Burnt ☐Steering: In order ☒ Jammed ☐ Leaked ☐ Burnt ☐ orBrake: In order ☒ Jammed ☐ Leaked ☐ Burnt ☐ orModi: Nil ☒ S/Rim ☐ STD A/Rim ☐ or

Tyre Size: F: 195R15Z

R: 195R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 6/6 mm

L/Bal. 7 mm L/Bal. 6/6 mm

D.O.A. 13/11/18 D.O.I. 16/11/18

Survey held at Kuo Li Auto

Des. of Damages: Frt ☒ Rear ☒ O/S ☐ N/S ☐ U/C ☐ Rooftop ☐ or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimate repair range \$4,800 - \$6,000.

RECEIVED 23 NOV 2018

21/11/2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format : PRS.

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

120

10

130

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Nov 2018 10:06		16 Nov 2018 09:51 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>
Insured:	ANN KEE TONG, ID: S8186171D	
Main Claimant:	FUSON MARINE SERVICES PTE LTD, Co. Reg. No.: 198902447H	
Vehicle Reg. No.:	GBD752T	Date of Loss: 13/11/2018 00:00 - :59 [53 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.: 29071659QMX Coverage: 24/02/2018 - 23/02/2019
Vehicle Reg. No. (Insured):	SJN6537L	Policy No. (Claimant):
		Excess:
Repairer:	Kuo Li Auto Workshop (HQ) Blk 5035 Ang Mo Kio Ind Park 2, #01-363, 569538 Ang Mo Kio - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/11/2018]	
Adj Asg. Remarks:	Liability clear. TP disagree with our SJE list. Proceed to appoint LKK. Contact Person: Alvin / 9694 3328.	

<b>ASSOCIATED MAIL RECEIVED</b>	<a href="#">View All</a> <a href="#">Compose Case Mail</a>
There are no mail for this case.	

<b>ALL ASSOCIATED TASKS</b>	<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>																				
<table style="width: 100%; border-collapse: collapse;"> <tr> <th style="text-align: left;">Due Date</th> <th style="text-align: left;">Priority</th> <th style="text-align: left;">Type</th> <th style="text-align: left;">Task Group</th> <th style="text-align: left;">Subject</th> <th style="text-align: left;">Handler</th> <th style="text-align: left;">Assigned By</th> <th style="text-align: left;">Completed On</th> <th style="text-align: left;">Created On</th> <th style="text-align: left;">Done?</th> </tr> <tr> <td colspan="10">No results.</td> </tr> </table>	Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.										
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?												
No results.																					

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	GBD752T		
Vehicle Type :	B31 - Goods (Open) Lorry (Metal Body)/Pickup		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	NISSAN		
Vehicle Model :	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5		
Chassis No. :	JN1SC2F24Z0855718		
Propellant :	Diesel		
Engine No. :	ZD30338050K		
Engine Capacity :	2953 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	3500 kg		
Unladen Weight :	1780 kg		
Year Of Manufacture :	2014		
Original Registration Date :	03 Jun 2014		
Lifespan Expiry Date :	02 Jun 2034		
COE Category :	C - Goods Vehicle & Bus		
PQP Paid :	\$4,521.00		
COE Expiry Date :	02 Jun 2024		
Road Tax Expiry Date :	02 Jun 2019		
Inspection Due Date :	02 Jun 2019		
Intended Transfer Date :	19 Nov 2018		
CO2 Emission :	284.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
This vehicle has a road tax Over Payment of \$266.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			

You may print this page for reference.

OK      Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	2447H
<b>Vehicle Details</b>	
Vehicle No.:	GBD752T
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Nov 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	ZD30338050K
Chassis No.:	JN15C2F24Z0855718
Maximum Power Output:	-
Open Market Value:	\$25,081.00
Original Registration Date:	03 Jun 2014
First Registration Date:	03 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$1,255.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	02 Jun 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$4,521.00
COE Rebate Amount:	\$2,503.00
<b>Total Rebate Amount:</b>	<b>\$2,503.00</b>

The information contained herein is correct as at 19 Nov 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/11/2018 10:45
Date Of Accident	13/11/2018 15:00
Exact Location Of Accident	PIE TOH GUAN TWDS AMK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD752T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	FUSON MARINE SERVICES PTE LTD
Co Reg No	198902447H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96705365
Alternative Phone No	OFFICE-96705365

### Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5071603118-03
Cover Note Number	

### Driver

Name of Driver	CHAN CHUAN YUAN
NRIC No	S1244073A
Date Of Birth	21/07/1957
Occupation	OUTDOOR
Date Of Driving Pass	05/05/1980
Driving Experience	38 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98804109
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 30 BENDEMEER ROAD #07-881
Postcode	330030
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

THE VEHICLE BEHIND ME KNOCKED INTO THE REAR PORTION OF MY VEHICLE, CAUSING ME TO KNOCK INTO ANOTHER VEHICLE IN FRONT. (ATTENDED BY: JAMES NG)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	CANNOT BE UPLOADED
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN6537L
Vehicle Make/Model/Colour	TOYOTA COROLLA ALTIS / BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKW6640L
Vehicle Make/Model/Colour	TOYOTA / WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Person's Signature  
Name: **NG WING KIN JAMES**  
NRIC/FIN No.: **S7927881E**

14 NOV 2018

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Refer  
Statement


DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

14 NOV 2018

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name: NG WING KIN JAMES  
NRIC/FIN No.: S7927881E

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Nov 2018 10:06		16 Nov 2018 09:51 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	ANN KEE TONG, ID: S8186171D	
Main Claimant:	FUSON MARINE SERVICES PTE LTD, Co. Reg. No.: 198902447H	
Vehicle Reg. No.:	GBD752T	Date of Loss: 13/11/2018 15:00 - :59 [53 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 576319	Policy/Cover Note No.: A29071659QMX (Comprehensive) Coverage: 24/02/2018 - 23/02/2019
Vehicle Reg. No. (Insured):	SJN6537L	Policy No. (Claimant):
		Excess: S\$400.00
Repairer:	Kuo Li Auto Workshop (HQ) Blk 5035 Ang Mo Kio Ind Park 2, #01-363, 569538 Ang Mo Kio - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 17/11/2018]	
Adj Asg. Remarks:	Liability clear. TP disagree with our SJE list. Proceed to appoint LKK. Contact Person: Alvin / 9694 3328.	






































ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		


















  

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Claim Documents

**\*GBD752T (576319)**  
**[SJN6537L]**  
**TP**  
**FUSON MARINE SERVICES PTE LTD**  
**Nov 13 2018 3:00PM**  
**[ANN KEE TONG]**  
**Kuo Li Auto Workshop**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
2	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
3	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
4	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
5	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
6	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
7	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
8	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
9	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
10	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
11	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
12	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
13	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
14	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
15	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
16	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
17	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
18	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
19	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
20	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
21	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
22	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
23	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
24	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
25	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
26	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
27	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
28	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
29	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
30	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
31	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
32	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
33	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
34	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
35	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
36	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
37	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
39	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
40	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
41	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
42	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
43	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
44	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
45	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
46	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
47	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
48	19/11/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/11/18 10:07	Email - PRI	 Load PDF	
2	15/11/18 10:07	SKW6640L GIA Rpt	 Load PDF	
3	15/11/18 10:08	GBD752T GIA Rpt	 Load PDF	
4	15/11/18 19:05	TP disagree with our SJE list, proceed to appoint LKK	 Load PDF	
5	15/11/18 19:11	OI repoty SJN6537L	 Load PDF	
6	15/11/18 19:14	OI driving Licence	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18020781/R1CD3E2

Date: 26/11/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29071659QMX

Claimant Vehicle  
No : GBD752T

Insured Vehicle No : SJN6537L

Date of Loss: 13/11/2018

Nature of Claim: TP

Claim No: 576319

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GBD752T

Make &amp; Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)

Engine No: ZD30338050K

Reg. Date: 03/06/2014 (Man. Year: 2014)

Chassis No: JN1SC2F24Z0855718

Colour: Grey

Odometer: 76154 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 155 R13 (D)

Front Left Side: Yokohama 7 mm

Rear Left Side: Yokohama 6/6 mm

Front Right Side: Yokohama 7 mm

Rear Right Side: Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 16/11/2018

Date Inspected: 16/11/2018 Inspected At:

Kuo Li Auto Workshop (HQ)  
Blk 5035 Ang Mo Kio Ind Park 2, #01-363  
Singapore 569538

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,800.00 -\$6,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 26 Nov 2018)	
<b>Parts:</b>	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBD752T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >