

ASS. REC. BY:

REF

CS/TMI18020798/K1+d3e2

Special Instruction:

Surveyor
menhen

Kalvin

ASSIGNMENT (Office)

From (Person): Fiona Gun Bee Song

of

TMI

Date/Time:

16/11/2018 12:20pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MY7 CS

To Inspect Vehicle No:

SH 6471S

Insured:

XD 6685D

at Workshop m/s

Comfort Delgro

Tel:

62148300

of

59 Loyang Drive

Policy No:

ME000003

Claim No:

M1805389

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

Date/Time:

12:24pm @ 16/11/18

Person Contacted:

Ng Yule phin

Vehicle

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

check consistency of damage

SH 6471S - CS

III 15000345 / H/qbu 2

DOA: 06/11/2015

XD 6685D - X

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / IWS / TP RES / OD RES / EVA / INV / MV

To Insp'd Vehicle No: _____

at Workshop m/s _____

at _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 64715 Yr Regn: 18 Jun 2015

Type: M. Car / M. Cycle / Bus / Van / Lorry / T. / Prime Mover /

Truck / Trailer or

Make: Hyundai IX C.C. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 593309 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLB414M54069479

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hangkok

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 15/11/18 D.O.I. 16/11/18

Survey held at CDGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

o/s Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/11/18 Call back L/S \$1300 / 3 Rps.

Red: 1610.58, 55%

Tokio

45.

RECEIVED 22 NOV 2018

Date/Time, File Pass to?

☐ : Prel. Report

1) 2111 Typist

☒ : Final Report

Date/Time, File Return to?

2) _____

Report Format: TP

Lump Sum / I.B.I: (\$ 1300/-)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____) S + RS \$ _____

☐ : Interview (\$ _____) Photos

☐ : Tech. Invs (\$ _____) Others

☐ : Weekend (\$ _____)

Survey Fee:	<u>250</u>
Transportation:	
	<u>10</u>
TOTAL	<u>260</u>

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Nov 2018 Sendback Est	16 Nov 2018 08:49 S\$2,910.58	16 Nov 2018 12:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	PECK TIONG CHOON LEASING PTE LTD, Co. Reg. No.: 199204891W		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SH6471S	Date of Loss:	15/11/2018 09:00 - :59 [40 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1805839	Policy/Cover Note No.:	ME000003 (Third Party Only) Coverage: 03/01/2018 - 02/01/2019
Vehicle Reg. No. (Insured):	XD6685D	Policy No. (Claimant):	MCOM0015
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/11/2018]		
Driver/Custodian (Insured):	GOH ZOO KIA (61), NRIC: S1261351B		
Adj Asg. Remarks:	PLS. CHECK CONSISTENCY OF THE DAMAGE. THKS		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

File Name	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
COMFORT TRANSPORTATION PTE LTD

Singapore

Claimant Insurer: India International Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	15/11/2018
Vehicle Reg. No.:	SH6471S	Driveable?	YES
Party At Fault:	UNKNOWN		
Driver (TP):	TAN YOO BENG		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	18/06/2015
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDGU614108	Chassis No:	KMHLB41UMFU069479
Odometer:	593309 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	PLS REFER TO ATTACHED		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,030.58
Miscellaneous Items	10.00
Labour	1,870.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,910.58
+ GST 7.00% (\$\$)	203.74
Nett Amount (\$\$)	3,114.32

This claim is handled by: NG NYUK PHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System


Team:	ARC Repair TP(CLSO)1	JOB CARD	Sales Order:	JC NO.: 305239751
STOMER	COMFORT TRANSPORTATION PTE LTD	REGN NO.:	SH 6471S	MILEAGE
VMS	7010045	MAKE:	HYUNDAI	FUEL
STOMER NO.	383 SIN MING DRIVE	MODEL	I-40	E.....1/2.....F
DRESS	Singapore SINGAPORE 575717	YR OF MANU	18.06.2015	DATE/TIME IN
(R)	65508755	CHASSIS CODE	KMHLB41UMFU069479	15.11.2018 10:40
(P)				TARGET DATE
				COMPLETION DATE/TIME:
ICOUNT CARD NO.				

JOB DESCRIPTION

Accident Date: 15.11.2018
NATURE: 3P 15.11.2018

S/NO LABOR CODE DESCRIPTION

TOKO - Rear Right damage
LRR/Kabin



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SH 6471S LARRY

Vehicle No.: SH 6471S

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/11/2018 15:23
Date Of Accident	15/11/2018 09:50
Exact Location Of Accident	ALEXANDRA RD > PASIR PANJANG RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH6471S
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	TAN YOO BENG
NRIC No	S1508387E
Date Of Birth	10/03/1961
Occupation	OUTDOOR
Date Of Driving Pass	19/10/1979
Driving Experience	39 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97366236
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 216B COMPASSVALE DRIVE #14-552
Postcode	542216
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD6685D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	GOH ZOO KIA
NRIC/Passport Number	S1261351B
Contact Number	93365652
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	LEFT FRT
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

15.11.2018
@ 12:30 hrs

Reporting Centre Personnel's Signature
Name: *Regina Chow*
NRIC/FIN No.:

SKETCH PLAN

A - SH 6471S
B - XD 6685D

Refer Attachment

Along Alexandra Rd Towards Pasir Panjang Rd

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15.11.2018 at about 09:50 hours I was travelling along Alexandra Road Towards Pasir Panjang
Road with no passenger onboard .
While travelling straight on the extreme Left lane , Suddenly Veh B (XD 6685D) cut into my lane from my
right and collided into my taxi A - Right Rear Portion .
After the accident my taxi A sustain damages on the Right Rear Portion .
No injury in this accident .
I have company video and photos at scene to support my claims .
Veh B (XD 6685D) - Mr Goh Zoo Kia I/C : S 1261351B H/P : 9336 5652

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time:

Driver's Signature


(If driver is not the policyholder)

Date & Time: 15.11.2018
@ 12:30 hrs

Reporting Centre Personnel's Signature


Name: Regina Chaw

NRIC/FIN No.:



A: SH6471S
B: XD 6685D

Tan Yoo Beng
S1508387E
15/11/18





COMFORTDELGRO ENGINEERING

Our Job Ref No : 305239751

Date : 20. Nov. 2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SH 6471S

Date of Accident: 15. Nov. 2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO XD6685D

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost \$1,300.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Larry Ng

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : Kalvin

Name : Kalvin

Date : 20/11/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR DETAILS**Reference**

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2018)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SH6471S/16/11/2018 08:49	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER — <i>Deformed</i>	20.00	0.00	*553.00 FL
2	1		*REAR BUMPER SPONGE X <i>su</i>	20.00	0.00	*118.40 FL
3	1		*REAR BUMPER SIDE BRACKET - RH — <i>ca</i>	20.00	0.00	*35.60 FL
4	10		*REAR BUMPER CLIPS — <i>su</i>	20.00	0.00	*22.00 FL
5	1		*REAR WHEEL COVER - RH — <i>frayed</i>	20.00	0.00	*107.10 FL
6	1		*REVERSE SENSOR X <i>su</i>	0	0.00	*135.70 FS
7	1		*REAR TYRE - RH X <i>su</i>	0	0.00	*216.00 FS
8	1		*REAR DOOR TEL NO. STICKER - RH — <i>su</i>	0	0.00	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

See Page (14) x report

Sub Total (\$\$)

1,197.80

- List Item Discount on L Items (\$\$)

167.22

Total Parts (\$\$)

1,030.58

ComfortDelGro Engineering Pte Ltd/SH6471S/16/11/2018 08:49. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Larry Ng

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	750.00 4.00
2	SPRAY PAINTING	New	750.00 600
3	WIRING CHARGE	New	50.00 44 X
4	TUFF KOTE	New	80.00 44 X
5	REMOVE/REFIX REVERSE SENSOR	New	120.00 30
6	REAR WHEEL ALIGNMENT	New	120.00 44 X
Gross Labour Cost (S\$)			1,870.00

ComfortDelGro Engineering Pte Ltd/SH6471S/16/11/2018 08:49. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Larry Ng

Ka/uh 10K4
 16/11/18 11:10 hrs
 3 Rty.
 4/5
 After Repair photo

LK the • T • T • P • T • N • S is	Acknowledged Signature: Date:
---	-------------------------------------

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Nov 2018 Sendback Est	16 Nov 2018 08:49 \$2,910.58	16 Nov 2018 12:20 Edit Adj Rpt	\$1,300.00 Edit Estimates	\$1,300.00 View Rpt		Pending for Survey Report Cancel Case




























Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	PECK TIONG CHOON LEASING PTE LTD , Co. Reg. No.: 199204891W								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SH6471S	Date of Loss:	15/11/2018 09:00 - :59 [40 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M1805839	Policy/Cover Note No.:	ME000003 (Third Party Only) Coverage: 03/01/2018 - 02/01/2019						
Vehicle Reg. No. (Insured):	XD6685D	Policy No. (Claimant):	MCOM0015						
		Excess:	\$0.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 27/11/2018]								
Driver/Custodian (Insured):	GOH ZOO KIA (61), NRIC: S1261351B								
Adj Asg. Remarks:	PLS. CHECK CONSISTENCY OF THE DAMAGE. THKS								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SH6471S (M1805839)
[XD6685D]
TP
COMFORT TRANSPORTATION PTE LTD
Nov 15 2018 9:00AM
[PECK TIONG CHOON LEASING PTE LTD]
ComfortDelGro Engineering Pte Ltd

Upload Documents | Upload Photos | Compose New Letter


View View in Browser

Assessment Reports					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print	
1	16/11/18 08:49	Repairer Estimates		Load HTM		
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print	
1	16/11/18 09:55	Accident Statement From: SC - Reg. No: XD6685D, Claimant: PECK TIONG CHOON LEASING PTE LTD		Load HTM		
Photos/Images					3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print	
1	15/11/18 15:38	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>	
2	15/11/18 15:38	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>	
3	15/11/18 15:38	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>	
4	15/11/18 15:38	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>	
5	15/11/18 15:38	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>	
6	15/11/18 15:38	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>	
7	15/11/18 15:38	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>	
8	15/11/18 15:38	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>	
9	15/11/18 15:38	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>	
10	15/11/18 15:38	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
2	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
3	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
4	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
5	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
6	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
7	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
8	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
9	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
10	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
11	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
12	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
13	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
14	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
15	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
16	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	
17	16/11/18 17:05	General View		Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
18	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
19	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
20	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
21	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
22	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
23	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
24	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
25	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
26	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
27	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
28	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
29	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
30	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
31	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
32	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
33	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
34	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
35	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
36	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
37	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
38	16/11/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
39	21/11/18 07:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	21/11/18 07:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	21/11/18 07:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	22/11/18 16:24	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	15/11/18 15:41	Sketch Plan [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	15/11/18 15:42	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	15/11/18 15:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	15/11/18 15:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	15/11/18 15:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	15/11/18 15:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	15/11/18 15:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	15/11/18 15:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	15/11/18 15:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	15/11/18 15:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	15/11/18 15:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	15/11/18 15:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	15/11/18 15:41	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div></div>	
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI18020798/K1TD3E2

Date: 27/11/2018

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: ME000003

Claimant Vehicle No : SH6471S

Insured Vehicle No : XD6685D

Date of Loss: 15/11/2018

Nature of Claim: TP Claim No: M1805839

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH6471S

Make & Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4FDGU614108

Reg. Date: 18/06/2015 (Man. Year: 2015)

Chassis No: KMHLB41UMFU069479

Colour: Blue

Odometer: 593309 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,030.58	584.16	446.42	43.32
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	1,870.00	1,030.00	840.00	44.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,910.58	1,624.16	1,286.42	44.20
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	2,910.58	1,300.00	1,610.58	55.34
+ GST 7.00/7.00% (S\$)	203.74	91.00	112.74	55.34
Nett Amount (S\$)	3,114.32	1,391.00	1,723.32	55.34

INSPECTION

Date of Assignment:	16/11/2018 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	16/11/2018 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: KALVIN ANG WEI KUN**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

NOTE : DAMAGES CONSISTENT TO ACCIDENT REPORT

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Nov 2018)
Parts: 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH6471S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	553.00 FL	*553.00 FL
2	1		*REAR BUMPER SPONGE	Serviceable	118.40 FL	*- FL
3	1		*REAR BUMPER SIDE BRACKET - RH	Cracked	35.60 FL	*35.60 FL
4	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
5	1		*REAR WHEEL COVER - RH	Grazed	107.10 FL	*107.10 FL
6	1		*REVERSE SENSOR	Serviceable	135.70 FS	*- FS
7	1		*REAR TYRE - RH	Serviceable	216.00 FS	*- FS
8	1		*REAR DOOR TEL NO. STICKER - RH	Necessary	10.00 FS	*10.00 FS
9	1		*REAR FENDER (RH) (NPA)	Repair	-	*- FL
					Sub Total (S\$)	1,197.80 727.70
					- List Item Discount on L Items 20.00/20.00% (S\$)	167.22 143.54
					Total Parts (S\$)	1,030.58 584.16

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	750.00	400.00
2	SPRAY PAINTING	New	750.00	600.00
3	WIRING CHARGE	New	50.00	0.00
4	TUFF KOTE	New	80.00	0.00
5	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
6	REAR WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (S\$)			1,870.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >