

REF: MED

PA 7856G

ASSIGNMENT

From:

Date:

21/10/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

PA 7856G

at Workshop m/s

Crown Asia

of

44 Sungai Kadut Ave

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

11am - 12:30pm

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

PA 7856G

Yr Regn 24 SEP / 2008

Type: M.Car / M.Cycle (Bus) / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

SCANIA K134X2

C.C. 11705

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading:

459,712

T/Radio: Insured / Std / NI / NA

Eng.No:

C.No:

YS2K4X20001861381

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

295/80R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

22/10/18

Survey held at

CROWN ASIA

Des. of Damages: Frt / Rear (O/S) / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Renewed COE 10 years. COE till 30 Jun 2028

MID L/S

Date/Time: File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$