

REF CS3 / MSG18003503 / GSD3-1

Meenon Guo Qiang
rene Tan

ASSIGNMENT (Office)

of MSIG Date/Time: 16/11/2018

Estimated Cost: Bill to:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 1357S - Insured: SGG 7362P

at Workshop no: N-SI Automotive Tel: 68420051

at 2 Kalci Bkt # 01-17/18

Policy No: A27710566QMX Claim No: 550353

Sum Insured: Excess:


Make of Veh: D.O.A. 21/2/18
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{cup} R.O.D Endorsement:

Date/Time: 2:10pm 23/2/18 Person Contacted: Amely Vehicle IN (OUT)

Date/Time	Action/Instruction (X) Estimate
	SLT 1357S - X
	SGG 7362P - X
	Dismantle: 9/3/2018
	After repair: 12/3/2018
	\$2500. 5 Days.

19/11/18 submit L/S \$2,300/- @ 5 days
(\$4,000/- red - 64%)


19/11/2018

Repair days 5

Terim
lin
19/11/18

Irene Tan

From: Irene Tan
Sent: Friday, 16 November, 2018 6:51 PM
To: KKLau; Olivia Lau (LKKAuto); Veron Chen (LKKAuto); Shiau Chan (LKKAuto); Admin-D (LKKAuto)
Cc: 'Denise Tay (LKKAuto)'
Subject: Please prepare & upload paper survey report on SLT1357S; Our claim no.: 550353/IT
Importance: High

FOR YOUR IMMEDIATE ACTION, PLEASE

Good evening Veron,

We refer to your PRI report dated 24.8.18.

The post/after repairs pictures of the subject car are not uploaded in the Merimen. If these pictures are in your surveyor's possession, please arrange to upload asap.

In addition, please prepare and upload a paper survey report in the Merimen immediately or within the next 3 days by Monday, 19.11.18 because our insured is disputing on the total repair costs claim @\$6,741.00 in the 3rd party's Letter of Demand submitted by law firm, M/s. Vision Law LLC.

Aside to Olivia, can you assist to ensure that your surveyor uploads his paper survey report asap or within the stipulated 3 days?

Best Regards

Irene Tan
Senior Executive, Claims Services (Motor)
Direct line +65 6594 2541 | Direct fax +65 6225 7402 | irene_tan@sg.msg-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msg.com.sg



A Member of **MS&AD** INSURANCE GROUP

VISION LAW LLC

Advocates & Solicitors - Notaries Public - Commissioners for Oaths
(Incorporated with limited liability)

REG / CS / PAY / FA

12 NOV 2018

Irene
Tan

ERIC NG CHING HOON
WONG KENG LEONG RAYNEE
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D'O MUNDANDY
REGA PARAM
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
JANICE HAN JIA LIN
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
EDISON TAM CHYI EE

Unique Entity Number: 200721148H



Head Office: 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Lorong 6 Toa Payoh
#03-11 HDD Hub (Biz 3 Lobby 1)
Singapore 310490

Main

TEL : (65) 6534 2811 (Hunting)
FAX : (65) 6535 6802
E-MAIL : annatan@visionlawllc.com

Branch

TEL : (65) 63580703

WHEN REPLYING, PLEASE QUOTE OUR REFERENCE. Please to HEAD OFFICE for this matter.

Our Ref : AKN-atv-Ins-N63-108101-18
Your Ref : SGG 7362 P / 550353

Date: 7 November 2018

MSIG INSURANCE (SINGAPORE) PTE LTD

4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Attn: Motor Claims Department

WITHOUT PREJUDICE
BY HAND

CAO WENJUN
53 Hillview Avenue
#02-09
Singapore 669566

CERTIFICATE OF POSTING
[For your information only]

Dear Sir,

CLAIMANT : TWINCAR LEASING PTE LTD
ACCIDENT INVOLVING SLT 1357 S & SGG 7362 P ON 21-FEB-2018 AT OPEN CARPARK OF PINE GROVE CONDO AT ABOUT 1820HOURS

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on **21-FEB-2018 AT OPEN CARPARK OF PINE GROVE CONDO AT ABOUT 1820HOURS** involving our client's vehicle registration number **SLT 1357 S** and vehicle registration number **SGG 7362 P** driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

01.	Cost of Repair	\$6,741.00
02.	Rental fees	\$ 513.60
03.	Survey report fees	\$ 676.00
04.	GIA & LTA search / report fees	\$ 43.98
05.	Cost Contribution (at this stage)	\$1,605.00
06.	Disbursements (at this stage)	\$ 50.00
	TOTAL	\$9,629.58

.../2 to be continued next page

Yanis
1. Uplog of
2. WHI & 2 bene
12/11/18

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

VISION LAW LLC

Advocates & Solicitors

Page 2

Our Ref : AKN-atv-Ins-N63-108101-18

Your Ref : SGG 7362 P

Date: 7 November 2018

MSIG INSURANCE (SINGAPORE) PTE LTD

4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Attn: Motor Claims Department

CAO WENJUN

53 Hillview Avenue
#02-09
Singapore 669566

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA report lodged by driver of SLT 1357 S;
- (b) Video footage of accident;
- (c) Photographs taken at scene of accident;
- (d) LTANet Search;
- (e) Certificate of Insurance;
- (f) Registration Card;
- (g) Rental agreement, rental invoice & rental receipt;
- (h) Final Repair Bill;
- (i) Surveyor's report & invoice; and
- (j) **52 coloured photographs** depicting the damages to motor vehicle SLT 1357 S.

(P.S:- Original photographs will be sent to insurance co. only)


The demand herein is in respect of our client's claim for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully


(HEAD OFFICE)

Enc.

cc: client: Twincar Leasing Pte Ltd

As per your instruction we have submitted your claim as set out above to the third party insurance company. Please do notify us if there is any discrepancy, if any, particularly, the number of days claimed for rental charges and/or loss of use as soon as possible. Thank you.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB
SINGAPORE 417921

Contact : 83802233 91911313

TAX INVOICE

Date : 15/09/2018

Date in : 09/03/2018

Vehicle Num. : SLT1357S

Make/Model : HONDA SHUTTLE HYBRID 1.5 AUTO-2017

Chassis/Eng# : GP71121020/LEB6325921

Accident Date : 15/02/2018

Claim No : CLM14423

Reference : FEB-31/2018

Policy No. : SD17V11639/VPZ/R02 (18/10/2018)

LUMPSUM REPAIR BILL
AS PER SURVEYOR REPORT
REF : 0544-18-N51 DATED 10/09/2018
BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$

6,300.00

E. & O.E. Sub S\$: 6,300.00

Add GST (7 %) S\$: 441.00

Total Amount S\$: 6,741.00



for N-51 AUTOMOTIVE PTE LTD



bizSAFE₃

TWINCAR LEASING PTE. LTD.

Company & GST Registration Number : 201533046C
2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921
Tel: 6744 0510 Fax: 6741 0510 email: twincar.rental@n5l.com.sg

Invoice To

PETER TAN SWEE HUAT
BLK 294A COM[ASSVALE CRESCENT
#15-13
SINGAPORE 541294

TAX INVOICE

Invoice No. CLM 18012
Date 17/9/2018
Terms Cash

No. Days	Description	Rate	Amount
4	LOSS OF RENTAL FOR SLT1357P - ACCIDENT DATED ON 21/02/2018 FROM 09/03/2018 TO 13/03/2018 (\$ 120 PER DAY) VEHICLE NO : SLT1357S VEHICLE MODEL : HONDA SHUTTLE HYBRID MANUFACTURING YEAR : 2017 ENGINE NO : LEB6325921 CHASSIS NO : GP71121020 Tax collected on sales	120.00 7.00%	480.00 33.60
		7% GST	\$33.60
		Total Amount	\$513.60

TWINCAR LEASING PTE.

Authorized Signature



Note : Kindly make payable to " TWINCAR LEASING PTE LTD"
or by Bank-in/transfer to UOB Bank A/c No. 310-307-697-6 (Bank Code 7375)



PAR Automotive Consultancy

Regn. No. 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0544-18-N51

10 September 2018

Twincar Leasing Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 575577

INVOICE No. 0544-18-N51

Vehicle No. SLT1357S

<u>S/NO</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$676.00
Total amount payable		<u>\$676.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



Report No: 0544-18-N51

10 September 2018

ACCIDENT VEHICLE SURVEY REPORT

Twincar Leasing Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 575577

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SLT1357S	<i>Odometer:</i>	035577km
<i>Make & Model:</i>	Honda Shuttle 1.5A	<i>Colour:</i>	Silver
<i>Chassis number:</i>	GP71121020	<i>Date of accident:</i>	21/02/2018
<i>Year of Regn.:</i>	19/10/2017	<i>Date inspected:</i>	09/03/2018
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	13/03/2018

STATIC CHECKS, where applicable:

<i>Steering :</i>	serviceable
<i>Footbrake :</i>	serviceable
<i>Handbrake :</i>	serviceable
<i>Paintwork :</i>	Good
<i>General condition :</i>	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
<i>Front:</i>	5mm/Yokohama	5mm/Yokohama	185/60R15
<i>Rear:</i>	5mm/Yokohama	5mm/Yokohama	185/60R15

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear RH portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
REAR BUMPER	1	squashed	1,150.60	1,150.60 X } NN
REAR BUMPER SIDE RETAINER L/R	2	necessary	53.00	53.00 X } NN
REAR RH ABS SENSOR	1	shorted	210.00	210.00 NN X
REAR RH DOOR	1	buckled	799.40	799.40 DDV ✓
REAR RH DOOR BLACK FRAME STICKER	1	necessary	25.00	25.00 NEC ✓
REAR RH DOOR BOTTOM RUBBER SEAL	1	deformed	55.40	55.40 ✓
REAR RH DOOR CHECKER	1	reuse	37.20	0.00
REAR RH DOOR FRONT WEATHERSTRIP	1	deformed	69.50	69.50 NN X
REAR RH DOOR GLASS OUTER LOCK HANDLE	1	reuse	81.70	0.00
REAR RH DOOR GLASS OUTER MOULDING	1	necessary	53.80	53.80 X NN
REAR RH DOOR HINGES (TOP & LOWER)	2	repair	97.20	0.00
REAR RH DOOR INNER TRIM BOARD	1	fractured	385.25	385.25 BR ✓
REAR RH DOOR MECHANISM LOCK	1	bent	240.20	240.20 BT ✓
REAR RH DOOR REAR WEATHERSTRIP	1	deformed	75.10	75.10 CUT ✓
REAR RH DOOR RUBBER GUIDE STOPPER	2	deformed	31.00	31.00 NN X
REAR RH FENDER	1	repair	1,010.90	0.00
REAR RH FENDER GLASS MOULDING	1	reuse	155.00	0.00
REAR RH FENDER INNER SHIELD	1	reuse	53.70	0.00
REAR RH FENDER INNER TRIM BOARD	1	reuse	489.60	0.00
REAR RH SHOCK ABSORBER	1	bent	530.00	530.00 NN X
REAR RH WHEEL CAP	1	abraded	195.00	195.00 CUT
REAR RH WHEEL HUB BEARING	1	dislodged	321.00	321.00 DL ✓
REAR SUSPENSION AXLE	1	distorted	1,080.00	1,080.00 NN X
ROCKER RH SIDE GARNISH	1	reuse	363.60	0.00
Subtotal before discount			S\$ 7,563.15	S\$ 5,274.25 ^{2096.35}
Percentage discount 20% and 20%			S\$ 1,512.63	S\$ 1,054.85
Sub-total 1			S\$ 6,050.52	S\$ 4,219.40 ^{1677.08}
REAR BUMPER CLIPS - SET	1	necessary	30.00	30.00 NEC
REAR RH 15" RIM	1	distorted	180.00	180.00 NN X
REAR RH 185/60R15 TYRE	1	abraded	350.00	350.00 NN X
REAR RH DOOR INNER TRIM BOARD CLIPS - SET	1	necessary	30.00	30.00 NEC
REAR RH FENDER GLASS SEALANT	1	reuse	80.00	0.00
REAR RH FENDER INNER SHIELD CLIPS - SET	1	necessary	30.00	30.00 NN X
REAR RH FENDER INNER TRIM BOARD CLIPS - SET	1	reuse	30.00	0.00
ROCKER RH SIDE GARNISH CLIPS - SET	1	reuse	30.00	0.00
Subtotal before discount			S\$ 760.00	S\$ 620.00
Sub-total 2			S\$ 760.00	S\$ 620.00 ⁶⁰
Parts-total			S\$ 6,810.52	S\$ 4,839.40

LABOUR

To remove, reinstall window glass. (to FR)	150.00	120.00 80.00
To remove, reinstall fender glass	150.00	0.00
To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knucke arm, wheel bearing, bearing hub and etc.	550.00	450.00 200.00 150
To road test driving, check and resetting wheel alignments system.	180.00	180.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00	60.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	200.00	120.00 RPT X
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00	400.00 880.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,700.00	600.00 750.00 400
To apply anti-rust chemical on repaired and replaced panel.	120.00	40.00 60.00 138
Labour Total	SS 4,190.00	SS 2,560.00
Parts & Labour Total	SS 11,000.52	SS 7,399.40

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 6,300.00 and the recommended number of working days for the repairs is within 6 day(s).

BJL

B J LOI (I Eng, MIMI, AIRTE)
Automotive Appraiser

Repair days 5

TGLim

Lim

19/11/18

PAR Automotive Consultancy

Thomson Hill Post Office PO Box 029 Singapore 918701 Tel: 645 31173, Fax: 645 36131

Page No: 00000006

Report No: 0544-18-NS1

10 September 2018

ACCIDENT VEHICLE SURVEY REPORT

Twincar Leasing Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 575577

VEHICLE INFORMATION:

Vehicle Reg No	SLT1357S	Odometer:	035577km
Make & Model	Honda Shuttle 1.5A	Colour:	Silver
Chassis number	GP71121020	Date of accident:	21/02/2018
Year of Regn.:	19/10/2017	Date inspected:	09/03/2018
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	13/03/2018

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3046C

Vehicle Details

Vehicle No.: SLT1357S

Vehicle to be Exported: No

Intended De-registration Date: 22 Feb 2018

Vehicle Make: HONDA

Vehicle Model: SHUTTLE HYBRID 1.5 AUTO

Primary Colour: Silver

Manufacturing Year: 2017

Engine No.: LEB6325921

Chassis No.: GP71121020

Maximum Power Output: 101.0 kW (135 bhp)

Open Market Value: \$21,297.00

Original Registration Date: 19 Oct 2017

First Registration Date: 19 Oct 2017

Transfer Count: 0

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Oct 2027

PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 18 Oct 2027

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid:	\$48,109.00
COE Rebate Amount:	\$46,444.00
Total Rebate Amount:	\$50,194.00

The information contained herein is correct as at 22 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/02/2018 16:44
Date Of Accident	21/02/2018 18:20
Exact Location Of Accident	PINE GROVE CONDO OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT1357S
Insured/Policyholder	
Name Of Registered Owner	TWINCAR LEASING PTE LTD
Co Reg No	201533046C
Email Address	SALES@N51.COM.SG
Mobile Phone No	(LOCAL) +65-83802233
Alternative Phone No	OFFICE-68420051

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE HYBRID-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD17V11639/VPZ/R02
Cover Note Number	

Driver

Name of Driver	PETER TAN SWEE HUAT
NRIC No	S1800876I
Date Of Birth	13/01/1967
Occupation	OUTDOOR
Date Of Driving Pass	13/01/1990
Driving Experience	28 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91911313
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 294A COMPASSVALE CRESCENT #15-13
Postcode	541294
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGG7362P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	PETER TAN SWEE HUAT
Approximate Age	

Injuries Sustain

Injured person in which vehicle?

SLT1357S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (POPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

VEHICLE A - SLT 13975
 VEHICLE B - SGA 7362P



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

<p>MY VEHICLE CAME TO A STATIONARY POSITION TO ALIGHT PASSENGER</p>
<p>AFTER MY PASSENGER ALIGHTED, I ABOUT TO MOVE OFF SUDDENLY A VEHICLE REVERSE AND HIT ONTO THE RIGHT SIDE OF MY VEHICLE.</p>
<p>ALIGHTED FROM MY VEHICLE AND REALIZED A VEHICLE BEARING (SGA 7362P) HAD COLLIDED TO THE RIGHT SIDE OF MY VEHICLE WHILE I'M IN THE STATIONARY POSITION.</p>
<p>THE WHOLE ACCIDENT FOOTAGE WAS CAPTURED BY MY IN-CAR CAMERA.</p>
<p>VEHICLE A - SLT 13975 VEHICLE B - SGA 7362P</p>

DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature
 Date & Time

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/ID No.

Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



本田技研工業株式会社
型式 DAA-GP7
車台番号 GP7-1121020
TD4H1C2-NH830M -A -J 

Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/02/2018 16:27
Date Of Accident	21/02/2018 18:40
Exact Location Of Accident	BLK 1F PINE GROVE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGG7362P
Insured/Policyholder	
Name Of Registered Owner	CAO WENJUN
NRIC No	S6978889J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92982003
Alternative Phone No	Office-92982003

Vehicle Particulars

Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A27710566QMX
Cover Note Number	

Driver

Name of Driver	LIN YU
NRIC No	S7076195E
Date Of Birth	11/06/1970
Occupation	INDOOR
Date Of Driving Pass	19/12/2005
Driving Experience	12 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98249157

Fax Number	
Contact Number	
E-Mail Address	MARIA.LIN.IPEXL@GMAIL.COM
Address	1F PINE GROVE #11-29
Postcode	595001
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident.	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I STARTED TO REVERSE INTO THE PARKING LOT (171). OUT OF SUDDEN, VEHICLE B DRIVE TOWARDS THE LOT 171 AND STOP AND HIT ONTO MY VEHICLE REAR PORTION (WHEN I START REVERSE THERE WAS NO VEHICLE BEHIND ME AND THE PARKING LOT. SO VEHICLE B CUT INTO THE LOT AND STOP TO ALIGHT PASSENGER FROM HIS CAR). TYPE OF COLLISION: REVERSING OF VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT1357S
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	PETER TAN SWEE HUAT
NRIC/Passport Number	S1800876I
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

22/2/18
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



(A) S667362P

(B) SLT 1357S

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I ~~was~~ START TO REVERSE INTO THE PARKING LOT (171) OUT OF SUDDEN VEHICLE B DRIVE ~~STRAIGHT~~ TOWARD THE LOT 171 AND STOP AND HIT ONTO MY VEHICLE REAR PORTION (WHEN I START REVERSE THERE WAS NO VEHICLE BEHIND ME AND THE PARKING LOT SO VEHICLE B WAS CUT INTO THE LOT AND STOP TO ~~ALIVE~~ ^{ALIVE} PASSENGERS FROM HIS CAR.)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Driving License

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7076195E



Lin Yu
LIN YU
林 毓
N.O.
CHINESE
Date of Birth: 11-08-1970
Date of Issue: 19-06-2018
Country of Birth: CHINA



REPUBLIC OF SINGAPORE DRIVING LICENCE

S7076195E

Lin Yu

Exp. Date: 11 Jun 2020
Issue Date: 19 Dec 2008



2004007



S7076195E



Print Date: 19-06-2018
Day of Issue: 19-06-2018

17 PINE GROVE #11-30
SINGAPORE 659332
NRC No: S7076195E Date: 01/06/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

CLASS 2A

Class 2A Motor cars without clutch pedals (Aster) <= 2000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles without clutch pedals <= 2000kg

18 Dec 2008

NP-1884





MSIG Insurance (Singapore) Pte. Ltd.
 4 Sunstar Way, #21-01, SGX Centre 2, Singapore 068917
 Tel: +65 (6) 277 7818, Fax: +65 (6) 277 7800
 Co. Reg. No. 200612212G, GST Reg. No. 20-04122-2U

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1989 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1990 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1 Individual Ownership	MOTOR MAX Comprehensive
Certificate No. A 27310546 QMK	
	Excess: SGD500 Windscreen Excess: SGD100
1. Index Mark and Registration Number of Vehicle	SGG73522
2. Name of Policyholder	Cao Wenjun
3. Effective Date of the Commencement of Insurance for the purposes of the Act	22/02/2018
4. Date of Expiry of Insurance	31/05/2018
5. Persons or Classes of Persons entitled to drive*	Cao Wenjun Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.
	* Provides that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to use*	Use only for social domestic and pleasure purposes and for the Policyholder's business. The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.
	* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.
PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG AUTHORIZED WORKSHOP LISTED IN THE ATTACHEE.	
This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).	

WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part V of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers


for Chief Executive Officer

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Feb 2018		23 Feb 2018 13:26 Edit Adj Rpt	S\$2,300.00 Edit Estimates	S\$2,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	DR CAO WENJUN , ID: S6978889								
Main Claimant:	TWINCAR LEASING PTE LTD , Co. Reg. No.: 201533046C								
Vehicle Reg. No.:	SLT1357S	Date of Loss:	21/02/2018 18:00 - :59 [4 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 550353	Policy/Cover Note No.:	A27710566QMX (Comprehensive) Coverage: 22/05/2017 - 21/05/2018						
Vehicle Reg. No. (Insured):	SGG7362P	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/11/2018]								
Driver/Custodian (Insured):	LIN YU (), NRIC: S7076195E								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_SG (16/11/2018): Report Send Back Alerts - SLT1357S (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT1357S (550353)
[SGG7362P]
TP
TWINCAR LEASING PTE LTD
Feb 21 2018 6:00PM
[DR CAO WENJUN]
N-51 Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Video							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print			
1	27/04/18 11:31	Video - Accident		Load MP4				
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print			
1	23/02/18 13:20	Accident Statement <small>From: SC - Reg. No: SGG7362P, Claimant: CAO WENJUN</small>		Load HTM				
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
2	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
3	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
4	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
5	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
6	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
7	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
8	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
9	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
10	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
11	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
12	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
13	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
14	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
15	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
16	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
17	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
18	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
19	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
20	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
21	07/05/18 10:38	General View		Load JPG	<input checked="" type="checkbox"/>			
22	07/05/18 10:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
23	07/05/18 10:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
24	07/05/18 10:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
25	07/05/18 10:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
26	07/05/18 10:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
27	07/05/18 10:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
28	07/05/18 10:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
29	07/05/18 10:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			
30	07/05/18 10:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	07/05/18 10:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
32	07/05/18 10:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
33	07/05/18 10:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
34	07/05/18 10:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
35	07/05/18 10:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
36	07/05/18 10:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
37	07/05/18 10:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
38	07/05/18 10:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
39	07/05/18 10:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
40	07/05/18 10:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
41	07/05/18 10:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
42	19/11/18 08:15	Photo After Spray		<input checked="" type="checkbox"/>
43	19/11/18 08:15	Photo After Spray		<input checked="" type="checkbox"/>
44	19/11/18 08:15	Photo After Spray		<input checked="" type="checkbox"/>
45	19/11/18 08:15	Photo After Spray		<input checked="" type="checkbox"/>
46	19/11/18 08:15	Photo After Spray		<input checked="" type="checkbox"/>
47	19/11/18 08:15	Photo After Spray		<input checked="" type="checkbox"/>
48	19/11/18 08:15	Photo After Spray		<input checked="" type="checkbox"/>
49	19/11/18 08:15	Photo After Spray		<input checked="" type="checkbox"/>
50	19/11/18 08:15	Photo After Spray		<input checked="" type="checkbox"/>
51	19/11/18 08:15	Photo After Spray		<input checked="" type="checkbox"/>
52	19/11/18 08:15	Photo After Spray		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/02/18 13:26	TP GIA REPORT		<input type="checkbox"/>
2	27/04/18 11:32	OI's email enclosing more pictures		<input type="checkbox"/>
3	27/04/18 11:33	1st pix		<input type="checkbox"/>
4	27/04/18 11:34	2nd pix		<input type="checkbox"/>
5	27/04/18 11:34	3rd pix		<input type="checkbox"/>
6	16/11/18 10:42	LOD with supporting documents		<input type="checkbox"/>
7	16/11/18 10:42	TPD SLT13575 - COLOUR PHOTO		<input type="checkbox"/>
8	16/11/18 18:53	instruction to LKK Auto to prepare paper survey report		<input type="checkbox"/>

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/11/18 14:17	Colour Photo		<input type="checkbox"/>
2	19/11/18 14:17	PRS Invoice		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18003503/GSD3E2-1
Date: 19/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A27710566QMX
Claimant Vehicle No : SLT1357S	Insured Vehicle No :	SGG7362P
Date of Loss: 21/02/2018	Nature of Claim:	TP Claim No: 550353

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT1357S	Engine No:	LEB6325921
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71121020
Reg. Date:	19/10/2017 (Man. Year: 2017)	Odometer:	35577 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,810.52	1,737.08	5,073.44	74.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,190.00	1,130.00	3,060.00	73.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,000.52	2,867.08	8,133.44	73.94
Approved Total (Overridden) (S\$)		2,300.00		
	(S\$)	11,000.52	2,300.00	8,700.52
	+ GST 7.00/7.00% (S\$)	770.04	161.00	609.04
	Nett Amount (S\$)	11,770.56	2,461.00	9,309.56

INSPECTION

Date of Assignment:	23/02/2018	
Date Inspected:	09/03/2018 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Nov 2018)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT1357S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	1,150.60 FL	*- FL
2	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	53.00 FL	*- FL
3	1		*REAR RH ABS SENSOR	Not Necessary	210.00 FL	*- FL
4	1		*REAR RH DOOR	Dented	799.40 FL	*799.40 FL
5	1		*REAR RH DOOR BLACK FRAME STICKER	Necessary	25.00 FL	*25.00 FL
6	1		*REAR RH DOOR BOTTOM RUBBER SEAL	Deformed	55.40 FL	*55.40 FL
7	1		*REAR RH DOOR CHECKER	Reuse	37.20 FL	*- FL
8	1		*REAR RH DOOR FRONT WEATHERSTRIP	Not Necessary	69.50 FL	*- FL
9	1		*REAR RH DOOR GLASS OUTER LOCK HANDLE	Reuse	81.70 FL	*- FL
10	1		*REAR RH DOOR GLASS OUTER MOULDING	Not Necessary	53.80 FL	*- FL
11	2		*REAR RH DOOR HINGES (TOP & LOWER)	Repair	97.20 FL	*- FL
12	1		*REAR RH DOOR INNER TRIM BOARD	Broken	385.25 FL	*385.25 FL
13	1		*REAR RH DOOR MECHANISM LOCK	Bent	240.20 FL	*240.20 FL
14	1		*REAR RH DOOR REAR WEATHERSTRIP	Cut	75.10 FL	*75.10 FL
15	2		*REAR RH DOOR RUBBER GUIDE STOPPER	Not Necessary	31.00 FL	*- FL
16	1		*REAR RH FENDER	Repair	1,010.90 FL	*- FL
17	1		*REAR RH FENDER GLASS MOULDING	Reuse	155.00 FL	*- FL
18	1		*REAR RH FENDER INNER SHIELD	Reuse	53.70 FL	*- FL
19	1		*REAR RH FENDER INNER TRIM BOARD	Reuse	489.60 FL	*- FL
20	1		*REAR RH SHOCK ABSORBER	Not Necessary	530.00 FL	*- FL
21	1		*REAR RH WHEEL CAP	Cut	195.00 FL	*195.00 FL
22	1		*REAR RH WHEEL HUB BEARING	Dislodged	321.00 FL	*321.00 FL
23	1		*REAR SUSPENSION AXLE	Not Necessary	1,080.00 FL	*- FL
24	1		*ROCKER RH SIDE GARNISH	Reuse	363.60 FL	*- FL
25	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
26	1		*REAR RH 15 RIM	Not Necessary	180.00 FS	*- FS
27	1		*REAR RH 185/60R15 TYRE	Not Necessary	350.00 FS	*- FS
28	1		*SET REAR RH DOOR INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
29	1		*REAR RH FENDER GLASS SEALANT	Reuse	80.00 FS	*- FS
30	1		*SET REAR RH FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
31	1		*SET REAR RH FENDER INNER TRIM BOARD CLIPS	Reuse	30.00 FS	*- FS
32	1		*SET ROCKER RH SIDE GARNISH CLIPS	Reuse	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	8,323.15	2,156.35
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,512.63	419.27
Total Parts (\$\$)	6,810.52	1,737.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL WINDOW GLASS (TO FR) }	New	150.00	80.00
2	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE }	New	200.00	0.00
3	TO REMOVE, REINSTALL FENDER GLASS	New	150.00	0.00
4	TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC	New	550.00	150.00
5	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM	New	180.00	60.00
6	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	New	140.00	0.00
7	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
8	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,700.00	400.00
9	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	40.00
Gross Labour Cost (S\$)			4,190.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >