

22/03/2002

ASS. REC. BY:

REF:

(63 / ASM18020843 / Rlcbr)

Special Instruction:

Surveyor:

Rusu

ASSIGNMENT (Office)

Smart Claim

From (Person):

Tan Wan Cong

of

ASM

Date/Time: 19-11-2018 9:41am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GY 4971 G

Insured:

GBF 1829P.

at Workshop m/s

GMA Automotiv

Tel:

9061 1218

of

38 Woodlands Ind Park E1 #05-01

Policy No:

Claim No:

S8MD1018

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23-10-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS^{ewp}

H.O.D. Endorsement:

Date/Time:

19-11-2018 10:35am

Person Contacted:

Cleon

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	GY 4971 G - X
	GBF 1829P - X
	Dismantle: 10/12/2018

SYNTHETIC

PRR

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **G4 49716**
 at Workshop m/s: **GMA Automotive**
 of **2, Kerasi: LMK**
 Insured: **AXA**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **10** days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **G4 49716** Yr Regn: **Apr / 05**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: **NISSAN** C.C. **3153**
 Colour: **GREY** A/C: Insured / Std / NI / NA
 Sp.Reading: **-** T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: **JN18FHFD3Z0854053**

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: **Order** / Jammed / Leaked / Burnt or
 Brake: **Order** / Jammed / Leaked / Burnt or
 Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: **195R15Z**
 R: **155R12C**

BS / DUN / EXNOVA / GY / FS / LIZA / **MIC** / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. 7 mm	R/Bal. 5/5 mm
L/Bal. 7 mm	L/Bal. 5/5 mm
D.O.A.	D.O.I. 06/12/18 @ 0425pm

Survey held at **GMA**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range \$ 18,000/2 - \$19,000/2

13/12/2018

TCU m

13/12/18

Date/Time. File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time. File Return to?

2) _____

Days Of Repair: **10**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation: _____ \$ + RS. _____ \$

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format: **PRR**

Lump Sum / I.B.I. (\$

TOTAL

100

100



Service Request Details

Claim

83M010I8

Reference

Done

Loss Date

October 23, 2018

Request Date

November 19, 2018

File Date

November 26, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Ident Vehicle Registration #

4971G

Make

PVD NISSAN



Service Address

Primary Contact/Insured

KHI AGRI HOLDING PTE LTD
90 VERDE CRESCENT, VILLA VERDE, 688510, Singapore

BERT_MAXY@HOTMAIL.COM

Claim Handler

AN Wancong

n.wancong@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	GY4971G		
Vehicle Type :	B31 - Goods (Open) Lorry (Metal Body)/Pickup		
Vehicle Attachment 1 :	With Hood		
Vehicle Scheme :	Normal		
Vehicle Make :	NISSAN		
Vehicle Model :	CABSTAR		
Chassis No. :	JN1SF4F23Z0854053		
Propellant :	Diesel		
Engine No. :	QD32205467		
Engine Capacity :	3153 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	3350 kg		
Unladen Weight :	1640 kg		
Year Of Manufacture :	2005		
Original Registration Date :	27 Apr 2005		
Lifespan Expiry Date :	26 Apr 2025		
COE Category :	C - Goods Vehicle & Bus		
PQP Paid :	\$27,286.00		
COE Expiry Date :	31 Mar 2020		
Lay Up Expiry Date :	27 Nov 2019		
Inspection Due Date :	26 Oct 2018		
Intended Transfer Date :	11 Dec 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.			

You may print this page for reference.

OK Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5603W
Vehicle Details	
Vehicle No.:	GY4971G
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Dec 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR
Primary Colour:	Gold
Manufacturing Year:	2005
Engine No.:	QD32205467
Chassis No.:	JN1SF4F23Z0854053
Maximum Power Output:	-
Open Market Value:	\$20,089.00
Original Registration Date:	27 Apr 2005
First Registration Date:	27 Apr 2005
Transfer Count:	0
Actual ARF Paid:	\$1,005.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$27,286.00
COE Rebate Amount:	\$7,321.00
Total Rebate Amount:	\$7,321.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 11 Dec 2018

Bal: 1 yr 6.1 mth
OK M.V. \$12,000.

Do you clean your
car fuel system?



Nissan Cabstar

Price Range

Depreciation

> 10 year(s)

Vehicle Type

Advanced Search

Home » Used Cars » M.Y Commercial Pte Ltd » Nissan Cabstar (COE till 11/2020)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



MSIG

Insurance
that sees
the heart in
every

Buy

Nissan Cabstar (COE till 11/2020)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$15,800

Depreciation \$8,090 /yr

Reg Date 26-Nov-2005
(1yr 11mths 12days COE left)

Lifespan 25-Nov-2025

Manufactured 2005

Mileage -

Transmission Manual

Engine Cap 3,153 cc

Curb Weight 1,500 kg

Fuel type Diesel

Features -

Accessories -

Description PQP Paid \$22,924. High Scrap Value! Well Maintenance By Previous Owner, Price Still Can Negotiable, High Loan With Lowest Interest Rate Available, Call Our Friendly Salesperson To View Now.

COE \$22,924

OMV \$20,070

ARF \$1,004

Dereg Value \$8,956 as of today (change)

No. of Owners 2

Type of Veh Truck

Category COE Car

Availability Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 21-Nov-2018 | Last Updated on: 23-Nov-2018

Tags: Nissan Cabstar, nissan cabstar, 2005 Nissan Cabstar, 2005 nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan

Upfront Payment

» more Financial Info

Transfer Fee \$25


Down Payment \$1,580 (change)

Maximum 90% Loan

1st Instalment \$672

Total Upfront Payment \$2,277 (excluding insurance)

Estimates based on 90% loan at 4.5% interest rate. Check with seller for exact figure.



Seller Information

Company	M.Y Commercial Pte Ltd	
	» dealer's pricelist	
	» 9 vehs sold 5 vehs available	
Address	7030 Ang Mo Kio Avenue 5 #02-16	
	Search cars nearby this location	
Location	Northstar @ AMK	
Office No	69093877	
Contact Person(s)	Kenny Tan	91853232
	Nick Ong	81684411

Useful Services



Afraid of lemons? Request to have
this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car.
Get a free Car Valuation.

Free Valuation

Recommended for you

Compare

1-6 of 18

MSYH18146302 / Sin Yew Hup Auto Pte Ltd - HQ
ENTRY DATE & TIME: 12/11/2018 15:30
SUBMITTED BY: Edwin Yap Kiat Beng

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 12/11/2018 15:53

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/11/2018 15:30
Date Of Accident	23/10/2018 19:40
Exact Location Of Accident	KRANJI WAY T JUNCTION WITH SUNGEI KADUT DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY4971G
Insured/Policyholder	
Name Of Registered Owner	FASTWELD ENGINEERING CONSTRUCTION PTE LTD
Co Reg No	199905603W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63686325

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR-3.0 (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	DMCVSN3022271800
Cover Note Number	

Driver

Name of Driver	ONG LIAN LYE
NRIC No	S0011012D
Date Of Birth	12/11/1951
Occupation	OUTDOOR
Date Of Driving Pass	28/10/1977
Driving Experience	40 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90293857
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address BLK 95B HENDERSON ROAD #05-28
 Postcode 152095
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 5
 Passenger 1 NAME: : NEYIDONDA NANAJI
 GENDER: : MALE
 Passenger 2 NAME: : SARAPATI SUBRAHMANYAM
 GENDER: : MALE
 Passenger 3 NAME: : MURUGAN KARUPPAIYAN
 GENDER: : MALE
 Passenger 4 NAME: : KARUPPIAH SANKAR
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name BUKIT MERAH WEST NPC
 Police Station Address ROAD: 500 BUKIT MERAH VIEW #01-01 , POSTCODE: 159682 ,
 COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT T/20181024/2046

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBF1829P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name ONG LIAN LYE

Approximate Age

Injuries Sustain

Injured person in which vehicle? GY4971G

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name MURUGAN KARUPPAIYAN

Approximate Age

Injuries Sustain

Injured person in which vehicle? GY4971G

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

DETAILS OF INJURED PERSON 3

Name NEYIDONDA NANAJI

Approximate Age

Injuries Sustain

Injured person in which vehicle? GY4971G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 4

Name SARAPATI SUBRAHMANYAM

Approximate Age

Injuries Sustain

Injured person in which vehicle? GY4971G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 5

Name	KARUPPIAH SANKAR
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GY4971G
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20181024/2046

Police Station Of Origin:
Bukit Merah West N.P.C
500 Bukit Merah View #01-01 SINGAPORE
159682
Tel No: 1800-3779999

1 of 3

Report No. T/20181024/2046

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/10/2018 11:55		Vide Report No.:		Station Diary No.: 23	
Informant's Particulars					
Name of Informant: ONG LIAN LYE			Address: APT BLK 95B HENDERSON ROAD #05-28 SINGAPORE 152095		
ID Type / ID No.: NRIC NO / S0011012D			Contact No.: Home/Office: Mobile: 90293857		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 66	Date of Birth: 12/11/1951	Type of Informant: Driver		
Race: Chinese			Language: Chinese		Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 23/10/2018 19:40	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 KRANJI WAY SUNGEI KADUT DRIVE Along Kranji Way towards Neo Tiew Road, T-Junction of Sungei Kadut Dr				
Weather: Cloudy		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF1829P	Lorry				Seriously Damaged	0
GY4971G	Lorry				Seriously Damaged	4

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Sketch Plan #2 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20181024/2046

2 of 3

Police Station Of Origin:
Bukit Merah West N.P.C
500 Bukit Merah View #01-01 SINGAPORE
159682
Tel No: 1800-3779999

Report No. T/20181024/2046

CONTINUATION OF REPORT

Driver			
Name	ONG LIAN LYE	ID No.	S0011012D
Related Vehicle	GY4971G (Lorry)	Contact No.	90293857
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	23/10/2018	Date Discharge	23/10/2018
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

On 23/10/2018 at about 1940hrs, I was driving my company lorry bearing GY4971G along Kranji Way towards Neo Tiew Road. While reaching the T-junction of Sungei Kadut Drive, another lorry bearing GBF1829P was coming from the opposite direction and was planning to turn right into Sungei Kadut Drive. I was driving on the right lane out of the 2 lane road and I was planning to drive straight. Suddenly the lorry from the opposite side make a sudden right turn and his front portion of the vehicle (slightly more to the right side), had collided onto my front right portion of my lorry.

I wish to state that I was trap inside the vehicle due to the accident passerby had help to force open the driver door so that I am able to come out from the lorry. I suspect that he make an illegal right turn as he was driving on the left lane of his directions and it was suppose to drive straight instead of turning right. Traffic Police had came down as well. There were 4 passenger inside my vehicle. Subsequently there were a total of 8 of us conveyed by Ambulance to Khoo Teck Puat Hospital for checkup. I had suffered lacerations on my right knee area and abrasions on my stomach area. I was then given 4 days MC. The vehicle have to be towed away as the front and right side windscreen were all shattered and could no longer be driven.

Sketch Plan #3 Pg. 1

**SINGAPORE
POLICE FORCE**

T/20181024/2046

Police Station Of Origin:
Bukit Merah West N.P.C
500 Bukit Merah View #01-01 SINGAPORE
159682
Tel No: 1800-3779999

3 of 3

Report No. T/20181024/2046

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 TAN HWA TIONG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

24/10/2018 11:55

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt RAZIZ BIN TAHAR

Contact No.: 65476200

Classification Of Case:

-

Authentication Stamp

NP168

SIGNATURE

Sketch Plan #4 Pg. 1



AMENDMENT


Traffic Police Department
Charge Office
10 Ubi Avenue 3
Singapore 408865

NP 168 No: T/2018/024/2046 Name: ONG LIAN LYE
 Accident Date/Time: 24/10/18/1153 Address: R10, 95B Henderson Road
 Vehicle(s) involved: GRF 18091 #05-28
SY 49716 NRIC No: S 00110120
 Tel No: 90293834
 Date: 23/10/18

Dear Sir / Madam

I wish to amend as follows:

On Thu. 23/10/2018 at 1949hrs at accident location
 along Kranji Way towards Neo Tiew Rd. T junction
 of Sungei Kadut Drive, the traffic light condition
 was in amber when my lorry was near the stop
 line and as such I continued to drive through the light
 all.


Yours faithfully

ONG LIAN LYE
S0011012/0

Bukit Merah West
Neighbourhood Police Centre
No 580 Bukit Merah View #01-01
Singapore 159682
Tel: 1860-3779999


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN : TAN WANCONG			Ref: CS3/ASM18020843/R1cbe2 Date: 02-01-2019 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBF 1829P	Veh. Inspected	GY 4971G	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M01018	Excess (\$)	0.00	
Assign From	TAN WANCONG	Assign Date	19/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN CABSTAR	c.c	3153	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	JN1SF4F23Z0854053	Colour	GREY	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	MICHELIN	7 mm	
L/H Front Tyre	195 R15C	MICHELIN	7 mm	
R/H Rear Tyre	155 R12C (D)	MICHELIN	5/5 mm	
L/H Rear Tyre	155 R12C (D)	MICHELIN	5/5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
5. General Information				
Accident Date	23/10/2018	Inspect Date / Time	06/12/2018 (04:25 PM)	
Survey held at	2 KRANJI LINK			
Repairer	GMA AUTOMOTIVE SERVICES			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$18,000-\$19,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	

Report Ref No. CS3/ASM18020843/R1cbe2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEE,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.