

ASS. REC. BY:

REF: CS3 / MSG18020859 / Bcd3⁹

Special Instruction:

Surveyor:
menmen

Mr. Lim

ASSIGNMENT (Office)

From (Person):

Monica chung

of

MSIG

Date/Time:

16/11/18 @ 4:06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

E 4008B

Insured:

SLC 28M

at Workshop m/s

Merlin Motor

Tel:

64845225

of

10 Amk Ind. park 2A #03-13

Policy No:

80453447 QMY

Claim No:

575981

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13/11/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:32am @ 19/11/18

Person Contacted:

May

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	E 4008B - X
	SLC 28M - X
	Dismantle: 21/11/2018


REF: MSIG

ASSIGNMENT

From _____ Date: 16/11/18
 Estimated Cost _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s MERLIN MOTOR
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No E 4008 B Yt Regn. 15/1/15
 Type M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: MERCEDES BENZ E250 c.c 1991
 Colour WHITE A/C: Insured / Std / NI / NA
 Sp. Reading 77203 T/Radio: Insured / Std / NI / NA
 Eng/No: 27492030078995
 C/No: WDD2073362F232169
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: order / Jammed / Leaked / Burnt or _____
 Brake: order / Jammed / Leaked / Burnt or _____
 Modi: Nil / SRim / STD A/Rim or _____
 Tyre Size: F: 245/35R19
 R: 275/30R19

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or NEXEN
 Front _____ Rear _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 13/11/2018 D.O.I. 25/16/11/18
 Survey held at MERLIN MOTOR
 Des. of Damages Frnt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range 5,800 - 6,000
	MV 124,000/2
	PV 86,313/2
	NV 37687/2
	<i>[Signature]</i> 11/11/2019
	<i>Team list</i> 10/1/19

Date/Time, File Pass to? : Prel. Report
 : Final Report
 Days Of Repair: 4
 Resurvey No. of Trip: 1
 Survey Fee: _____
 Transportation: _____
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____) Photos
 : Tech. Invs (\$ _____) Others
 : Weekend (\$ _____)
 Report Format: PRS
 Lump Sum / I.B.I: (\$ _____)
 TOTAL _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case No.	Created	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Nov 2018		16 Nov 2018 16:06 Assign				New Assignment Cancel Case

	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHONG SIEW LOONG , ID: S7224364A, Tel: +6598590051, Email: SLCHONG@STARHUB.COM								
Main Claimant:	LIAN MEI LING EILEEN , ID: S7539080G								
Vehicle Reg. No.:	E4008B	Date of Loss:	13/11/2018 12:00 - :59 [45 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 575981	Policy/Cover Note No.:	80453447QMY (Comprehensive) Coverage: 26/01/2018 - 25/01/2019						
Vehicle Reg. No. (Insured):	SLC28M	Policy No. (Claimant):							
Excess:									
Repairer:	Merlin Motor & Engineering Works (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-13 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64845225								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/11/2018]								
Driver/Co-driver (Insured):	CHONG SIEW LOONG (46 / Male), NRIC: S7224364A, Tel: +6598590051								
Adj Asp. Remarks:	SJE DISAGREE APPOINT LKK. LIAB 100%. PLS CONTACT MAY (6484 5225)								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/11/2018 20:57
Date Of Accident	13/11/2018 12:25
Exact Location Of Accident	JALAN MEMBINA INFORN BLK 23 CAR PARK GANTRY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	E4008B
Insured/Policyholder	
Name Of Registered Owner	LIAN MEI LING EILEEN
NRIC No	S7539080G
Email Address	EILEENLML@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96418805
Alternative Phone No	OFFICE-96418805

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV0101430
Cover Note Number	

Driver

Name of Driver	LIAN MEI LING EILEEN
NRIC No	S7539080G
Date Of Birth	24/12/1975
Occupation	OUTDOOR
Date Of Driving Pass	31/03/1998
Driving Experience	20 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96418805
Fax Number	
Contact Number	OFFICE-96418805
EMail Address	EILEENLML@HOTMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was travelling along JALAN MEMBINA before entering HDB CARPARK GANTRY OF BLK 23 JALAN MEMBINA the vehicle SLC28M which was in front of me reversed and collided onto my vehicle E4008B rear despite me honking at him several times. No injuries involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WILL FORWARD TO INSURANCE ONCE INSURED SEND
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC28M
Vehicle Make/Model/Colour	BMW X5 XDRIVE25D M SPORT 7 SEAT LED NAV BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHONG SIEW LOONG
NRIC/Passport Number	S7224364A
Contact Number	98590051
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


[Handwritten signature]

VERIFIED BY AJAX MARS
 REPORTING OFFICER
 Mohamed Saifullah S/O Syed
 Masood
 Witnessed by Reporting Centre
 Personnel

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was travelling along JALAN MEMBINA before entering HDB CARPARK GANTRY OF BLK 23 JALAN MEMBINA the vehicle SLC28M which was in front of me reversed and collided onto my vehicle E4008B rear despite me honking at him several times. No injuries involved.

Taxi Voucher No.:

DECLARATION

We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMED SAIFULLAH S/O SYED MASOOD

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

14 November 2018 at 6:35 PM

Date/Time:

14 November 2018 at 6:35 PM

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9080G
Vehicle Details	
Vehicle No.:	E4008B
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E250 AT ABS D/AIRBAG 2WD COUPE
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	27492030078995
Chassis No.:	WDD2073362F232169
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$50,706.00
Original Registration Date:	15 Jan 2015
First Registration Date:	15 Jan 2015
Transfer Count:	1
Actual ARF Paid:	\$58,271.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jan 2025
PARF Rebate Amount:	\$43,703.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jan 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$71,300.00
COE Rebate Amount:	\$42,610.00
Total Rebate Amount:	\$86,313.00

The information contained herein is correct as at 10 Jan 2019

OK

Dep 16,120/yr
1,343/mth

MV 124,000/2
PV 86,313/2
NV 37,687/2



Republic Auto

Posted: 29-Dec-2018

Tags: 2015 Mercedes-Benz E250, 2015 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

Mercedes-Benz E-Class E250 Edition E

N.A

16-Nov-2015

1,991 cc

Luxury

SOLD

90% Loan Available! 1 Owner Only! Highest Spec AMG Edition E Model 1 And Only In The Market! Fully Serviced And Maintained By C&C! Excellent Condition! 100% Accident Free! Hurry, Call Us Now For A Vie...

ST Carz Pte Ltd

Posted: 27-Dec-2018

Tags: 2015 Mercedes-Benz E250, 2015 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

Mercedes-Benz E-Class E250

\$123,666

\$15,360 /yr

15-May-2015

1,991 cc

99,000 km

Luxury

Available

95% Loan Available. C&C Unit, Agent Maintained, Low Mileage Done, Immaculate Condition, 100% Accident Free, PHV Special Deal! Call Now.

Privilege Motors Pte Ltd

Posted: 26-Dec-2018

Tags: 2015 Mercedes-Benz E250, 2015 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

Mercedes-Benz E-Class E250 CGI Avantgarde

\$125,800

\$16,120 /yr

29-Jan-2015

1,991 cc

26,590 km

Luxury

Available

C&C Unit! Full Service History With C&C. Facelifted Avantgarde R18 Model. Lady Driver Who Seldom Drives Her Car, Prefers Her Husband And Kids To Chauffeur Her Around, Hence The Very Low Mileage, Accid...

CONSIGNMENT

Prem Roy Motoring

Posted: 20-Dec-2018

Tags: 2015 Mercedes-Benz E250, 2015 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz



Auction your Car to 500+ Dealers

Get a Bid Price ready in 1 hour with sgCarMart Quotz - Singapore's most efficient bidding system with a network of 500+ Dealers. Get paid immediately with FAST iBanking and a flexible 2-week handover. Highest Price Guaranteed, or get \$100 cash from us.

Find out more!



Mercedes-Benz E-Class E250 Edition E

N.A

13-Nov-2015

1,991 cc

Luxury

SOLD

Auto Zoom Enterprise Pte Ltd

Posted: 19-Dec-2018

Tags: 2015 Mercedes-Benz E250, 2015 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

Mercedes-Benz E-Class E250

N.A

02-Jan-2015

1,991 cc

Luxury

SOLD

Director Owner. C&C Unit, R18 Model, Fully Agent Maintained Since Day One, Super Low Mileage Done, Car Like New. See To Believe. Loan/Trade In Avail.

PREMIUM EO

Posted: 19-Dec-2018

Tags: 2015 Mercedes-Benz E250, 2015 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

Mercedes-Benz E-Class E250 Edition E

N.A

13-Nov-2015

1,991 cc

Luxury

CLOSED

Auction Closing Time: 16th Dec 2018 at 11:00 PM

2 Keys Available. Only For Business Entities To Tender. Not Applicable For Private Individuals. This Is Not A Repossessed Vehicle. Vehicles Are Sold "As Is Where Is" Conditions. Carplate Number Is SKW...

AUCTION VEH

Posted: 10-Dec-2018

Tags: 2015 Mercedes-Benz E250, 2015 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

Mercedes-Benz E-Class E250 Avantgarde

\$122,000

\$15,790 /yr

13-Jan-2015

1,991 cc

67,000 km

Luxury

Available

1 Owner, Flawless & Immaculate E250 Avantgarde. 20% Down Payment Drive Away, Easy 80% Loan At 2.78%! Welcome STA Evaluation To Assure Condition, Guaranteed Accident Free. No Wear & Tear Replacement Ne...

PREMIUM EO

Bavarian Marques Pte Ltd

Posted: 06-Dec-2018

Tags: 2015 Mercedes-Benz E250, 2015 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

Mercedes-Benz E-Class E250

N.A

06-May-2015

1,991 cc

Luxury

SOLD

2nd Owner And 2nd Car In The Family, Well Taken Care Of. Please Call To Arrange A Test Drive Etc.

DIRECT OWNER

Posted: 04-Dec-2018

Tags: 2015 Mercedes-Benz E250, 2015 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

Mercedes-Benz E-Class E250 CGI Avantgarde

N.A

29-Jan-2015

1,991 cc

Luxury

SOLD

Lady Driver Who Seldom Drives Her Car. Prefers Her Husband And Kids To Chauffeur Her Around, Hence The Very Low Mileage. Accident-Free. Nano-Coated Polish. Extreme Pristine Condition, Almost Like New....

DIRECT OWNER

Posted: 30-Nov-2018

Tags: 2015 Mercedes-Benz E250, 2015 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

Mercedes-Benz E-Class E250

N.A

14-Sep-2015

1,991 cc

Luxury

SOLD

Compare

ment Unit, Cheapest 2015 C&C Unit In Singapore, Full Agent Service, Call Now To View, In House Loan And Trade In Available.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins' Auth'ed	Status
Main	14 Nov 2018		16 Nov 2018 16:06 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHONG SIEW LOONG , ID: S7224364A, Tel: +6598590051, Email: SLCHONG@STARHUB.COM		
Main Claimant:	LIAN MEI LING EILEEN , ID: S7539080G		
Vehicle Reg. No.:	E4008B	Date of Loss:	13/11/2018 12:00 - :59 [45 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 575981	Policy/Cover Note No.:	80453447QMY (Comprehensive) Coverage: 26/01/2018 - 25/01/2019
Vehicle Reg. No. (Insured):	SLC28M	Policy No. (Claimant):	
		Excess:	
Repairer:	Merlin Motor & Engineering Works (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-13 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64845225		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Imm.Advice due 17/11/2018]		
Driver/Custodian (Insured):	CHONG SIEW LOONG (46 / Male), NRIC: S7224364A, Tel: +6598590051		
Adj Asg. Remarks:	SJE DISAGREE APPOINT LKK. LIAB 100%. PLS CONTACT MAY (6484 5225)		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***E4008B (575981)**
[SLC28M]
TP
LIAN MEI LING EILEEN
Nov 13 2018 12:00PM
[CHONG SIEW LOONG]
Merlin Motor & Engineering Works

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/11/18 14:29	Accident Statement From:SC - Reg. No: SLC28M, Claimant: CHONG SIEW LOONG	Load HTM	<input type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
2	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
3	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
4	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
5	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
6	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
7	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
8	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
9	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
10	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
11	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
12	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
13	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
14	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
15	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
16	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
17	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
18	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
19	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
20	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
21	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
22	11/01/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
23	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
24	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
25	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
26	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
27	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
28	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
29	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
30	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
31	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
33	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
34	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
35	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
36	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
52	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
53	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
54	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
55	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
56	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
57	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
58	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
59	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
60	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
61	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
62	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
63	11/01/19 12:02	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/11/18 14:29	Third Party Accident Report From:SC - Reg. No: SLC28M, Claimant: CHONG SIEW LOONG	Load PDF	
2	16/11/18 14:29	PRI From:SC - Reg. No: SLC28M, Claimant: CHONG SIEW LOONG	Load PDF	
3	16/11/18 15:32	SJE DISAGREE APPOINT LKK	Load PDF	
4	16/11/18 15:33	workshop details	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18020859/BCD3S2
Date: 15/01/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80453447QMY
Claimant Vehicle No :	E4008B	Insured Vehicle No :	SLC28M
Date of Loss:	13/11/2018	Nature of Claim:	TP
		Claim No:	575981

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	E4008B	Engine No:	27492030078995
Make & Model:	MERCEDES-BENZ E250, 1.8 (A)	Chassis No:	WDD2073362F232169
Reg. Date:	15/01/2015 (Man. Year: 2013)	Odometer:	77203 km
Colour:	White		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/55R19	Rear Tyre Size:	275/30R19
Front Left Side:	Nexen 7 mm	Rear Left Side:	Nexen 7 mm
Front Right Side:	Nexen 7 mm	Rear Right Side:	Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	16/11/2018	Merlin Motor & Engineering Works (HQ)
Date Inspected:	20/11/2018 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #03-13 AMK
Estimated Period of Repair:	4.0 days	Autopoint
		Singapore 568047

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Jan 2019)

Parts: 143 MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for E4008B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >