

ASS. REC. BY:

REF: CS3/CTF18020860/Bc d3

Special Instruction:

Surveyor: Mr. Jim ASSIGNMENT (Office)

From (Person): MUMEN Chong Boon Gen of CTF Date/Time: 16/11/18 @ 15:55pm.

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No: SLR 2533D Insured: SLX536/G

at Workshop m/s Lee Luen Sing Motor Tel: 6483 7412 / 9668 6354

of 10 AMK Ind. park 2A # 03-10

Policy No: DMPCS N 3031621800 Claim No: SNM18D05312C02

Sum Insured: Excess:

Make of Veh: D.O.A. 08/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (up) 20/11/2018

H.O.D. Endorsement:

Date/Time: 10:41am @ 19/11/18 Person Contacted: Kim Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLR 2533D - X
	SLX5624P - NBA/CTF18020294/Y DVA: 08/11/2018
	Dismantle: 21/11/2018
	After repair: 23/11/2018

PRs

REF: C11

Mafimen

ASSIGNMENT

From _____ Date: 20-11-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLR 2533D
at Workshop m/s Lee Kew Sing Motor
of 10 AMK Ind Park 2A #03-10

Insured:

Policy No.:

Claims No.:

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLR 2533D Yr Regn: 19/4/2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X3 cc 1997

Colour: SILVER A/C: Insured / Std / NI / NA

Sp. Reading: 123666 T/Radio: Insured / Std / NI / NA

Eng/No: A36601106 N28B28A

C/No: WBAW X320300 R26110

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/50R18

R: 245/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 7 mm R/Bal: 7 mm

L/Bal: 7 mm L/Bal: 7 mm

D.O.A: 8/11/18 D.O.I: 20/11/18

Survey held at Lee Kew Sing Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$6,000 - \$8,000

MLV 73,000/2

PV 63,052/2

NV 29,700/2

RECEIVED 07 DEC 2018



26/11/2018

Tettim Lin
20/11/18

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2)

Report Format: PRS

Lump Sum / I.B.I. (\$)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Filed	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Nov 2018		16 Nov 2018 15:55 Assign				New Assignment Cancel Case

Reference	Claim Details	Documents	Show All
-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:			
Main Claimant:	WU JUNWEI, KELVIN		
Vehicle Reg. No.:	SLR2533D	Date of Loss:	08/11/2018 00:00 - :59
Claim Type	TP / SNM18D05312C02	Policy/Cover Note No.:	DMPCSN3031621800
Vehicle Reg. No. (Insured):	SLX5361G	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Lee Luew Sing Motor (HQ) No. 10 Ang Mo Kio Industrial Park 2A, #03-10 AMK Autopoint, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/11/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Task	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

From: Sow-ye Wong <wongsylaw@gmail.com>
Sent: Sunday, 11 November, 2018 12:43 PM
To: Irene Tay; Claims Dept of CTI
Subject: Fwd:
Attachments: VID-20181108-WA0033.mp4; VID-20181108-WA0031.mp4; VID-20181108-WA0032.mp4; NOTICE OF ACCIDENT - SLR 2533D & SLX 5361G, SLU 5624P, GBJ 9162E ON 08.11.18 ALONG PIE TUAS AT 08.40 AM.pdf

Our Ref : FCY / 493 / 18

Your Ref : SLX 5361G - NG BOON KIAT (HUANG WENJIE) - S6927577Z

M/s China Taiping Insurance (S) P L

Attn: M/s Irene Tay, The Executive - Motor Claims

Dear Sirs

NOTICE OF ACCIDENT

CLAIMANT: WU JUNWEI KELVIN - S8432153B

ACCIDENT INVOLVING SLR 2533D (# 1) / SLX 5361G (# 2) / SLU 5624P (# 3) / GBJ 9162E (# 4) ON 08.11.18 ALONG PIE (TUAS / CLEMENTI EXIT) @ 08:40 AM

We act for WU JUNWEI KELVIN, Owner & Driver

Our Client's Car	:	SLR 2533D (# 1)
Your Insured's Car	:	<u>SLX 5361G (# 2)</u>
Date & Time of Accident	:	08 NOVEMBER 2018 / 08:40
Place of Accident	:	PIE (TUAS / CLEMENTI EXIT)

Before our Client proceeds to repair the damaged car, we are requesting a Pre-Repair Survey. Kindly let us know within **2 working days** of this Notice whether you or your Insurers would like to conduct a PRS of the car.

If we do not receive any reply from you/your Insurers within the stipulated timeline, our Client shall proceed to repair the car without further reference to you & our Client will be compensated for the loss of use of the car for this period of time.

Our Client's Appointed Workshop **MR LEE KIM WAH - 9668 6354 / 6483 7416**

M/s Lee Luew Sing Motors

10 Ang Mo Kio Industrial Park 2A

03 - 11 AMK Autopoint

S 568017 Tel : 6483 7412 / 6483 0827

Our Client's Appointed Surveyor

Mr Erol Tan

M/s Pro Plus Automobile Engineers

Mobile : 9673 0595 / 9788 9809

Please contact - **Mr Lee Kim Wah - 9668 6354**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/11/2018 09:52
Date Of Accident	08/11/2018 08:40
Exact Location Of Accident	PIE TUAS BEFORE CLEMENTI EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR2533D
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	WU JUNWEI, KELVIN
NRIC No	S8432153B
Email Address	KELVIN2784@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98514270
Alternative Phone No	OFFICE-98514270

Vehicle Particulars

Manufacturer	BMW
Model	X3 XDRIVE20I ABS 4WD SR HID DSC NAV
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097763495
Cover Note Number	

Driver

Name of Driver	WU JUNWEI, KELVIN
NRIC No	S8432153B
Date Of Birth	18/10/1984
Occupation	INDOOR
Date Of Driving Pass	22/05/2007
Driving Experience	11 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98514270
Fax Number	
Contact Number	OFFICE-98514270
Email Address	KELVIN2784@GMAIL.COM

Address	BLK 440B FERNVALE LINK #18-165
Postcode	792440
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN. VEHICLE WILL REPAIR & CLAIM AT LEE LUEW SING MOTORS.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PASS TO PREFERRED WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLX5361G
Vehicle Make/Model/Colour	HONDA CIVIC / RED
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SEAN NG
NRIC/Passport Number	S9738124J
Contact Number	91061680
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLU5624P
-----------------------------	----------

Vehicle Make/Model/Colour	HONDA VEZEL / BLUE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	AMIAN BIN YEM
NRIC/Passport Number	S1580573J
Contact Number	82006163
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	GBJ9162E
Vehicle Make/Model/Colour	FIAT / SILVER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	WONG SENG FATT
NRIC/Passport Number	S7588449D
Contact Number	93671631
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers or the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 9/11/18



Driver's Signature
(If driver is not the policyholder)
Date & Time: 9/11/18


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

P1E TOWARDS THAS.



A: SLR 2533 D

B: SLX 5361 G

C: SLN 5624 P

D: GBS 9162 E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 3/11/18 AT 8:40 AM, I WAS DRIVING MY VEHICLE SLR 2533 D ON P1E TOWARDS THAS BEFOR CLEMENTI EXIT ON LANE 2. BEFOR THE TRAFFIC IN FRONT CAME TO A GRADUAL STOP. AFTER MY VEHICLE COULD COME TO A STOP. I FELT A SUDDEN COLLISION FROM THE REAR OF MY VEHICLE. I THEN EXIT THE VEHICLE & FOUND OUT THAT VEHICLE SLX 5361 G HAD COLLIDED INTO MY VEHICLE FOLLOW BY 2 OTHER VEHICLE BEHIND HIM. THE OTHER 2 VEHICLE NUMBER IS SLN 5624 P & GBS 9162 E. AFTER LOOKING AT MY IN CAR RECORDING, I REALISE THAT SLX 5361 G HAD COLLIDED INTO MY REAR AND SECONDLY AFTER THE COLLISION THE OTHER 2 VEHICLE THEN COLLIDED TOGETHER. NO ONE WAS INJURED AT THE SCENE.

Will Repair at Lee Luen Sing Motor and Clam at the same workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect



Policyholder's Signature

Date & Time: 9/11/18



Driver's Signature

(if driver is not the policyholder)

Date & Time: 9/11/18



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2153B
Vehicle Details	
Vehicle No.:	SLR2533D
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Nov 2018
Vehicle Make:	B.M.W.
Vehicle Model:	X3 XDRIVE20i ABS 4WD SR HID DSC NAV
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	A3660406N20B20A
Chassis No.:	WBAWX320500B26990
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$39,926.00
Original Registration Date:	19 Apr 2013
First Registration Date:	19 Apr 2013
Transfer Count:	1
Actual ARF Paid:	\$47,897.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Apr 2023
PARF Rebate Amount:	\$33,527.00
Intended COE Rebate Details	
COE Expiry Date:	18 Apr 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$66,989.00
COE Rebate Amount:	\$29,525.00
Total Rebate Amount:	\$63,052.00

The information contained herein is correct as at 22 Nov 2018

OK

Dep 16,610/yr
1384/mile
MV 93,000/-
PV 63,052/-
NV 29,900/-

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Mercedes C180 Avantgarde low mileage. C&C warranty.

Highest trade in value. Brand
new condition. Leasing available.
Price Neg
Speedo Motoring StarAdLake View
Credit Pte Ltd

VIEW OUR CARS

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category









Sort by Date Posted

100 results/page

17 vehicles

BMW X3

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection BMW X3 Any Any 2013 Any Any Any All								
	BMW X3 xDrive20i Sunroof	\$99,800	\$15,630 /yr	30-Aug-2013	1,997 cc	45,339 km	SUV	Available
Graded B by  1 Year Comprehensive Warranty Inclusive! \$5K Down Payment! STA Certified Accident Free Quality Pre-Owned With Low Mileage And Full Agent Service History For Peace Of Mind. 100% Loan Approval With Our ... Cosmo Automobiles Posted: 22-Nov-2018 Tags: 2013 BMW X3, 2013 bmw x3, BMW X3, bmw x3, BMW, X3, x3, Used BMW								
	BMW X3 xDrive20i Sunroof	\$88,800	\$16,610 /yr	11-Jan-2013	1,997 cc	62,000 km	SUV	Available
Well Maintained Tip Top Condition! 100 % Accident Free No Repairs Needed! Flexible Loans And Trade In Available! Call Us For Appointment To Arrange For Viewing Now! Posted: 16-Nov-2018 Tags: 2013 BMW X3, 2013 bmw x3, BMW X3, bmw x3, BMW, X3, x3, Used BMW								
	BMW X3 xDrive30d M-Sport	\$113,000	\$15,790 /yr	09-Sep-2013	2,993 cc	77,000 km	SUV	Available
Fuel Type: Diesel (Euro 5 Engine and Above) Super Rare X3 30D Diesel For Sale. All Wheel Drive System. Can Clock 700-800km Per Full Tank. Full Spec Option PML Unit With HUD Display, Idrive Navigation System, Blue Tooth, Full Leather Semi Bucket... Posted: 14-Nov-2018 Tags: 2013 BMW X3, 2013 bmw x3, BMW X3, bmw x3, BMW, X3, x3, Used BMW								
	BMW X3 xDrive20i	\$99,800	\$15,050 /yr	30-Dec-2013	1,997 cc	92,000 km	SUV	Available
1 Owner Agent Unit! Black With Red Leather Seats. Low Mileage. Warranty Provided! Flexible Loan Options To Cater To Your Financial Needs. Hurry, Call Me Now To View This Spacious SUV! Bank Loan Offer ... Posted: 12-Nov-2018 Tags: 2013 BMW X3, 2013 bmw x3, BMW X3, bmw x3, BMW, X3, x3, Used BMW								
	Ace Motorsports Pte Ltd - Repair & Servicing We strive to provide excellent and professional customer service for our customers and whenever they are in need. More info about this shop							
	BMW X3 xDrive20i Sunroof	\$93,800	\$14,460 /yr	19-Aug-2013	1,997 cc	111,000 km	SUV	Available
One Owner, Agent Unit. Well Maintained And Service. Excellence Condition! No Further Repairs Needed. Original Paintwork With Clean And Neat Interior. Bank Or In-House Loan Available. Purchased With As... Henly Enterprises Co Posted: 12-Nov-2018 Tags: 2013 BMW X3, 2013 bmw x3, BMW X3, bmw x3, BMW, X3, x3, Used BMW								
	BMW X3 xDrive28i Sunroof	\$102,288	\$15,930 /yr	27-Jun-2013	1,997 cc	93,000 km	SUV	Available
Swift And Powerful, Superb Handling, Best Selling SUV, 2.0L Engine Turbo Claims To Be Quicker And Greener, With The All Wheel Drive And BMW Drive Dynamic Control System Can Bring You To Any Terrain, M... Posted: 09-Nov-2018 Tags: 2013 BMW X3, 2013 bmw x3, BMW X3, bmw x3, BMW, X3, x3, Used BMW								

Select used cars to Compare or Add to Alert

Shortlist [1]

Add to Shortlist

Compare Now

Clear All

BMW X3 xDrive20i
Sunroof
11-Jan-2013To compare cars,
select from the
search results.To compare cars,
select from the
search results.To compare cars,
select from the
search results.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Nov 2018		16 Nov 2018 15:55 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	WU JUNWEI, KELVIN		
Vehicle Reg. No.:	SLR2533D	Date of Loss:	08/11/2018 00:00 - :59 [66 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D05312C02	Policy/Cover Note No.:	DMPCSN3031621800
Vehicle Reg. No. (Insured):	SLX5361G	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Lee Luew Sing Motor (HQ) No. 10 Ang Mo Kio Industrial Park 2A, #03-10 AMK Autopoint, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 27/11/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

*SLR2533D (SNM18D05312C02)
[SLX5361G]

TP
WU JUNWEI, KELVIN
Nov 8 2018 12:00AM
[-]
Lee Luew Sing Motor

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/12/18 09:51	General View	1 Load PDF	
2	07/12/18 09:52	Photographs of Damaged Parts	1 Load PDF	
3	07/12/18 09:52	Photo After Spray	1 Load PDF	
Documentation			1 per page ▼	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/11/18 15:55	PRS CONTACT	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118020860/BCD3S2

Date: 14/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3031621800
Claimant Vehicle No :	SLR2533D	Insured Vehicle No :	SLX5361G
Date of Loss:	08/11/2018	Nature of Claim:	TP
		Claim No:	SNM18D05312C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR2533D	Engine No:	A3660406N20B20A
Make & Model:	BMW X3, 2.0 (A)	Chassis No:	WBAWX320500B26990
Reg. Date:	19/04/2013 (Man. Year: 2013)	Odometer:	123600 km
Colour:	Silver		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/50R18	Rear Tyre Size:	245/50R18
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	16/11/2018	Lee Luew Sing Motor (HQ)
Date Inspected:	20/11/2018 Inspected At:	No. 10 Ang Mo Kio Industrial Park 2A, #03-10 AMK Autopoint
Estimated Period of Repair:	5.0 days	Singapore 568047

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$8,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Dec 2018)
Parts:	M1-SUV	BMW X3 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR2533D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >