

ASS. REC. BY:

REF: CS/MSG18020862/Ng d3

Special Instruction:

Survivor:
Mamen

Nq2

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

M81G

Date/Time:

19/11/18 @ 9:40am

Estimated Cost:

Bill to:

OD-TP-WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SME 677S

Insured:

SKL 9673E

at Workshop m/z

Kelh Motor

Tel:

65145248/82886302

of

6A Menderi Estate

Policy No.:

B29080481 MCX

Claim No.:

576177

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13/11/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9:46am @ 19/11/18

Person Contacted:

Anikka

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SME 677S-X

SKL 9673E-X

21/11/18 @ 3:43pm REVISD TO Katherine Wong na Mamen.

Surveyor: NAZ

REF:

MS19

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehl: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Secor: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SME 6775 Yr Regn: 17/9/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA JAZZ 1.3 LXR C.C. 1294

Colour: BROWN A/C: Insured / Std / NI / NA

Sp. Reading: 1,488 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: J11MGR3850JX226817

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 13/11/18 U.O.A. 19/11/18

Survey held at KAH MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
12/3/19	FINALIZED PART BY PART REPAIR @ 6395.70 (5 DAY)
	(Red #3702.14, 3716)
	RECEIVED 12 MAR 2019

Date/Time, File Pass to?

☐ : Preli Report
☐ : Final Report

1) Date/Time, File Return to?

2) _____

Report Format: over-TP

Lump Sum / I.B.I: (\$) 6395.70

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee: 200

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS \$ _____
☐ : Interview (\$ _____) ☐ : Photos
☐ : Tech. Invs (\$ _____) ☐ : Others
☐ : Weekend (\$ _____)

TOTAL

200

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case No.	Insured	Tel Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Authored	Status
15818	15 Nov 2018		19 Nov 2018 09:40 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured	PREMIER RENT A CAR PTE LTD, Co. Reg. No.: 200612929E								
Main Claimant	DANARENHUA, ID: 57583760G								
Vehicle Reg. No.	SME677S	Date of Loss:	13/11/2018 15:00 - :59 [1 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type	TP / 576177	Policy/Cover Note No.:	B29080481MCX (TP, Fire & Theft) Coverage: 01/05/2018 - 30/04/2019						
Vehicle Reg. No. (Insured)	SKL9673E	Policy No. (Claimant):							
		Excess:							
Repairer	Kah Motor Co Sdn Bhd (HQ) 6A MANDAI ESTATE, SINGAPORE 729903, 729903 Mandai - Tel:								
Handling Insurer	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/11/2018]								
Driver/Custodian (Insured)	SPRINGFIELD RALPH EDWARD (), NRIC: 569821787, Tel: +6597842938								
Adj /sg Remarks	Car in today, survey after 11am. liability 100%. TP request to arrange survey on Monday (19 Nov 2018) after 11am, contact: Anikka - 6514 5248 / 8288 6302								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 21 Nov 2018

Preliminary Advice

Insured Vehicle No	: SKL9673E	Accident Date	: 13/11/2018
TP Vehicle No	: SME677S	Assignment Date	: 19/11/2018
Make	: HONDA JAZZ	Est. Duration of Repair	: 4.00
Date of Inspection	: 19/11/2018		
Inspection At	: KAH MOTOR CO SDN BHD (HQ) 6A MANDAI ESTATE, SINGAPORE 729903 SINGAPORE 729903		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,094.39
Revised Amount	:S\$	6,075.64
Check Items (Estimated)	:S\$	549.58
Total	:S\$	6,625.22

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	13/11/2018 21:03
Date Of Accident	13/11/2018 15:50
Exact Location Of Accident	FILTER FROM JURONG EAST ST 11 INTO BOON LAY WAY
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SME977S - 2nd reg veh no
Insured/Policyholder	
Name Of Registered Owner	DANARENHUA
NRIC No	S7583760G
Email Address	NNMM0483@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90885791
Alternative Phone No	OFFICE-90885791
Vehicle Particulars	
Manufacturer	HONDA
Model	JAZZ
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10869298
Cover Note Number	
Driver	
Name of Driver	DANARENHUA
NRIC No	S7583760G
Date Of Birth	13/08/1975
Occupation	INDOOR
Date Of Driving Pass	07/05/2018
Driving Experience	0 YEAR AND 6 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-90885791
Fax Number	
Contact Number	OFFICE-90885791
EMail Address	NNMM0483@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was filtering left from Jurong East St 11 into Boon Lay Way. I stopped my car before the give way line as there were oncoming traffic when car SKL9673E from behind collided onto the rear of my car. Damages to my car were on the rear portion. No injuries were involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKL9673E
Vehicle Make/Model/Colour	NISSAN SYLPHY 1.6 CVT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SPRINGFIELD RALPH EDWARD
NRIC/Passport Number	G3380515U
Contact Number	97842938
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may have permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me in being about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law or administering, processing, handling and/or dealing with my claims.
 - (ii) collectively the "Purposes";
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may have permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER

Muhammad Faizal


Rin Pebble

Witnessed by Reporting Centre Personnel

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was filtering left from Jurong East St 11 into Boon Lay Way. I stopped my car before the give way line as there were oncoming traffic when car SKL9673E from behind collided onto the rear of my car. Damages to my car were on the rear portion. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD FAIZAL BIN PABILA

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

13 November 2018 at 7:36 PM

Date/Time:

13 November 2018 at 7:36 PM

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Monday

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581

Registration No : SME677S

Chassis No : JHMGK3850JX226817

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : DANARENHUA

Ins Policy No. :

Date of Accident : 13/11/2018

Document No. : SQT18004907 Page 1

Date : 15. Nov 2018

Customer No. : WZM003

Svc Advisor :

Engine No : L13B11031168

Date | Time : 15. Nov 2018 7:44:42 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: OWNER: MS DANARENHUA OWNER INSURER: AVIVA ACC DATE: 13/11/2018 SURVEYED BY: DATE: REF NO: TP INSURER: MSIG TP VEH: <i>SKL9673E</i>						
68100-TAR-U10ZZ	TAILGATE COMP	1	730.60	25	547.95 ✓	38.36	586.31 ✓
68210-T5A-J03ZZ	HINGE COMPTAILGATE	1	30.80	25	23.10	1.62	24.72 ? X
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07 ? X
74801-T5S-K01	LOCK ASSY, TAILGATE	1	78.90	25	59.17	4.14	63.31 ? X
04715-T5A-J50ZZ	FACE, RR.BUMPER	1	492.70	25	369.52 ✓	25.87	395.39 ✓
71593-T5A-J50	SPACER, R.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56 ? X
71598-T5A-J50	SPACER, L.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56 ? X
91505-TM8-003	CLIP, BUMPER	7	2.30	25	12.07 ✓	0.84	12.91 ? X
71505-T5A-J50	GARNISH, RR.BUMPER	1	38.30	25	28.72 ✓	2.01	30.73 ? X
71507-T5A-J60	COVER, L.RR.BUMPER	1	20.70	25	15.52 ✓	1.09	16.61 ? X
71502-T5A-J60	COVER, R.RR.BUMPER	1	20.70	25	15.52	1.09	16.61 ? X
66100-TAR-T00ZZ	PANEL COMPRR.	1	320.40	25	240.30 ✓	16.82	257.12 ? X
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40 X ✓
BO-NUM-CASE	NUMBER PLATE CASING-L (N)	1	20.00		20.00	1.40	21.40 X ✓
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.40	25	8.55	0.60	? 9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER	1	6.50	25	4.87	0.34	? 5.21 X
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	? 6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20 X
75722-T5L-T01	EMBLEMRR.	1	10.90	25	8.17 ✓	0.57	8.74 ✓
Sum Item					1834.39	128.43	1,962.82



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SME677S
Chassis No : JHMGK3850JX226817
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : DANARENHUA
Ins Policy No. :
Date of Accident : 13/11/2018

Document No. : SQT18004907
Date : 15. Nov 2018
Customer No. : WZM003
Svc Advisor :
Engine No : L13B11031168
Date | Time : 15. Nov 2018 7:44:42 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT END PANEL	1	100.00	80	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00	80	100.00	7.00	107.00
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00	80	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	140.00	80	140.00	9.80	149.80
BOMISC1	REMOVE & INSTALL REAR VIEW CAMERA (N)	1	220.00		220.00	15.40	235.40
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	600.00	280	600.00	42.00	642.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	600.00	280	600.00	42.00	642.00
BKRP02S	CUT & RENEW RR PANEL & RENEW DAMAGE PARTS.	1	3300.00	1,080/2,240	3300.00	231.00	3531.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	3000.00	900/1,800	3000.00	210.00	3210.00
Sum Labor					8260.00	578.20	8,838.20

Survey By

Date & Time

Excess

Status

Signature

Total Amount 10,094.39 706.63 10,801.02

Total (Inclusive of GST) 10,801.02

NAZ LKK

19/11/18

P/c

4 Days

- CHECK ITEMS PHOTOS

- BEFORE PAINT PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is permitted
- Supplementary work must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 15/11/2018 8:03:22 PM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)

10094.84

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
 Chassis No: JHMGK3850JX226817
 License No: SME677S
 Mileage: 1488
 Engine No: L13B11031168

Document No: SVO18068687
 Printed By: ANIKKALAI
 Order Date: 19. November 2018
 Order Time: 4:29:36 PM
 Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	incld GST
	TP DIRECT SETTLEMENT (J/NO: OWNER: MS DANARENHUA OWNER INSURER: AVIVA ACC DATE: 13/11/2018 SURVEYED BY: NAZ / LKK DATE: 19/11/2018 REF NO: 576177 (Katherine Wong) TP INSURER: MSIG TP VEH: SKL9673E ADDITIONAL PART						
68100-TAR-U10ZZ	TAILGATE COMP	1	730.60	25	547.95	38.36	586.31
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	492.70	25	369.52	25.87	395.39
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
71505-T5A-J50	GARNISH,RR.BUMPER	1	38.30	25	28.72	2.01	30.73
71507-T5A-J60	COVER,L,RR.BUMPER	1	20.70	25	15.52	1.09	16.61
66100-TAR-T00ZZ	PANEL COMPRR.	1	320.40	25	240.30	16.82	257.12
75722-T5L-T01	EMBLEMRR.	1	10.90	25	8.17	0.57	8.74
90661-SC7-003	GROMMET SCREW	2	2.30	25	3.45	0.24	3.69
	SUM PARTS:				1,225.70	85.80	1,311.50
BOSUN		1	30.00		30.00	2.10	32.10
	SUNDRIES						
BOJSE	1718	1	80.00		80.00	5.60	85.60
	BODY JOINT SEALANT END PANEL						
BOJSE	1718	1	80.00		80.00	5.60	85.60
	BODY JOINT SEALANT TAILGATE						
BODAMKIT		1	80.00		80.00	5.60	85.60
	WINDSCREEN DAM KIT.						
BA02R	1729	1	80.00		80.00	5.60	85.60
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BOMISC1	1438	1	220.00		220.00	15.40	235.40
	REMOVE & INSTALL REAR VIEW CAMERA (N)						
BKTG02R	1729	1	280.00		280.00	19.60	299.60
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)						
BMI03D	1438	1	280.00		280.00	19.60	299.60
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)						
BKRP02S	1729	1	2,240.00		2,240.00	156.80	2,396.80
	CUT & RENEW RR PANEL & RENEW DAMAGE PARTS.						
BP05R	1718	1	1,800.00		1,800.00	126.00	1,926.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)						
	SUM LABOUR:				5,170.00	361.90	5,531.90
	TOTAL SGD				6,395.70	447.70	6,843.40

Total Payable (SGD)

6,843.40



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: S7583760G / DANARENHUA
Chassis No: JHMGK3850JX226817
License No: SME677S
Mileage: 1488
Engine No: L13B11031168

Document No: SVO18068687
Printed By: ANIKKALAI
Order Date: 19. November 2018
Order Time: 4:29:36 PM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Incl GST
90061-SC7-003	ADDITIONAL PART GROMMET SCREW	2	2.30	25	3.45	0.24	3.69
SUM PARTS:					3.45	0.24	3.69
TOTAL SGD					3.45	0.24	3.69

Total Payable (SGD) 3.69

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: S7583760G / DANARENHUA
Chassis No: JHMGK3850JX226817
License No: SME677S
Mileage: 1488
Engine No: L13B11031168

Document No: SVO18068687
Printed By: ANIKKALAI
Order Date: 19. November 2018
Order Time: 4:29:36 PM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incl'd GST
90661-SC7-003	ADDITIONAL PART GROMMET SCREW	2	2.30	25	3.45	0.24	3.69
	SUM PARTS:				3.45	0.24	3.69
	TOTAL SGD				3.45	0.24	3.69
	Total Payable (SGD)						3.69

GST Amount is calculated from individual line(s)

PARTS \$1225.70
LABOUR \$5170.00
TOTAL \$6395.70 / 5 DAYS

FINALIZED PART BY PART REPAIR \$6395.70 / 5 DAYS

NAZUK
H

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Nov 2018		19 Nov 2018 09:40 Edit Adj Rpt	S\$6,395.70 Edit Estimates	S\$6,395.70 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	PREMIER RENT A CAR PTE LTD , Co. Reg. No.: 200612929E								
Main Claimant:	DANARENHUA , ID: S7583760G								
Vehicle Reg. No.:	SME677S	Date of Loss:	13/11/2018 15:00 - :59 [1 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 576177	Policy/Cover Note No.:	B29080481MCX (TP, Fire & Theft) Coverage: 01/05/2018 - 30/04/2019						
Vehicle Reg. No. (Insured):	SKL9673E	Policy No. (Claimant):							
		Excess:							
Repairer:	Kah Motor Co Sdn Bhd (HQ) 6A MANDAI ESTATE, SINGAPORE 729903, 729903 Mandai - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 19/12/2018]								
Driver/Custodian (Insured):	SPRINGFIELD RALPH EDWARD (), NRIC: 569821787, Tel: +6597842938 Email:								
Adj Asg. Remarks:	Car in today, survey after 11am. liability 100%. TP request to arrange survey on Monday (19 Nov 2018) after 11am. contact: Anikka - 6514 5248 / 8288 6302								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SME677S (576177)
[SKL9673E]
TP
DANARENHUA
Nov 13 2018 3:00PM
[PREMIER RENT A CAR PTE LTD]
Kah Motor Co Sdn Bhd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	19/11/18 08:55	Accident Statement From: SC - Reg. No: SKL9673E, Claimant: PREMIER RENT A CAR PTE LTD	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/11/18 15:43	Adjuster Immediate Advice	1	Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/03/19 17:46	General View	1	Load JPG	☒
2	07/03/19 17:46	General View	1	Load JPG	☒
3	07/03/19 17:46	General View	1	Load JPG	☒
4	07/03/19 17:46	General View	1	Load JPG	☒
5	07/03/19 17:46	General View	1	Load JPG	☒
6	07/03/19 17:46	General View	1	Load JPG	☒
7	07/03/19 17:46	General View	1	Load JPG	☒
8	07/03/19 17:46	General View	1	Load JPG	☒
9	07/03/19 17:46	General View	1	Load JPG	☒
10	07/03/19 17:46	General View	1	Load JPG	☒
11	07/03/19 17:46	General View	1	Load JPG	☒
12	07/03/19 17:46	General View	1	Load JPG	☒
13	07/03/19 17:46	General View	1	Load JPG	☒
14	07/03/19 17:46	General View	1	Load JPG	☒
15	07/03/19 17:46	General View	1	Load JPG	☒
16	07/03/19 17:46	General View	1	Load JPG	☒
17	07/03/19 17:46	General View	1	Load JPG	☒
18	07/03/19 17:46	General View	1	Load JPG	☒
19	07/03/19 17:46	General View	1	Load JPG	☒
20	07/03/19 17:46	General View	1	Load JPG	☒
21	07/03/19 17:46	General View	1	Load JPG	☒
22	07/03/19 17:46	General View	1	Load JPG	☒
23	07/03/19 17:46	General View	1	Load JPG	☒
24	07/03/19 17:46	General View	1	Load JPG	☒
25	07/03/19 17:46	General View	1	Load JPG	☒
26	07/03/19 17:46	General View	1	Load JPG	☒
27	07/03/19 17:46	General View	1	Load JPG	☒
28	07/03/19 17:46	Dismantled Parts	1	Load JPG	☒
29	07/03/19 17:46	Dismantled Parts	1	Load JPG	☒
30	07/03/19 17:46	Dismantled Parts	1	Load JPG	☒
31	07/03/19 17:46	Dismantled Parts	1	Load JPG	☒
32	07/03/19 17:46	Dismantled Parts	1	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	07/03/19 17:46	Dismantled Parts	Load JPG	☒
34	07/03/19 17:46	Dismantled Parts	Load JPG	☒
35	07/03/19 17:46	Dismantled Parts	Load JPG	☒
36	07/03/19 17:46	Dismantled Parts	Load JPG	☒
37	07/03/19 17:46	Dismantled Parts	Load JPG	☒
38	07/03/19 17:46	Dismantled Parts	Load JPG	☒
39	07/03/19 17:46	Dismantled Parts	Load JPG	☒
40	07/03/19 17:47	Replacement Part Photo	Load JPG	☒
41	07/03/19 17:47	Replacement Part Photo	Load JPG	☒
42	07/03/19 17:47	Replacement Part Photo	Load JPG	☒
43	07/03/19 17:47	Replacement Part Photo	Load JPG	☒
44	07/03/19 17:47	Replacement Part Photo	Load JPG	☒
45	07/03/19 17:47	Replacement Part Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/11/18 08:50	TP ESTIMATE	Load PDF	
2	19/11/18 08:55	SME677S E-FILE REPORT From: SC - Reg. No: SKL9673E, Claimant: PREMIER RENT A CAR PTE LTD	Load PDF	
3	19/11/18 08:58	email to arrange survey	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/03/19 14:51	SUPPLEMENTARY PART	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18020862/NQD3Q2

Date: 18/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B29080481MCX

Claimant Vehicle No: SME677S

Insured Vehicle No: SKL9673E

Date of Loss: 13/11/2018

Nature of Claim: TP

Claim No: 576177

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME677S

Make & Model: HONDA JAZZ, 1.3 CVT (A)

Engine No: L13B11031168

Reg. Date: 17/09/2018 (Man. Year: 2018)

Chassis No: JHMGK3850JX226817

Colour: Brown

Odometer: 1488 km

Engine Capacity: 1318 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R15

Rear Tyre Size: 175/65 R15

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,937.84	1,255.70	682.14	35.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,160.00	5,140.00	3,020.00	37.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,097.84	6,395.70	3,702.14	36.66
+ GST 7.00/7.00% (S\$)	706.85	447.70	259.15	36.66
Nett Amount (S\$)	10,804.69	6,843.40	3,961.29	36.66

INSPECTION

Date of Assignment: 19/11/2018

Date Inspected: 19/11/2018 Inspected At:

Kah Motor Co Sdn Bhd (HQ)
6A MANDAI ESTATE, SINGAPORE
729903
Singapore 729903

Estimated Period of Repair: 5.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Mar 2019)
Parts: 144	HONDA JAZZ 1.3 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SME677S)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE COMP	Dented	547.95 FS	*547.95 FS
2	1		*HINGE COMPTAILGATE	Serviceable	23.10 FS	*- FS
3	1		*WEATHERSTRIPTAILGATE	Serviceable	69.22 FS	*- FS
4	1		*LOCK ASSY ,TAILGATE	Serviceable	59.17 FS	*- FS
5	1		*FACE,RR.BUMPER	Cracked	369.52 FS	*369.52 FS
6	1		*SPACER,R.RR.BUMPER SIDE	Serviceable	12.67 FS	*- FS
7	1		*SPACER,L.RR.BUMPER SIDE	Serviceable	12.67 FS	*- FS
8	1		*CLIP,BUMPER (7 PCS)	Necessary	12.07 FS	*12.07 FS
9	1		*GARNISH,RR.BUMPER	Cracked	28.72 FS	*28.72 FS
10	1		*COVER,L.RR.BUMPER	Cracked	15.52 FS	*15.52 FS
11	1		*COVER,R.RR.BUMPER	Serviceable	15.52 FS	*- FS
12	1		*PANEL COMPRR	Deformed	240.30 FS	*240.30 FS
13	4		*ACT RR.SENSOR	Serviceable	320.00 FS	*- FS
14	1		*NUMBER PLATE CASING-L	Serviceable	20.00 FS	*- FS
15	1		*RUBBER CWINDSHIELD DAMPER	Serviceable	8.55 FS	*- FS
16	1		*RUBBERWINDSHIELD DAMPER	Serviceable	4.87 FS	*- FS
17	1		*DAMPERSTD 5X5	Serviceable	6.37 FS	*- FS
18	1		*WINDSCREEN SEALANT	Serviceable	60.00 FS	*- FS
19	1		*EMBLEMRR	Necessary	8.17 FS	*8.17 FS
20	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
21	1		*GROMMET SCREW (2 PCS)	Necessary	3.45 FS	*3.45 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	1,937.84	1,255.70
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	BODY JOINT SEALANT END PANEL	New	100.00	80.00
2	BODY JOINT SEALANT TAILGATE	New	100.00	80.00
3	WINDSCREEN DAM KIT	New	100.00	80.00
4	REMOVE & RENEW REVERSE SENSORS	New	140.00	80.00
5	REMOVE & INSTALL REAR VIEW CAMERA	New	220.00	220.00
6	REMOVE & TRANSFER ITEMS TO NEW TAILGATE.ADJUST &	New	600.00	280.00
7	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	600.00	280.00
8	CUT & RENEW RR PANEL & RENEW DAMAGE PARTS	New	3,300.00	2,240.00
9	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,000.00	1,800.00
Gross Labour Cost (S\$)			8,160.00	5,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >