

ASS. REC. BY:

REF:

CS3/AIG18020868/Jcd3b

Special Instruction:

Surveyor:

Hwee Jee

ASSIGNMENT (Office)

From (Person):

chin Jee Ying

of

AIG

Date/Time:

19/11/18 @ 10:55am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLN 1625A

Insured:

SLU 1088M

at Workshop in/s

Choon Hock Autocare

Tel:

64530778

of

176 Sin Ming Drive #05-03

Policy No.:

1700079958

Claim No.:

78655959998G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/11/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:27am @ 19/11/18

Person Contacted:

Mr. AU

Vehicle IN OUT

Date/Time

Action/Instruction (X) Estimate

SLN 1625A - X

SLU 1088M - X

Dismantle: 20/11/2018.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of 176 Sin ming Dr #05-03
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN 1625A Yr Regn: 25 Apr 2017
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Kia Cerato K3 CC: 1591
 Colour: Red A/C: Insured / Std / NI / NA
 Sp Reading: 84544 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: KNAFX411MH5705519
 Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRM / STD A/Rim or

Tyre Size: F: 205/55 R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Road Stone

| | | | |
|------------------------|--|------------------------|--|
| Front | | Rear | |
| R/Bal. <u>6</u> mm | | R/Bal. <u>6</u> mm | |
| L/Bal. <u>6</u> mm | | L/Bal. <u>6</u> mm | |
| D.O.A. <u>14/11/18</u> | | D.O.I. <u>19/11/18</u> | |

Survey held at Choon Hock @ 1520

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6 4 days

Date/Time: File Pass to?

: Preli. Report
 : Final Report

Days Of Repair: 6

1) _____
 Date/Time: File Return to?

Resurvey No. of Trip: 2

2) _____

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee
 Transportation
) \$ + RS. \$

Report Format : DAR

Lump Sum / I.B.I: (\$)

) Photos
) Other

TOTAL

| |
|-----|
| 180 |
| 20 |
| 200 |

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 19/11/2018 10:55:06 AM
Attachments:  18_1589 PR.PDF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Friday, November 16, 2018 3:05 PM
To: Azlan, Syazairdina
Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU1088M AND SLN1625A ON 14/11/2018

Dear Sirs,

We confirm that you have **objected** to our client's list of surveyors. Our client's vehicle is at the following address:

Choon Hock AutoCare Pte Ltd

Blk 176 Sin Ming Drive

#05-03 Sin Ming AutoCare

Singapore 575721

Tel: **64530778**

Please inform your surveyor to conduct the pre-repair survey within 2 working days, failing which our client will have no alternative but to proceed with the repair of his vehicle.

Thanks / Rgds,

Lena

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|--------------------------------------|
| Owner ID Type: | Business |
| Owner ID: | 5245A |
| Vehicle Details | |
| Vehicle No.: | SLN1625A |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 21 Nov 2018 |
| Vehicle Make: | KIA |
| Vehicle Model: | CERATO K3 1.6A |
| Primary Colour: | Red |
| Manufacturing Year: | 2017 |
| Engine No.: | G4FGGH651197 |
| Chassis No.: | KNAFX411MH5705519 |
| Maximum Power Output: | 95.3 kW (127 bhp) |
| Open Market Value: | \$13,048.00 |
| Original Registration Date: | 25 Apr 2017 |
| First Registration Date: | 25 Apr 2017 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$13,048.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 24 Apr 2027 |
| PARF Rebate Amount: | \$9,786.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 24 Apr 2027 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$51,765.00 |
| COE Rebate Amount: | \$43,612.00 |
| Total Rebate Amount: | \$53,398.00 |

The information contained herein is correct as at 21 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|--------------------|
| Date Of Report | 15/11/2018 16:53 |
| Date Of Accident | 14/11/2018 18:35 |
| Exact Location Of Accident | UPPER SERANGOON RD |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SLN1625A |
| Insured/Policyholder | |
| Name Of Registered Owner | MISIR TRANSPORT |
| Co Reg No | NA 53355246A |
| Email Address | ANANDMISIR@YMAIL.COM |
| Mobile Phone No | (LOCAL) +65-96972577 |
| Alternative Phone No | OFFICE-NOPHONE |

Vehicle Particulars

| | |
|--|--------------|
| Manufacturer | KIA |
| Model | CERATO K3 |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE HIRE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|---------------------------|
| Name of Insurance Company | LIBERTY INSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | SD18V03358/VPL/R00 |
| Cover Note Number | 25/04/2018 TO 24/04/2019 |

Driver

| | |
|----------------------|--------------------------------------|
| Name of Driver | SACHITHANAND MISIR S/O RAMPHER MISIR |
| NRIC No | S7231786F |
| Date Of Birth | 28/08/1972 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 21/10/1997 |
| Driving Experience | 21 YEARS AND 0 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-96972577 |
| Fax Number | |
| Contact Number | |
| Email Address | ANANDMISIR@YMAIL.COM |

Address APT BLK 577 HOUGANG AVE 4 #10-668
 Postcode 530577
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : SEEMAMISHRA
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name HOUGANG NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4890999 - FAX NO: 63128989
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN & POLICE REPORT NO. T/20181115/2050 DATED 15/11/2018

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLU1088M
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver HEAH KWAN SEEK
 NRIC/Passport Number S9008496H
 Contact Number
 Address
 Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SFX9317E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver CHIONG WEI ZHONG ALVIN
NRIC/Passport Number S9423614B
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SACHITHANAND MISIR S/O RAMPHER MISIR
Approximate Age
Injuries Sustain BACK & LEG
Injured person in which vehicle? SLN1625A
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name SEEMAMISHRA
Approximate Age
Injuries Sustain NECK & HEAD
Injured person in which vehicle? SLN1625A
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN

*Liberty
Insurance*

Vehicle: - SLN 1622 A

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

MISIR TRANSPORT
Co Reg No: 53365245A

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


15/11/2018



Ma Lu
15/11/2018

Sketch Plan Pg. 2

Date of accident: 14/11/18 Time: 18:35 Location: UPPER SERANJUN RD
 My Vehicle A: SLN165A Vehicle B: SLV1088 M Vehicle C: SFX 9317E
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG UPPER SERANJUN RD TOWARD HONGKAY AND IT WAS SLOW TRAFFIC I SLOW DOWN AND ~~STOP~~ SUDDENLY I WAS HIT VERY HARD AND WAS A HEAVY IMPACT THAT MY WIFE S757294H SEPERA INJURED AND SHE ITAILED BACK PAIN AS I COME OUT I SAW SLV1088 M HIT MY BACK OF MY CAR AND THE OTHER SFX 9317E HIT THE SIDE CAR

Claim OD/TP at Ah Lim Motor Claim OD/TP at other workshop Reporting Only

Remarks : Please forward a copy of my efile accident report to :
 My workshop : CHOON HOCK AUTO
 Email address : choonhock@gmail.com
 & myself :
 Email address : ahlim.motor@gmail.com

Note : Please take note that your Insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own Insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Vehicle SLN 165A

MISIR TRANSPORT
 Co Reg No: 5335245A

Policyholder's Signature

Date & Time:

[Signature]
15/11/2018

Driver's Signature


(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



Ma Lu

15/11/2018

MOTORCAR (Rear)

Rear Portion

Vehicle No: **SLN 1625A**

| NAC | INC | Item | CON | AC | Qty |
|------|--------|----------------------------------|-----|----|-----|
| 1137 | 993626 | Rear Number Plate | | | |
| 1138 | 993627 | Rear Number Plate Base | | | |
| 1139 | 993630 | Rear Number Plate Garnish | | | |
| 1140 | 993632 | Rear Number Plate Lamp | | | |
| 1141 | 992958 | Rear Bumper | DD | ✓ | 1 |
| 1142 | 993085 | Rear Bumper Upper | | | |
| 1143 | 993017 | Rear Bumper Lower | | | |
| 1144 | 993054 | Rear Bumper Side | | | |
| 1145 | 993103 | Rear Bumper Tow Cover | | | |
| 1146 | 992341 | Rear Bumper Clips | NEC | ✓ | |
| 1147 | 992976 | Rear Bumper Bracket | | | |
| 1148 | 993068 | Rear Bumper Side Retainer(LH,RH) | CRA | ✓ | 2 |
| 1149 | 993045 | Rear Bumper Reinforcement | DD | ✓ | |
| 1150 | 992970 | Rear Bumper Beam | | | |
| 1151 | 993077 | Rear Bumper Sponge | CRA | ✓ | 1 |
| 1152 | 992999 | Rear Bumper Damper | | | |
| 1153 | 993040 | Rear Bumper Protector | | | |
| 1154 | 993036 | Rear Bumper Pad | | | |
| 1155 | 993026 | Rear Bumper Moulding | | | |
| 1156 | 993044 | Rear Bumper Reflector (LH,RH) | CRA | ✓ | 2 |
| 1157 | 993023 | Rear Bumper Lower Spoiler | DD | ✓ | 1 |
| 1158 | 994023 | Reverse Sensor | DD | ✓ | 1 |
| 1159 | 993327 | Rear End Panel | DD | ✓ | 1 |
| 1160 | 993339 | Rear End Panel Top Garnish | CRA | ✓ | 1 |
| 1161 | 993333 | Rear End Panel Inner Trim | | | |
| 1162 | 990333 | Boot Compartment Inner Trim | | | |
| 1163 | 993851 | Rear LH Taillamp | | | |
| 1164 | 993853 | Rear LH Taillamp Garnish | | | |
| 1165 | 993859 | Rear LH Taillamp Panel | | | |
| 1166 | 995116 | Rear RH Taillamp | | | |
| 1167 | 993853 | Rear RH Taillamp Garnish | | | |
| 1168 | 993859 | Rear RH Taillamp Panel | | | |
| 1169 | 993554 | Rear Apron Panel | | | |
| 1170 | 992895 | Bootlid | DD | ✓ | 1 |
| 1171 | 991328 | Bootlid Emblem | NEC | ✓ | 3 |
| 1172 | 990356 | Bootlid Handle | | | |
| 1173 | 995250 | Bootlid Moulding | | | |
| 1174 | 990376 | Bootlid Reflector | | | |
| 1175 | 995222 | Bootlid Lamp LH | | | |
| 1176 | 992899 | Bootlid Lamp RH | | | |
| 1177 | 995243 | Bootlid Lock | BT | ✓ | |
| 1178 | 990377 | Bootlid Rubber | DD | ✓ | |
| 1179 | 990382 | Bootlid Hinge | | | |
| 1180 | 993877 | Bootlid Spoiler | | | |
| 1181 | 994543 | Tailgate | | | |
| 1182 | 991328 | Tailgate Emblem | | | |
| 1183 | 994643 | Tailgate Outer Handle | | | |
| 1184 | 994640 | Tailgate Moulding | | | |
| 1185 | 994545 | Tailgate Garnish | | | |
| 1186 | 994648 | Tailgate Reflector | | | |
| 1187 | 994549 | Tailgate Lamp | | | |
| 1188 | 994646 | Tailgate Protector | | | |
| 1189 | 994676 | Tailgate Wiper Arm | | | |
| 1190 | 994677 | Tailgate Wiper Blade | | | |
| 1191 | 994679 | Tailgate Wiper Nozzle | | | |
| 1192 | 994555 | Tailgate Wiper Motor | | | |
| 1193 | 994602 | Tailgate Glass | | | |
| 1194 | 994606 | Tailgate Glass Rubber | | | |
| 1195 | 994604 | Tailgate Glass Moulding | | | |
| 1196 | 994607 | Tailgate Glass Sealant | | | |
| 1197 | 994629 | Tailgate Lock | | | |
| 1198 | 994651 | Tailgate Rubber | | | |
| 1199 | 994611 | Tailgate Hinge | | | |
| 1200 | 994594 | Tailgate Damper | | | |
| 1201 | 994613 | Tailgate Inner Board | | | |

| NAC | INC | Item | CON | AC | Qty |
|------|--------|--------------------------------|-----|----|-----|
| 1202 | 993784 | Spare Tyre Board | | | |
| 1203 | 994328 | Spare Tyre Panel | | | |
| 1204 | 995065 | Spare Tyre | | | |
| 1205 | 994326 | Spare Tyre Lock Screw | | | |
| 1206 | 993787 | Spare Tyre Cover | | | |
| 1207 | 995323 | Triangle Breakdown Sign | | | |
| 1208 | 990507 | CD Changer Assy | | | |
| 1209 | 990164 | Antenna | | | |
| 1210 | 990534 | Centre Exhaust Pipe Assy | DD | R | |
| 1211 | 990532 | Centre Exhaust Mounting | | | |
| 1212 | 993364 | Rear Exhaust Pipe | | | |
| 1213 | 993357 | Rear Exhaust Chrome Pipe | | | |
| 1214 | 993361 | Rear Exhaust Mounting | | | |
| 1215 | 993358 | Rear Exhaust Heat Shield | | | |
| 1216 | 995223 | Rear LH Chassis Member | | | |
| 1217 | 993165 | Rear RH Chassis Member | | | |
| 1218 | 993436 | Rear LH Fender | | | |
| 1219 | 993449 | Rear LH Fender Protector | | | |
| 1220 | 993420 | Rear LH Fender Inner Panel | | | |
| 1221 | 993431 | Rear LH Fender Inner Trim | | | |
| 1222 | 993415 | Rear LH Fender Inner Garnish | | | |
| 1223 | 993425 | Rear LH Fender Inner Shield | | | |
| 1224 | 993621 | Rear LH Mudflap | | | |
| 1225 | 993933 | Rear LH Wheel Rim | | | |
| 1226 | 994025 | Rear LH Rim Cover | | | |
| 1227 | 995065 | Rear LH Tyre | | | |
| 1228 | 993456 | Rear RH Fender | | | |
| 1229 | 993450 | Rear RH Fender Protector | | | |
| 1230 | 993420 | Rear RH Fender Inner Panel | | | |
| 1231 | 993431 | Rear RH Fender Inner Trim | | | |
| 1232 | 993415 | Rear RH Fender Inner Garnish | | | |
| 1233 | 993425 | Rear RH Fender Inner Shield | | | |
| 1234 | 993622 | Rear RH Mudflap | | | |
| 1235 | 993934 | Rear RH Wheel Rim | | | |
| 1236 | 994025 | Rear RH Rim Cover | | | |
| 1237 | 995065 | Rear RH Tyre | | | |
| 1238 | 995162 | Rear Fender Extension Panel LH | | | |
| 1239 | 993401 | Rear Fender Extension Panel RH | | | |
| 1240 | 993430 | Rear Fender Inner Top Garnish | | | |
| 1241 | 993673 | Rear Fender 1/4 Glass | | | |
| 1242 | 993452 | Rear Fender 1/4 Glass Rubber | | | |
| 1243 | 993453 | Rear Fender 1/4 Glass Sealant | | | |
| 1244 | 993949 | Rear Windscreen Glass | | | |
| 1245 | 993976 | Rear Windscreen Rubber | | | |
| 1246 | 993961 | Rear Windscreen Moulding | | | |
| 1247 | 993955 | Rear Windscreen Sealant | | | |
| 1248 | 994729 | Third Brake Light | | | |
| 1249 | 993385 | Rear Fender Air Grille | | | |
| 1250 | 992167 | Fuel Lid | | | |
| 1251 | 992168 | Fuel Neck | | | |
| 1252 | 992179 | Fuel Tank | | | |
| 1253 | 992184 | Fuel Tank Bracket | | | |
| 1254 | 992191 | Fuel Tank Float | | | |
| 1136 | 990247 | Sticker | | | |

[Handwritten Signature]
 23/11/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|---|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 16 Nov 2018 Edit Reg | | 19 Nov 2018 00:00 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|--|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | HEAH KWAN SEEK , ID: S9008496H | | | | | | | | |
| Main Claimant: | - | | | | | | | | |
| Vehicle Reg. No.: | SLN1625A | Date of Loss: | 14/11/2018 00:00 - :59 [18 Months and 20 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 7865595999SG | Policy/Cover Note No.: | 1700079958 (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): | SLU1088M | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Choon Hock Autocare Pte Ltd (HQ) Blk 176 Sin Ming Drive #05-03, Sin Ming AutoCare Singapore 575721, 575721 Sin Ming - Tel: 64530778 | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 28/11/2018] | | | | | | | | |
| Claimant's Solicitor: | KURU & CO - Tel: 65322009 | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| • AIG_SG (20/11/2018): Request to upload TP GIA Report | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SLN1625A (7865595999SG)
[SLU1088M]

TP

Nov 14 2018 12:00AM
[HEAH KWAN SEEK]
Choon Hock Autocare Pte Ltd

| Upload Documents | | Upload Photos | | Compose New Letter | | Upload Video | | Upload Audio | | View | | View in Browser | |
|----------------------|-----------------|-----------------------------------|--|--------------------|--|--------------|--|--------------|--|------------|-------------------------------------|-----------------|--|
| Photos/Images | | | | | | | | | | 3 per page | <input checked="" type="checkbox"/> | | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | Thumbnail | Print | | | | |
| 1 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 2 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 3 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 4 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 5 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 6 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 7 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 8 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 9 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 10 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 11 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 12 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 13 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 14 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 15 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 16 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 17 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 18 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 19 | 21/11/18 17:48 | General View | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 20 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 21 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 22 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 23 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 24 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 25 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 26 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 27 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 28 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 29 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 30 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 31 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 32 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 33 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 34 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 35 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 36 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |
| 37 | 21/11/18 17:49 | Photographs of Damaged Parts | | | | | | | Load JPG <input checked="" type="checkbox"/> | | | | |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|---|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 38 | 21/11/18 17:49 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 21/11/18 17:49 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 21/11/18 17:49 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 21/11/18 17:49 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 21/11/18 17:49 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 21/11/18 17:49 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 21/11/18 17:49 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 21/11/18 17:49 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 21/11/18 17:49 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 21/11/18 17:49 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 21/11/18 17:49 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 07/12/18 11:20 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 07/12/18 11:20 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 07/12/18 11:20 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 07/12/18 11:20 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 1 | 20/11/18 09:44 | OI GIA REPORT |  Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTOur File No: CS3/AIG18020868/JCD3 E2
Date: 17/12/2018REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 1700079958 |
| Claimant Vehicle No : | SLN1625A | Insured Vehicle No : | SLU1088M |
| Date of Loss: | 14/11/2018 | Nature of Claim: | TP |
| | | Claim No: | 7865595999SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SLN1625A | Engine No: | G4FGGH651197 |
| Make & Model: | KIA CERATO K3, 1.6 (A) | Chassis No: | KNAFX411MH5705519 |
| Reg. Date: | 25/04/2017 (Man. Year: 2017) | Odometer: | 84544 km |
| Colour: | Red | | |
| Engine Capacity: | 1591 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size: | 205/55 R16 | Rear Tyre Size: | 205/55 R16 |
| Front Left Side: | Roadstone 6 mm | Rear Left Side: | Roadstone 6 mm |
| Front Right Side: | Roadstone 6 mm | Rear Right Side: | Roadstone 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

| | | |
|-----------------------------|------------|--|
| Date of Assignment: | 19/11/2018 | |
| Date Inspected: | 19/11/2018 | Inspected At: Choon Hock Autocare Pte Ltd (HQ) Blk 176 Sin Ming Drive #05-03, Sin Ming AutoCare Singapore 575721 Singapore 575721 |
| Estimated Period of Repair: | 6.0 days | |

Adjuster: ONG HWEE JIE**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|--------------------------|-----|----------|-----------------------------------|-----------|-------------|-------------|
| 1 | 1 | | *REAR BUMPER | Dented | 0.00 F | *- F |
| 2 | 1 | | *REAR BUMPER CLIPS | Necessary | 0.00 F | *- F |
| 3 | 2 | | *REAR BUMPER SIDE RETAINER LH, RH | Cracked | 0.00 F | *- F |
| 4 | 1 | | *REAR BUMPER REINFORCEMENT | Dented | 0.00 F | *- F |
| 5 | 1 | | *REAR BUMPER SPONGE | Cracked | 0.00 F | *- F |
| 6 | 2 | | *REAR BUMPER REFLECTOR (LH,RH) | Cracked | 0.00 F | *- F |
| 7 | 1 | | *REAR BUMPER LOWER SPOILER | Dented | 0.00 F | *- F |
| 8 | 1 | | *REVERSE SENSOR | Shorted | 0.00 F | *- F |
| 9 | 1 | | *REAR END PANEL | Dented | 0.00 F | *- F |
| 10 | 1 | | *REAR END PANEL TOP GARNISH | Cracked | 0.00 F | *- F |
| 11 | 1 | | *BOOTLID | Dented | 0.00 F | *- F |
| 12 | 3 | | *BOOTLID EMBLEM | Necessary | 0.00 F | *- F |
| 13 | 1 | | *BOOTLID LOCK | Bent | 0.00 F | *- F |
| 14 | 1 | | *BOOTLID RUBBER | Dented | 0.00 F | *- F |
| 15 | 1 | | *CENTRE EXHAUST PIPE ASSY | Repair | 0.00 F | *- F |
| Total Parts (S\$) | | | | | 0.00 | 0.00 |

F=Franchise part.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >