

ASS. REC. BY:

REF

CS3/AIG18020872/Jcd302

Special Instruction:

Surveyor:

From (Person):

H. W. Y. He

ASSIGNMENT (Office)

Chin Lee Ying

of

AIG

Date/Time:

19/11/18 10:45am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGU 4672R

Insured:

GBD 3911G

at Workshop n/s:

Guan Auto Service

Tel:

9388 4210

of

Blk 7 Sin Ming Ind. Est Sec C #01-80/82

Policy No:

0999994377

Claim No:

35523486893G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19/11/18

CA / REV / REP. / REV 24 HRS Cup

H.O.D. Endorsement:

Date/Time: 11:33am @ 19/11/18

Person Contacted:

Jucky

Vehicle ☒ IN / OUT


| Date/Time | Action/Instruction (X) Estimate                    |
|-----------|----------------------------------------------------|
|           | SGU 4672R - CC3/MSG/14022261 / Avbk3 JDA: 26/11/18 |
|           | GBD 3911G - X                                      |
|           | Dismantle: 20/11/2018                              |
|           | After repair: 22/11/2018                           |
|           |                                                    |
|           |                                                    |

PRS  
Hwee Jie

REF: A16

# ASSIGNMENT

Front: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop no: \_\_\_\_\_  
 of **BLK 7 Sim wing Ind Est Sec C**  
 Insured **#01-80/82**  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

Ball. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: **8** days Res: Yes or No  
 Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **S6U4672R** Yr Regn: **16 May 2007**  
 Type of Car: **MCycle / Bus / Van / Lotry / Taxi / Prime Mover /**  
 Truck / Trailer or \_\_\_\_\_  
 Make: **Suzuki Swift** cc: **1328**  
 Colour: **Pink** A/C: Insured / Std / NI / NA  
 Sp. Reading: **246145** T/Radio: Insured / Std / NI / NA  
 Eng No: \_\_\_\_\_  
 CNo: **ZC11S186853**  
 Gen. Cond: **Good** / Fair / Poor / Burnt  
 Steering: **Insider** / Jammed / Leaked / Burnt or  
 Brake: **Insider** / Jammed / Leaked / Burnt or  
 Modi: **Nil** / S/Rim / STD A/Rim or  
 Tyre Size: F: **195/55 R15**  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **NEUTON**

Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: **6** mm R/Bal: **6** mm  
 L/Bal: **6** mm L/Bal: **6** mm  
 D.O.A: **14/11/18** D.O.I: **19/11/18**  
 Survey held at: **Yap motor @ 1415**  
 Des. of Damages: Frt / Rear / **O/S** N/S / U/C / Rooftop or  
**O/S**

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

~~4 days - 5 days~~

Hwee Jie

Pls add in the 4 carriage parts  
 as well.

Date/Time: File Pass to? ☐ : Prel. Report  
☐ : Final Report

Date/Time: File Return to?

to

Report Format: **DAR**

Lump Sum / I.B.I: IS

Days/Of Repair: **8**

Resurvey No. of Trip: **2**

Add Fee: ☐ Site Insp IS  
☐ Interview IS  
☐ Tech Insp IS  
☐ Weekend IS

Survey Fee

Transportation

1. S + P + A

2. Photo

3. Other

TOTAL

|     |
|-----|
| 180 |
| 20  |
| 200 |

*[Signature]*

23/11

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying  
To: assignments, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 19/11/2018 10:45:07 AM  
Attachments:  tmp4505.tif

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**COGARAJAH LLC**  
ADVOCATES & SOLICITORS

663 North Bridge Road  
#11-03 Southbank  
Singapore 166785  
T: 6292 8838  
F: 6292 9936  
(UEN No. 201333127N)  
(GST Reg No. 201333127N)

Our Ref : CY.SGU4072R.10.GA(HW).wp(Lh)

Your Ref :  
 Your Insured vehicle GBD 3911G

15 November 2018

CAIANG EBI EET MANAGEMENT SINGAPORE PTE LTD

c/o The Motor Claims Department

**AIG Asia Pacific Insurance**  
78 Shenton Way #07-16

Singapore 079120

By Fax No: 6835 7416

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SGU 4672R & GBD 3911G ON 14.11.2018 @ 21:00HRS ALONG EDGEDALE PLAINS

We are instructed by GOH YI MING DANNY to notify you of a road traffic accident on 14.11.2018 @ 21:00hrs along Edgemark Plains involving our client's customer's vehicle registration number SGU 4672R and vehicle registration number GBD 3911G driven by you at the scene of the above accident. Statement report is enclosed

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

C. Yoganathan LLC  
Encl

Cc: M/s. Guan Auto Service  
Block 7 Sin Ming Industrial Estate Sector C  
#01-82 / #01-80 Singapore 575642  
Mr. Jacky Fong (9388 4210)  
Fax no : 6451 1706

[illegible]



883 North Bridge Road  
#11-03 Southbank  
Singapore 196785  
T: 6292 5838  
F: 6292 5938  
(UEN No. 201333127N)  
(GST Reg No. 201333127N)

Our Ref : CY.SGU4672R.18.GA(HW).wp(Lh)

Your Ref : Your insured vehicle GBD 3911G

15 November 2018

**DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD**

c/o The Motor Claims Department  
**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way #07-16  
Singapore 079120

By Fax No: 6835 7416

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SGU 4672R & GBD 3911G ON 14.11.2018 @ 21:00HRS ALONG EDGEDALE PLAINS**

We are instructed by GOH YI MING DANNY to notify you of a road traffic accident on 14.11.2018 @ 21:00hrs along Edgedale Plains involving our client's customer's vehicle registration number SGU 4672R and vehicle registration number GBD 3911G driven by you at the material time. A copy of the Singapore accident statement report is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

  
**C. Yogarajah LLC**  
Enc

Cc: M/s. Guan Auto Service  
Block 7 Sin Ming Industrial Estate Sector C  
#01-82 / #01-80 Singapore 575642  
Mr. Jacky Fong (9388 4210)  
Fax no : 6451 1706

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

|                                                                                                                                                                                                                         |                          |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|
| <b>Vehicle Owner Particulars</b>                                                                                                                                                                                        |                          |
| Owner ID Type:                                                                                                                                                                                                          | Singapore NRIC           |
| Owner ID:                                                                                                                                                                                                               | 8646D                    |
| <b>Vehicle Details</b>                                                                                                                                                                                                  |                          |
| Vehicle No.:                                                                                                                                                                                                            | SGU4672R                 |
| Vehicle to be Exported:                                                                                                                                                                                                 | No                       |
| Intended Deregistration Date:                                                                                                                                                                                           | 21 Nov 2018              |
| Vehicle Make:                                                                                                                                                                                                           | SUZUKI                   |
| Vehicle Model:                                                                                                                                                                                                          | SWIFT 1.3 A              |
| Primary Colour:                                                                                                                                                                                                         | Pink                     |
| Manufacturing Year:                                                                                                                                                                                                     | 2007                     |
| Engine No.:                                                                                                                                                                                                             | M13A1900497              |
| Chassis No.:                                                                                                                                                                                                            | ZC11S186853              |
| Maximum Power Output:                                                                                                                                                                                                   | 67.0 kW (89 bhp)         |
| Open Market Value:                                                                                                                                                                                                      | \$10,200.00              |
| Original Registration Date:                                                                                                                                                                                             | 16 May 2007              |
| First Registration Date:                                                                                                                                                                                                | 16 May 2007              |
| Transfer Count:                                                                                                                                                                                                         | 3                        |
| Actual ARF Paid:                                                                                                                                                                                                        | \$11,220.00              |
| <b>Intended PARF Rebate Details</b>                                                                                                                                                                                     |                          |
| PARF Eligibility:                                                                                                                                                                                                       | Forfeited                |
| PARF Eligibility Expiry Date:                                                                                                                                                                                           | -                        |
| PARF Rebate Amount:                                                                                                                                                                                                     | \$0.00                   |
| <b>Intended COE Rebate Details</b>                                                                                                                                                                                      |                          |
| COE Expiry Date:                                                                                                                                                                                                        | 30 Apr 2022              |
| COE Category:                                                                                                                                                                                                           | A - Car (1600cc & below) |
| COE Period(Years):                                                                                                                                                                                                      | 5                        |
| PQP Paid:                                                                                                                                                                                                               | \$25,115.00              |
| COE Rebate Amount:                                                                                                                                                                                                      | \$17,287.00              |
| <b>Total Rebate Amount:</b>                                                                                                                                                                                             | <b>\$17,287.00</b>       |
| <b>Message</b>                                                                                                                                                                                                          |                          |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                          |

The information contained herein is correct as at 21 Nov 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                  |
|----------------------------|------------------|
| Date Of Report             | 15/11/2018 11:48 |
| Date Of Accident           | 14/11/2018 21:00 |
| Exact Location Of Accident | EDGEDALE PLAINS  |
| Country/State of Loss      | SINGAPORE        |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SGU4672R             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | GOH YI MING DANNY    |
| NRIC No                     | S8828646D            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-90998051 |
| Alternative Phone No        | OFFICE-90998051      |

### Vehicle Particulars

|              |        |
|--------------|--------|
| Manufacturer | SUZUKI |
| Model        | -      |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

|                           |                                               |
|---------------------------|-----------------------------------------------|
| Name of Insurance Company | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage          | COMPREHENSIVE                                 |
| Fleet Policy              | NO                                            |
| Policy Number             | DMPCSN3037211801                              |
| Cover Note Number         |                                               |

### Driver

|                      |                      |
|----------------------|----------------------|
| Name of Driver       | GOH YI MING DANNY    |
| NRIC No              | S8828646D            |
| Date Of Birth        | 08/08/1988           |
| Occupation           | INDOOR               |
| Date Of Driving Pass | 07/07/2009           |
| Driving Experience   | 9 YEARS AND 4 MONTHS |
| Gender               | MALE                 |
| Mobile Number        | (LOCAL) +65-90998051 |
| Fax Number           |                      |
| Contact Number       | OFFICE-90998051      |
| Email Address        | NOEMAIL              |

Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle  
 Insurance Company of Driver's Own Vehicle

#### General Information of the Accident

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name BISHAN NEIGHBOURHOOD POLICE CENTRE  
 Police Station Address ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-5529999 - FAX NO: 65561905  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

refer attached police report.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD3911G  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name GOH YI MING DANNY

Approximate Age

Injuries Sustain

Injured person in which vehicle? SGU4672R

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firm, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police Report.

## DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature \_\_\_\_\_  
Date & Time \_\_\_\_\_

Driver's Signature \_\_\_\_\_  
(if driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Reporting Center Personnel's Signature  
Name \_\_\_\_\_  
NRIC/FIN No. \_\_\_\_\_



**SINGAPORE  
POLICE FORCE**



T/2018/115/2021

1 of 3

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-6529999

Report No: T/2018/115/2021

**REPORT OF A TRAFFIC ACCIDENT**

|                                            |                  |                         |
|--------------------------------------------|------------------|-------------------------|
| Date/Time Report Made:<br>15/11/2018 10:39 | Vide Report No.: | Station Diary No.<br>35 |
|--------------------------------------------|------------------|-------------------------|

**Informant's Particulars**

|                                          |                                                                  |                              |                              |
|------------------------------------------|------------------------------------------------------------------|------------------------------|------------------------------|
| Name of Informant:<br>GOH YI MING, DANNY | Address<br>APT BLK 311 HOUGANG AVENUE 5 #03-177 SINGAPORE 530311 |                              |                              |
| ID Type / ID No.:<br>NRIC NO / S6828646D | Contact No.:                                                     | Mobile: 90998051             |                              |
| Nationality:<br>SINGAPORE CITIZEN        | Home/Office:                                                     | Email:                       |                              |
| Sex:<br>Male                             | Age:<br>30                                                       | Date of Birth:<br>08/08/1988 | Type of Informant:<br>Driver |
| Race:<br>Chinese                         | Language:                                                        |                              | Institution / School Name:   |
| Occupation:<br>AIRFORCE                  | Driving Licence Information:<br>Class: 3                         |                              | Date of Expiry:              |

**General Information of the Accident**

| General Information of the Accident                                         |                  |                      |                                            |                   |
|-----------------------------------------------------------------------------|------------------|----------------------|--------------------------------------------|-------------------|
| Type of Accident:                                                           | Injury<br>Others | Drink Drive:<br>No   | Date/Time of Accident:<br>14/11/2018 21:00 | Type of Location: |
| Location:<br>Along Road 1<br>EDGEDALE PLAINS                                |                  |                      |                                            |                   |
| Weather:<br>Clear                                                           |                  | Road Surface:<br>Dry | Road Speed Limit:                          |                   |
| Traffic Flow:                                                               |                  | Traffic Control:     | Traffic Volume<br>Light                    |                   |
| Type of Collision:<br>Between Moving Vehicles - Side Swipe - Same Direction |                  |                      | Anyone conveyed by ambulance<br>No         |                   |

**Details of Vehicle Involved**

| Vehicle No. | Type | Make             | Model                                                 | Color | Condition           | No. of Passenger |
|-------------|------|------------------|-------------------------------------------------------|-------|---------------------|------------------|
| GBD3911G    | Van  | MERCEDES<br>BENZ | CITAN 109<br>CDI VAN<br>EXTRA-<br>LONG - 2<br>SEATERS | White | Slightly<br>Damaged | 0                |
| SGU4672R    | Car  | SUZUKI           | SWIFT 1.3 A                                           | Pink  | Slightly<br>Damaged | 0                |



**SINGAPORE  
POLICE FORCE**



T:20181115/2021

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

2 of 3

Report No. T:20181115/2021

## CONTINUATION OF REPORT

| Details of Vehicle Insurance |                                                  |                      |            |             |
|------------------------------|--------------------------------------------------|----------------------|------------|-------------|
| Vehicle No.                  | Insurance Company                                | Insurance No.        | Effective  | Expiry Date |
| SGU4872R                     | CHINA TAIPING INSURANCE<br>(SINGAPORE) PTE. LTD. | DMPCSN30372118<br>01 | 16/05/2018 | 15/05/2019  |

| Details of Person Involved        |                     |                                        |                                   |
|-----------------------------------|---------------------|----------------------------------------|-----------------------------------|
| Any Pedestrian Involved: No       |                     |                                        |                                   |
| No. of Pedestrians Injured: NIL   |                     | Use of Pedestrian Crossing: NA         |                                   |
| Driver                            |                     |                                        |                                   |
| Name                              | Tan Yin Soon        | ID No.                                 | S7486448A                         |
| Related Vehicle                   | GBD3911G (Van)      | Contact No.                            | 81984807                          |
| Hospital/Clinic                   | NIL                 | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL |
| Date Treatment                    | NIL                 | Date Discharge                         | NIL                               |
| No. of Days granted Medical Leave | NIL                 | Degree of Injury                       | NIL                               |
| Driver                            |                     |                                        |                                   |
| Name                              | GOH YI MING, DANNY  | ID No.                                 | S8828646D                         |
| Related Vehicle                   | SGU4672R (Car)      | Contact No.                            | 90998051                          |
| Hospital/Clinic                   | STAT MEDICAL CLINIC | Class of Driving Licence & Expiry Date | Class: 3<br>Date of Expiry: NIL   |
| Date Treatment                    | 15/11/2018          | Date Discharge                         | 15/11/2018                        |
| No. of Days granted Medical Leave | 03                  | Degree of Injury                       | Slight                            |

**Brief Details.**

On the 14/11/2018 at 2100hrs, my vehicle (SGU4872R) was travelling along Edgedale Plains on a two lane road. The weather was clear and traffic volume was light. I was on lane two when I observed that there was a van (GBD3911G) travelling on lane 1. The van started to drive into my lane and collided into my vehicle. I got out of my vehicle and made a check. The damages to my vehicle is the right portion dented and covered with scratches. The damages to the van is the left portion scratched. There is an in-car camera installed in my vehicle however there was no SD card. After the accident, I wrote a letter stating that the van driver was at fault and both parties sign the letter. I then went to see a doctor and received 3 days MC. I am lodging this report for insurance claim.



**SINGAPORE  
POLICE FORCE**



T:20181115/2021

3 of 3

Police Station Of Origin:

Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

Report No: T:20181115/2021

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 1 CASSIDY TAN GIA LOK

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

15/11/2018 10:39

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt MOHAMAD ZULFAZDLI BIN

ABDULLAH

Contact No: 65478204

Authentication Stamp

NP158

SN 061

## MOTOR CAR (RTD)

## Right Portion

| NAC  | INC     | Item                              | CON | AC | Qty |
|------|---------|-----------------------------------|-----|----|-----|
| 1316 | 9915327 | Fit RH Door                       | DD  | /  | 1   |
| 1317 | 991654  | Fit RH Door Protector             |     |    |     |
| 1318 | 991601  | Fit RH Door Hinge                 |     |    |     |
| 1319 | 991685  | Fit RH Door Wing Mirror           | DD  | /  | 1   |
| 1320 | 991583  | Fit RH Door Garnish               |     |    |     |
| 1321 | 991639  | Fit RH Door Glass Outer Moulding  |     |    |     |
| 1322 | 991588  | Fit RH Door Glass Inner Moulding  |     |    |     |
| 1323 | 991584  | Fit RH Door Glass                 |     |    |     |
| 1324 | 991595  | Fit RH Door Glass Regulator       |     |    |     |
| 1325 | 991596  | Fit RH Door Glass Regulator Motor |     |    |     |
| 1326 | 991662  | Fit RH Door Rubber                |     |    |     |
| 1327 | 991636  | Fit RH Door Outer Handle          | DD  | /  | 1   |
| 1328 | 991607  | Fit RH Door Inner Handle          |     |    |     |
| 1329 | 991625  | Fit RH Door Lock w/Key            |     |    |     |
| 1330 | 991624  | Fit RH Door Lock                  |     |    |     |
| 1331 | 991562  | Fit RH Door Central Lock          | BT  | /  | 1   |
| 1332 | 991675  | Fit RH Door Switch                |     |    |     |
| 1333 | 991617  | Fit RH Door Inner Trim Board      | CRA | /  | 1   |
| 1334 | 991568  | Fit RH Door Checker               |     |    |     |
| 1335 | 991575  | Fit RH Door Felt                  |     |    |     |
| 1336 | 991688  | Fit RH Door Wire Harness          |     |    |     |
| 1337 | 991683  | Fit RH Door Window Glass Pillar   |     |    |     |
| 1338 | 991640  | Fit RH Door Outer Pillar          |     |    |     |
| 1339 | 991613  | Fit RH Door Inner Pillar          |     |    |     |
| 1340 | 991646  | Fit RH Door Pillar Inner Garnish  |     |    |     |
| 1341 | 990554  | Centre Pillar RH                  |     |    |     |
| 1342 | 990543  | Centre Inner Pillar RH            |     |    |     |
| 1343 | 990518  | Centre Pillar Upper Garnish RH    |     |    |     |
| 1344 | 990565  | Centre Pillar Lower Garnish RH    |     |    |     |
| 1345 | 991670  | Fit RH Door Step Garnish          |     |    |     |
| 1346 | 994058  | Rocker Panel RH                   |     |    |     |
| 1347 | 994049  | Rocker Panel Inner Panel RH       |     |    |     |
| 1348 | 994047  | Rocker Panel Garnish RH           |     |    |     |
| 1349 | 994055  | Rocker Panel Outer Side Skirt RH  | DD  | /  | 1   |
| 1004 | 991300  | Fit Bumper                        |     |    |     |
| 1006 | 991325  | Fit Bumper Bracket                |     |    |     |
| 1007 | 991462  | Fit Bumper Side Retainer          |     |    |     |
| 1008 | 991433  | Fit Bumper Reinforcement          |     |    |     |
| 1010 | 991468  | Fit Bumper Sponge                 |     |    |     |
| 1011 | 991427  | Fit Bumper Protector              |     |    |     |
| 1014 | 991301  | Fit Bumper Moulding               |     |    |     |
| 1015 | 991407  | Fit Bumper Lower Spoiler          |     |    |     |
| 1030 | 991821  | Fit RH Headlamp Assy              |     |    |     |
| 1032 | 995089  | Fit RH Side Lamp                  | SCR | /  | 1   |
| 1105 | 995071  | Fit RH Fender                     | DD  | /  | 1   |
| 1107 | 991744  | Fit RH Fender Lamp                |     |    |     |
| 1108 | 991752  | Fit RH Fender Protector           |     |    |     |
|      |         | Fit RH RIM                        | SCR | /  | 1   |

## Vehicle No: SGU 4672R

[illegible]

23/11/2018

No. of Items: \_\_\_\_\_ Accessory: \_\_\_\_\_


## MOTOR CAR (UC)

### Undercarriage

| NAC  | INC    | Item                            | CON | AC | Qty |
|------|--------|---------------------------------|-----|----|-----|
| 1372 | 995163 | Frt LH Shock Absorber           |     |    |     |
| 1373 | 991944 | Frt LH Shock Absorber Mounting  |     |    |     |
| 1374 | 990632 | Frt LH Coil Spring              |     |    |     |
| 1375 | 995198 | Frt LH Knuckle Arm              |     |    |     |
| 1376 | 995199 | Frt LH Knuckle Arm Bearing      |     |    |     |
| 1377 | 995178 | Frt LH Lower Arm                |     |    |     |
| 1378 | 995169 | Frt LH Upper Arm                |     |    |     |
| 1379 | 995183 | Frt LH Tie Rod                  |     |    |     |
| 1380 | 995143 | Frt LH Drive Shaft              |     |    |     |
| 1381 | 990661 | Frt LH Control Arm              |     |    |     |
| 1382 | 992062 | Frt LH Trailing Arm             |     |    |     |
| 1383 | 991848 | Frt LH Leaf Spring              |     |    |     |
| 1384 | 991293 | Frt LH Brake Disc Rotor         |     |    |     |
| 1385 | 991281 | Frt LH Brake Caliper            |     |    |     |
| 1386 | 991292 | Frt LH Brake Pipe               |     |    |     |
| 1387 | 991287 | Frt LH Brake Hose               |     |    |     |
| 1388 | 991295 | Frt LH Brake Sensor Wire        |     |    |     |
| 1389 | 991989 | Frt Stay Bar Bracket            |     |    |     |
| 1390 | 994455 | Steering Rack & Pinion          |     |    |     |
| 1391 | 994435 | Steering Cross Member           |     |    |     |
| 1392 | 994519 | Frt Sub Frame                   |     |    |     |
| 1393 | 992003 | Frt Sub Frame Mounting          |     |    |     |
| 1394 | 991217 | Frt Anti Roll Bar               |     |    |     |
| 1395 | 991219 | Frt Anti Roll Bar Linkage       |     |    |     |
| 1396 | 990887 | Engine Block                    |     |    |     |
| 1397 | 990890 | Engine Block Gasket             |     |    |     |
| 1398 | 990972 | Engine Oil Sump                 |     |    |     |
| 1399 | 990960 | Engine Oil                      |     |    |     |
| 1400 | 992224 | Gear Box Assy                   |     |    |     |
| 1401 | 992229 | Gear Box Gasket                 |     |    |     |
| 1402 | 992241 | Gear Box Oil Sump               |     |    |     |
| 1403 | 992257 | Gear Oil                        |     |    |     |
| 1410 | 990534 | Centre Exhaust Pipe Assy        |     |    |     |
| 1411 | 990532 | Centre Exhaust Mounting         |     |    |     |
| 1404 | 991134 | Floor Panel                     |     |    |     |
| 1405 | 993719 | Rear LH Shock Absorber          |     |    |     |
| 1406 | 993723 | Rear LH Shock Absorber Mounting |     |    |     |
| 1407 | 993170 | Rear LH Coil Spring             |     |    |     |
| 1408 | 993550 | Rear LH Knuckle Arm             |     |    |     |
| 1409 | 993551 | Rear LH Knuckle Arm Bearing     |     |    |     |
| 1410 | 993597 | Rear LH Lower Arm               |     |    |     |
| 1411 | 993884 | Rear LH Upper Arm               |     |    |     |
| 1412 | 995161 | Rear LH Drive Shaft             |     |    |     |
| 1413 | 995216 | Rear LH Control Arm             |     |    |     |
| 1414 | 993881 | Rear LH Trailing Arm            |     |    |     |
| 1415 | 993573 | Rear LH Leaf Spring             |     |    |     |
| 1416 | 992941 | Rear LH Brake Disc Rotor        |     |    |     |
| 1417 | 992937 | Rear LH Brake Caliper Assy      |     |    |     |
| 1418 | 990434 | Rear LH Brake Pipe              |     |    |     |
| 1419 | 992946 | Rear LH Brake Hose              |     |    |     |
| 1420 | 993819 | Rear Sub Frame                  |     |    |     |
| 1421 | 993820 | Rear Sub Frame Mounting         |     |    |     |
| 1422 | 992813 | Rear Anti Roll Bar              |     |    |     |
| 1423 | 990168 | Rear Anti Roll Bar Linkage      |     |    |     |
| 1424 | 990202 | Axle Beam                       |     |    |     |
| 1425 | 990170 | Rear Axle Panhard Rod           |     |    |     |
| 1426 | 990810 | Differential Assy               |     |    |     |
| 1427 | 992706 | Propeller Shaft                 |     |    |     |

Vehicle No: SGU4672R

| NAC  | INC    | Item                            | CON | AC | Qty |
|------|--------|---------------------------------|-----|----|-----|
| 1428 | 991935 | Frt RH Shock Absorber           |     |    |     |
| 1429 | 991944 | Frt RH Shock Absorber Mounting  |     |    |     |
| 1430 | 990632 | Frt RH Coil Spring              |     |    |     |
| 1431 | 991844 | Frt RH Knuckle Arm              | DD  | ✓  | 1   |
| 1432 | 991845 | Frt RH Knuckle Arm Bearing      | DD  | ✓  | 1   |
| 1433 | 991851 | Frt RH Lower Arm                | DD  | ✓  | 1   |
| 1434 | 992064 | Frt RH Upper Arm                |     |    |     |
| 1435 | 992040 | Frt RH Tie Rod                  |     |    |     |
| 1436 | 991692 | Frt RH Drive Shaft              |     |    |     |
| 1437 | 990661 | Frt RH Control Arm              |     |    |     |
| 1438 | 992062 | Frt RH Trailing Arm             |     |    |     |
| 1439 | 991848 | Frt RH Leaf Spring              |     |    |     |
| 1440 | 991293 | Frt RH Brake Disc Rotor         |     |    |     |
| 1441 | 991281 | Frt RH Brake Caliper            |     |    |     |
| 1442 | 991292 | Frt RH Brake Pipe               |     |    |     |
| 1443 | 991287 | Frt RH Brake Hose               |     |    |     |
| 1444 | 991295 | Frt RH Brake Sensor Wire        |     |    |     |
| 1445 | 993720 | Rear RH Shock Absorber          |     |    |     |
| 1446 | 993723 | Rear RH Shock Absorber Mounting |     |    |     |
| 1447 | 993173 | Rear RH Coil Spring             |     |    |     |
| 1448 | 993550 | Rear RH Knuckle Arm             |     |    |     |
| 1449 | 993551 | Rear RH Knuckle Arm Bearing     |     |    |     |
| 1450 | 993601 | Rear RH Lower Arm               |     |    |     |
| 1451 | 993885 | Rear RH Upper Arm               |     |    |     |
| 1452 | 993322 | Rear RH Drive Shaft             |     |    |     |
| 1453 | 993178 | Rear RH Control Arm             |     |    |     |
| 1454 | 995117 | Rear RH Trailing Arm            |     |    |     |
| 1455 | 995110 | Rear RH Leaf Spring             |     |    |     |
| 1456 | 992942 | Rear RH Brake Disc Rotor        |     |    |     |
| 1457 | 992938 | Rear RH Brake Caliper Assy      |     |    |     |
| 1458 | 990434 | Rear RH Brake Pipe              |     |    |     |
| 1459 | 992947 | Rear RH Brake Hose              |     |    |     |

  
 23/11/2018

23/11/2018

No. of Items: \_\_\_\_\_ Assessor: \_\_\_\_\_

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

## CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                          | Adj Submitted                              | Ins Auth'd | Status                                                          |
|------|-----------------------------------------|---------------|---------------------------------------------------|--------------------------------------------------|--------------------------------------------|------------|-----------------------------------------------------------------|
| Main | 17 Nov 2018<br><a href="#">Edit Reg</a> |               | 19 Nov 2018 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                          | Reference                                                                                                                  | Claim Details          | Documents                                                                     | Show All |         |             |              |            |       |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------|------------------------|-------------------------------------------------------------------------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>                                                                                       |                                                                                                                            |                        |                                                                               |          |         |             |              |            |       |
| Insured:                                                                                                                                                                      | DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z                                                     |                        |                                                                               |          |         |             |              |            |       |
| Main Claimant:                                                                                                                                                                | GOH YI MING DANNY                                                                                                          |                        |                                                                               |          |         |             |              |            |       |
| Vehicle Reg. No.:                                                                                                                                                             | SGU4672R                                                                                                                   | Date of Loss:          | 14/11/2018 21:00 - :59<br>[137 Months and 29 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:                                                                                                                                                                   | TP / 3552348589SG                                                                                                          | Policy/Cover Note No.: | 0999994377 (Comprehensive)                                                    |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):                                                                                                                                                   | G8D3911G                                                                                                                   | Policy No. (Claimant): |                                                                               |          |         |             |              |            |       |
|                                                                                                                                                                               |                                                                                                                            | Excess:                |                                                                               |          |         |             |              |            |       |
| Repairer:                                                                                                                                                                     | Guan Auto Service (Sin Ming) Block 7 Sin Ming Industrial Estate Sector C, #01-80/ # 01-82, 575642 Sin Ming - Tel: 93884210 |                        |                                                                               |          |         |             |              |            |       |
| Handling Insurer:                                                                                                                                                             | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M]                      |                        |                                                                               |          |         |             |              |            |       |
| Adjuster:                                                                                                                                                                     | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG SWEE PENG] ... [Final Rpt due 28/11/2018]           |                        |                                                                               |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>                                                 |                                                                                                                            |                        |                                                                               |          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>AIG_SG (20/11/2018): Request to upload TP GIA Report</li> </ul>                                                                        |                                                                                                                            |                        |                                                                               |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |                                                                                                                            |                        |                                                                               |          |         |             |              |            |       |
| Due Date                                                                                                                                                                      | Priority                                                                                                                   | Type                   | Task Group                                                                    | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                   |                                                                                                                            |                        |                                                                               |          |         |             |              |            |       |

## Claim Documents

\*SGU4672R (3552348589SG)  
[GBD3911G]

TP

GOH YI MING DANNY

Nov 14 2018 9:00PM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Guan Auto Service

|                  |                 |                                   |               |  |  |                    |  |  |              |  |  |              |  |  |            |                                     |                                     |  |
|------------------|-----------------|-----------------------------------|---------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|--|------------|-------------------------------------|-------------------------------------|--|
| Upload Documents |                 |                                   | Upload Photos |  |  | Compose New Letter |  |  | Upload Video |  |  | Upload Audio |  |  | View       |                                     | View in Browser                     |  |
| Photos/Images    |                 |                                   |               |  |  |                    |  |  |              |  |  |              |  |  | 3 per page |                                     | <input checked="" type="checkbox"/> |  |
| No               | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |               |  |  |                    |  |  |              |  |  |              |  |  | Thumbnail  | Print                               |                                     |  |
| 1                | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 2                | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 3                | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 4                | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 5                | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 6                | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 7                | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 8                | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 9                | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 10               | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 11               | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 12               | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 13               | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 14               | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 15               | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 16               | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 17               | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 18               | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 19               | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 20               | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 21               | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 22               | 21/11/18 17:23  | General View                      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 23               | 21/11/18 17:23  | Photographs of Damaged Parts      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 24               | 21/11/18 17:23  | Photographs of Damaged Parts      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 25               | 21/11/18 17:23  | Photographs of Damaged Parts      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 26               | 21/11/18 17:23  | Photographs of Damaged Parts      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 27               | 21/11/18 17:23  | Photographs of Damaged Parts      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 28               | 21/11/18 17:23  | Photographs of Damaged Parts      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 29               | 21/11/18 17:23  | Photographs of Damaged Parts      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 30               | 21/11/18 17:23  | Photographs of Damaged Parts      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 31               | 21/11/18 17:23  | Photographs of Damaged Parts      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 32               | 21/11/18 17:23  | Photographs of Damaged Parts      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 33               | 21/11/18 17:23  | Photographs of Damaged Parts      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 34               | 21/11/18 17:23  | Photographs of Damaged Parts      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 35               | 21/11/18 17:23  | Photographs of Damaged Parts      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 36               | 21/11/18 17:23  | Photographs of Damaged Parts      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |
| 37               | 21/11/18 17:23  | Photographs of Damaged Parts      |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |  |

| Photos/Images |                 |                                           | 3 per page                                                                                   | <input checked="" type="checkbox"/> |
|---------------|-----------------|-------------------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail                                                                                    | Print                               |
| 38            | 21/11/18 17:23  | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 39            | 21/11/18 17:23  | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 40            | 21/11/18 17:23  | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 41            | 21/11/18 17:23  | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 42            | 07/12/18 17:01  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 43            | 07/12/18 17:01  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 44            | 07/12/18 17:01  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 45            | 07/12/18 17:01  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 46            | 07/12/18 17:01  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| 47            | 07/12/18 17:01  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation |                 |                                           | 1 per page                                                                                   | <input checked="" type="checkbox"/> |
| No            | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail                                                                                    | Print                               |
| 1             | 20/11/18 09:15  | OI GIA REPORT                             |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                                                                                                |  | Reset | Save | Print |
|----------------------------------------------------------------------------------------------------------------------------------------------------|--|-------|------|-------|
| There are no document checklists configured.                                                                                                       |  |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>       |  |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |  |       |      |       |

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18020872/JCD3E2

Date: 11/12/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 0999994377

Claimant Vehicle  
No : SGU4672R

Insured Vehicle No : GBD3911G

Date of Loss: 14/11/2018

Nature of Claim: TP

Claim No: 3552348589SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SGU4672R

Make &amp; Model: SUZUKI SWIFT, 1.5 (A)

Engine No: M13A1900497

Reg. Date: 16/05/2007 (Man. Year: 2007)

Chassis No: ZC11S186853

Colour: Pink

Odometer: 246145 km

Engine Capacity: 1328 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size: 195/55 R15

Front Left Side: Neuton 6 mm

Rear Left Side: Neuton 6 mm

Front Right Side: Neuton 6 mm

Rear Right Side: Neuton 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

## INSPECTION

Date of Assignment: 19/11/2018

Date Inspected: 19/11/2018 Inspected At:

Guan Auto Service (Sin Ming)  
Block 7 Sin Ming Industrial Estate Sector  
C, #01-80/ # 01-82  
Singapore 575642

Estimated Period of Repair: 8.0 days

Adjuster: ONG SWEE PENG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                       | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------|-----------|------------|--------|
| 1   | 1   |          | *FRT RH DOOR                      | Dented    | 0.00 F     | *- F   |
| 2   | 1   |          | *FRT RH DOOR WING MIRROR          | Dented    | 0.00 F     | *- F   |
| 3   | 1   |          | *FRT RH DOOR OUTER HANDLE         | Dented    | 0.00 F     | *- F   |
| 4   | 1   |          | *FRT RH DOOR INNER TRIM BOARD     | Cracked   | 0.00 F     | *- F   |
| 5   | 1   |          | *ROCKER PANEL OUTER SIDE SKIRT RH | Dented    | 0.00 F     | *- F   |
| 6   | 1   |          | *FRT RH SIDE LAMP                 | Scratched | 0.00 F     | *- F   |
| 7   | 1   |          | *FRT RH FENDER                    | Dented    | 0.00 F     | *- F   |
| 8   | 1   |          | *FRT RH RIM                       | Scratched | 0.00 F     | *- F   |
| 9   | 1   |          | *REAR RH DOOR                     | Dented    | 0.00 F     | *- F   |
| 10  | 1   |          | *REAR RH RIM                      | Scratched | 0.00 F     | *- F   |
| 11  | 1   |          | *REAR RH TYRE                     | Scratched | 0.00 F     | *- F   |
| 12  | 1   |          | *FRT RH KNUCKLE ARM               | Dented    | 0.00 F     | *- F   |
| 13  | 1   |          | *FRT RH KNUCKLE ARM BEARING       | Dented    | 0.00 F     | *- F   |
| 14  | 1   |          | *FRT RH LOWER ARM                 | Dented    | 0.00 F     | *- F   |
| 15  | 1   |          | *FRT RH DOOR LOCK                 | Bent      | 0.00 F     | *- F   |

F=Franchise part.

|                           |             |             |
|---------------------------|-------------|-------------|
| <b>Total Parts (\$\$)</b> | <b>0.00</b> | <b>0.00</b> |
|---------------------------|-------------|-------------|

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

< END OF ESTIMATES >