

INSURANCE

INS. CASE OWNER:

CC / AXA1802

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$5

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age: VIM JIA QI MAHIS

Driver Tel No.:

(V/L: YES / NO )

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

GBR 4481C



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup):

After call 1st to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

f

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

\$5

Loss of Rental (LOR):

\$5

f

days)

Loss of Use (LOU):

\$5

(5

x

days)

Loss of Income (LOI):

\$5

(5

x

days)

LOR only

LOU only

LOR + LOI

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

COPY SENT 12/4/19

OLD CHANGED

LANE

PASS TO LAUNCH WP

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

Total:

\$5

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

Name 1:

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

(05/11/13) wef

ASS. REC. BY: Marcus

REF:

## ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lump Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) \$ + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

) TOTAL

Report Format :

Lump Sum / I.B.I. (\$

)

R (\$1,299.56/46%)

20/11/18 confirmed L/S \$1600 with winner.

J.MART - L/S \$1,500



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                         |                            |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------|----------------------------|------------|-------------------------------------------------------------------------------------|
| AXA INSURANCE PTE LTD                                                                                                                  |                                                                         | Ref : CC4/ASM18020876/Ujb3 |            |                                                                                     |
| 8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811                                                                                      |                                                                         | Date : 19-11-2018          |            |  |
|                                                                                                                                        |                                                                         | Code : ASM                 |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                         |                            |            |                                                                                     |
| Insured Veh.                                                                                                                           | SLX 4419G                                                               | Veh. Inspected             | GBH 4481C  |                                                                                     |
| Policy No.                                                                                                                             |                                                                         | Coverage (\$)              | 0.00       |                                                                                     |
| Claim No.                                                                                                                              |                                                                         | Excess (\$)                | 0.00       |                                                                                     |
| Assign From                                                                                                                            |                                                                         | Assign Date                | 19/11/2018 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                         |                            |            |                                                                                     |
| Make & Model                                                                                                                           |                                                                         | c.c                        | 0          |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                  | Year of Reg.               |            |                                                                                     |
| Chassis No.                                                                                                                            |                                                                         | Colour                     |            |                                                                                     |
| Odometer                                                                                                                               | -                                                                       | Steering                   |            |                                                                                     |
| Brakes                                                                                                                                 |                                                                         | Modification               |            |                                                                                     |
| General                                                                                                                                |                                                                         |                            |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                         |                            |            |                                                                                     |
|                                                                                                                                        | Size                                                                    | Make                       | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                         |                                                                         |                            | mm         |                                                                                     |
| L/H Front Tyre                                                                                                                         |                                                                         |                            | mm         |                                                                                     |
| R/H Rear Tyre                                                                                                                          |                                                                         |                            | mm         |                                                                                     |
| L/H Rear Tyre                                                                                                                          |                                                                         |                            | mm         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                         |                            |            |                                                                                     |
|                                                                                                                                        |                                                                         |                            |            |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                         |                            |            |                                                                                     |
| Accident Date                                                                                                                          | 14/11/2018                                                              | Inspection Date            |            |                                                                                     |
| Survey held at                                                                                                                         | KOON HENG MOTOR<br>BLK 1 KAKI BUKIT AVE 6<br>#02-14<br>SINGAPORE 417883 |                            |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                         |                            |            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                         |                            |            |                                                                                     |

# J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,  
Defu Industrial Park C, Singapore 539186  
Tel : 6343-0934 Fax : 6343-0921  
Email : jmartauto@gmail.com  
Registration No: 201400246D  
GST Reg. No: 201400246D

Joy

8-Jan-19

Our ref : TP/4628/19

Megacool (Singapore) Pte Ltd

RE : estimate cost for vehicle no : GBH 4481C

|      |                        |          |          |          |      |
|------|------------------------|----------|----------|----------|------|
| 1 pc | frt bumper             | Deep cut | \$       | 514.70   | nett |
| 1 pc | frt bumper lh retainer | surf     |          | 147.00   |      |
| 1 pc | lh headlamp            | na       |          | 403.00   | X    |
| 1 pc | frt step garnish lh    | cut      |          | 72.50    |      |
| 1 pc | hup cap                | cut      |          | 151.20   |      |
|      |                        |          |          | 1,288.40 |      |
|      |                        |          | less 10% | 128.84   |      |
|      |                        |          |          | 1,159.56 |      |

1 pc body sticker  
Panel beating.  
Spray painting.  
Wiring.

|          |       |   |
|----------|-------|---|
| 10.00    | snett | ✓ |
| 600.00   | 400   |   |
| 1,000.00 | 700   |   |
| 30.00    | 20    |   |
| 2,799.56 |       |   |
| 195.96   |       |   |
| 2,995.52 |       |   |

Plus 7% GST

SD : Two thousand nine hundred ninety-five & cents fifty-two only.

24/1/19

not Authorized  
Lkm  
2/5 @ 1500/  
3 day

take photo of the car

P-888-40  
102 796.86  
S.N-10.00  
10km-1120.00  
1926.86  
202  
1541

# J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,  
Defu Industrial Park C, Singapore 539186  
Tel : 6343-0934 Fax : 6343-0921  
Email : jmartauto@gmail.com  
Registration No: 201400246D  
GST Reg. No: 201400246D

8-Jan-19

Our ref : TP/4628/19

Megacool (Singapore) Pte Ltd

## RE : estimate cost for vehicle no : GBH 4481C

|      |                        |             |          |       |
|------|------------------------|-------------|----------|-------|
| 1 pc | frt bumper             | \$          | 514.70   | nett  |
| 1 pc | frt bumper lh retainer |             | 147.00   |       |
| 1 pc | lh headlamp            |             | 403.00   |       |
| 1 pc | frt step garnish lh    |             | 72.50    |       |
| 1 pc | hup cap                |             | 151.20   |       |
|      |                        |             | 1,288.40 |       |
|      |                        | less 10%    | 128.84   |       |
|      |                        |             | 1,159.56 |       |
| 1 pc | body sticker           |             | 10.00    | snett |
|      | Panel beating.         |             | 600.00   |       |
|      | Spray painting.        |             | 1,000.00 |       |
|      | Wiring.                |             | 30.00    |       |
|      |                        |             | 2,799.56 |       |
|      |                        | Plus 7% GST | 195.96   |       |
|      |                        |             | 2,995.52 |       |

SD : Two thousand nine hundred ninety-five & cents fifty-two only.

# KOON HENG MOTOR

(Reg. No: 24840700K)

BLK 1 KAKI BUKIT AVE 6 #02-14 (AUTO BAY @ KAKI BUKIT) SINGAPORE 417883

TEL: 67487348 FAX: 67432524

email: koonhengmotor@gmail.com

M/S **AXA Insurance Pte Ltd**  
8 Shenton Way  
#24-01 AXA Tower  
Singapore 068811

Estimation No : 16112018 / 4481

Type : TP

Date : 16/11/2018

A/C No : GBH4481C

## Re: ESTIMATION ON REPAIR COST TO VEHICLE NO: GBH4481C

Make/ Model : Nissan Urvan NV350

Accident Date : 14/11/2018

Chassis No : JN1NC2E26Z0030323

### PARTS REQUIRED

|                   | Description                              | Qty | U/Price (S\$) | Amount (S\$)      |
|-------------------|------------------------------------------|-----|---------------|-------------------|
| 1                 | Front LH Door <i>R</i>                   | 1   | 1,015.00      | 1,015.00 <i>X</i> |
| 2                 | Front LH Door Lower Garnish <i>cut</i>   | 1   | 163.40        | 163.40 <i>✓</i>   |
| 3                 | Front Bumper <i>Deep cut</i>             | 1   | 514.70        | 514.70 <i>✓</i>   |
| 4                 | Front Bumper LH Side Retainer <i>Ref</i> | 1   | 147.00        | 147.00 <i>✓</i>   |
| 5                 | Front LH Tyre Rim <i>11</i>              | 1   | 450.00        | 450.00 <i>X</i>   |
| 6                 | Front LH Tyre Knuckle Arm <i>11</i>      | 1   | 409.00        | 409.00 <i>X</i>   |
| 7                 | Front Bumper Side Clips <i>new</i>       | 2   | 8.00          | 16.00 <i>✓</i>    |
| TOTAL             |                                          |     |               | 2,715.10          |
| LESS DISCOUNT 10% |                                          |     |               | 271.51            |
| TOTAL SPARE PARTS |                                          |     |               | 2,443.59          |

### LABOUR CHARGES

|                                     |                                                                    |          |            |
|-------------------------------------|--------------------------------------------------------------------|----------|------------|
| 8                                   | TO KNOCK/REPAIR/WELDING OF DAMAGED PARTS, CHANGING OF ACCIDENT PAR | 1,000.00 | <i>400</i> |
| 9                                   | TO SPRAY PAINT FOR AFFECTED AREAS                                  | 1,000.00 | <i>700</i> |
| 10                                  | TO WIRING                                                          | 80.00    | <i>20</i>  |
| 11                                  | TO UNDERCOAT                                                       | 200.00   | <i>X</i>   |
| 12                                  | DOOR SIDE ROC STICKER                                              | 30.00    | <i>✓</i>   |
| 13                                  | WHEEL ALIGNMENT                                                    | 70.00    | <i>60</i>  |
| 14                                  | TO UNDER CARRIAGE                                                  | 350.00   | <i>X</i>   |
|                                     |                                                                    | 2,730.00 |            |
| GRAND TOTAL AMOUNT (PARTS & LABOUR) |                                                                    | 5,173.59 |            |

LKKK Auto Centre will notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*not Allowed*  
*like*  
*20/11/18*  
*L/S #1600/2*  
*Take photo After repair*  
*30h.*

*P-841.10*  
*less 50%*  
*P-420.55*  
*L-1210.00*  
*1630.55*

2

**B**

T

OK

## TP passed the case to lawyer. Please submit survey report and invoice

Type

🔗 Question

Message

TP passed the case to lawyer. Please submit survey report and invoice

Reply



## Service Request Details

Claim

M013AX

Reference

Line

Loss Date

November 14, 2018

Request Date

November 19, 2018

Due Date

November 26, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

19.11.2018 @ 9.51am

Mr. Tan vln nulin

## Actions

Next Step

Agree to perform service

Decline Work

Accept Work

## Vehicle Information

Incident Vehicle Registration #

BH4481C

Make

VD NISSAN

Model  
V350

### Service Address

---

### Primary Contact/Insured

---

AUDI SINGAPORE PTE LTD  
KALLANG AVENUE, #08-01 to 09 APERIA TOWER 1, 339509, Singapore  
2333513  
my.chong@audi.com.sg

### Claim Handler

---

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[View Message](#)

**Catherine Chong (LKK Auto)**

---

**From:** pengkoon tan <koonhengmotor@gmail.com>  
**Sent:** Friday, 16 November, 2018 4:46 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Subject:** Arrange Surveyor / Make Appointment for TP Claim GBH4481C  
**Attachments:** Arrange Surveyor GBH4481C.pdf

**Categories:** Santosh

Dear Sir,

TP Claim Vehicle (GBH4481C) is not at workshop must make appointment next week. Detail as attached !

Thank you & Best regards,  
**Tan Peng Koon**

Managing Director | Koon Heng Motor  
Blok 1 Kaki Bukit Ave 6 #02-14 Auto bay @Kaki Bukit Singapore 417883  
**t:** +65 3748 7348 | **hp:** +65 9831 2232 | **Fax:** +65 6743 2524  
**e:** [koonhengmotor@gmail.com](mailto:koonhengmotor@gmail.com)

---

This email(including any attachments to it) is confidential, legally privileged, subject to copyright and is sent for the personal attention of the intended recipient only. If you have received this email in error, please advise us immediately and delete it. You are notified that disclosing, copying, distributing or taking in reliance on the contents of this information is strictly prohibited. Although we have reasonable precautions to ensure no viruses are present in this email, we cannot accept reasonable precautions to ensure no viruses are present in this email, we cannot responsibility for any loss or damage arising from the viruses in this email or attachments. We exclude any liability for the content of this email, or for the consequences of any action taken on the basis of the information provided in this email or it's attachments, unless that information is subsequently confirmed in writing. If this email contains an offer, that should be considered as an invitation to treat.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18020876/Ujb3q2

8 SHENTON WAY #24-01  
AXA TOWERS SINGAPORE 068811  
ATTN: PETER

Date : 23-05-2019



Code : ASM

**1. Policy Particulars :- THIRD PARTY CLAIM**

|              |           |                |            |
|--------------|-----------|----------------|------------|
| Insured Veh. | SLX 4419G | Veh. Inspected | GBH 4481C  |
| Policy No.   |           | Coverage (\$)  | 0.00       |
| Claim No.    | S8M013AX  | Excess (\$)    | 0.00       |
| Assign From  |           | Assign Date    | 19/11/2018 |

**2. Vehicle Particulars & Condition**

|              |                   |              |          |
|--------------|-------------------|--------------|----------|
| Make & Model | NISSAN NV350      | c.c          | 2488     |
| Engine No.   | HIDDEN            | Year of Reg. | 2018     |
| Chassis No.  | JN1MC2E26Z0030323 | Colour       | SILVER   |
| Odometer     | 20425             | Steering     | IN ORDER |
| Brakes       | IN ORDER          | Modification | NIL      |
| General      | GOOD              |              |          |

**3. Conditions of Tyres**

|                | Size    | Make   | Balance |
|----------------|---------|--------|---------|
| R/H Front Tyre | 195 R15 | DUNLOP | 6 mm    |
| L/H Front Tyre | 195 R15 | DUNLOP | 6 mm    |
| R/H Rear Tyre  | 195 R15 | DUNLOP | 6 mm    |
| L/H Rear Tyre  | 195 R15 | DUNLOP | 6 mm    |

**4. Description of Damages**

|                                                                                              |
|----------------------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY.<br>DAMAGES SEE DETAILS. |
|----------------------------------------------------------------------------------------------|

**5. General Information**

|                |                                                                                                     |                 |            |
|----------------|-----------------------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 14/11/2018                                                                                          | Inspection Date | 20/11/2018 |
| Survey held at | J-MART MOTOR PTE LTD<br>BLK 5 DEFU LANE 10<br>#01-578<br>DEFU INDUSTRIAL PARK C<br>SINGAPORE 539186 |                 |            |

**5a. Remarks**

|                                                                                                                                           |
|-------------------------------------------------------------------------------------------------------------------------------------------|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|-------------------------------------------------------------------------------------------------------------------------------------------|

**5b. Estimate Days of Repair**

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|----------------|

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 4481C**

| Qty                                                                         | Description of Parts                    | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|-----------------------------------------|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>                                                 |                                         |               |                           |                   |
| 1                                                                           | FRT BUMPER (N) (CONSISTENT)             | DEEP CUT      | 514.70                    | 514.70            |
| 1                                                                           | FRT BUMPER LH RETAINER (N) (CONSISTENT) | BENT          | 147.00                    | 147.00            |
| 1                                                                           | LH HEADLAMP (N) (CONSISTENT)            | NOT NECESSARY | 403.00                    | -                 |
| 1                                                                           | FRT STEP GARNISH LH (N) (CONSISTENT)    | CUT           | 72.50                     | 72.50             |
| 1                                                                           | HUP CAP (N) (CONSISTENT)                | CUT           | 151.20                    | 151.20            |
|                                                                             | LESS 10% DISCOUNT                       |               | -128.84                   | -88.54            |
|                                                                             |                                         |               | 1,159.56                  | 796.86            |
| <b>SPECIAL NETT ITEMS</b>                                                   |                                         |               |                           |                   |
| 1                                                                           | BODY STICKER (SN) (CONSISTENT)          | NECESSARY     | 10.00                     | 10.00             |
|                                                                             |                                         |               | 10.00                     | 10.00             |
| <b>LABOUR</b>                                                               |                                         |               |                           |                   |
|                                                                             | PANEL BEATING.                          |               | 600.00                    | 400.00            |
|                                                                             | SPRAY PAINTING .                        |               | 1,000.00                  | 700.00            |
|                                                                             | WIRING.                                 |               | 30.00                     | 20.00             |
|                                                                             |                                         |               | 1,630.00                  | 1,120.00          |
| <b>GRAND TOTAL</b>                                                          |                                         |               | <b>2,799.56</b>           | <b>1,926.86</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                         |               |                           | <b>1,500.00</b>   |

Report Ref No. CC4/ASM18020876/Ujb3q2

**CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

<<   Service Request Details

|              |                                                                                                           |
|--------------|-----------------------------------------------------------------------------------------------------------|
| Claim        | SBM01JAX                                                                                                  |
| Reference    | CCA/ASM180208761U0342  |
| Loss Date    | 14 November 2018                                                                                          |
| Report Date  | 16 Nov 2018 12:00:00 AM                                                                                   |
| Request Date | 14 May 2019                                                                                               |
| Due Date     |                                                                                                           |
| Vendor Name  | LKX AUTO CONSULTANTS PTE LTD (TP)                                                                         |
| Type of Loss | Third Party Vehicle Damage                                                                                |
| Services     | Pending verification - Direct Settlement                                                                  |

Actions

Next Step

Wait for Approval Invoice

Add Invoice

|                                 |             |
|---------------------------------|-------------|
| Vehicle Information             |             |
| Incident Vehicle Registration # | GBH4481C    |
| Make                            | TRVD NISSAN |
| Model                           | NV350       |
| Service Address                 |             |
| ...                             |             |

Primary Contact/Insured

AUDI SINGAPORE PTE LTD  
8 KALLANG AVENUE, #08-01 to 09 APERIA  
TOWER 1, 339509, Singapore  
92333513  
amy.chong@audl.com.sg

Claim Handler

TAN Wincong  
tan.wancong@axa.com.sg

Additional Instructions

Messages   Invoices   History   Documents   Assessment   Metrics   Notes

Document Type

Document SubType

+ Upload Documents

| NAME                                                                                                        | TYPE    | SUB-TYPE                   | AUTHOR                            | DATE UPLOADED |
|-------------------------------------------------------------------------------------------------------------|---------|----------------------------|-----------------------------------|---------------|
|  LKX Invoice 1 (7).pdf | Invoice | Surveyor/ Assessor expense | LKX AUTO CONSULTANTS PTE LTD (TP) | 6 June 2019   |

| NAME                                                                                                                               | TYPE                       | SUB TYPE | AUTHOR                            | DATE<br>UPLOADED |
|------------------------------------------------------------------------------------------------------------------------------------|----------------------------|----------|-----------------------------------|------------------|
|  LKK PHOTO-3.pdf                                | Forms / Claim Documents    | Others   | LKK AUTO CONSULTANTS PTE LTD (TP) | 6 June 2019      |
|  LKK PHOTO-2.pdf                                | Forms / Claim Documents    | Others   | LKK AUTO CONSULTANTS PTE LTD (TP) | 6 June 2019      |
|  LKK PHOTO.pdf                                  | Forms / Claim Documents    | Others   | LKK AUTO CONSULTANTS PTE LTD (TP) | 6 June 2019      |
|  LKKInspection (1).pdf                          | Forms / Claim Documents    | Others   | LKK AUTO CONSULTANTS PTE LTD (TP) | 6 June 2019      |
|  LKKAdjustment1a.pdf                            | Forms / Claim Documents    | Others   | LKK AUTO CONSULTANTS PTE LTD (TP) | 6 June 2019      |
|  INSURED DRIVER VIDEO.mp4                       | Evidence                   | Video    | LKK AUTO CONSULTANTS PTE LTD (TP) | 17 May 2019      |
|  LETTER FROM OJD.pdf                            | Reports & Statement        | Others   | LKK AUTO CONSULTANTS PTE LTD (TP) | 17 May 2019      |
|  INSURED DRIVER K..pdf                          | Reports & Statement        | Others   | LKK AUTO CONSULTANTS PTE LTD (TP) | 4 March 2019     |
|  IA-IMART.pdf                                   | Reports & Statement        | Others   | LKK AUTO CONSULTANTS PTE LTD (TP) | 4 March 2019     |
|  INSURED DRIVING LICENCE.pdf                   | Reports & Statement        | Others   | LKK AUTO CONSULTANTS PTE LTD (TP) | 4 March 2019     |
|  AUTHORIZATION FROM AUTO-INSURED.pdf          | Reports & Statement        | Others   | LKK AUTO CONSULTANTS PTE LTD (TP) | 4 March 2019     |
|  INSURED DRIVERS PASSPORT SHOT FROM IMART.jpg | Reports & Statement        | Others   | LKK AUTO CONSULTANTS PTE LTD (TP) | 20 February 2019 |
|  SCENE PHOTO FROM IMART.jpg                   | Reports & Statement        | Others   | LKK AUTO CONSULTANTS PTE LTD (TP) | 20 February 2019 |
|  EMAIL FROM WORKSHOP.jpg                      | Letters and Correspondence | Workshop | DHIVAR Namvra                     | 30 January 2019  |

| NAME                                                                                                                                     | TYPE                          | SUB-TYPE    | AUTHOR                   | DATE<br>UPLOADED    |
|------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|-------------|--------------------------|---------------------|
|  EMAIL.msg                                            | Letters and<br>Correspondence | Workshop    | RATAN BHOSALE Pragati    | 9 January 2019      |
|  EMAIL FROM WORKSHOP.msg                              | Forms / Claim<br>Documents    | Others      | KUMAR Shalendra          | 8 January 2019      |
|  TRPO LOD - MEGACOOD PTE LTD.pdf                      | Letters and<br>Correspondence | Third Party | DHINWAR Namrata          | 11 December<br>2018 |
|  EMAIL FROM WORKSHOP INCLUDING GBH4481C<br>TP GIA.msg | Letters and<br>Correspondence | Workshop    | NIKAM Santosh Padurazang | 19 November<br>2018 |
|  GBH4481C TP.PDF                                      | Reports & Statement           | GIA Report  | KUMAR Shalendra          | 19 November<br>2018 |
|  SLX4419G INS GIA.pdf                                 | Reports & Statement           | GIA Report  | KUMAR Shalendra          | 19 November<br>2018 |