

ASS. REC. BY:

REF:

CS/FCT 18020885/ Jcds<sup>57</sup>

Special Instruction:

Surveyor

## ASSIGNMENT (Office)

CWS

From (Person): Karen tan

of

FCT

Date/Time: 19/11/18 @ 2:41pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKS 7319E

Insured:

SHD 6806L

at Workshop m/s

Motor Intel

Tel:

8838 3318

of

13 kaki Bukit Rd 4 #01-20

Policy No:

Claim No:

D18008151MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13/11/2018

(Client's Record)

20/11/18

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS (wp)

Date/Time: 3:14pm @ 19/11/18

Person Contacted:

Wilson

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

SKS 7319E - x

SHD 6806L - CS/GAE 18013254/G4d 3n2

Don: 14/17/18

PRS  
Hwee Jie

REF: TOL

# ASSIGNMENT

From: Date: 20-11-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKS 7319E

at Workshop m/s: Motor Intel

of: 13 Kaki Bukit Rd 4 #01-20

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKS 7319E Yr Regn: 29 Jan 2014

Type: ☒ Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Veloster C.C. 1591

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 75315 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHTC61EMDU171206

Gen. Cond: Good ☒ Fair / Poor / Burnt

Steering: Inorder / ☒ Jammed / Leaked / Burnt or

Brake: Inorder / ☒ Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 225/40 ZR18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Sumitomo

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 13/11/18 D.O.I. 20/11/18 11:19am

Survey held at Motor Intel @ 1130

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

Front / Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - \$63,500 \$61,000

PV - \$50,750

NV - \$10,250

RECEIVED 07 DEC 2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip: -

Survey Fee:

Date/Time, File Return to?

Transportation

2)

Add Fee: ☐ Site Insp (\$

) \$ + RS \$

☐ Interview (\$

) Photos

☐ Tech. Invs (\$

) Other

☐ Weekend (\$

)

Report Format: PRS

Lump Sum / I.B.I. (\$

TOTAL

### MOTOR SURVEY ASSIGNMENT

Date 15-11-2018 Our Ref No. D18008151MFSH

Accident Date 13-11-2018 Claim Type. Third Party

Insured Vehicle SHD6806L Third Party Vehicle. SKS7319E

Survey Location 13 KAKI BUKIT ROAD 4#01-20 BARTLEY BIZ CENTRE

Contact Person. WILSON ONG

Contact No. 62810087/ 88383318 Fax No. 65073849

Survey Type WITHOUT PREJUDICE:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA Fax No. 68416315

Contact Number. NA

### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

Cc : Workshop MOTOR INTEL AUTOMO PTE LTD Attention. NIL

Cc : TP Solicitor ALLISTER LIM & THRUMURGAN TP Solicitor Fax No. NA

Officer Incharge KARENT

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	16/11/2018 16:01
Date Of Accident	13/11/2018 23:15
Exact Location Of Accident	CTE >SLE AFTER MOULMEIN EXIT
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SKS7319E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HUANG LIN
NRIC No	S7069313E
Email Address	HUANG_LYNN@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97255729
Alternative Phone No	OTHERS-97255729
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	VELOSTER FS 1.6 TURBO AT ABS D/AB SR 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

**Insurance Company**

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI18V09140/VPC/R03
Cover Note Number	

**Driver**

Name of Driver	RICHARD PAUL FREEMAN
NRIC No	S2765458D
Date Of Birth	20/06/1946
Occupation	INDOOR
Date Of Driving Pass	18/04/1978
Driving Experience	40 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93892005
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHD6806L  
Vehicle Make/Model/Colour HYUNDAI SONATA  
Details Of Properties  
Vehicle Category TAXI  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1


Name RICHARD PAUL FREEMAN  
Approximate Age 48  
Injuries Sustain  
Injured person in which vehicle? SKS7319E  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO  
Address 25 KELULUT HILL  
Postcode 805879

#### DETAILS OF INJURED PERSON 2

Name HUANG LIN  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SKS7319E  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance?  
Address 25 KELULUR HILL  
Postcode 805879

# Accident Sketch Plan Pg. 1

## SKETCH PLAN



VEH A > SKS 7319E

VEH B > SHD 6806L

VEH C > SFW 3666S

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to police report T/20181115/7009.

## DECLARATION

I/We declare the foregoing particulars are true in every respect

x *[Signature]*

Policyholder's Signature  
Date & Time

x *[Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

16 NOV 2018

IDAC KAKI BUKIT (VAC)

23 KAKI BUKIT AVE 4

Reporting Centre  
Name: Singapore 415933

NRIC/PIN No: Tel: 67416697

Fax: 67492305

Email: vackb@sine.net.com.sg

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

10,000  
Bal = 5 yrs. 2.2m + 8

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	9313E
<b>Vehicle Details</b>	
Vehicle No.:	SKS7319E
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Nov 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	VELOSTER FS 1.6 TURBO AT ABS D/AB SR 4DR
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	G4FJDS576287
Chassis No.:	KMHTC61EMDU171206
Maximum Power Output:	137.0 kW (183 bhp)
Open Market Value:	\$17,661.00
Original Registration Date:	29 Jan 2014
First Registration Date:	29 Jan 2014
Transfer Count:	1
Actual ARF Paid:	\$17,661.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2024
PARF Rebate Amount:	\$13,245.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	28 Jan 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$70,133.00
COE Rebate Amount:	\$37,505.00
<b>Total Rebate Amount:</b>	<b>\$50,750.00</b>

8,830

The information contained herein is correct as at 20 Nov 2018

OK

**K & P Auto Services Pte Ltd - Repair & Servicing**

K & P Auto Services Pte Ltd is a Service Centre specializing in the service and repair of Japanese & Korean car-makes.

[More info about this shop](#)

**Hyundai Veloster 1.6A GDI Turbo****\$52,800****\$10,650 /yr****16-Jan-2013****1,591 cc****11**

3 Months Warranty From Our In-house Workshop. Excellent Condition, Accident Free, No Repair Needed, Bank Loan In F Welcome.

Posted: 11-Nov-2018

Tags: 2013 Hyundai Veloster, 2013 hyundai veloster, Hyundai Veloster, hyundai veloster, Hyundai, Ve veloster, Used Hyundai

**Hyundai Veloster 1.6M GLS****\$78,900****\$9,300 /yr****12-Jul-2016****1,591 cc****22**

Look No Further, One And Only Manual Sports Coupe In Town! Experience Quick Acceleration Of 130BHP On This Mid 20 Manual Owned By 1 Owner Selling Due To New Member In The ...

Posted: 02-Nov-2018

Tags: 2016 Hyundai Veloster, 2016 hyundai veloster, Hyundai Veloster, hyundai veloster, Hyundai, Ve veloster, Used Hyundai

**Hyundai Veloster 1.6A GDI Turbo****\$59,888****\$12,060 /yr****19-Feb-2013****1,591 cc****88**

In Good Pristine Condition. Smooth Drive With Great Power. A Nice And Sleek Outlook. Definitely A Head Turner. Don't V

Posted: 23-Oct-2018

Tags: 2013 Hyundai Veloster, 2013 hyundai veloster, Hyundai Veloster, hyundai veloster, Hyundai, Ve veloster, Used Hyundai

**Hyundai Veloster 1.6A GDI****\$46,500****\$9,530 /yr****26-Nov-2012****1,591 cc****48**

Limited Period Only Enjoy Loan Interest Rate At 2.28%! 1 Lady Owner Only! Galant White Sporty Hyundai Hatchback. Ex Performance. Well Maintained And Service. No Further Rep...

Posted: 05-Oct-2018

Tags: 2012 Hyundai Veloster, 2012 hyundai veloster, Hyundai Veloster, hyundai veloster, Hyundai, Ve veloster, Used Hyundai

[Save this search criteria, to get email alerts whenever a match is found.](#)

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mile

[For old advertisements, view Expired ads](#)

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [For](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, buy used Hyundai Veloster, Hyundai Veloster Singapore, used Hyundai Veloster Singapore, used Hyundai Veloster, used vehicles Singapore or have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car la sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, (

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart. that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or wa

**Follow sgCarMart.com**

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection](#)

©2004-2018 sgCarMart. All rights reserved.

[Compare](#)



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

**PRE-REPAIR INSPECTION REPORT**

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Ref: CS3/FCI18020885/Jcd3s2

Date: 14-12-2018



Code: FCI2

**1. Policy Particulars :- (THIRD PARTY CLAIM)**

Insured Veh.	SHD 6806L	Veh. Inspected	SKS 7319E
Policy No.		Coverage (\$)	0.00
Claim No.	D18008151MFSH	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	19/11/2018

**2. Vehicle Particulars & Condition**

Make & Model	HYUNDAI VELOSTER	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KMHTC61EMDU171206	Colour	WHITE
Odometer	75315 KM	Steering	JAMMED
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	225/40ZR18	SUMITOMO	6 mm
L/H Front Tyre	225/40ZR18	SUMITOMO	6 mm
R/H Rear Tyre	225/40ZR18	SUMITOMO	6 mm
L/H Rear Tyre	225/40ZR18	SUMITOMO	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

**5. General Information**

Accident Date	13/11/2018	Inspect Date / Time	20/11/2018 ( 11:19 AM )
Survey held at	MOTOR INTEL AUTOMO PTE LTD 13 KAKI BUKIT ROAD 4 @ BARTLEY BIZ CENTRE #01-20 SINGAPORE 147807		

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.  
D) MARKET VALUE: \$61,000.00

Report Ref No. CS3/FCI18020885/Jcd3s2

**Inspected By**

ONG HWEE JIE

Automotive Assessor

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.