

Surveyor: Kelvin

REF: CC3/TML18020904/K14052

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspected Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: **SLL 8511J**
 Policy No: **MU002931**
 Claims No: **M1805882**
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: **3** days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SHC 667R** Yr Regn: **15 Dec, 2017**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Hyundai Ix0** C.C. **1685**
 Colour: **Yellow** A/C: Insured / Std / NI / NA
 Sp. Reading: **150044** T/Radio: Insured / Std / NI / NA
 Eng. No: _____
 C/No: **KMHCB4111111111111111**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD / A/Rim or
 Tyre Size: F: **205/60R16**
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Haruh**

Front		Rear	
R/Bal. 7	mm	R/Bal. 7	mm
L/Bal. 7	mm	L/Bal. 7	mm
D.O.A. 16/11/18		D.O.I. 19/11/18	

Survey held at **CPGE (Loyang)**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHC 667R - CS / FCL 5019065 / Fgbd1
	SLL 8511J - X
20/11/18 @ 2.18pm	Email GIA & estimate to TML.
20/11/18	Letter P/P \$3240.88 / 3 Pys. (Red to 459.68, 12%)
	X DAMAGES CONSISTENT TO ACCIDENT REPORT.
	RECEIVED 21 NOV 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) 21/11 12:00pm ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: **250**

Transportation: _____

____ S + RS ____ SI

Photos

Others

TOTAL

Report Format: **MEP-TP**

Lump Sum / I.B.I. (\$ **3240.88**)

250
10

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 20 November 2018 2:18 PM
To: Motor Claims
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - COMFORTDELGRO ENGINEERING PTE LTD, DOA: 16/11/2018, SHC 667R (TP VEHICLE), SLL 8511J (OI VEHICLE)
Attachments: SHC667 EST.pdf; SHC667 GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 667R, M/s: COMFORTDELGRO ENGINEERING PTE LTD, 59 LOYANG DRIVE SINGAPORE 508969 on 19/11/2018.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/11/2018 14:32
Date Of Accident	16/11/2018 11:00
Exact Location Of Accident	BUKIT TIMAH RD TWDS UPP B.TIMAH B4 WINSTEDT RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC667R
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

Driver

Name of Driver	SELVARAJOO RAJA SEKARAN
NRIC No	S1239280Z
Date Of Birth	15/08/1957
Occupation	OUTDOOR
Date Of Driving Pass	07/07/1983
Driving Experience	35 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91625768
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 409 YISHUN RING ROAD #04-1787
Postcode	760409
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED / Type Of Accident : HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL8511J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN JIAN SHENG
NRIC/Passport Number	S8212459D
Contact Number	97562193
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	WHOLE LEFT SIDE
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CITYCAB PTE LTD
CO. REG. NO. 199502839C


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 16.11.2018 @ 12:05 Hrs


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16.11.2018 at about 11:00 hrs, I was travelling along Bukit Timah Rd before Winstedt Rd
with no passenger on board.
I was travelling on the extreme left lane. I slowed down my vehicle and wanted to turn left into
the petrol kiosk on my left. Suddenly, veh (B) (SLL 8511J) cut into my lane from my right and
collided into my taxi (A) front right portion.
Both of us then alighted and exchanged the particulars. I have company video fixed in my taxi
and photos taken at scene to support my claims.
Veh (B) (SLL 8511J) was driven by Mr. Tan Jian Sheng. NRIC : S 8212459D. Hp : 9756 2193.
No injury in this accident.

DECLARATION



I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 16.11.2018 @ 12:05 Hrs

Reportline Centre Personnel's Signature
Name: J. H. Tan
NRIC/FIN No.: 16/11





Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
229 Ubi Road 3 Singapore 408999

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

A member of COMFORTDELGRO

Date/Time: 19.11.2018 11:23

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD

Sales Order: 3874484

JC NO.: 305240622

CUSTOMER
CITYCAB PTE LTD
7010070
CUSTOMER NO.
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188 (R) (O)
(P)

REGN NO.: SHC 667R	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 19.11.2018 09:15
YR OF MANU 15.12.2017	TARGET DATE
CHASSIS CODE KMHLB41UMEU052434	COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION


Accident Date: 16.11.2018
NATURE: 3P 16.11.18/B-

TOKIO MAKE

S/NO LABOR CODE

DESCRIPTION

FRONT



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC 667R FZ TOKIO

Vehicle No.: SHC 667R

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 667R

DATE 16/11/2018 14:00

MAKE :

MODEL : HYUNDAI i40

F2

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>Refined</i>			\$ 1,052.20
	Front Bumper Bracket (RH) <i>Xin</i>			\$ 24.60
	Headlamp (RH) <i>Car</i>			\$ 1,388.00
	Front Fender (RH) <i>Art</i>			\$ 566.30
	Frt Wheel Hub Cap, RH <i>braded</i>			\$ 107.10
	SUB TOTAL			\$ 3,138.20
	LESS 20%			\$ 627.64
	DISCOUNTED TOTAL			\$ 2,510.56
	Labour Charge			
	Panel Beating			\$ 500.00 <i>300</i>
	Spray Painting Charge			\$ 50.00 <i>500</i>
	Wiring			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Frt Wheel Alignment			\$ 80.00 <i>X</i>
	<i>Marine Fee \$10/-</i>			
	TOTAL LABOUR			\$ 980.00 <i>1180</i>
	ESTIMATE TOTAL			\$ 3,490.56 <i>3690.56</i>
<p><i>Kaluh 10/11/18</i></p> <p><i>19/11/18 1215hrs.</i></p> <p><i>3 hrs</i></p> <p><i>P/P</i></p> <p><i>Before Paint photo</i></p>				
<p>LKK Auto Centre (Pte) Ltd</p> <p>the Repairer of the above vehicle</p> <ul style="list-style-type: none"> To resolve any dispute between the parties To display the repair estimate to the customer Parts prices are subject to change without notice Third party survey is subject to the insurance company's approval No liability for consequential damage Supplementary charges for parts and labour are subject to the insurance company's approval <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305240622
Date : 20.11.2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN

Fax :

Vehicle Reg No. : SHC 667R


Date of Accident : 16.11.2018


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SLL8511J
2. The finalized amount shall be:

(a) Spare Parts after List discount		\$2,490.88
(b) Labour Charges		\$750.00
Total for Part-By-Part Repair Cost		\$3,240.88
(c.) Lumpsum Repair (if applicable)		
Total for Lumpsum repair cost after Less:	20%	\$0.00
Final Lumpsum Repair cost		\$0.00
3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : FAUZY BIN MOKHTAR
Tel : 62148319
Fax : 65468156

Signature : 
Name : Kalvin
Date : 20/11/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 20.11.2018

Time: 17:39:01

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305240622
REGN NO : SHC 667R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 15.12.2017
DATE/TIME IN : 19.11.2018 09:15
ACCIDENT DATE : 16.11.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1	1,052.20	20.00	841.76
0002 04-01-0103-0782-A	I40V2 LAMP ASSY-HEAD RH#	1	1,388.00	20.00	1,110.40
0003 04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	107.10	20.00	85.68
0004 04-01-0103-0573-A	I40VC PANEL-FENDER RH+	1	566.30	20.00	453.04

SUB-TOTAL : 2,490.88

JOB NATURE

0000 L	PANEL BEATING	300.00
0001 L	SPRAY PAINTING CHARGE	400.00
0002 L	WIRING CHARGE	20.00
0003 L	TUFF KOTE	20.00
0004 L	MERIMEN FEE	10.00

SUB-TOTAL : 750.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 20.11.2018

Time: 17:39:01

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305240622

REGN NO : SHC 667R

MILEAGE : 0000000000

MAKE : HYUNDAI

MODEL : I-40

DATE OF REGN : 15.12.2017

DATE/TIME IN : 19.11.2018 09:15

ACCIDENT DATE : 16.11.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,240.88

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE

DATE :

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CITYCAB PTE LTD

Singapore

Claimant Insurer: MS First Capital Insurance Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	16/11/2018
Vehicle Reg. No.:	SHC667R	Driveable?	NO
Party At Fault:	UNKNOWN		
Driver (TP):	SELVARAJOO RAJA SEKARAN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	15/12/2017
Vehicle Colour:	YELLOW	Gen Condition:	FAIR
Engine No:	D4FDHU730816	Chassis No:	KMHLB41UMEU052434
Odometer:	100000 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	PLS REFER TO ATTACHED / TYPE OF ACCIDENT : HEAD TO SIDE		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	2,530.24
Miscellaneous Items	10.00
Labour	1,180.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,720.24
+ GST 7.00% (S\$)	260.42
Nett Amount (S\$)	3,980.66

This claim is handled by: FAUZY BIN MOKHTAR

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Nov 2018)

Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC667R/19/11/2018 18:00

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	20.00	0.00	*1,052.20 FL De
2	1		*FRONT BUMPER BRACKET RH	20.00	0.00	*24.60 FL S4C
3	1		*HEADLAMP RH	20.00	0.00	*1,388.00 FL cca
4	1		*FRONT FENDER RH	20.00	0.00	*566.30 FL dd
5	1		*FRONT WHEEL HUP CAP RH	20.00	0.00	*107.10 FL Gra
6	1		*FRONT FENDER SIDE RETAINER	20.00	0.00	*24.60 FL S4C

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	3,162.80
- List Item Discount on L Items (S\$)	632.56
Total Parts (S\$)	2,530.24

ComfortDelGro Engineering Pte Ltd/SHC667R/19/11/2018 18:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (\$\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	500.00 300
2	SPRAY PAINTING CHARGE	New	500.00 400
3	WIRING CHARGE	New	50.00 20
4	TUFF KOTE	New	50.00 20
5	FRONT WHEEL ALIGNMENT	New	80.00
Gross Labour Cost (\$\$)			1,180.00

ComfortDelGro Engineering Pte Ltd/SHC667R/19/11/2018 18:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Nov 2018 17:55 Sendback Est	19 Nov 2018 18:00 S\$3,720.24	20 Nov 2018 09:42 Edit Adj Rpt	S\$3,240.88 Edit Estimates	S\$3,240.88 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	CITYCAB PTE LTD , Co. Reg. No.: 199502839G		
Main Claimant:	CITYCAB PTE LTD , Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	SHC667R	Date of Loss:	16/11/2018 11:00 - :59 [11 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1805882	Policy/Cover Note No.:	MU002931 (Comprehensive) Coverage: 13/03/2017 - 12/03/2019
Vehicle Reg. No. (Insured):	SLL8511J	Policy No. (Claimant):	D-18088937MFSH
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 29/11/2018]		
Adj Asg. Remarks:	PLS. CHECK THE CONSISTENCY OF THE DAMAGE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.


























ALL ASSOCIATED TASKS

















[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHC667R (M1805882)
[SLL8511J]
TP
CITYCAB PTE LTD
Nov 16 2018 11:00AM
[CITYCAB PTE LTD]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	20/11/18 09:41	Video - Accident From:SC - Reg. No: SLL8511J, Claimant: TAN JIANSHENG JASON	 Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	16/11/18 15:04	Accident Statement	 Load HTM	
2	19/11/18 18:00	Repairer Estimates	 Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	20/11/18 09:41	Accident Statement From:SC - Reg. No: SLL8511J, Claimant: TAN JIANSHENG JASON	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	16/11/18 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	16/11/18 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	16/11/18 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	16/11/18 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	16/11/18 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	16/11/18 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	16/11/18 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	16/11/18 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	16/11/18 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	16/11/18 14:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/11/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
2	20/11/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
3	20/11/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
4	20/11/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
5	20/11/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
6	20/11/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
7	20/11/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
8	20/11/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
9	20/11/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
10	20/11/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>
11	20/11/18 18:41	General View	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page ▼	✓
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
12	20/11/18 18:41	General View	 Load JPG	✓
13	20/11/18 18:41	General View	 Load JPG	✓
14	20/11/18 18:41	General View	 Load JPG	✓
15	20/11/18 18:41	General View	 Load JPG	✓
16	20/11/18 18:41	General View	 Load JPG	✓
17	20/11/18 18:41	General View	 Load JPG	✓
18	20/11/18 18:41	General View	 Load JPG	✓
19	20/11/18 18:41	General View	 Load JPG	✓
20	20/11/18 18:41	General View	 Load JPG	✓
21	20/11/18 18:41	General View	 Load JPG	✓
22	20/11/18 18:41	General View	 Load JPG	✓
23	20/11/18 18:41	General View	 Load JPG	✓
24	20/11/18 18:41	General View	 Load JPG	✓
25	20/11/18 18:41	General View	 Load JPG	✓
26	20/11/18 18:41	General View	 Load JPG	✓
27	20/11/18 18:52	Reinspection Photo	 Load JPG	✓
28	20/11/18 18:52	Reinspection Photo	 Load JPG	✓
29	20/11/18 18:52	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	16/11/18 15:02	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

View View in Browser ▾

Assessment Reports			1 per page ▾	▾
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	16/11/18 15:04	Accident Statement	 Load HTM	

Photos/Images			3 per page ▾	▾
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	16/11/18 14:37	Accident Photo	 Load JPG	▾
2	16/11/18 14:37	Accident Photo	 Load JPG	▾
3	16/11/18 14:37	Accident Photo	 Load JPG	▾
4	16/11/18 14:37	Accident Photo	 Load JPG	▾
5	16/11/18 14:37	Accident Photo	 Load JPG	▾
6	16/11/18 14:37	Accident Photo	 Load JPG	▾
7	16/11/18 14:37	Accident Photo	 Load JPG	▾
8	16/11/18 14:37	Accident Photo	 Load JPG	▾
9	16/11/18 14:37	Accident Photo	 Load JPG	▾
10	16/11/18 14:37	Accident Photo	 Load JPG	▾

Documentation			1 per page ▾	▾
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	16/11/18 15:02	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18020904/K1QBS2

Date: 27/11/2018

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MU002931

Claimant Vehicle No: SHC667R

Insured Vehicle No: SLL8511J

Date of Loss: 16/11/2018

Nature of Claim: TP

Claim No: M1805882

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC667R

Make & Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4FDHU730816

Reg. Date: 15/12/2017 (Man. Year: 2016)

Chassis No: KMHLB41UMHU100068

Colour: Yellow

Odometer: 150044 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes

Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No

Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 205/60R16

Rear Tyre Size: 205/60R16

Front Left Side: Hankook 7 mm

Rear Left Side: Hankook 7 mm

Front Right Side: Hankook 7 mm

Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,530.24	2,490.88	39.36	1.56
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	1,180.00	740.00	440.00	37.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,720.24	3,240.88	479.36	12.89
+ GST 7.00/7.00% (S\$)	260.42	226.86	33.56	12.89
Nett Amount (S\$)	3,980.66	3,467.74	512.92	12.89

INSPECTION

Date of Assignment: 20/11/2018 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 19/11/2018 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

* DAMAGES CONSISTENT TO ACCIDENT REPORT.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Nov 2018)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC667R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,052.20 FL	*1,052.20 FL
2	1		*FRONT BUMPER BRACKET RH	Serviceable	24.60 FL	*- FL
3	1		*HEADLAMP RH	Cracked	1,388.00 FL	*1,388.00 FL
4	1		*FRONT FENDER RH	Dented	566.30 FL	*566.30 FL
5	1		*FRONT WHEEL HUP CAP RH	Grazed	107.10 FL	*107.10 FL
6	1		*FRONT FENDER SIDE RETAINER	Serviceable	24.60 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,162.80	3,113.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	632.56	622.72
Total Parts (\$\$)	2,530.24	2,490.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	300.00
2	SPRAY PAINTING CHARGE	New	500.00	400.00
3	WIRING CHARGE	New	50.00	20.00
4	TUFF KOTE	New	50.00	20.00
5	FRONT WHEEL ALIGNMENT	New	80.00	-
Gross Labour Cost (S\$)			1,180.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >