#### SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

aforesaid.	ent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	20/11/2018 10:24
Date Of Accident	19/11/2018 08:45
Exact Location Of Accident	BLK 795A YISHUN RING RD CARPARK ENTRANCE
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	XE2209S
Insured/Policyholder	
Name Of Registered Owner	JET-VACS SERVICE PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68420828
Vehicle Particulars	
Manufacturer	ISUZU
Model	CYZ52R
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MCV0001316
Cover Note Number	-
Driver	
Name of Driver	HENG CHOON MENG (WANG JUNMING)
NRIC No	S7132434F
Date Of Birth	10/09/1971
Occupation	OUTDOOR
Date Of Driving Pass	17/03/2014
Driving Experience	4 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94870302
Fax Number	

**NOEMAIL** 

Address 630 HOUGANG AVE 8 #10-60

Postcode 530630

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

\_

Insurance Company of Driver's Own Vehicle

-

NO

NO

#### **General Information of the Accident**

Type Of Accident NO COLLISION

Weather Conditions CLEAR
Road Surface DRY

#### **Other Information**

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 3

Passenger 1

NAME: : UNKNOWN

GENDER: : MALE

Passenger 2 NAME: : UNKNOWN

GENDER: : MALE

### **Details of Police Action**

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### **Circumstances of Accident**

PLEASE REFER TO ATTACHED STATEMENT.

### Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

Vehicle Make/Model/Colour BARRIER CONTROL BOX

**Details Of Properties** 

Vehicle Category NA/UNKNOWN

Name of Driver

NRIC/Passport Number

**Contact Number** 

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 3. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- S Consent under the Personal Data Protection Act (PDPA)

understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (iii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents[including their lawyers/law firms], which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

(O)

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

## **Accident Sketch Plan**

7951		
4	Partier control box	
		A = XE 2209S
RIBE CIRCUMSTAN	CES OF THE ACCIDENT	
Please	Refer to	statement
		,
	/	
RATION		
RATION clare the pregoing pa	articulars are true in every respect.	The state of the s

### Accident Sketch Plan

WHILE ENTERING INTO BLK 795A YISHUN RING RD CARPARK. THAT WAS A PARKED LORRY BLOCKING MY PATH, I HAVE TO MAKE AN EARLY LEFT TURN, AS THE RESULT, MY LORRY RIGHT REAR MISJUDGED HIT ONTO THE BARRIER CONTROL BOX.

















