

ASS. REC. BY:

REF: CS

EQ 118020936 / Utd307

Special Instruction:

Surveyor:

Manus

ASSIGNMENT (Office)

From (Person):

Joel Goh

of

EQI

Date/Time:

20/11/18 @ 9:40am

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG1451P

Insured:

at Workshop m/s

SME Motor

Tel:

6747 6106

of

1 Kaki Bkt Ave 6 #02-15 Autobay

Policy No:

DMCPH018-003465

Claim No:

DM18H003118

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A.

12/11/18

(Client's Record)

☒ CA

if consistent

/ REV

/ REP.

/ REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:46am @ 20/11/18

Person Contacted:

pei ying

Vehicle IN ☒ OUT

Date/Time

Action/Instruction

(✓)

Estimate

GBG1451P-X

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 9361451Pat Workshop m/s SMC 10am.

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 5000.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: 2 Consistent?: Yes or NoEst. Repairs: 4 days Res.: Yes or NoLum Sum: 1.72 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: G361451P Yr Regn: 6117

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CMMake: Toyota hiace c.c. 2982Colour: silver A/C: Insured / Std / NI / NASp. Reading: 110775 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KD14 201 0.2 / 5288

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195-12.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 2/1/18 D.O.I. 2/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 13 DEC 2010

Date/Time, File Pass to?

☐ : Preli. Report1) 31/12 typist ☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4Resurvey No. of Trip: 1Survey Fee: 160

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) S + RS, SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.L. (\$) 1585.30

17/12/18 confirmed final by 1585-30 with AH ying.
(Red: 1085, 40%)

160
160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Nov 2018 Sendback Est	19 Nov 2018 13:20 S\$2,670.30	20 Nov 2018 09:40 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	LHH VEGETABLE PTE LTD, Co. Reg. No.: 201604822N		
Vehicle Reg. No.:	GBG1451P	Date of Loss:	12/11/2018 21:00 - :59 [16 Months and 30 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DM18HO03118	Policy/Cover Note No.:	DMCPHQ18-003465 (Comprehensive)
		Excess:	S\$500.00
Repairer:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/11/2018]		
Driver/Custodian:	CHAN LEI KHEONG (55 / Male), NRIC: S1518920G, Tel: +6581266437		
Adj Asg. Remarks:	EXCESS: \$500.00 (NO WAIVER) AUTHORISE IF CONSISTENT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	13/11/2018 16:47
Date Of Accident	12/11/2018 21:05
Exact Location Of Accident	603 WOODLANDS DRIVE 42
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBG1451P
Insured/Policyholder	
Name Of Registered Owner	LHH VEGETABLE PTE LTD
Co Reg No	201604822N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65474393
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ18-003465
Cover Note Number	
Driver	
Name of Driver	CHAN LEI KHEONG
NRIC No	S1518920G
Date Of Birth	13/11/1962
Occupation	INDOOR
Date Of Driving Pass	24/03/1983
Driving Experience	35 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81266437
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 169 LORONG 1 TOA PAYOH #07-1070
Postcode	310169
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DOING A REVERSE. BEFORE I GET INTO MY VEHICLE, I NOTICED THAT THERE WAS NO VEHICLE. SUDDENLY, I FELT AN IMPACT AND REALISED THAT VEHICLE B WAS THERE AND I KNOCKED INTO VEHICLE B REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLW5844K
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4822N
Vehicle Details	
Vehicle No.:	GBG1451P
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 3.0 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2682000
Chassis No.:	KDH2010215298
Maximum Power Output:	-
Open Market Value:	\$32,138.00
Original Registration Date:	13 Jun 2017
First Registration Date:	13 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$1,607.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jun 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$30,600.00
COE Rebate Amount:	\$26,194.00
Total Rebate Amount:	\$26,194.00

The information contained herein is correct as at 21 Nov 2018

OK



ANNOUNCING Carway as sgCarMart Premium Dealer 2018



CARWAY
Your Satisfaction Is Our Success

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan. Trade In Are
Welcome. 100% Deposit Refund
For Unapproved Loan.
Classic Credit [Star Ad](#)






Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼


15 vehicles

toyota hiace

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota hiace		Any	Any	2017	Any	Any	Any	Available
	Toyota Hiace		\$74,800	\$8,560 /yr	16-Aug-2017	2,982 cc	-	Van	Available
Fuel Type: Diesel Deliver Before End Of June 2018! Euro 6 Toyota Hiace Turbo 5DR Manual, Borneo Unit, Ready Stock, Agent Warranty 3 Years Or 100000Kml 90% To 100% Loan Available!									
Posted: 22-Nov-2018 Tags: 2017 Toyota Hiace, 2017 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace		\$73,800	\$8,620 /yr	15-Jun-2017	2,982 cc	65,000 km	Van	Available
Fuel Type: Diesel Only One Available In The Market! Still Under Warranty Till 3years/80,000 Mileage! Tinted Windows! 2.5" Lowered! Well Maintained By Owner! Flexible Loan Packages Available!									
Posted: 21-Nov-2018 Tags: 2017 Toyota Hiace, 2017 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace Commuter		\$88,888	\$10,360 /yr	22-Jun-2017	2,982 cc	-	Bus	Available
Fuel Type: Diesel Free 1 Year Warranty! Super Tip Top Condition! Hiroof Super GL Model 13+1s! Flexible In-house Loan! \$500 Drive Away!									
ABWIN Bus Pte Ltd									
Posted: 19-Nov-2018 Tags: 2017 Toyota Hiace, 2017 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace		\$57,800	\$6,800 /yr	23-May-2017	2,982 cc	38,000 km	Van	Available
Fuel Type: Diesel Well Maintained! Engine And Gearbox In Superb Condition. Agent Unit Vehicle.Warranty Still Valid With 2 Free Servicing From Borneo Motors Still Not Utilised. High Loan And Trade In Welcomed! Call Now ...									
Car (S) Pte Ltd									
Posted: 19-Nov-2018 Tags: 2017 Toyota Hiace, 2017 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	DVD Panel	Daihatsu Materia dvd panel / Toyota b8 P anel							
More info about this product									
	Toyota Hiace		\$59,800	\$6,630 /yr	30-Nov-2017	2,982 cc	10,687 km	Van	Available
Fuel Type: Diesel Cheapest In Town, 3 Day Delivery, Price Negotiable, Flexible Loan With Lowest Interest Rate, In House Finance Available, Super High Trade In, Call Now!									
ABWIN Bus Pte Ltd									
Posted: 17-Nov-2018 Tags: 2017 Toyota Hiace, 2017 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace		\$59,800	\$6,920 /yr	13-Jul-2017	2,982 cc	-	Van	Available
Fuel Type: Diesel Used For Only A Year, Well Kept And Maintained By Owner! No Repairs Needed. Under Warranty. Monthly Cheaper Than Rental, High Loan Available. Call Now To View!									
ABWIN (1994) Pte Ltd									
Posted: 16-Nov-2018 Tags: 2017 Toyota Hiace, 2017 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
Compare	yota Hiace		\$67,800	\$7,560 /yr	09-Nov-2017	2,982 cc	30,107 km	Van	Available
Fuel Type: Diesel									

Compare



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
DAIHATSU / KIA / SUZUKI / HONDA
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: SME MOTOR PTE LTD

1 KAKI BUKIT AVE.6

#02-15/16/17/18 AUTOBAY @KAKI BUKIT

SINGAPORE 417883

GBG1451P

GARY

NO: DLI9211208

PAGE: 1

DATE: 07/12/2018

A/C CODE: LDSM446

TERMS: CR

P/O NO: GBG1451P

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
Our D/O No: DDO9022520						
1	T75441-26241	BOOT PLATE (HIACE)	DD1AS3-9	1	28.00	28.00
2	T52159-26490	BUMPER RR -W/STEP	DDS	1	160.00	160.00
3	T52166-26020-B1	COVER LH -	DU1E44-3	1	60.00	60.00
4	T81561-26201	TAILLEN LH	DBCC2	1	120.00	120.00
5	T90975-02064	BOOT LOGO	DDS	1	35.00	35.00
6	T90467-09185	CLIP BUMPER	DDS	10	2.00	20.00
			TOTAL QUANTITY:	15	TOTAL	SIN 423.00
					ADD GST @ 7%	29.61
					GRAND TOTAL	SIN 452.61

Print / LSK / 7/12/2018 9:03:51 AM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY



SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: EQ Insurance Company Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE) Ref. No: 18/EQ/OD-524 (11)
 Policy No: DMCPHQ18-003465 Date of Loss: 12/11/2018
 Vehicle Reg. No.: GBG1451P Driveable?
 Driver Age/Info: 55 / MALE Party At Fault: UNKNOWN
 TP Injury Involved? NO Third Party Involved? YES
 Insured/Claimant: LHH VEGETABLE PTE LTD
 Driver: CHAN LEI KHEONG

Make/Model: TOYOTA HIACE, 3.0 D DX (M) Vehicle Reg. Date: 13/06/2017
 Vehicle Colour: SILVER
 Engine No: 1KD2682000 Chassis No: KDH2010215298
 Odometer: 0 KM

Paint Type:
 Total Loss? NO
 Est. Duration of Repair 5 (day)

Description of Accident/Loss: I WAS DOING A REVERSE. BEFORE I GET INTO MY VEHICLE, I NOTICED THAT THERE WAS NO VEHICLE. SUDDENLY, I FELT AN IMPACT AND REALISED THAT VEHICLE B WAS THERE AND I KNOCKED INTO VEHICLE B REAR PORTION.
 Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS	Amount
Parts	1,290.30
Miscellaneous Items	30.00
Labour	1,350.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,670.30
+ GST 7.00% (\$\$)	186.92
Nett Amount (\$\$)	2,857.22

This claim is handled by: CHIA PEI YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Nov 2018)

Parts: 213 TOYOTA HIACE 3.0 D DX (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/GBG1451P/19/11/2018 13:20

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR GATE <i>2</i>	0.00	0.00	*750.00 F <i>X</i>
2	1		*REAR CENTER LOGO <i>101</i>	0.00	0.00 <i>/</i>	*35.00 F <i>/</i>
3	1	<i>hiace</i>	*REAR GATE STICKER <i>101</i>	0.00	0.00 <i>/</i>	*28.00 F <i>/</i>
4	1		*REAR BUMPER <i>101</i>	0.00	0.00 <i>/</i>	*160.00 F <i>/</i>
5	10		*REAR BUMPER CLIP <i>101</i>	0.00	0.00 <i>/</i>	*20.00 F <i>/</i>
6	1		*REAR LH CORNER PANEL <i>101</i>	0.00	0.00 <i>/</i>	*60.00 F <i>/</i>
7	1		*REAR LH TAIL LAMP <i>101</i>	0.00	0.00 <i>/</i>	*120.00 F <i>/</i>

F=Franchise part.

Sub Total (S\$) **1,173.00**
+ Margin on L,N Items 10.00% (S\$) **117.30**

Total Parts (S\$) **1,290.30**

SME Motor Pte Ltd/GBG1451P/19/11/2018 13:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

423
1%
465.30

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	REAR GATE LH STICKER 70KM/H	15.00
2	1	REAR GATE RH STICKER 8 PAX	15.00
Sub Total (S\$)			30.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New	30.00
2	REMOVE & REFIX REAR WINDSCREEN	New	120.00
3	LABOUR CHARGE	New	600.00
4	SPRAY PAINTING	New	600.00
Gross Labour Cost (S\$)			1,350.00

SME Motor Pte Ltd/GBG1451P/19/11/2018 13:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

GRK Auto Consultants hereby certify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Warranted Advice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1586.30

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time:

LHH Vegetable Pte Ltd

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was doing a reverse. Before i get into my vehicle i notice that there was no vehicle. Suddenly i felt an impact and realized that vehicle B was there and i knock into vehicle B rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

LHH Vegetable Pte Ltd

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Nov 2018 Sendback Est	19 Nov 2018 13:20 S\$2,670.30	20 Nov 2018 09:40 Edit Adj Rpt	S\$1,585.30 Edit Estimates	S\$1,585.30 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: LHH VEGETABLE PTE LTD , Co. Reg. No.: 201604822N									
Vehicle Reg. No.: GBG1451P		Date of Loss: 12/11/2018 21:00 - :59 [16 Months and 30 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / DM18HO03118		Policy/Cover Note No.: DMCPHQ18-003465 (Comprehensive)							
		Excess: S\$500.00							
Repairer: SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)									
Handling Insurer: EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Joel Goh]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 29/11/2018]									
Driver/Custodian: CHAN LEI KHEONG (55 / Male), NRIC: S1518920G, Tel: +6581266437									
Adj Asg. Remarks: EXCESS: \$500.00 (NO WAIVER) AUTHORISE IF CONSISTENT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBG1451P (DM18H003118)
OD
Nov 12 2018 9:00PM
[LHH VEGETABLE PTE LTD]
SME Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)								Thumbnail	Print	
1	19/11/18 13:20	Repairer Estimates							1	Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
2	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
3	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
4	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
5	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
6	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
7	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
8	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
9	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
10	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
11	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
12	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
13	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
14	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
15	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
16	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
17	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
18	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
19	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
20	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
21	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
22	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
23	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
24	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
25	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
26	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
27	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
28	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
29	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
30	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
31	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
32	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
33	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
34	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	
35	13/12/18 12:03	General View							1	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
36	13/12/18 12:03	General View		Load JPG	<input checked="" type="checkbox"/>
37	13/12/18 12:03	General View		Load JPG	<input checked="" type="checkbox"/>
38	13/12/18 12:03	General View		Load JPG	<input checked="" type="checkbox"/>
39	13/12/18 12:03	General View		Load JPG	<input checked="" type="checkbox"/>
40	13/12/18 12:04	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
41	13/12/18 12:04	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
42	13/12/18 12:04	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	13/12/18 12:04	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	19/11/18 13:20	E-filed GIA report		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/12/18 11:49	Parts Invoice		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	13/11/18 16:58	Accident Statement		Load HTM	
2	16/11/18 14:48	Addendum Sheet		Load TIF	
3	16/11/18 14:48	Accident Statement Addm. #1		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	13/11/18 16:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	13/11/18 16:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	13/11/18 16:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	13/11/18 16:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	13/11/18 16:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	13/11/18 16:54	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	13/11/18 16:53	Sketch Plan		Load TIF	
2	13/11/18 16:53	Sketch Plan #2		Load TIF	
3	13/11/18 16:53	Sketch Plan #3		Load TIF	
4	13/11/18 16:53	Sketch Plan #4		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQ118020936/UTD3E2

Date: 27/12/2018

REFERENCE

Insured/Claimant: LHH VEGETABLE PTE LTD Policy No: DMCPHQ18-003465
Date of Loss: 12/11/2018 Nature of Claim: OD Claim No: DM18HO03118

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG1451P**
Make & Model: TOYOTA HIACE, 3.0 D DX (M) Engine No: 1KD2682000
Reg. Date: 13/06/2017 (Man. Year: 2016) Chassis No: KDH2010215298
Colour: Silver Odometer: 110775 km
Engine Capacity: 2982 cc
Market Value/New Car Price: S\$50,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,290.30	465.30	825.00	63.94
Miscellaneous Items	30.00	20.00	10.00	33.33
Labour	1,350.00	1,100.00	250.00	18.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,670.30	1,585.30	1,085.00	40.63
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	2,670.30	1,085.30	1,585.00	59.36
+ GST 7.00/7.00% (S\$)	186.92	75.97	110.95	59.36
Nett Amount (S\$)	2,857.22	1,161.27	1,695.95	59.36

INSPECTION

Date of Assignment: 20/11/2018 Present Location: SME Motor Pte Ltd (Kaki Bukit)
Date Inspected: 21/11/2018 Inspected At: SME Motor Pte Ltd (Kaki Bukit)
1 Kaki Bukit Ave 6 #02-15, AutoBay @
Kaki Bukit
Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2018)
Parts: 213	TOYOTA HIACE 3.0 D DX (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBG1451P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR GATE (WCP)	Repair	750.00 F	*- F
2	1		*REAR CENTER LOGO (WCP)	Necessary	35.00 F	*35.00 F
3	1		*REAR GATE STICKER (WCP)	Necessary	28.00 F	*28.00 F
4	1		*REAR BUMPER (WCP)	Deformed	160.00 F	*160.00 F
5	10		*REAR BUMPER CLIP (WCP)	Necessary	20.00 F	*20.00 F
6	1		*REAR LH CORNER PANEL (WCP)	Twisted	60.00 F	*60.00 F
7	1		*REAR LH TAIL LAMP (WCP)	Cracked	120.00 F	*120.00 F
				Sub Total (S\$)	1,173.00	423.00
				+ Margin on L,N Items 10.00/10.00% (S\$)	117.30	42.30
				Total Parts (S\$)	1,290.30	465.30

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	REAR GATE LH STICKER 70KM/H (NECESSARY)	15.00	10.00
2	1	REAR GATE RH STICKER 8 PAX (NECESSARY)	15.00	10.00
Sub Total (S\$)			30.00	20.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX REAR WINDSCREEN	New	120.00	0.00
3	LABOUR CHARGE	New	600.00	580.00
4	SPRAY PAINTING	New	600.00	500.00
Gross Labour Cost (S\$)			1,350.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >