

ASS. REC. BY:

REF:

CS/SMO/18020941/Agd3

Special Instruction:

Surveyor:

Adnan

ASSIGNMENT (Office)

From (Person):

chan shuhui agnes

of

SMO

Date/Time:

20/11/18 @ 10:02am

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GZ1522J

Insured:

SDD8088B

at Workshop n/s

JCN Autolution

Tel:

96775772

of

1 kaki Blk Ave 6 #01-85

Policy No:

DIGMTPV 01005419

Claim No:

CM1D1805033

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A.

15/11/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

10:24am @ 20/11/18

Person Contacted:

Erik

Vehicle  IN /  OUT

Date/Time	Action/Instruction
	(✓) Estimate Insp: 8 kaki Blk Ave 4 #06-21
	GZ1522J-X
	SDD8088B - CS/RS108028007/Kbg1 DOA: 13/10/2008
21/11/18 @ 4PM	informed Agnes Chan, we are pending estimate from receiver.
20/11/19 @ 9.30am	revised to Agnes Chan via messenger.
	LS @ 1600, 4 days (Red @ 2959, 65%)

Adrian

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: G21522J Yr Regn: 2005 / Dec

Type: M.Car / M.Cycle / Bus /  Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Pregio C.C. 2665

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 357896 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNCTB241257206603

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  Inorder / Jammed / Leaked / Burnt or

Brake:  Inorder / Jammed / Leaked / Burnt or

Modi:  Nil /  S/Rim / STD A/Rim or

Tyre Size: F: 185R14C

R: 185R14C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hifly

Front R/Bal. 06 mm Rear R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 20/11/18

Survey held at ICN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Sampo</u>
	<u>COE Expiry: 29/12/20</u>
	<b>RECEIVED 29 MAR 2019</b>
	<u>MV: 15K</u>
	<u>PV: 9.5K</u>
	<u>Nett: 5.5K</u>
	<b>RECEIVED 29 MAR 2019</b>

Date/Time, File Pass to?	Date/Time, File Return to?
1) <u>24/3</u> <u>Kyran</u>	2) _____
3) _____	4) _____
5) _____	6) _____

Prel. Report: \_\_\_\_\_  
Final Report: \_\_\_\_\_

Part Prices Check:

IN	OUT

Survey Fee: \_\_\_\_\_ Date: \_\_\_\_\_

Basic & Add.	<u>250</u>
S + RS, SI	<u>10</u>
Photos	
Others	
TOTAL	<u>260</u>

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 29 Mar 2019

**Preliminary Advice**

Insured Vehicle No	: SDD8088B	Accident Date	: 15/11/2018
TP Vehicle No	: GZ1522J	Assignment Date	: 20/11/2018
Make	: KIA PREGIO	Est. Duration of Repair	: 4.00
Date of Inspection	: 20/11/2018		
Inspection At	: JCN AUTOLUTION PTE LTD - KAKI BUKIT (HQ) NO.1 KAKI BUKIT AVENUE 6, BLK D #01-85 , AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,559.00
Revised Amount	:S\$	2,004.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,004.50
Lump Sum Repair	:S\$	1,600.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Nov 2018		20 Nov 2018 10:02 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	CHOO SONG CHYE, ID: S1536819E, Tel: +6594594328, Email: RICKY_CHOO2002@YAHOO.COM.SG								
Main Claimant:	COOLWIN AIR-CON SERVICE ENGRG PTE LTD, Co. Reg. No.: 201700435Z								
Vehicle Reg. No.:	GZ1522J	Date of Loss:	15/11/2018 18:00 - :59						
Claim Type:	TP / CMTD1805033	Policy/Cover Note No.:	D18MTPV01005419 (Comprehensive)						
Vehicle Reg. No. (Insured):	SDD8088B	Policy No. (Claimant):							
		Excess:							
Repairer:	Jcn Autolution Pte Ltd - Kaki Bukit (HQ) NO.1 KAKI BUKIT AVENUE 6, BLK D #01-85 , AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 96775772								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/11/2018]								
Driver/Custodian (Insured):	CHOO SONG CHYE (56 / Male), NRIC: S1536819E, Tel: +6594594328								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Tuesday, 20 November 2018 10:01 AM  
**To:** erik@jcngrp.com; admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** Chan, Shu Hui Agnes; Henry, Irene James  
**Subject:** CMTD1805033/AGC - SUV(LKK)/ SDD8088B & GZ1522J ACC ON 15-Nov-2018

### Without Prejudice

Our Claim Reference: CMTD1805033/AGC  
Your Reference: GZ1522J

Hi Erik,

We acknowledged receipt of your claim documents.

As spoken, we will appoint **LKK AUTO** to conduct the survey.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for GZ1522J on a without Prejudice and any admission of liability basis.

Please submit with your report via merimen upon completion of survey.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG

Download now @  or 

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** erik@jcngroup.com [mailto:erik@jcngroup.com]

**Sent:** Monday, November 19, 2018 5:55 PM

**To:** Claims - Motor Survey

**Subject:** Pre Repair Inspection for GZ1522J involving in an accident with SDD8088B on 15-Nov-2018

Hi Sir/Madam

Please kindly arrange PRI for GZ1522J at:

**Location for PRI:** No.8 Kaki Bukit Ave 4, #06-21, Premier@KakiBukit S415875.

Regards

Erik Chan

M: 96775772

E: erik@jcngroup.com

## Shiau Chan (LKKAuto)

---

**From:** Do-Not-Reply <do-not-reply@merimen.com>  
**Sent:** Wednesday, 21 November 2018 4:00 PM  
**To:** do-not-reply@merimen.com  
**Cc:** SUR  
**Subject:** VEHICLE GZ 1522J (YOUR REF: CMTD1805033)

This mail is associated with :

**\*GZ1522J (CMTD1805033)**

**[SDD8088B]**

TP

COOLWIN AIR-CON SERVICE ENGRG PTE LTD

Nov 15 2018 6:00PM

[CHOO SONG CHYE]

Jcn Autolution Pte Ltd - Kaki Bukit

Dear Agnes,

Please be informed that we have inspected the vehicle GZ 1522J on 20/11/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)  
LKK Auto Consultants Pte Ltd  
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

**dyson cyclone v10**  
**Deep cleans.**  
**Wherever pets get.**

**New 5 Years Coe Renewal Toyota Altis 1.6a**

2.88% p.a. Lowest Interest @ GV  
 Cars Financing \$2000  
 Downpayment Monthly From  
 \$568  
 GV Credit Pte Ltd StarAd

**CERTIFIED PRE-OWNED MERCEDES-BENZ**

[View our cars](#)

**FOR SALE BY OWNER**

Post an Advertisement  
 Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#) | [Advertiser Login](#) | [Ways of Selling](#)

Browse by Category Save Search Print Sort by Date Posted | 20 results/page

1 vehicles | Search **Kia Pregio** | [Advanced Search](#) | [Search](#) | [View All](#)

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Kia Pregio		Any	Any	> 10 year(s) old	Any	Any	Any	Available

**Kia Pregio (COE till 03/2021)** | **\$20,800** | **\$9,000 /yr** | **14-Mar-2006** | **2,665 cc** | **-** | **Van** | **Available**

**Fuel Type: Diesel** **CREDIT OWNER**

Powerful And Reliable Van. Excellent Condition. Easier And Cheaper To Maintain.

★ Posted: 01-Nov-2018 | Tags: 2005 Kia Pregio, 2005 kia pregio, Kia Pregio, kia pregio, Kia, Pregio, pregio, Used Kia

Save this search criteria, to get email alerts whenever a match is found. [Save Search](#)

Make  Model  Price  Depreciation  Reg Date  Eng Cap  Mileage  Veh Type  Status

For old advertisements, view Expired ads

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Kia Pregio, Kia Pregio Singapore, used Kia Pregio Singapore, used Kia Pregio, used vehicles Singapore or even buy used Kia Pregio Singapore. We have now car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[Download on the App Store](#) | [GET IT ON Google play](#)

SHORTLISTED | HISTORY  
**Compare**

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0435Z
Vehicle Details	
Vehicle No.:	GZ1522J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Nov 2018
Vehicle Make:	KIA
Vehicle Model:	PREGIO 2.7M
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	J2421782
Chassis No.:	KNCTB241257206603
Maximum Power Output:	-
Open Market Value:	\$12,748.00
Original Registration Date:	30 Dec 2005
First Registration Date:	30 Dec 2005
Transfer Count:	3
Actual ARF Paid:	\$638.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Dec 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,416.00
COE Rebate Amount:	\$9,448.00
<b>Total Rebate Amount:</b>	<b>\$9,448.00</b>
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 20 Nov 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/11/2018 14:28
Date Of Accident	15/11/2018 18:45
Exact Location Of Accident	ALONG SIMS AVE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GZ1522J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COOLWIN AIR-CON SERVICE ENGRG PTE LTD
Co Reg No	201700435Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90211528
Alternative Phone No	OFFICE-90211528

### Vehicle Particulars

Manufacturer	KIA
Model	PREGIO 2.7M
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	CV3 / GA222289
Cover Note Number	

### Driver

Name of Driver	MARIMUTHU GANESAN
Passport No/FIN	G2044753U
Date Of Birth	03/03/1991
Occupation	OUTDOOR
Date Of Driving Pass	25/10/2018
Driving Experience	0 YEAR AND 0 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-82854778
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	NO 26A FLANDERS SQUARE
Postcode	209308
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDD8088B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHOO SONG CHYE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (c) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




*[Handwritten signature]*

*[Handwritten signature]*

*[Handwritten signature]*

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15 Nov 2018 at 0645 pm, I was travelling along Sims Ave towards Changi. I signalled my intention to filter to the extreme left lane as the lane ahead was clear. Suddenly, I felt a collision impact from the left. Vehicle B who was travelling along the bus lane collided onto my vehicle. As per scene photo, vehicle B failed to slow down and collided onto my vehicle. At the point of accident, traffic was heavy and slow.

DECLARATION



*[Handwritten signature]*


*[Handwritten signature]*

*[Handwritten signature]*

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





**JCN Autolution Pte Ltd** COMPANY REG NO.: 201813309W  
 8 Kaki Bukit Ave 4, #07-23, Premier @ Kaki Bukit,  
 Singapore 415875  
 +65 6881 1772 sales@jcngroup.com

**ESTIMATE**

COOLWIN AIR-CON SERVICE ENGRG PTE LTD  
 Singapore  
 Contact : 90211528

TP Sompo  
 Xiao Chmy

Code : C100014  
 Date in : 16/11/2018  
 Vehicle Num. : GZ1522J  
 Model : KIA PREGIO 2.7M  
 Chassis/Eng# : KNCTB241257206603/J2421782

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Distorted</i>	1	365.00	365.00 ✓
FRONT BUMPER BRACKET LH/RH <i>Distorted</i>	2	27.00	27.00 ✓
FRONT BUMPER FOG LAMP LH <i>New</i>	1	106.00	106.00 ✓
FRONT BUMPER REINFORCEMENT BEAM <i>Best</i>	1	272.00	272.00 ✓
FRONT BUMPER REINFORCMENT BEAM CLIP <i>new</i>	1	5.00	5.00 ✓
FRONT BUMPER RETAINER LH/RH <i>new</i>	2	21.00	21.00 ✓
FRONT BUMPER STAY CLIP LH/RH <i>new</i>	2	5.00	5.00 ✓
FRONT CORNER FENDER LH <i>Rp</i>	1	353.00	353.00 ✓
FRONT DOOR LH <i>Rp</i>	1	885.00	885.00 ✓
FRONT GRILLE <i>could</i>	1	91.00	91.00 ✓
FRONT GRILLE CLIP <i>new</i>	1	5.00	5.00 ✓
FRONT HEADLAMP L.H <i>could</i>	1	314.00	314.00 ✓
Subtotal before discount			2,449.00
Percentage discount 0%			0.00
Sub-total 1			2,449.00
FRONT DOOR "COMPANY ADDRESS STICKER" <i>SN</i>	1	50.00	<del>50.00</del> 30 ✓
FRONT DOOR "BIZ SAFE STICKER" <i>SN</i>	1	50.00	50.00 ✓

GE 1522J



### JCN Autolution Pte Ltd

8 Kaki Bukit Ave 4, #07-23, Premier @ Kaki Bukit,  
Singapore 415875

+65 6881 1772 sales@jcngroup.com

Subtotal before discount	100.00
Percentage discount 0%	0.00
<b>Sub-total 2</b>	<b>100.00</b>
<b>Parts-total</b>	<b>2,549.00</b>

### LABOUR

Description	Price
TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING (FR)	30 <del>60.00</del>
TO DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY FRONT PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	X 200.00
TO RESPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	930 500 <del>1,000.00</del>
TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	400 <del>750.00</del>
<b>Labour Total</b>	<b>2,010.00</b>
<b>Parts &amp; Labour Total</b>	<b>4,559.00</b>

total: 20045  
 A/S: 1.6K  
 OA Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

## LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18020941/AQD3N2

Date: 02/04/2019

**REFERENCE**

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01005419
Claimant Vehicle No :	GZ1522J	Insured Vehicle No :	SDD8088B
Date of Loss:	15/11/2018	Nature of Claim:	TP
		Claim No:	CMTD1805033

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	GZ1522J	Engine No:	J2421782
Make & Model:	KIA PREGIO, 2.7 D (M)	Chassis No:	KNCTB241257206603
Reg. Date:	30/12/2005 (Man. Year: 2005)	Odometer:	357896 km
Colour:	Silver		
Engine Capacity:	2665 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185 R14C	Rear Tyre Size:	185 R14C
Front Left Side:	HIFLY 6 mm	Rear Left Side:	HIFLY 6 mm
Front Right Side:	HIFLY 6 mm	Rear Right Side:	HIFLY 6 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,549.00	1,074.50	1,474.50	57.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	930.00	1,080.00	53.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>4,559.00</b>	<b>2,004.50</b>	<b>2,554.50</b>	<b>56.03</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,600.00</b>		
<b>Nett Amount (\$\$)</b>	<b>4,559.00</b>	<b>1,600.00</b>	<b>2,959.00</b>	<b>64.90</b>

**INSPECTION**

Date of Assignment:	20/11/2018	
Date Inspected:	20/11/2018	Inspected At:
		Jcn Autolution Pte Ltd - Kaki Bukit (HQ) NO.1 KAKI BUKIT AVENUE 6, BLK D #01-85, AUTOBAY @ KAKI BUKIT Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b>	(Last Synchronised: 02 Apr 2019)
<b>Parts:</b>	N/A KIA PREGIO 2.7 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GZ1522J)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	365.00 F	*365.00 FL
2	2	*FRONT BUMPER BRACKET LH/RH	Damaged	27.00 F	*27.00 FL
3	1	*FRONT BUMPER FOG LAMP LH	Not Necessary	106.00 F	*- FL
4	1	*FRONT BUMPER REINFORCEMENT BEAM	Bent	272.00 F	*272.00 FL
5	1	*FRONT BUMPER REINFORCEMENT BEAM CLIP	Necessary	5.00 F	*5.00 FL
6	2	*FRONT BUMPER RETAINER LH/RH	Necessary	21.00 F	*21.00 FL
7	2	*FRONT BUMPER STAY CLIP LH/RH	Necessary	5.00 F	*5.00 FL
8	1	*FRONT CORNER FENDER LH	Repair	353.00 F	*- FL
9	1	*FRONT DOOR LH	Repair	885.00 F	*- FL
10	1	*FRONT GRILLE	Cracked	91.00 F	*91.00 FL
11	1	*FRONT GRILLE CLIP	Necessary	5.00 F	*5.00 FL
12	1	*FRONT HEADLAMP LH	Cracked	314.00 F	*314.00 FL
13	1	*FRONT DOOR COMPANY ADDRESS STICKERRH	Necessary	50.00 FS	*30.00 FS
14	1	*FRONT DOOR BIZ SAFE STICKER	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,549.00</b>	<b>1,185.00</b>
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	110.50
<b>Total Parts (\$\$)</b>	<b>2,549.00</b>	<b>1,074.50</b>

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING (FR)	New	60.00	30.00
2	TO DIAGNOSE ,REPLACE AND /OR REPAIR TO RECTIFY FRONT PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	200.00	0.00
3	TO RESPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	500.00
4	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	750.00	400.00
<b>Gross Labour Cost (S\$)</b>			<b>2,010.00</b>	<b>930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >