

Ameyan Ram

REF: ALG

20944 / 12/18 35287

ASSIGNMENT

From: \_\_\_\_\_ Date: 23-11-2018

Estimated Cost: \_\_\_\_\_

OD:  TR / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJY 5054L

at Workshop m/s: Volkswagen

of: 247 Alexandra Rd

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition) 11am

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SJY 5054L Yr Regn: 2010 / SGP

Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Volkswagen Jetta 1.4 TSI c.c 1396

Colour: GRAY A/C: Insured / Std / NI / NA

Sp. Reading: 99173 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: NVW2221KZAM095755

Gen. Cond: Good  / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16 R: -


BS / DUN / EXNOVA / GY / FS / LIZA /  MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 22/10/18	D.O.I. 23/11/18

Survey held at 518, Jelapah Rd

Des. of Damages:  Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
	* Kindly check the damages consistency as insured driver reported that her car 'NO DAMAGE' TP car only had a dent on number plate. TP & OE staff got scene photo.

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee:  Site Insp (\$ \_\_\_\_\_)  S + RS, SI

Interview (\$ \_\_\_\_\_)  Photos

Tech. Invs (\$ \_\_\_\_\_)  Others

Weekend (\$ \_\_\_\_\_) \_\_\_\_\_

TOTAL \_\_\_\_\_