

ASS. REC. BY:

REF: CS3/ALG18020952/Riddar

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALG

Date/Time: 20/12/018 12:44pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SNC 6038H

Insured:

SLQ 3850L

at Workshop m/s

Neo Automotive

Tel:

9091 4853

of

53 Ubi Ave 1 #05-44

Policy No:

1700025106

Claim No:

026553899556

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19/12/018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

20/12/018 1:34pm

Person Contacted:

Mrs Neo

Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SNC 6038H - NA / TM18020955/r3
	SLQ 3850L - NA / ALG18020951/L4
	Dismantle: 22/11/2018
	After repair: 28/11/2018

D.A: 19/12/018

D.A: 19/12/018



- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLQ3850L AND SMC6038H ON 19/11/2018

From: Chin, Lee-Ying  
To: assignments, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: Tuesday, 20 November, 2018 12:44:06 PM  
Attachments:  tmpDFA8.tif

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



883 North Bridge Road  
#11-03 Southbank  
Singapore 198785  
T: 6292 5838  
F: 6292 5938  
(UEN No. 201333127N)  
(GST Reg No. 201333127N)

Our Ref : CY.SMC6038H.18.NA.wp(Lh)

Your Ref : Your insured vehicle **SLQ 3850L**

19 November 2018

**Albert Speed Enterprise**  
c/o The Motor Claims Department  
**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way #07-16  
Singapore 079120

**By Fax No: 6835 7416**

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SMC 6038H & SLQ 3850L ON 19.11.2018 @ 10:00HRS AT CRAWFORD STREET**

We are instructed by Forte Auto Leasing Pte Ltd to notify you of a road traffic accident on 19.11.2018 at about 10:00Hrs along Crawford Street involving our client's vehicle registration number SMC 6038H and vehicle registration number SLQ 3850L driven by you at the material time. A copy of the Singapore accident statement report is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

  
**C. Yogarajah/LLC**  
Enc

cc: M/s. Neo Automotive Pte Ltd  
53 Ubi Ave 1  
#05 - 44 Paya Ubi Industrial Park  
Singapore (408934)  
Mrs. Neo (9091 4853/6385 5262)  
Fax no : 6385 8262

Confidentiality & Privilege: This message is intended for the recipient to whom it is addressed. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Disclaimer: Mail/Fax/Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has been securely transmitted and not been tampered with, C. Yogarajah LLC cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this communication for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the firm shall be understood as neither given nor endorsed by C. Yogarajah LLC Advocates & Solicitors. Thank you

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	1486C
<b>Vehicle Details</b>	
Vehicle No.:	SMC6038H
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Nov 2018
Vehicle Make:	KIA
Vehicle Model:	CARENS 1.7 DCT DIESEL 5DR FWD
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	D4FDJH551974
Chassis No.:	KNAHU815VJ7205871
Maximum Power Output:	104.0 kW (139 bhp)
Open Market Value:	\$21,489.00
Original Registration Date:	12 Jul 2018
First Registration Date:	12 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$22,085.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jul 2028
PARF Rebate Amount:	\$16,563.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	11 Jul 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,900.00
COE Rebate Amount:	\$32,672.00
<b>Total Rebate Amount:</b>	<b>\$49,235.00</b>

The information contained herein is correct as at 21 Nov 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/11/2018 12:16
Date Of Accident	19/11/2018 10:00
Exact Location Of Accident	CRAWFORD ST TWDS NORTH BRIDGE RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC6038H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	FORTE AUTO LEASING PTE LTD
Co Reg No	201631486C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91449265

### Vehicle Particulars

Manufacturer	KIA
Model	CARENS
Exact Purpose for which vehicle was being used at time of accident	OTW TO FOOD CENTRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5097558305
Cover Note Number	

### Driver

Name of Driver	TAN SIONG HOE(CHEN XIANGHE)
NRIC No	S7809478H
Date Of Birth	13/04/1978
Occupation	OUTDOOR
Date Of Driving Pass	12/08/2010
Driving Experience	8 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91140422
Fax Number	
Contact Number	
Email Address	CHLOETAN2405@GMAIL.COM

Address	BLK 217A SUMANG WALK #15-246
Postcode	821217
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS TRAVELLING ALONG CRAWFORD ST TWDS NORTH BRIDGE RD ON THE 2ND LANE. SUDDENLY VEH(B) BEARING REG NO SLQ3850L FROM MY RIGHT LANE CUT INTO MY LANE AND HIT ONTO MY RIGHT SIDE PORTION OF MY VEH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ3850L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HOE CHEE KHIONG
NRIC/Passport Number	S1591114Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Pls refer to the statement.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

19/11/18  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Condition (CON)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched  
 (07) Deformed (08) Shuffled (09) Buckled (10) Broken (11) Necessary (12) Missing  
 (13) Torn (14) Unconfirmed (15) Not Working

## ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)  
 (4) Not Consistent (NC)

Aug 2008

## MOTOR CAR (RH)

Vehicle No:

SMC 6038H

## Right Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door	BUC	✓	
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator	DIS	✓	
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber	DD	✓	
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock	BT	✓	
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door	BUC	✓	
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge	LOWRY	BT	✓
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber	DD	✓	
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1371	994070	Roof Top Panel			
1372	994098	Roof Top Moulding			
1373	994085	Roof Top Air-bag			
1374	994084	Roof Top Air-bag Sensor			
1375	994083	Roof Top Air-bag Control Unit			
1376	992958	Rear Bumper	ERR	R	
1377	992976	Rear Bumper Bracket			
1378	993068	Rear Bumper Side Retainer			
1379	993045	Rear Bumper Reinforcement			
1380	993077	Rear Bumper Sponge			
1381	993040	Rear Bumper Protector			
1382	993026	Rear Bumper Moulding			
1383	993023	Rear Bumper Lower Spoiler			
1384	995116	Rear RH Taillamp			
1385	993456	Rear RH Fender	DD	R	
1386	993450	Rear RH Fender Protector			
1387	990247	Sticker			
		Rear RH Wheel Bearing	DIS	✓	
		" " " Rim	CUT	✓	

No of Items: \_\_\_\_\_

Assessor: \_\_\_\_\_

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI




































## CLAIM SUBFOLDER TRACKING
























Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Nov 2018 <a href="#">Edit Reg</a>		20 Nov 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>ALBERT SPEED ENTERPRISE</b> , Co. Reg. No.: 53336036J									
Main Claimant: <b>FORTE AUTO LEASING PTE LTD</b> , Co. Reg. No.: 201631486C									
Vehicle Reg. No.: <b>SMC6038H</b>		Date of Loss: 19/11/2018 10:00 - :59 [4 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 0265538995SG</b>		Policy/Cover Note No.: 1700025106 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SLQ3850L</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Neo Automotive Pte Ltd (HQ)</b> 53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK, 408934 Kaki Bukit - Tel:									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ] BernardJiQian.Ler@aig.com									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 29/11/2018]									
Claimant's Solicitor: <b>C YOGARAJAH LLC</b> - Tel: 62925838									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (21/11/2018): Request to upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SMC6038H (0265538995SG)  
[SLQ3850L]  
TP  
FORTE AUTO LEASING PTE LTD  
Nov 19 2018 10:00AM  
[ALBERT SPEED ENTERPRISE]  
Neo Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images												3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print
1	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
2	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
3	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
4	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
5	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
6	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
7	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
8	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
9	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
10	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
11	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
12	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
13	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
14	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
15	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
16	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
17	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
18	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
19	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
20	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
21	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
22	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
23	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
24	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
25	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
26	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
27	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
28	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
29	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
30	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
31	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
32	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
33	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
34	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
35	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
36	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>
37	21/11/18 15:59	General View											Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	07/12/18 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	07/12/18 16:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	07/12/18 16:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	07/12/18 16:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	07/12/18 16:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	07/12/18 16:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18020952/R1CBE2

Date: 17/12/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1700025106

**Claimant Vehicle No :** SMC6038H

**Insured Vehicle No :** SLQ3850L

Date of Loss: 19/11/2018

Nature of Claim:

TP

Claim No: 0265538995SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC6038H**

Make &amp; Model: KIA CARENS, 1.7 (A)

Engine No: D4FDJH551974

Reg. Date: 12/07/2018 (Man. Year: 2018)

Chassis No: KNAHU815VJ7205871

Colour: Grey

Odometer: 45858 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Hankook 6 mm

Rear Left Side:

Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side:

Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 20/11/2018

Date Inspected: 20/11/2018 Inspected At:

 Neo Automotive Pte Ltd (HQ)  
 53 UBI AVE 1, #05-44 PAYA UBI  
 INDUSTRIAL PARK  
 Singapore 408934

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Buckled	0.00 F	*- F
2	1		*FRT RH DOOR GLASS REGULATOR	Distorted	0.00 F	*- F
3	1		*FRT RH DOOR RUBBER	Dented	0.00 F	*- F
4	1		*FRT RH DOOR LOCK	Bent	0.00 F	*- F
5	1		*REAR RH DOOR	Buckled	0.00 F	*- F
6	1		*REAR RH DOOR HINGE LOWER	Bent	0.00 F	*- F
7	1		*REAR RH DOOR RUBBER	Dented	0.00 F	*- F
8	1		*REAR BUMPER	Repair	0.00 F	*- F
9	1		*REAR RH FENDER	Repair	0.00 F	*- F
10	1		*REAR RH WHEEL BEARING	Distorted	0.00 F	*- F
11	1		*REAR RH WHEEL RIM	Cut	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >