

INSURANCE

INS. CASE OWNER:

CC / FWD1802

LKK:
IDAC:

Surveyor:

DOE:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting Ir (1st)

Non-Reporting Ir (2nd)

Non-Reporting Ir (Final)

Notification Ir (if non-pickup):

Call OE:

After call Ir to OE:

Documentation Check List: Handler Typist

Notification Ir (if non-pickup):

After call Ir to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28. Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

(S a days)

Loss of Income (LOI):

SS

(S a days)

LOR only

☐

LOU only

☐

LOR + LOU

☐

LOR + LO

☐

[Tick only one]

GIA/LTA Search:

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP / WP

3) Survey fee:

+250

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
14/1/19

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / IWS / TP RES / OD RES / EVA / INV / MV
 To Insured Vehicle No: _____
 at Workshop m/s _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Ball or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SHB 3557K** Yr Regn: **30 Sep 2013**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /
 Truck / Trailer or
 Make: **Hyundai** cc: **1680**
 Colour: **Yellow** A/C: Insu ☒ Std / NI / NA
 Sp. Reading: **910890** T/Radio: Insu ☒ Std / NI / NA
 Eng/No: _____
 C/No: **KMHLBx1w4D4040079**
 Gen. Cond: Good / ☒ Poor / Burnt
 Steering: Ino ☒ Jammed / Leaked / Burnt or
 Brake: Ino ☒ Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD ☒ Rrim or
 Tyre Size: F: **205/60R16**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Went to**
 Front: **7** mm Rear: **7** mm
 R/Bal: **7** mm L/Bal: **7** mm
 D.O.A: **17/11/18** D.O.I: **20/11/18**
 Survey held at **CDGE (Loyang)**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear s/s
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Report Format: _____
 Lump Sum / I.B.I: (\$ _____)

Survey Fee:	
Transportation:	
\$ + RS \$	
Photos	
Others	
TOTAL	

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 3557K

DATE 20/11/2018 9:35

MAKE :

MODEL : HYUNDAI i40

FWB

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>Refined</i>			\$ 553.00	
	Rear Bumper Clip 10 pcs <i>ne</i>			\$ 22.00	
	Rear Bumper Bracket <i>Xin</i>		\$ 35.60	\$ 71.20	
	Rear Bumper Sponge <i>Xin</i>			\$ 103.50	
	SUB TOTAL			\$ 749.70	
	LESS 20%			\$ 149.94	
	DISCOUNTED TOTAL			\$ 599.76	
	Rear Bumper Advertisement Logo <i>ne</i>			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) <i>ne</i>		\$ 100.00	\$ 200.00	Nett
				\$ 250.00	
	Labour Charge				
	Panel Beating			\$ 350.00 <i>200</i>	
	Spray Painting Charge			\$ 250.00 <i>200</i>	
	Wiring Charge			\$ 50.00 <i>Xin</i>	
	Remove/Refix Reverse Sensor			\$ 80.00 <i>20</i>	
	TOTAL LABOUR			\$ 730.00	
	ESTIMATE TOTAL			\$ 1,579.76	
<div style="display: flex; justify-content: space-between; align-items: flex-start;"> <div style="width: 45%;"> <p><i>Ka hi idan</i></p> <p><i>20/11/18 Bish</i></p> <p><i>2 Rep.</i></p> <p><i>L/S</i></p> <p><i>After Repair photo</i></p> </div> <div style="width: 45%; border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hereby notify the Reparer of the following:</p> <ul style="list-style-type: none"> • To resume before/after survey coming • To display damaged panel during survey • Parts prices are subject to commission • Third party survey is on a "without prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be documented and is subject to final approval from the insurance Company <p>Acknowledged by Reparer</p> <p>Signature: _____</p> <p>Date: _____</p> </div> </div>					
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					

Our Job Ref No : 305241011
Date : 21/11/18

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN
Vehicle Reg No. : SHB3557K

Fax :
17/11/2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: FWD SLE9413P
- The finalized amount shall be:
 - Spare Parts after List discount
 - Labour Charges
 - Total for Part-By-Part Repair Cost
 - Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less:
Final Lumpsum Repair cost \$900.00
- Estimated normal period for repairs: 2 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature :
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature :
Name : Kalvin
Date : 22/11/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:


A member of COMFORTDELGRO

Date/Time: 19.11.2018 17:05 Page : 1

Team:	ARC Repair TP(CFSO)1	JOB CARD	Sales Order:	JC NO.: 305241011
Customer:	CITYCAB PTE LTD	REGN NO.:	SHB3557K	MILEAGE
MS:	7010070	MAKE:	HYUNDAI	FUEL
Customer NO.:	383 SIN MING DRIVE	MODEL:	I-40	E.....1/2.....F
Address:	Singapore SINGAPORE 575717	DATE/TIME IN:	19.11.2018 13:40	
(R)	65551188	YR OF MANU:	30.09.2013	TARGET DATE
(P)		CHASSIS CODE:	KMHLB41UMDU040079	COMPLETION DATE/TIME:
Count Card NO.:				

JOB DESCRIPTION

Accident Date: 17.11.2018
NATURE: 3P 17.11.2018



BOOKED & PASSED OUT BY: _____

SERVICE ADVISOR	CUSTOMER'S SIGNATURE
-----------------	----------------------

(Acknowledgement) Slip

Vehicle No.: SHB3557K

CHIANG

Signature/Date

returned to Service Reception upon collection

Exit Pass

Vehicle No.: SHB3557K

Name of Service Advisor

Date

To be kept by Security Guard

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 3557K

DATE 20/11/2018 9:35

MAKE :

MODEL : HYUNDAI i40

FWD

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 553.00	
	Rear Bumper Clip 10 pcs ✓			\$ 22.00	
	Rear Bumper Bracket ?		\$ 35.60	\$ 71.20	
	Rear Bumper Sponge ?			\$ 103.50	
	SUB TOTAL			\$ 749.70	
	LESS 20%			\$ 149.94	
	DISCOUNTED TOTAL			\$ 599.76	
	 Rear Bumper Advertisement Logo ✓			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
				\$ 250.00	
	Labour Charge				
	Panel Beating			\$ 350.00 ²⁰⁰	
	Spray Painting Charge			\$ 250.00 ²⁰⁰	
	Wiring Charge			\$ 50.00 ²⁰	
	Remove/Refix Reverse Sensor			\$ 80.00 ²⁰	
	TOTAL LABOUR			\$ 730.00	
	ESTIMATE TOTAL			\$ 1,579.76	
<p><i>Kali 1004</i></p> <p><i>20/11/18 Bish.</i></p> <p><i>2 Reps.</i></p> <p><i>L/S</i></p> <p><i>After Repair photo</i></p> <div> <p>Liability Acknowledgement</p> <p>The Repairer has advised that the following work is required:</p> <ul style="list-style-type: none"> To remove and replace the rear bumper To replace the rear bumper clip Parts prices are based on the latest market prices Third party liability is not covered No single item is covered by insurance Some insurance items must be covered and is subject to final approval from insurance company <p>Acknowledged by Repairer</p> <p>Signature _____</p> <p>Date: _____</p> </div>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

Nivitha (LKK Auto)

From: lionel.tan@fwd.com
Sent: Tuesday, 20 November 2018 12:48 PM
To: assignments@lkkauto.com; sur@lkkauto.com
Cc: AsherSng@lkkauto.com
Subject: FW: SHB3557K VS SLE9413P THIRD PARTY CLIAM Our Ref: PNPV2018-00010482/JL
Attachments: img-Y20115105-0001.pdf

12.52pm @ 20/11/18
vehicle In
SURB Kalvin

Please attend to the PRS & direct settlement.

Regards,
Lionel

From: Chiang Liat Choon [mailto:chianglc@cdge.com.sg]
Sent: Tuesday, 20 November, 2018 11:55 AM
To: Motor Claims SG - SG Common
Subject: Fw: SHB3557K VS SLE9413P THIRD PARTY CLIAM Our Ref: PNPV2018-00010482/JL

Dear Sir,

Attached herewith repair estimate & gia.

Best Regards
Chiang Liat Choon
Taxi Crash Repair ComfortDelGro Engineering Pte Ltd
Off: 62148314 Fax: 65468156

From: ApeosPort-IV C5570 <sbs-singnalling@sbstransit.com.sg>
Sent: Tuesday, 20 November 2018 11:51 AM
To: Chiang Liat Choon
Subject: Scan Data from CDG_LO_AW_A5570

Number of Images: 9
Attachment File Type: PDF

Device Name: ApeosPort-IV C5570
Device Location:

This message and any attachments may contain confidential, privileged or proprietary information. If you are not

the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

SBS Transit Ltd [Registration No. 199206653M]

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

SBS Transit Ltd [Registration No. 199206653M]

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Shu Pei (LKKAUTO)

From: josey.loh@fwd.com
Sent: Thursday, 6 June 2019 3:08 PM
To: jimwong@cdge.com.sg
Cc: assignments; SUR; Admin A; Admin-D (LKKAUTO); Asher Sng (LKKAUTO); motorclaims.sg@fwd.com
Subject: RE: Yref 1201800015300/JL, Oref CC18110565/SHB3557K/jw

Without Prejudice

Dear Jim,

We refer to the above matter.

We have repudiated all liability.

Kindly re-direct your client's claim to our insured for handling.

Thank you.

****Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.***

Kind Regards

Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com
W fwd.com.sg

FWD
insurance



From: Jim Wong See Pah [mailto:jimwong@cde.com.sg]
Sent: Friday, 17 May, 2019 12:13 PM
To: Josey Loh Kah Wai - SGUser <josey.loh@fwd.com>
Subject: Yref PNPV2018-0010482/JL, Oref CC18110565/SHB3557K/jw

Dear Ms Loh

We refer the attached mail of 01.03.2019.

Please advise the status of our property damage claim.

Thank you.

Best Regards
Jim Wong
Claims Dept / ComfortDelgro Engineering Pte Ltd

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506045W]

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Nov 2018 Edit Reg		20 Nov 2018 00:00 Edit Adj Rpt	S\$900.00 Edit Estimates	S\$900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Jin Chensu, ID: 58281394B		
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	SHB3557K	Date of Loss:	17/11/2018 21:00 - :59 [61 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201800015300	Policy/Cover Note No.:	PNPV2018-00010482
Vehicle Reg. No. (Insured):	SLE9413P	Policy No. (Claimant):	D-18088937MFSH
		Excess:	
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 29/11/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB3557K (1201800015300)
[SLE9413P]
TP
CITYCAB PTE LTD
Nov 17 2018 9:00PM
[Jin Chensu]
ComfortDelGro Engineering Pte Ltd

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/11/18 15:04	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
2	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
3	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
4	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
5	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
6	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
7	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
8	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
9	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
10	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
11	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
12	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
13	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
14	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
15	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
16	23/11/18 16:14	General View		Load JPG	<input checked="" type="checkbox"/>
17	23/11/18 16:14	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
18	23/11/18 16:14	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
19	23/11/18 16:15	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
20	23/11/18 16:15	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
21	23/11/18 16:15	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/11/18 14:53	EMAIL FROM FWD DD 20112018		Load PDF	
2	20/11/18 14:53	TP EST & GIA REPORT		Load PDF	
3	21/11/18 18:57	TP ESTIMATE- MARKED		Load PDF	
4	10/06/19 10:31	EMAIL FROM FWD DD 06062019.		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18020959/K1EB3Q2

Date: 25/06/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00010482

Claimant Vehicle No : SHB3557K **Insured Vehicle No :** SLE9413P

Date of Loss: 17/11/2018 Nature of Claim: TP Claim No: 1201800015300

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB3557K**
 Make & Model: HYUNDAI I40, 1.7 D (A) Engine No: HIDDEN
 Reg. Date: 30/09/2013 (Man. Year: 2013) Chassis No: KMHLB41UMDU040079
 Colour: Yellow Odometer: 910890 km
 Engine Capacity: 1685 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: West Lake 7 mm Rear Left Side: West Lake 7 mm
 Front Right Side: West Lake 7 mm Rear Right Side: West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	849.76	710.00	139.76	16.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	730.00	430.00	300.00	41.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,579.76	1,140.00	439.76	27.84
Approved Total (Overridden) (S\$)		900.00		
(S\$)	1,579.76	900.00	679.76	43.03
+ GST 7.00/7.00% (S\$)	110.58	63.00	47.58	43.03
Nett Amount (S\$)	1,690.34	963.00	727.34	43.03

INSPECTION

Date of Assignment: 20/11/2018

Date Inspected: 20/11/2018 Inspected At:

 ComfortDelGro Engineering Pte Ltd
 (Loyang)
 59 Loyang Drive
 Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2019)
Parts: 143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB3557K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	553.00 FL	*553.00 FL
2	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
3	2		*REAR BUMPER BRACKET	Serviceable	71.20 FL	*- FL
4	1		*REAR BUMPER SPONGE	Serviceable	103.50 FL	*- FL
5	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
6	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	999.70	825.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	149.94	115.00
Total Parts (\$\$)	849.76	710.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	200.00
2	SPRAY PAINTING CHARGE	New	250.00	200.00
3	WIRING CHARGE	New	50.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (S\$)			730.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >