

22/03/2002

ASS. PEC. BY:

REF: CS/SPF18020975/KH202

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Frankie Thay of SPF Date/Time: 21.11.2018 1024am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 4090A Insured: BX 228H

at Workshop m/s City Auto Tel: 61453 1235

of Bk 8 Sin Ming Ind Est #01-58

Policy No: Claim No: AEMD/105/009/2018/165

Sum Insured: Excess:

Make of Veh: D.O.A. 20.11.2018
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time: 21.11.2018 1035am Person Contacted: Veronica Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLD 4090A - x
	BX 228H - CS1 / SPF18020719 / KH202 OCA: 05-10-18
	\$3209.96 (Red: 1783.96, 35%)
	Submit Part by Part.

ASS. REC. BY:

REF: JPR /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ City _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-R1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

22/11 File pass to Catherine

Range \$3000 - \$4000

RECEIVED 16 JAN 2019

Veh No: SLD 4090A Yr Regn: 06, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1896

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading 45430 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RUI 1114768

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: MIE 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 20/11/18

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 21/11/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 16/1 Typist

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B. (\$) 3209.96

☐ : Prel. Report☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee: 280

Transportation:

S - RS, SI

Photos

Others

TOTAL

280

Catherine Chong (LKK Auto)

From: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Sent: Wednesday, 21 November, 2018 10:24 AM
To: assignments
Cc: Abdul Rahman MOHAMAD SALIM (SPF); Rosalyn TAN (SPF)
Subject: RE : Pre-Repair Inspection (SLD4090A)

Your reference : SLD4090A

Our reference : AEMD/105/009/2018/165

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Dear Sir/Madam,

ACCIDENT INVOLVING GOVERNMENT VEHICLE QX228H AND OTHER VEHICLE SLD4090A ON 20 NOVEMBER 2018

We refer to the above matter.

Please arrange for an Inspection of vehicle No. SLD4090A at City Auto Pte Ltd, Blk 8, Sin Ming Industrial Estate, #01-58/60, Sin Ming Road, Singapore 575643.

For appointment, Please contact the workshop at Tel: 64531235 or 64520850.

Estimated were not provided by the workshop.

Thank You.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/11/2018 13:40
Date Of Accident	20/11/2018 08:10
Exact Location Of Accident	BLK. 740 YISHUN AVE 5 OPEN SPACE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD4090A
Insured/Policyholder	
Name Of Registered Owner	SUNARTO HARTONO
NRIC No	S7264211B
Email Address	SUNARTOIKE@YAHOO.COM
Mobile Phone No	(LOCAL) +65-93201021
Alternative Phone No	OTHERS-93201021

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X CVT ABS D/AIRBAG 2WD 5DR (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099605889
Cover Note Number	

Driver

Name of Driver	INEKE CHRISTINA PRANJOTO
NRIC No	S7663162Z
Date Of Birth	23/08/1976
Occupation	OUTDOOR
Date Of Driving Pass	30/11/2006
Driving Experience	11 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92258494
Fax Number	
Contact Number	
Email Address	SUNORTOIKE@YAHOO.COM

Address	BLK. 288 YISHUN AVE 6 #02-50
Postcode	760288
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SUNARTO HARTONO GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT NO: T/20181120/2018

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX228H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd
38 Woodlands Industrial Estate
No. 17-17 Admiralty Industrial Park
NRIC/FIN (Singapore) 757700
Tel: 6219 2096 (3 lines) Fax: 6219 2096

2 - 2x22 H

Yishmun Ave. 5

FDB block 740 Yishmun Ave 5

Car park lots

Yishmun Ave. open car park

Two way traffic


Shelter

Car park lots

FDB block 739 Yishmun Ave 5

Refer Police Rpt no T/2018/1120/2018

I/We declare the foregoing particulars are true in every respect.

 遠友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd
38 Woodlands Industrial Park East 1
#07-17 Admiralty Industrial Park
Reporting Centre Singapore
Name: Tel: 6212 0988 (China) Fax: 6219 2096
NRIC/FIN No.: S8460307D



**SINGAPORE
POLICE FORCE**



T/20181120/2018

1 of 3

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20181120/2018

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/11/2018 10:12	Vide Report No.: F/20181120/0081	Station Diary No.: 64
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: INEKE CHRISTINA PRANJOTO			Address: APT BLK 288 YISHUN AVENUE 6 #02-50 SINGAPORE 760288	
ID Type / ID No.: NRIC NO / S7663162Z			Contact No.: Home/Office:	Mobile: 92258494
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Female	Age: 42	Date of Birth: 23/08/1976	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

General Information of the Accident				
Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 20/11/2018 08:10	Type of Location: Car Park
Location: Along Road 1 YISHUN AVENUE 5				
Blk 740 Yishun Avenue 5 open space carpark				
Weather: Clear		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX228H	Police Vehicle					0
SLD4090A	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL		



**SINGAPORE
POLICE FORCE**



T/20181120/2018

2 of 3

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20181120/2018

CONTINUATION OF REPORT

Driver			
Name	INEKE CHRISTINA PRANJOTO	ID No.	S7663162Z
Related Vehicle	SLD4090A (Car)	Contact No.	92258494
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 20/11/2018 at about 0815hrs, I was driving my vehicle (SLD4090A) at the carpark of Blk 740 Yishun Avenue 5 carpark. I was going to park my vehicle.

2) As I was approaching a shelter (and in front of lot 254), I noticed a stationary Police vehicle in front of me. I then stopped. I wish to state that I had kept 1 car distance from the said Police vehicle as I assumed that the Police vehicle had wanted to park even though there was no hazard light on, indicating the intention to park.

3) It was at this moment that the Police vehicle reverse light came on and it started to reverse towards me. I had then horned continuously to alert the driver, however, the Police vehicle continued to reverse towards me, eventually colliding with the front of my vehicle.

4) I had then alighted from my vehicle and discovered that my front bumper and front of the bonnet was dented and scratched badly. The Police vehicle also had dents on its back bumper and boot area. I had then spoken to the male/Malay officer who was driving (Fauzi) and was informed that Traffic Police will be notified and for me to lodge a Police report accordingly on the matter.

5) I wish to state that I have no injury and that I have an in car camera. That is all.



**SINGAPORE
POLICE FORCE**



T/20181120/2018

3 of 3

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20181120/2018

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

SI LEE YAO MING, KEVIN GABRIEL

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / DDGVT /

Sr Staff Sgt LIM JUN HUI, ADRIAN

Contact No.: 65476350

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

20/11/2018 10:12

Classification Of Case:



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201811-000309(00)

SDF ACCIDENT CLAIM SECTION

NO. 1

MOUNT PLEASANT RD

SINGAPORE 298333

Contact : 93201021

Fax No. : 64784848

*Not With claim
1-B1
Running by claim
4 days*

Date : 21/11/2018

Vehicle No. : SLD4090A

Make/Model : HONDA VEZEL 1.5X CVT ABS
D/AIRBAG 2WD 5DR

Mileage (km) : 0

Chassis No. : RU11114768

Accident Date : 20/11/2018 00:00:00

Claim No. : QX228H

Reference : SLD4090A

Policy No. : 5099605889

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

LIST ITEMS :

1	Front grille base	1.0	268.90	CM 268.90 ✓
2	Front grille cover	1.0	203.40	CM 203.40 ✓
3	Front grille logo	1.0	24.00	CM 24.00 ✓
4	Front grille chrome	2.0	56.90	CM 113.80 ✓
5	Front bumper - upper	1.0	459.80	CM 459.80 ✓
6	Front bumper - lower	1.0	195.60	CM 195.60 ✓
7	Front bumper lower grille	1.0	77.50	CM 77.50 ✓
8	Front bumper retainer	2.0	20.60	CM 41.20 ✓
9	Front bumper reinforcement	1.0	321.00	CM 321.00 ✓
10	RH headlamp	1.0	1,784.50	CM 1,784.50 ✓
11	RH headlamp lower bracket	2.0	35.00	CM 70.00 ✓
12	Front grille bracket - LH	1.0	19.60	CM 19.60 ✓
13	Front grille bracket - RH	1.0	19.60	CM 19.60 ✓
14	Front grille bracket - Mid	1.0	38.70	CM 38.70 ✓
15	Front bonnet	1.0	892.30	CM 892.30 ✓

List Total :

4,529.90

20% Discount S\$

905.98

3,623.92

SPECIAL NET :

1	Number plate	1.0	25.00	CM 25.00 ✓
2	Number plate casing	1.0	35.00	CM 35.00 ✓

SPECIAL NET Total S\$:

60.00

LABOUR :

*To check wiring and lighting	1.0	60.00	CM 60.00 ✓
-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	450.00	CM 450.00 ✓
- Spray painting on affected & replace parts	1.0	800.00	CM 800.00 ✓
			1,310.00

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201811-000309(00)

Date : 21/11/2018

Vehicle No. : SLD4090A

Make/Model : HONDA VEZEL 1.5X CVT ABS
D/AIRBAG 2WD 5DR

Mileage (km) : 0

Chassis No. : RU11114768

Accident Date : 20/11/2018 00:00:00

Claim No. : QX228H

Reference : SLD4090A

Policy No. : 5099605889

SDF ACCIDENT CLAIM SECTION

NO. 1

MOUNT PLEASANT RD

SINGAPORE 298333

Contact : 93201021

Fax No. : 64784848

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. & O.E.

Total S\$: 4,993.92

GST 7% S\$: 349.57

Amount Due S\$: 5,343.49

for CITY AUTO PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18020975/Ktbe2

ACCIDENT CLAIM SECTION(SINGAPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMYSINGAPORE 298333

Date : 18-01-2019



ATTN : FRANKIE THAY

Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 228H	Veh. Inspected	SLD 4090A
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/165	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	21/11/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11114768	Colour	METALLIC BLACK
Odometer	45430	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	MICHELIN	9 mm
L/H Front Tyre	215/60 R16	MICHELIN	9 mm
R/H Rear Tyre	215/60 R16	YOKOHAMA	7 mm
L/H Rear Tyre	215/60 R16	YOKOHAMA	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/11/2018	Inspection Date	21/11/2018
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 4090A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT GRILLE BASE	CRACKED	268.90	268.90
1	FRONT GRILLE COVER	CRACKED	203.40	203.40
1	FRONT GRILLE LOGO	NECESSARY	24.00	24.00
2	FRONT GRILLE CHROME @\$56.90	NECESSARY	113.80	113.80
1	FRONT BUMPER - UPPER	TO REPAIR SEE LABOUR	459.80	-
1	FRONT BUMPER - LOWER	CUT	195.60	195.60
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	77.50	-
2	FRONT BUMPER RETAINER @\$20.60	SERVICEABLE	41.20	-
1	FRONT BUMPER REINFORCEMENT	BENT	321.00	321.00
1	RH HEADLAMP	MTG CRACKED	1,784.50	1,784.50
2	RH HEADLAMP LOWER BRACKET @\$35.00	CRACKED	70.00	70.00
1	FRONT GRILLE BRACKET - LH	SERVICEABLE	19.60	-
1	FRONT GRILLE BRACKET - RH	SERVICEABLE	19.60	-
1	FRONT GRILLE BRACKET - MID	SERVICEABLE	38.70	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	892.30	-
	LESS 20% DISCOUNT		-905.98	-596.24
			3,623.92	2,384.96
<u>SPECIAL NETT ITEMS</u>				
1	NUMBER PLATE (SN) }	DENTED	25.00	45.00
1	NUMBER PLATE CASING (SN) }		35.00	-
			60.00	45.00
<u>LABOUR</u>				
	TO CHECK WIRING AND LIGHTING.		60.00	20.00
	TO KNOCK JACKOUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER - UPPER AND FRONT BONNET.		450.00	320.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		800.00	440.00
			1,310.00	780.00
GRAND TOTAL			4,993.92	3,209.96
RECOMMENDED COST OF REPAIRS				3,209.96

Report Ref No. CS/SPF18020975/Ktbe2



Report Ref No. CS/SPF18020975/Ktbe2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.