

Aidah

CC 3, 111 180 20983, Clear3y

Sub/vehr: Avk DOI: ASSIGNMENT 19-11-18 Date/Time: 19-11-18 Registered in Merimen: 20-11-18

Pre-assign / CCU / FTE

SHA 1841H
CPL



Insured Vehicle No. : _____
Name of Insured : _____
Insured Tel No. : _____ HP: _____
Excess Sec II :SS _____ D.O.A: 18-11-18
Is driver the owner? (YES / NO) Nature of Accident : _____

Claim No. : _____
Policy No. : _____
Make / Model : _____
Place of Accident : Yek cc c/p

If NO, Driver Name / Age : _____ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Driver Tel No. : _____ (V/L: YES / NO) Insured Liability : % Final ? Yes / No

SHC 6677K



INSRS: _____
WSP: Premier
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/Time	STAGE	DATE / PIC
<u>21/11</u> <u>10/11</u>	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Others:	<input checked="" type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: AME

Repair Cost: PIP SS 5500 (> days) Reduction: 81 % Email Call

FINAL SETTLEMENT Date/Time: 5/11/19 Confirm with: RHAWATI Email Call

Final Liability: 100% % 60 (Agreed / Assessed) BOLA S/N No.: 26 If NO or B 28, Ass. Lia: _____

Repair Cost: SS 353.10 NO REPAIR, TP EXIT FROM PROBABLY LOY.

Loss of Rental (LOR): SS 82.59 (3 days) = 101.44

Loss of Use (LOU): SS - (5 x days)

Loss of Income (LOI): SS 72 (5 x 2 days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: SS -

Medical: SS -

Disbursement: SS - (e.g. Tow/Independent)

Legal Cost: SS -

Total: 71,013.82 SS 607.64 Global Sum SS: 607.00

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: SS 600.00 Name 1: Premier Automotive Services Pte Ltd

Payee 2: (Strike if N/A) SS - Name 2: _____

Payee 3: (Strike if N/A) SS - Name 3: _____

COPY SENT
20/11/19

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspected Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 6672K Yr Regn: 9 Mar, 2015
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /
 Truck / Trailer or _____
 Make: KIA Optima cc 1685
 Colour: Silver A/C: Insured / Std / Nil / NA
 Sp. Reading: 459340 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: 1KNAH M44 MF5588219
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brakes: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD / Rim or _____
 Tyre Size: F: 205 / 65 R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Maxxis
 Front Rear
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 18/11/18 D.O.I. 19/11/18
 Survey held at Premier
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Body.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PIP: +550 (SPD: +2404.10 817/-)

Date/Time, File Pass to? : Prel. Report
 : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ + RS: \$1	
Photos	
Others	
TOTAL	

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

19-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6672 K

1 pc	Front n/s door @ \$791.00	X repair	\$ 791.00
2 pcs	Front n/s door hinges @ \$34.00	X repair	\$ 68.00
1 pc	n/s mirror assy @ \$590.00	X repair	\$ 590.00
			<hr/>
			\$ 1,449.00
		Less 10%	\$ 144.90
			<hr/>
			\$ 1,304.10

S/NETT

1 set n/s door stickers @ \$100.00 *— ne* \$100.00

Sundry *me*

\$ ~~50.00~~ *20*

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~180.00~~ *X 27*

To dismantle / refit the inner components of the front n/s door into new shell door

\$ ~~150.00~~ *X 27*

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc

\$ ~~650.00~~ *200*

To putty and spray painting on front n/s door, n/s side mirror

\$ ~~400.00~~ *230*

To apply rustproofing on the repaired and replaced panels.

\$ ~~120.00~~ *X 27*

\$ 2,954.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hereby advise the Repairer of the following:

- To reserve before/after survey pending
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- Supplementary work must be reviewed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalin (LKK)

19/11/18

2 Dgrs

4/5

After Repair photo.

*21/11/18
advised PIP \$550/2018*

[Signature]

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

19-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6672 K

1 pc	Front n/s door @ \$791.00	X repair	\$	791.00
2 pcs	Front n/s door hinges @ \$34.00	X	\$	68.00
1 pc	n/s mirror assy @ \$590.00	X repair	\$	590.00
			\$	1,449.00
		Less 10%	\$	144.90
			\$	1,304.10

S/NETT

1 set	n/s door stickers @ \$100.00	✓		\$100.00
	Sundry		\$	50.00 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 X
	To dismantle / refit the inner components of the front n/s door into new shell door		\$	150.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc		\$	650.00 200
	To putty and spray painting on front n/s door, n/s side mirror		\$	400.00 230
	To apply rustproofing on the repaired and replaced panels.		\$	120.00 X
			\$	<u>2,954.10</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalina (Kia)
19/11/18 1350 hrs.
2 Pgs.
L/S
After Repair photo.

LKK Auto Care (Pty) Ltd is a fully
the Repairer of the following:
 • To resurvey the vehicle after repair
 • To display damaged parts to being recovered
 • Parts prices are subject to market value
 • Third party survey is on a "no liability" basis
 All work is done on a "no liability" basis
 This estimate is subject to insurance and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:	09 Mar 2015 / 10:06:52	Receipt No.:	AACCK001-AX239-150309-000011
Asset Type:	Vehicle	Transaction Amount:	\$65,354.00
Asset ID:	SHC8672K	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150309100652356013		

Vehicle No.:	SHC8672K
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	09 Mar 2015
Original Registration Date:	09 Mar 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA.1.7(A) DIESEL
Chassis No.:	KNAGM414MF5588219
Engine No.:	D4FDEH313317
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2014
Open Market Value:	\$21,158.00
Minimum PARF Benefit:	\$8,473.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	09 Mar 2015 10:06:52
COE No.:	2015030901002140W
COE Expiry Date:	08 Mar 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$51,092.00
Lifespan Expiry Date:	08 Mar 2023

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	09 Mar 2015 / 10:06:52	Receipt No.:	AACCK001-AX239-150309-000011
Asset Type:	Vehicle	Transaction Amount:	\$65,354.00
Asset ID:	SHC6672K	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150309100652356013		

Vehicle No.:	SHC6672K
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	09 Mar 2015
Original Registration Date:	09 Mar 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA.1.7(A) DIESEL
Chassis No.:	KNAGM414MF5588219
Engine No.:	D4FDEH313317
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2014
Open Market Value:	\$21,158.00
Minimum PARF Benefit:	\$8,473.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	09 Mar 2015 10:06:52
COE No.:	2015030901002140W
COE Expiry Date:	08 Mar 2023
COE Bid Category:	-
Actual GP/PQP Paid Amount:	\$51,092.00
Lifespan Expiry Date:	08 Mar 2023

Print Received Message

This mail is associated with :

***SHC6672K (MCT18110568)**
[SHA1841H]

TP

PREMIER TAXIS PTE LTD

Nov 18 2018 2:00PM

[-]

Premier Automotive Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 10/06/2019 15:38 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$510.00) - SHC6672K - Claim Handler: Zuhaidah Bte Samsuri

Approved:510.00.

Print Received Message

This mail is associated with :

***SHC6672K (MCT18110568)**
[SHA1841H]

TP

PREMIER TAXIS PTE LTD

Nov 18 2018 2:00PM

[-]

Premier Automotive Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 22/07/2019 11:05 AM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - SHC6672K - Claim Handler: Zuhaidah Bte Samsuri

Maintained: Please maintain our offer at 50% based on BOLA 24A, do not offer more than that.

Print Received Message

This mail is associated with :

***SHC6672K (MCT18110568)**
[SHA1841H]

TP

PREMIER TAXIS PTE LTD

Nov 18 2018 2:00PM

[-]

Premier Automotive Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 25/10/2019 11:06 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$600.00) - SHC6672K - Claim Handler: Zuhaidah Bte Samsuri

Approved:600.00:Please wrap up the matter at global \$600.

Premier Automotive Services Pte Ltd

23 Changi South Avenue 2

#04-02

Singapore 486443

GST: 200707743D ROC: 200707743D

Phone: (65) 6214 8880

Fax: (65) 6214 4498

Tax Invoice



Date	Page
Nov 07, 2019	1
Invoice Number	
IV1911017097	

Sold To:

INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street #04/#05
IOB Building
Singapore 049711
049711

Ship To:


INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street #04/#05
IOB Building
Singapore 049711
049711

Shipment / DO No. SM1911021728	Order Date	Vehicle No. SHC6672K	Case ID TP/181118/SHC6672K	PO Number	Terms 30D
-----------------------------------	------------	-------------------------	-------------------------------	-----------	--------------

S/N	Item Number	Description	Qty. Shp.	Unit Price	Total Discount	Total Amount
1	ICGST1	Cost of Repair (subject to GST)			0.00	362.47
2	ICGST2	Loss of Rental (subject to GST)			0.00	142.21
3	ICNGST	Misc Charges (not subject to GST)			0.00	60.00

Comments:

Accident involving SHA18A1H on 18/11/18

 Authorised By: 

Subtotal	564.68
Less discount	0.00
Total amount	564.68
GST 7%	35.32
Grand total	600.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Nov 2018 Edit Reg		19 Nov 2018 00:00 Edit Adj Rpt	S\$550.00 Edit Estimates	S\$550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, ID: 199303821R								
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHC6672K	Date of Loss:	18/11/2018 14:00 - :59 [44 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18110568	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA1841H	Policy No. (Claimant):	5095103893						
		Excess:							
Repairer:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 29/11/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • III_SG (25/10/2019): Alert - Adj Mandate Approved (S\$600.00) - SHC6672K - Claim Handler: Zuhaidah Bte... • III_SG (11/10/2019): Alert - Adj Mandate Maintained - SHC6672K - Claim Handler: Zuhaidah Bte Samsuri • III_SG (06/09/2019): Alert - Adj Mandate Maintained - SHC6672K - Claim Handler: Zuhaidah Bte Samsuri • III_SG (22/07/2019): Alert - Adj Mandate Maintained - SHC6672K - Claim Handler: Zuhaidah Bte Samsuri • III_SG (10/06/2019): Alert - Adj Mandate Approved (S\$510.00) - SHC6672K - Claim Handler: Zuhaidah Bte... • III_SG (03/12/2018): Alert - Adj Mandate Approved (S\$0.00) - SHC6672K - Claim Handler: Zuhaidah Bte S... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC6672K (MCT18110568)
[SHA1841H]
TP
PREMIER TAXIS PTE LTD
Nov 18 2018 2:00PM
[COMFORT TRANSPORTATION PTE LTD]
Premier Automotive Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
2	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
3	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
4	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
5	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
6	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
7	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
8	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
9	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
10	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
11	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
12	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
13	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
14	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
15	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
16	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
17	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
18	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
19	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
20	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
21	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
22	20/11/18 18:43	General View		Load JPG	<input checked="" type="checkbox"/>						
23	21/11/18 17:12	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
24	21/11/18 17:12	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
25	21/11/18 17:12	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
26	21/11/18 17:12	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
27	21/11/18 17:12	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	21/11/18 10:45	TP ESTIMATE - MARKED		Load PDF							
2	21/11/18 10:45	TP GIA REPORT		Load PDF							
3	03/06/19 14:25	RENTAL RECEIPT		Load PDF							
4	03/06/19 14:25	RENTAL MILEAGE		Load PDF							
5	03/06/19 14:25	LOD		Load PDF							
6	25/11/19 09:06	WORKSHOP INVOICE		Load PDF							
7	25/11/19 09:06	AUTHORISATION TO ACT FORM		Load PDF							
8	25/11/19 09:06	DISCHARGE VOUCHER		Load PDF							
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print						
1	21/11/18 09:33	Singapore Accident Statement		Load PDF							

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18020983/K1GA3Q2

Date: 25/11/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant			
Vehicle No : SHC6672K	Insured Vehicle No :	SHA1841H	
Date of Loss: 18/11/2018	Nature of Claim:	TP	Claim No: MCT18110568

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6672K		
Make & Model:	KIA OPTIMA, 1.7 D (A)	Engine No:	D4FDEH313317
Reg. Date:	09/03/2015 (Man. Year: 2014)	Chassis No:	KNAGM414MF5588219
Colour:	Silver	Odometer:	459340 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Maxxis 7 mm	Rear Left Side:	Maxxis 7 mm
Front Right Side:	Maxxis 7 mm	Rear Right Side:	Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,454.10	120.00	1,334.10	91.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	430.00	1,070.00	71.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,954.10	550.00	2,404.10	81.38
+ GST 7.00/7.00% (S\$)	206.79	38.50	168.29	81.38
Nett Amount (S\$)	3,160.89	588.50	2,572.39	81.38
+ Loss of Use (3.0 x S\$40.00/day) (S\$)		120.00		
+ Car Rental (3.0 x S\$101.44/day) (S\$)		304.32		
		(S\$) 1,012.82		
Liabile Amount (60.00%) (S\$)		607.69		
Global Sum Settlement (S\$)		600.00		

INSPECTION

Date of Assignment:	19/11/2018	
Date Inspected:	19/11/2018 Inspected At:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 488443
Estimated Period of Repair:	2.0 days	

Adjuster: KALVIN ANG WEI KUN

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Jun 2019)
Parts: 143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC6672K)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT N/S DOOR	Repair	791.00 FL	*-FL	
2	2		*FRONT N/S DOOR HINGES	Serviceable	68.00 FL	*-FL	
3	1		*N/S MIRROR ASSY	Repair	590.00 FL	*-FL	
4	1		*SET N/S DOOR STICKERS	Necessary	100.00 FS	*100.00 FS	
5	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS	
					Sub Total (\$\$)	1,599.00	120.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	144.90	0.00
					Total Parts (\$\$)	1,454.10	120.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
2	TO DISMANTLE /REFIT THE INNER COMPONENTS OF THE FRONT N/S DOOR INTO NEW SHELL DOOR	New	150.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SAME,ETC	New	650.00	200.00
4	TO PUTTY AND SPRAY PAINTING ON FRONT N/S DOOR ,N/S SIDE MIRROR	New	400.00	230.00
5	TO APPLY RUSTPOOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	0.00
Gross Labour Cost (S\$)			1,500.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >