

Surveyor

XKL

REF: EQI

20986 / Gpa3

6668F

ASSIGNMENT

From: Date: 3/12/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 5844K
at Workshop m/s: Hui Hong
of 25D Sungai Kedut st.1

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: after 2pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lup

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SCL 222 P Yr Regn: 17 Apr 2009

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X5 C.C. - 2996

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 96632 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBAFE 420 10CK 96738

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255 / 55 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 03-12-18

Survey held at w/s 3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1) Date/Time, File Return to?

☐ : Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6668F
Vehicle Details	
Vehicle No.:	SCL2222P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Dec 2018
Vehicle Make:	B.M.W.
Vehicle Model:	X5 XL
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	04826863N52B30AF
Chassis No.:	WBAFE42010LK96738
Maximum Power Output:	200.0 kW (268 bhp)
Open Market Value:	\$80,745.00
Original Registration Date:	17 Apr 2009
First Registration Date:	17 Apr 2009
Transfer Count:	3
Actual ARF Paid:	\$80,745.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Apr 2019
PARF Rebate Amount:	\$40,372.00
Intended COE Rebate Details	
COE Expiry Date:	16 Apr 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$7,326.00
COE Rebate Amount:	\$270.00
Total Rebate Amount:	\$40,642.00

The information contained herein is correct as at 03 Dec 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6668F
Vehicle Details	
Vehicle No.:	SCL2222P
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2018
Vehicle Make:	B.M.W.
Vehicle Model:	X5 XL
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	04826863N52B30AF
Chassis No.:	WBAFE42010LK96738
Maximum Power Output:	200.0 kW (268 bhp)
Open Market Value:	\$80,745.00
Original Registration Date:	17 Apr 2009
First Registration Date:	17 Apr 2009
Transfer Count:	3
Actual ARF Paid:	\$80,745.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Apr 2019
PARF Rebate Amount:	\$40,372.00
Intended COE Rebate Details	
COE Expiry Date:	16 Apr 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$7,326.00
COE Rebate Amount:	\$268.00
Total Rebate Amount:	\$40,640.00

The information contained herein is correct as at 04 Dec 2018

OK