

Summary

Tougher

Ally.

SKT 9523K.

Yr Regn: 2013 May

Veh No: SKJ 152SR. Yr Regn: 2013
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw x6+ C.C. 1598

Colour Black A/C: Insured / Std / NI / NA

Sp. Reading 82562. T/Radio: Insured / Std / NI / NA

Eng/No: 22222222

CINo: WBVSA/20705.1-116

Gen. Cond: ~~Good~~ / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/40R18

Re:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation.

Add Fee: : Site Insp (\$

Lump Sum / I.B.I: (\$)

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$)
$$S + RS \rightleftharpoons S_2$$

) Photos

) Others

TOTAL