

000000

INS. CASE OWNER:

Bonnie.

CC 3 /AIG1802

0994 TIPBⁿ²

LKK:
HAC:

Surveyor:

Tau-Arn

DOI:

ASSIGNMENT

26/11/18

Date / Time:

20/11/18

Registered in Merimen:

20/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUK 68337

Name of Insured:

KOH NEE NOI

Insured Tel No.:

HP:

Claim No.:

216018706254

Policy No.:

110042007

Excess Sec II :SS

D.O.A.:

8/11/18

Make / Model:

MERCEDES

Place of Accident:

PRK PARKS LAND O BNSMENT

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

216 KIM HAN PHU BEE

OI GIA REPORT: (YES / NO)

TP GIA REPORT: (YES / NO)

Driver Tel No.:

(V/L: (YES / NO)

Insured Liability:

% Final ? Yes / No



INSRS:
WSP:
Tel:
Liability:
RMKS:

SEJAGAR
performance



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

26/11/18
26/11/18 - 15/12/18
26/11/18 - 15/12/18

STAGE	DATE / PIC
Non-Reporting hr (1st):	
Non-Reporting hr (2nd):	
Non-Reporting hr (Final):	
Notification hr (if non-pickup):	
Call OI:	26/11/18
After call hr to OI:	
Documentation Check List: Handler Typist	
Notification hr (if non-pickup):	
After call hr to OI:	
Authorization To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	\$S	days Reduction:	%
FINAL SETTLEMENT Date/Time:		Confirm with:	
Final Liability:	%	(Assessed) BOLA S/N No.:	
Repair Cost:	\$S	days Reduction:	%
Loss of Rental (LOR):	\$S	days	
Loss of Use (LOU):	\$S	days	
Loss of Income (LOI):	\$S	days	
LOR only	<input type="checkbox"/>	LOU only	<input type="checkbox"/>
GIA/LTA Search	\$S	LOR + LOU	<input type="checkbox"/>
Medical:	\$S	LOR + LD	<input type="checkbox"/>
Disbursement:	\$S	(e.g. Tow/ Independent)	
Legal Cost:	\$S		
Total:	\$S	Global Sum SS:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	\$S	Name 1:	
Payee 2: (Strike if N.A.)	\$S	Name 2:	
Payee 3: (Strike if N.A.)	\$S	Name 3:	

Invoice *Tough*

REF:

Alt.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. _____

at Workshop m/s. _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____

Excess _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value _____

IDAC Accident Report. Consistent? : Yes or No

GIA / FR Seen. Consistent? : Yes or No

Est. Repairs: *4* days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: *Mike Chen*

Vehicle IN / OUT

Veh No. *SKJ 9523K* Yr Regn: *2013 May*
 Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or

Make: *BMW 36I* 4x *1598*

Colour: *Black* A/C Insured / Std / NI / NA

Sp Reading: *82562* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/Nr: *WBNSA/20703720416*

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: *255/40R18*

R: *~ ~ ~*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal: *6* mm R/Bal: *6* mm

L/Bal: *6* mm L/Bal: *6* mm

D.O.A. D.O.I. *26/1/18 0440pm*

Survey held at *PHL*

Des. of Damages: Frt / Rear / O/S / ☒ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

PIP \$ 4363.10 (Red \$ 1365.10 / 74%)

Copy/Time, File Pass 10/

☐ : Prel. Report

Days Of Repair:

☐ : Final Report

Resurvey No. of Trip:

Survey Fee

Copy/Time, File Return 10/

Transportation

2/

Add Fee: ☐ Site Insp (\$

3 S-R

☐ Interview (\$

1 Period

☐ Tech. Insp (\$

1 Extra

☐ Weekend (\$

1 ...

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18020994/pb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 20-11-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 6833Z	Veh. Inspected	SKJ 9523R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	20/11/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/11/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401519W GST Reg. No. M2-0020081-X

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 478180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159946
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796602 (AfterSales)
64796624 (Motorrad)

11 NOV 2018



Survey & repair

26.11 @ 10am

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 49063
Date Estimated : 10/11/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Matthew Thomas Chin
47 Hume Avenue
#09-08

Singapore 598748

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ9523R	J720416	30/05/2013	316iA/4	0

DESCRIPTION

Replacing rear left door

VALUE

1,275.00

Painting left rear door

885.00

To carry out body cavity preservation.
(Per panel).

118.00

To supply and install rear left window glass quoter
solar film.

425.00

Sundries. *Ne*

150.00

To transfer lock mechanism from old to new door including
conduct checks on new door power window system for proper
function. (1 door).

531.00

Total Labour 1: 3,384.00

DESCRIPTION

REAR LH DOOR

Abdichtung B

SEALING STRIP

RR LH DOOR OUTER DUCT COVER (GLANZS

REAR LH DOOR INNER WERTHERSTRIP

REAR DOOR WEATHERSTRIP

RR LH DOOR WINDOW FRAME COVER

LH EXTERIOR COVER WINDOW GUIDE WEB

REAR LH SIDE WINDOW FIXED

Seal

REAR LH DOOR WINDOW GUIDE

(DG) CLEANER R1 (100ML)

(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)

(DG/SL) GLASS PRIMER 30ML (VP206)

QTY PRIC

1 1,267.50

1 4.60

1 20.60

1 111.90

1 71.70

1 140.70

1 73.25

1 61.75

1 171.70

1 17.35

1 124.40

1 26.15

1 131.55

1 27.85

VALUE

1,267.50

4.60

20.60

111.90

71.70

140.70

73.25

61.75

171.70

17.35

124.40

26.15

131.55

27.85

Total Parts : 2,251.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747779

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63448773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49063
Date Estimated : 10/11/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ9523R	J720416	30/05/2013	316iA/4	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Logo No. _____ Claim No. _____

Unit/Time 24/11/18 448m Excess \$5 _____

Surveyor's Name Tanpin Sign Tanpin

Customer's Tel 97445744 Authorised Yes / No _____

Follow-up Date wp Time _____

REPAIRS PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's Email Tanpin@kklauto.com

Working Days Recommend 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	3,384.00
Parts	:	2,251.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	394.45
Grand Total	:	6,029.45

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sims Derby Group
Co. Reg. No. 107401559W, GET Reg. No. M2-002008T-K



SUPPLEMENTARY

Estimate No. : b1 49063
Date Estimated : 10/11/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Matthew Thomas Chin
47 Hume Avenue
#09-08

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 598748

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKJ9523R	J720416	30/05/2013	316iA/4	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	2.00	5.00		10.00
# REAR DOOR BRAKE *	77.20	1.00		77.20
# EXPANDING NUT (4.8) *	1.00	1.00	(A)	1.00
# EXPANDING NUT (4.8) *	1.00	5.00		5.00

Total Labour :
Total Parts : 93.20
Total Labour & Parts : 93.20

5728.20

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 49063
Date Estimated : 10/11/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Matthew Thomas Chin
47 Hume Avenue
#09-08

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 598748

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKJ9523R	J720416	30/05/2013	316iA/4	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear LH door and attachments include knocking out dents caused by the accident	850.00		850.00	✓
To spray paint rear LH door	796.00		796.00	✓
To carry out body cavity preservation. (Per panel).	100.00		100.00	✓
(M) * To replace rear LH side window fixed include conducting water leak tests	413.00		413.00	not ✓
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function	451.00		451.00	✓
Sundries	80.00		80.00	✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	2.00	5.00		10.00
REAR LH DOOR	1,267.50	1.00		1,267.50
# REAR DOOR BRAKE *	77.20	1.00		77.20
REAR DOOR WEATHERSTRIP	140.70	1.00		140.70
REAR LH SIDE WINDOW FIXED	171.70	1.00		171.70
# EXPANDING NUT (4.8) *	1.00	1.00		1.00
# EXPANDING NUT (4.8) *	1.00	5.00		5.00

SUPPLEMENTARY ITEMS

Total Labour :	2,690.00
Total Parts :	1,673.10
Total Labour & Parts :	4,363.10
Deduction for Excess :	0.00
Total Repair Costs less Excess:	4,363.10
GST @7%:	305.42
Grand Total :	4,668.52

Hsiao Tong (LKKAuto)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Thursday, 20 December 2018 1:26 PM
To: Taufikh (LKKAuto); Hsiao Tong (LKKAuto); SUR
Subject: FINAL REPORT / SKJ9523R
Attachments: Final Report SKJ9523R_2.pdf; Final Report SKJ9523R.pdf

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,690.00
Total Parts : 1,673.10
Total Labour & Parts : 4,363.10

Repair days: 4

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 22 November 2018 2:09 PM
To: PBSP
Cc: CS A Team; Admin A
Subject: RE: REQ FOR DIRECT SETTLEMENT - SKJ9523R & SLK6833Z ON 8 NOV 2018 ***LKK
REF:CC3/AIG18020994/pb3

Without Prejudice

Dear Sirs/ Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)
Sent: Tuesday, 20 November 2018 5:28 PM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: FW: REQ FOR DIRECT SETTLEMENT - SKJ9523R & SLK6833Z ON 8 NOV 2018 ***LKK
REF:CC3/AIG18020994/pb3

Dear Caroline,

We refer to the below email.

Please be informed that we are currently pending for our insured's report.

Kindly note that for liability, claim negotiation and settlement, please contact Hsiao Tong at 6742 3197.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Tuesday, 20 November 2018 4:29 PM

To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: REQ FOR DIRECT SETTLEMENT - SKJ9523R & SLK6833Z ON 8 NOV 2018

Dear Sirs

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SKJ 9523R	Model:	
Date of Accident:	8.11.18		

Global Sum Settlement	: [] Yes [] No	
Repair Estimate	: \$	6,029.45
Final Repair Cost	: \$	4,668.52
Loss of Use	: \$	240.00
Rental (if any)	: \$	—
LTA / GIA Search Fee	: \$	2.00
Others:	: \$	/
	: \$	/
Final Settlement Sum	: \$	4,910.52

Is Third Party Workshop GIA Registered? [] YES [] NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Ltd	: \$	4,668.52
2)	Performance Motors Ltd.	: \$	2.00
3)	Matthew Thomas Chin	: \$	240.00

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))

MOTOR INSURANCE COVER NOTE

Cover Note No. 10114235

The Insured named in the Schedule below having proposed for insurance in respect of the Motor Vehicle described in the Schedule below the risk is hereby HELD COVERED in the terms of the Company's usual form of Policy applicable thereto for the period as stated below unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE

Agent No. : 212165
Name of Insured : MATTHEW THOMAS CHIN
Make and Description of Vehicle : BMW 316i 1.6 AT D/AB M SPORT 4DR ABS HID
Vehicle Registration No. : ~~SKJ9253R~~ SKJ9523R
Year of Manufacture : 2013
Engine No. : B376J463N13B16A
Chassis No. : WBA3A12070J720416
Capacity : 1,598 Cubic Capacity
Cover Type : Comprehensive
Sum Insured (SGD) : Market Value
Period of Insurance : 30/05/2017 to 29/05/2018
Excess (SGD) : 1,500
Finance Company : BMW FINANCIAL SERVICES SINGAPORE PTE. LTD.



I/We hereby certify that this Covering note is issued in accordance with the Provisions of the Motor Vehicles (Third Party Risks & Compensation) Act (Cap. 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Not valid unless countersigned by the
Company's Authorised Representative



Sime Darby Insurance Brokers (Singapore) Pte. Ltd.

MSIG Insurance (Singapore) Pte. Ltd.
Authorised Insurers



Mary Tan
Senior Vice President, Brokers

Date of Issue : 29/05/2017

This covering note is valid for 30 days from the date of issue.

Mass. Reg. No. 0000000000



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18020994/T1pb3

29 NOV 2018

KOH NEE NOI
49 HUME AVE
#06-02
SINGAPORE 598749

Dear Sir/Madam,

**ACCIDENT INVOLVING SLK 6833Z & SKJ 9523R ALONG/AT PARC PALAIS
CONDO BASEMENT CARPARK ON 08/11/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SKJ 9523R against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Matthew Thomas Chin (the third party claimant) of 47 Hume Avenue
#01-08 S (548748) (address), owner of SKJ9523R (vehicle no.)
hereby authorize Performance Motors Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SKJ9523R that was damaged pursuant to the accident which occurred on 08/11/2018
(date) along Carpark at 47 Hume Ave (location) involving vehicle no/s
SLK 6633 Z ("the accident").


I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 29 (day) of 11 (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$448.52 (Repair Cost), S\$240.00 (Loss of ~~rental~~/use), S\$2.00 (Disbursement), for vehicle no. SKJ 9532R that was damaged pursuant to the accident which occurred on 26-11-18 (date) along Cempaka at 47 Hume Ave (location) involving vehicle no/s SKJ 68332. This is pursuant to the inspection conducted on 26-11-18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Matthew Thomas Chin ("the third party claimant") of vehicle no. SKJ 9532R make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKJ 9532R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 07 (day) of Feb (month) 2019 (year)



MTH

Signed by appointed surveyor



Signed by "the workshop" (with chop)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190688 (AfterSales)
Fax. 63449771

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190328 (AfterSales)
63190333/339 (Motorrad)
Fax. 64796801 (AfterSales)
64796824 (Motorrad)

SERVICE TAX INVOICERepair Order No. : **B1 1318031**Date IN : **26/11/2018**Cust. Svc. Advisor: **Chua Kee Sin**Page No. : **1 of 2**Invoice Number : **2048638 / WSB**Invoice Date : **31/12/2018**Payment Terms : **30 Days From Invoice**Invoice By : **Toh Jing Xuan****- CUSTOMER INFORMATION -**

Mr Matthew Thomas Chin
47 Hume Avenue
#09-08

Singapore 598748

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.
SKJ9523R

CHASSIS NO.
J720416

REGN. DATE
30/05/2013

MODEL
316IA/4

MILEAGE
82562

- - - - LABOUR 1 - - - -

To replace rear left door and attachments including knock
out dented area caused by the accident.

NETT

850.00

To respray rear left door.

796.00

To carry out body cavity preservation.
(Per panel).

100.00

To replace rear left side window fixed including conduct
water leak tests.

413.00

To transfer lock mechanism from old to new door including
conduct checks on new door power window system for proper
function.

451.00

Sundries.

80.00

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

0.00

DATE OF ACCIDENT : 08.11.2018. 3RD PARTY CAR : SLK6833Z.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO ON
26.11.2018 AT 4:40PM. AUTHORISED REPAIR BY MR CHEW
HSIAO TONG FROM LKK AUTO ON 22.11.2018 VIA EMAIL.

PROPOSE LOSS OF USE = \$60x4. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

0.00

GIA SEARCH FEE = \$2.00.

0.00

Total Labour 1: **2,690.00**

- - - - PARTS - - - -

REAR LH DOOR

Retail
Qty Price

1

1,267.50

NETT
1,267.50

REAR DOOR WEATHERSTRIP

1

140.70

140.70

REAR DOOR BRAKE

1

77.20

77.20

REAR LH SIDE WINDOW FIXED

1

171.70

171.70

EXPANDING NUT (4.8)

1

1.00

1.00

EXPANDING NUT

5

2.00

10.00

EXPANDING NUT (4.8)

5

1.00

5.00

Total Parts : **1,673.10**

**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-197745

Date of Request: 26/12/2018

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 26/12/2018
Enquiry By Toh Jing Xuan
TP Vehicle No. SLK6833Z
Accident Date 08/11/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLK6833Z	AIG Asia Pacific Insurance Pte. Ltd.	24/01/2018-23/01/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-197745
Date of Request: 26/12/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 26/12/2018
Enquiry By Toh Jing Xuan
TP Vehicle No. SLK6833Z
Accident Date 08/11/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Nov 2018 Edit Reg		26 Nov 2018 00:00 Edit Adj Rpt	S\$4,363.10 Edit Estimates	S\$4,363.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
<div style="border: 1px solid black; padding: 5px;"> <div style="display: flex; justify-content: space-between;"> CLAIM SUBFOLDER DETAILS [Created by adjuster] </div> <div style="margin-top: 5px;"> <p>Insured: KOH NEE NOI, ID: S1607678C</p> <p>Main Claimant: MATTHEW THOMAS CHIN, ID: G5413582W</p> <p>Vehicle Reg. No.: SKJ9523R Date of Loss: 08/11/2018 07:00 - :59 [65 Months and 9 Days From LTA Reg Date (Man Yr)]</p> <p>Claim Type: TP / 2960187363SG Policy/Cover Note No.: 2100497047 (Comprehensive)</p> <p>Vehicle Reg. No. (Insured): SLK6833Z Policy No. (Claimant):</p> <p>Excess:</p> <p>Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174</p> <p>Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com</p> <p>Claimant's Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888</p> <p>Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 29/11/2018]</p> </div> </div>																								
<div style="border: 1px solid black; padding: 5px;"> ASSOCIATED MAIL RECEIVED <div style="float: right;"> View All Compose Case Mail </div> <p>There are no mail for this case.</p> </div>																								
<div style="border: 1px solid black; padding: 5px;"> ALL ASSOCIATED TASKS <div style="float: right;"> View All Search Tasks Create New Task Complete </div> <table style="width: 100%; border-collapse: collapse; font-size: small;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

*SKJ9523R (2960187363SG)
[SLK6833Z]
TP
MATTHEW THOMAS CHIN
Nov 8 2018 7:00AM
[KOH NEE NOI]
Performance Motors Limited

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼	
----------------------------------	--	-------------------------------	------------------------------------	------------------------------	------------------------------	---	--

Letters/Correspondences					1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit		

Photos/Images					3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	17/12/18 11:35	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>	
2	17/12/18 11:35	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>	
3	17/12/18 11:35	General View	1	Load JPG	<input checked="" type="checkbox"/>	
4	17/12/18 11:35	General View	1	Load JPG	<input checked="" type="checkbox"/>	
5	17/12/18 11:35	General View	1	Load JPG	<input checked="" type="checkbox"/>	
6	17/12/18 11:35	General View	1	Load JPG	<input checked="" type="checkbox"/>	
7	17/12/18 11:35	General View	1	Load JPG	<input checked="" type="checkbox"/>	
8	17/12/18 11:35	General View	1	Load JPG	<input checked="" type="checkbox"/>	
9	17/12/18 11:35	General View	1	Load JPG	<input checked="" type="checkbox"/>	
10	17/12/18 11:35	General View	1	Load JPG	<input checked="" type="checkbox"/>	
11	17/12/18 11:35	General View	1	Load JPG	<input checked="" type="checkbox"/>	
12	17/12/18 11:35	General View	1	Load JPG	<input checked="" type="checkbox"/>	
13	17/12/18 11:35	General View	1	Load JPG	<input checked="" type="checkbox"/>	
14	17/12/18 11:35	General View	1	Load JPG	<input checked="" type="checkbox"/>	
15	17/12/18 11:35	General View	1	Load JPG	<input checked="" type="checkbox"/>	

Documentation					1 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	20/11/18 17:24	TP ESTIMATE	1	Load PDF		
2	20/11/18 17:24	TP GIA REPORT	1	Load PDF		
3	27/11/18 18:59	TP ESTIMATE- MARKED	1	Load PDF		
4	12/02/19 08:40	WORKSHOP INVOICE	1	Load PDF		
5	12/02/19 08:40	AUTHORISATION TO ACT FORM	1	Load PDF		
6	12/02/19 08:40	Release Voucher	1	Load PDF		
7	12/02/19 08:40	GIA SEARCH	1	Load PDF		
8	12/02/19 08:40	LETTER TO OI	1	Load PDF		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	21/11/18 09:56	OI GIA REPORT	1	Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLK6833Z (Insd veh)	Model:	BMW 316I 1.6 (A)
	SKJ9523R (TP veh)		
Date of Accident:	08/11/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$		6,571.08
Final Repair Cost	:	\$		4,668.52
Loss of Use	:	\$		240.00
				4.00 days at \$60.00 per day
Rental (if any)	:	\$		0.00
				days
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		4,910.52

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability _____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 4,670.52
2)	Matthew Thomas Chin	:	\$ 240.00
3)		:	\$

HUEY YON

12 Feb
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18020994/T1PB3N2

Date: 12/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100497047

Claimant Vehicle No: SKJ9523R Insured Vehicle No: SLK6833Z

Date of Loss: 08/11/2018 Nature of Claim: TP Claim No: 2960187363SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKJ9523R
 Make & Model: BMW 316I, 1.6 (A) Engine No: 376J463N13B16
 Reg. Date: 30/05/2013 (Man. Year: 2013) Chassis No: WBA3A12070J720416
 Colour: Black Odometer: 82562 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40 R18 Rear Tyre Size: 255/40 R18
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,494.20	1,753.10	741.10	29.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,647.00	2,610.00	1,037.00	28.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,141.20	4,363.10	1,778.10	28.95
+ GST 7.00/7.00% (S\$)	429.88	305.42	124.46	28.95
Nett Amount (S\$)	6,571.08	4,668.52	1,902.56	28.95
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,910.52		

INSPECTION

Date of Assignment: 26/11/2018

Date Inspected: 26/11/2018 Inspected At:

Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*REAR LH DOOR	Dented	1,267.50 FS	*1,267.50 FS
3	1		*ABDICHTUNG B	Not Necessary	4.60 FS	*- FS
4	1		*SEALING STRIP	Not Necessary	20.60 FS	*- FS
5	1		*RR LH DOOR OUTER DUCT COVER (GLANZS)	Not Necessary	111.90 FS	*- FS
6	1		*REAR LH DOOR INNER WEATHERSTRIP	Not Necessary	71.70 FS	*- FS
7	1		*REAR DOOR WEATHERSTRIP	Necessary	140.70 FS	*140.70 FS
8	1		*RR LH DOOR WINDOW FRAME COVER	Not Necessary	73.25 FS	*- FS
9	1		*LH EXTERIOR COVER WINDOW GUIDE WEB	Not Necessary	61.75 FS	*- FS
10	1		*REAR LH SIDE WINDOW FIXED	Necessary	171.70 FS	*171.70 FS
11	1		*SEAL	Not Necessary	17.35 FS	*- FS
12	1		*REAR LH DOOR WINDOW GUIDE	Not Necessary	124.40 FS	*- FS
13	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS
14	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	131.55 FS	*- FS
15	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*- FS
16	5		*EXPANDING NUT	Necessary	10.00 FS	*10.00 FS
17	1		*REAR DOOR BRAKE	Necessary	77.20 FS	*77.20 FS
18	1		*EXPANDING NUT (4.8)	Necessary	1.00 FS	*1.00 FS
19	5		*EXPANDING NUT (4.8)	Necessary	5.00 FS	*5.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **2,494.20** **1,753.10**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACING REAR LEFT DOOR	New	1,275.00	850.00
2	PAINTING LEFT REAR DOOR	New	885.00	796.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
4	TO SUPPLY AND INSTALL REAR LEFT WINDOW GLASS QUOTER SOLAR FILM	New	425.00	0.00
5	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	451.00
6	TO REPLACE REAR LH SIDE WINDOW FIXED INCLUDE CONDUCTING WATER LEAK TESTS	New	413.00	413.00
Gross Labour Cost (S\$)			3,647.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >