

ASS. REC. BY:

REF: CS/CT11802607/719d3n2 Special Instruction:

Surveyor: Richmond ASSIGNMENT (Office)

From (Person): Catherine Fria of CTI Date/Time: 20/11/18 @ 4:10pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKM 55721 Insured: SGW 7382Y

at Workshop m/s: Weames Automotive Tel: 64304890

of 28 Jeng Kee Road

Policy No: DMPCSN2004781800 Claim No: SNM18D05421C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 16/11/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 4:53pm 20/11/18 Person Contacted: Richmond H.O.D. Endorsement: \_\_\_\_\_  
Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKM 55721 - NA/AIG 17013247/h4 JDA: 7/7/2017
	SGW 7382Y - CS/CT118015880/Utd3n2 JDA: 26/8/2018
20/12/18 @	12:07pm confirmed with Richmond final fig \$ 5781.73, 4 days CRed to 4509.17, 44%

Garrett *Tanpas*

REF: **CFI**

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_


Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_



(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: Derek Vehicle: IN / OUT

Veh No: **SKM 552J** Yr Regn: **2014 March**

Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: **Volvo S60** C.C. **1560**

Colour: **Black** A/C: Insured / Std / NI / NA

Sp. Reading: **99788** T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: **YV1FSS4ABE 2274311**

Gen. Cond: Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **235 / 45 R17**

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front R/Bal: 6 mm Rear R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 26/11/18 @ 330

Survey held at Waters Alexander

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction \_\_\_\_\_

RECEIVED 28 DEC 2018

Date/Time, File Pass to?  Preli. Report

11/12/18  Final Report

Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee \_\_\_\_\_

Transportation \_\_\_\_\_

) \$ + PS \$ \_\_\_\_\_

) Photo \_\_\_\_\_

) Other \_\_\_\_\_

Report Format: MEM-TP

Lump Sum / L.B.I: (\$) 5781.23

TOTAL **220**

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Nov 2018		20 Nov 2018 16:10 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main
Reference
Claim Details
Documents
[Show All](#)

**[Created by insurer]**

**CLAIM SUBFOLDER DETAILS**

Insured:	SIA FOOK SENG, ID: S2736952I		
Main Claimant:	JOSHUA TJANDRA TJAHJONO, ID: S7270447I		
Vehicle Reg. No.:	SKM5572J	Date of Loss:	16/11/2018 23:00 - :59
Claim Type:	TP / SNM18D05421C02	Policy/Cover Note No.:	DMPCSN3004781800 (Comprehensive)
Vehicle Reg. No. (Insured):	SGW7382Y	Policy No. (Claimant):	2100367665
		Excess:	S\$0.00
Repairer:	Wearnes Automotive Pte Ltd (Leng Kee) 28 Leng Kee Road, 159105 Leng Kee - Tel: 63782680		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Final Rpt due 29/11/2018]</b>		
Driver/Custodian (Insured):	SIA FOOK SENG (58 / Male), NRIC: S2736952I		
Adj Asg. Remarks:	EST \$11,010.75, CASE WITH SJE.		

[View All](#)
[Compose Case Mail](#)

**ASSOCIATED MAIL RECEIVED**

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 20 December 2018 12:07 PM  
**To:** 'Richmond Ho'; Taufikh (LKKAuto); SUR  
**Cc:** Derek Oh Siong Wee  
**Subject:** RE: Final Bill For SKM5572J

Dear Richmond,

WITHOUT PREJUDICE

Confirm final fig \$5,781.23 before GST and 4 repair days.

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Richmond Ho <[richmond.ho@wearnes.com](mailto:richmond.ho@wearnes.com)>  
**Sent:** Monday, 10 December 2018 11:52 AM  
**To:** Taufikh (LKKAuto) <[Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** Derek Oh Siong Wee <[derek.oh@wearnes.com](mailto:derek.oh@wearnes.com)>  
**Subject:** Final Bill For SKM5572J  
**Importance:** High

Hi Taufikh

Please refer to above attachment for the final bill.

**Richmond Ho**  
Senior Service Consultant  
Body & Paint – Insurance Claim



**Wearnes Automotive Pte Ltd**  
249 Alexandra Road Singapore 159935  
D (65) 6430 4890 M (65) 9176 8543  
[www.wearnesauto.com](http://www.wearnesauto.com) [richmond.ho@wearnes.com](mailto:richmond.ho@wearnes.com)

*This email, including any attachment, is confidential and may also be privileged.  
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.  
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/11/2018 13:55
Date Of Accident	16/11/2018 23:30
Exact Location Of Accident	JUNCTION OF MARYMOUNT RD & ANG MO KIO AVE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKM5572J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	JOSHUA TJANDRA TJAHJONO
NRIC No	S72704471
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98346465
Alternative Phone No	OFFICE-98346465

### Vehicle Particulars

Manufacturer	VOLVO
Model	S60-1.6 D2 (A)
Exact Purpose for which vehicle was being used at time of accident	SOCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100367665
Cover Note Number	

### Driver

Name of Driver	JOSHUA TJANDRA TJAHJONO
NRIC No	S72704471
Date Of Birth	26/02/1972
Occupation	INDOOR
Date Of Driving Pass	12/05/1994
Driving Experience	24 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98346465
Fax Number	
Contact Number	OFFICE-98346465
EEmail Address	NOEMAIL

Address BLK 350 ANG MO KIO ST 32 #22-115  
 Postcode 560350  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 3  
 Passenger 1

NAME: : JOEL CHEN  
 GENDER: : MALE

Passenger 2

NAME: : NEVIN CHUA  
 GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO SKETCH PLAN

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SGW7382Y  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver SIA FOOK SENG  
 NRIC/Passport Number S2736952I  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

\_\_\_\_\_  
Driver's Signature (if driver is not the policyholder) / Date & Time

\_\_\_\_\_  
Witnessed by Reporting Centre Personnel

**Sketch Plan**



Marymount Rd

**Describe Circumstance of the Accident**

I was driving home on 16 Nov 2018 evening with 2 passengers. I stopped my car at the traffic light at Marymount Rd - AMK ave junction as it is red. After 8 seconds waiting at the traffic light, a car behind my car did hit my car from the back.

I exited from my car to inspect on the damage.

**IMPORTANT NOTE**

Under General Condition - Conduct of Claim of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

**Declaration**

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

\_\_\_\_\_  
Driver's Signature (if driver is not the policyholder) / Date & Time

\_\_\_\_\_  
Witnessed by Reporting Centre Personnel

✓  
 in 231118  
 survey on 261118

**SERVICE ESTIMATE**

51578 - C00001 SL: SERVICE SALES - PC  
 Mr Joshua Tjandra Tjahjono  
 Blk 350 Ang Mo Kio Street 32  
 #22-115

Singapore 560350

Closed by .... : Richmond Ho  
 Svc Consultant :  
 Remarks ..... : Mr Joshua Tjandra Tj

GST Reg.No: M28920628X  
 Inv.No. : B&P 0 Page 1  
 Inv.date. : 19/11/2018  
 WIP No. : 39047  
 Veh.In/Out: 19/11/2018  
 \*Tel.No. : Mobile: 98346465  
 Reg.No. : SKM5872J  
 Reg.date : 14/03/2014  
 Mileage : 0  
 Chassis No: YV1FS84ABE2274311

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR LOWER SPOILER, REAR SKID PLATE REAR BRACKET, REAR TOW COVER, ETC		0	2400.00	0		2,400.00	S
800	TO PUTTY SPRAY PAINT ON REAR BUMPER, REAR LOWER SPOILER, ETC		0	2100.00	0		2,100.00	S
280	TO CHECK WIRING INCLUDE RESETTNG OF ALL ELECTRICAL MODULES		0	450.00	0		450.00	S
	BUMPER COVER REAR S6	1.0	EA	1428.70	1285.83		1,428.70	S de
	BUMPER SPOILER REAR	1.0	EA	486.40	437.76		486.40	S at
	BUMPER SPOILER REAR	1.0	EA	486.40	437.76		486.40	S ale
	BUMPER BRACKET LHR S	1.0	EA	54.30			54.30	S ? x n1
	BUMPER BRACKET RHR S	1.0	EA	54.30			54.30	S ? x n1
	BUMPER BRACKET LHR S	1.0	EA	54.30			54.30	S ? x n1
	BUMPER BRACKET RHR S	1.0	EA	54.30			54.30	S ? x n1
	BUMPER BRACKET CTR R	1.0	EA	88.70	79.83		88.70	S mis
	TOW COVER REAR S60 1	1.0	EA	73.90	66.51		73.90	S mis

1200 /  
~~87000~~

1400 /

de  
 at  
 ale  
 ? x n1  
 ? x n1  
 ? x n1  
 ? x n1  
 mis

*Signature*  
 27/11/18

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Taufik 97495749  
 'WP'  
 26/11/18 @ 330pm  
 Resurvey before paint  
 off days  
 sur@lkkauto.com

### SERVICE ESTIMATE

51578 - C00001 SL: SERVICE SALES - PC

Mr Joshua Tjandra Tjahjono  
 Blk 350 Ang Mo Kio Street 32  
 #22-115

Singapore 560350

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2  
 Inv.date. : 19/11/2018  
 WIP No. . : 39047  
 Veh.In/Out: 19/11/2018  
 \*Tel.No. . : Mobile: 98346465  
 Reg.No. . : SKM5572J  
 Reg.date. : 14/03/2014  
 Mileage . : 0  
 Chassis No: YV1F384ABE2274311

Closed by .... : Richmond Ho  
 Svc Consultant :  
 Remarks ..... : Mr Joshua Tjandra Tj

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER RAIL (BEAM) R	1.0 EA	1277.20			1,277.20	S ? X An
	PARK ASSIST REAR SV6	1.0 EA	811.30			811.30	S ? X An
	BUMPER INSTALLING MT	1.0 EA	83.40	Hand		83.40	S ? X An
	BLIND RIVET 4.0*21 P	10.0 EA	3.00	2%		30.00	S nec ✓
	BUMPER CLIP 8x8,5	10.0 EA	5.40	48.60		54.00	S nec ✓
	ADHESIVE TUBE CHEMIC	4.0 EA	75.80	277.88		303.20	S nec ✓

Gross Total. 10,290.40  
 Net..... 10,290.40  
 GST @ 7.0% 720.33  
 Total..... 11,010.75  
 Paid..... 0.00  
 Please Pay.. 11,010.75

Labour Total 4,950.00  
 Parts Total 5,340.40  
 Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

### SERVICE ESTIMATE

0 - C00010      SL: CHINA TAIPING INSURANCE (SINGAPORE)  
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD      GST Reg.No: M28920628X  
 3 ANSON ROAD      Inv.No. . : B&P      0 Page 1  
 #16-00, SPRINGLEAF TOWER      Inv.date. : 10/12/2018  
 SINGAPORE 079909      WIP No. . : 39047  
    Veh.In/Out: 23/11/2018 28/11/2018  
    \*Tel.No. . : 63896111  
    Reg.No. . : SKM5572J  
    Reg.date .: 14/03/2014  
    Mileage .: 0  
    Chassis No: YV1FS84ABE2274311

Closed by .... : Richmond Ho  
 Svc Consultant :  
 Remarks ..... : Mr Joshua Tjandra Tj

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
302	TO REPLACE REAR BUMPER, REAR LOWER SPOILER, REAR SKID PLATE	0	1200.00	0		<del>1,200.00</del>	S
300	TO PUTTY SPRAY PAINT ON REAR BUMPER, REAR LOWER SPOILER, ETC	0	1400.00	0		<del>1,400.00</del>	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		<del>450.00</del>	S
	BUMPER COVER REAR 36 (1)	1.0 EA	1428.70	10		1,285.83	S
	BUMPER SPOILER REAR (2)	1.0 EA	486.40	10		437.76	S
	BUMPER SPOILER REAR (3)	1.0 EA	486.40	10		437.76	S
	BUMPER BRACKET CTR R (4)	1.0 EA	88.70	10		79.83	S
	TOW COVER REAR S60 (5)	1.0 EA	73.90	10		66.51	S
	BUMPER INSTALLING HT (6)	1.0 EA	83.40	10		75.06	S
	BLIND RIVET 4.0*21 P (7)	10.0 EA	3.00	10		27.00	S
	BUMPER CLIP 8x8, 5 (8)	10.0 EA	5.40	10		48.60	S
	ADHESIVE TUBE CHEMIC (9)	4.0 EA	75.80	10		272.88	S
						<b>Gross Total.</b>	5,781.23
						<b>Net.....</b>	5,781.23
						<b>GST @ 7.0%</b>	404.69
						<b>Total.....</b>	6,185.92
						<b>Paid.....</b>	0.00
						<b>Please Pay..</b>	6,185.92
	<b>Labour Total</b>		3,050.00				
	<b>Parts Total</b>		2,731.23				
	<b>Package Total</b>		0.00				

GST: S=StdRated; Q=OutOfScope; Z=ZeroRated

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118021007/T1QD3N2  
Date: 21/12/2018

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3004781800
Claimant Vehicle No :	SKM5572J	Insured Vehicle No :	SGW7382Y
Date of Loss:	16/11/2018	Nature of Claim:	TP
		Claim No:	SNM18D05421C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM5572J	Engine No:	D4162T2520010
Make & Model:	VOLVO S60, 1.6 D2 (A)	Chassis No:	YV1FS84ABE2274311
Reg. Date:	14/03/2014 (Man. Year: 2013)	Odometer:	99788 km
Colour:	Black		
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/45R17	Rear Tyre Size:	235/45R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,340.40	2,731.23	2,609.17	48.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,950.00	3,050.00	1,900.00	38.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,290.40</b>	<b>5,781.23</b>	<b>4,509.17</b>	<b>43.82</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>720.33</b>	<b>404.69</b>	<b>315.64</b>	<b>43.82</b>
<b>Nett Amount (S\$)</b>	<b>11,010.73</b>	<b>6,185.92</b>	<b>4,824.81</b>	<b>43.82</b>

### INSPECTION

Date of Assignment: 20/11/2018  
Date Inspected: 26/11/2018 Inspected At:

Wearnes Automotive Pte Ltd (Alexandra Road)  
249 Alexandra Road  
Singapore 159935

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**REPAIR DETAILS****Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Dec 2018)  
 Parts: 143 VOLVO S60 1.6 D2 (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: (Unsubmitted, no print-code for SKM5572J)  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR S6	Deformed	1,428.70 FS	*1,285.83 FS
2	1		*BUMPER SPOILER REAR	Cut	486.40 FS	*437.76 FS
3	1		*BUMPER SPOILER REAR	Deformed	486.40 FS	*437.76 FS
4	1		*BUMPER BRACKET LHR S	Not Necessary	54.30 FS	*- FS
5	1		*BUMPER BRACKET RHR S	Not Necessary	54.30 FS	*- FS
6	1		*BUMPER BRACKET LHR S	Not Necessary	54.30 FS	*- FS
7	1		*BUMPER BRACKET RHR S	Not Necessary	54.30 FS	*- FS
8	1		*BUMPER BRACKET CTR R	Necessary	88.70 FS	*79.83 FS
9	1		*TOW COVER REAR S60 1	Missing	73.90 FS	*66.51 FS
10	1		*BUMPER RAIL (BEAM) R	Not Necessary	1,277.20 FS	*- FS
11	1		*PARK ASSIST REAR SV6	Not Necessary	811.30 FS	*- FS
12	1		*BUMPER INSTALLING MT	Necessary	83.40 FS	*75.06 FS
13	10		*BLIND RIVET 4.0*21 P	Necessary	30.00 FS	*27.00 FS
14	10		*BUMPER CLIP 8X8.5	Necessary	54.00 FS	*48.60 FS
15	4		*ADHESIVE TUBE CHEMIC	Necessary	303.20 FS	*272.88 FS
<b>Total Parts (S\$)</b>					<b>5,340.40</b>	<b>2,731.23</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER,REAR LOWER SPOILER,REAR SKID PLATE REAR BRACKET,REAR TOW COVER,ETC	New	2,400.00	1,200.00
2	TO PUTTY SPRAY PAINT ON REAR BUMPER,REAR LOWER SPOILER,ETC	New	2,100.00	1,400.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	450.00	450.00
<b>Gross Labour Cost (S\$)</b>			<b>4,950.00</b>	<b>3,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >