

ASS. REC. BY: Surveyor REF: CS3/Lpc/18010797/77rd3-1 and instructions

ASSIGNMENT (Office)

From (Person) Gerard Poh of Lpc Date/Time: 21-11-2018

Estimated Cost: _____ Bill to: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBC 2957L Insured: SGG 2741L

at Workshop no/s 88 Motoring Tel: 6298 9596

of 1084 Serangoon Rd - 328186

Policy No: _____ Claim No: 18/18/18 / VP05 / 020653

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 4/6/2018

(Client's Record) 14/06/18

CA / REV / REP. / REV 24 HRS lup H.O.D. Endorsement: _____

Date/Time: 4:31pm @ 12/6/18 Person Contacted: Sam Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate	
	FBC 2957L - NBA / Lpc / 18010221 / Y	D.O.A: 4/6/2018
	SGG 2741L - NBA / Lpc / 18010221 / Y	D.O.A: 04/06/2018

Submit PRs report

Submit L/S \$1900 @ 4 days
(Red: \$2300, 55%)

Repair days 4

[Signature]
22/11/2018

RECEIVED 23 NOV 2018

Return
line
22/11/18

REVISED

Tanjin

REF: IPC

ASSIGNMENT

From: _____ Date: 11/06/18

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBC 2957L

at Workshop m/s: SS Motoring

of: 1084 Serunggan Rd

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Sumo G298 9596

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / FR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{hup}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBC 2957L Yr Regn: _____

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Wave 125 cc

Colour: Red A/C: Insured / Std / NI / NA

Sp Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SiRim / STD A/Rim or

Tyre Size: F: 70 / 100R7 R: 60 / 100R7

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. mm	L/Bal. mm
D.O.A.	D.O.I. 14/6/18 @ 3pm

Survey held at: SS Motoring

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 15 OCT 2018

Case/Time: File Pass to? : Prell. Report

ti ^{typist} : Final Report

Date/Time: File Return to?

Days Of Repair: _____

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

3 - RE - \$

1 - Prev

1 - Other

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$)

450
450



LONPAC INSURANCE BHD

(S98FC5635C)

Our Ref : 18/18/18/VP05/020653

Your Ref : CS3/LPC18010797/T1rd3e2

20 November 2018

M/s LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933

Dear Sirs/Madam

PAPER SURVEY OF FBC2957L

We refer to the above matter.


We enclose the following documents :-

- a) Survey report & photos of FBC2957L
- b) GIA report of FBC2957L
- c) GIA report & photos of SGG2741L

Kindly study the documents and let us have your report by 30 November 2018.

Yours faithfully

GERALD POH
SENIOR EXECUTIVE
(CLAIMS)
Email : mt_claim@lonpac.com



VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 354/TP/2018

Date: 1/10/2018

REFERENCE

Date of loss: 4/6/2018
Claimant: Muhammad Rizal Bin Tasran

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBC2957L	Make &	Honda
Reg date:	16/1/2008	Model	ANF 125MSS A
Colour:	Red	Engine No:	NF125MME5000736
Type:	Motorbike	Chassis No:	NF125MM5000736
Type of Claims:	Third Party	Odometer No:	N.A
		Engine Cap:	125cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY (STATIC ONLY)

General Condition: Good	Steering: N.A.	Engine Modification: Nil
Paint work: Good	Front brake: Good	Pre-accident
	Footbrake: Good	Damage: Nil

CONDITION OF TYRES

Front Wheel Size: Michelin 70/90R17 70%
Rear Wheel Size: Pirelli 80/90R17 70%
The above percentages represent the remaining life of the tyre threads

COST OF REPAIRS


	Repairer S\$	Adjuster S\$
Parts	S 4,088.50	S 4,088.50
Labour	S 1,390.00	S 1,190.00
Calculated Cost (S\$) :	<u>S 5,478.50</u>	<u>S 5,278.50</u>

Recommended Lump Sum Repair Cost (S\$) : S 4,200.00

Date of Assignment: 18/6/2018
Date Inspected: 18/6/2018
Est. repair Period: 07 days

Inspected At: SS Motoring
1084 Serangoon Road
Singapore 328186

POINT OF IMPACT

Damaged at the front, right hand front, right hand rear and rear portion	
--	--

BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle at the roundabout of Hillview Avenue towards Glendale Park.

GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are the front, right hand front, right hand rear and rear portion.

SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$5,478.50. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$4,200.00.

We have not authorised the repair. Under normal circumstances, estimated 07 working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Dave Chang
Automotive Appraiser
AUTO. ENG, CAE, CGI
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount	
1	1	Front headlamp	grazed/cut	\$ 185.00	\$ 185.00	NNX
2	1 set	Front headlamp side cover	slack/bent	\$ 85.00	\$ 85.00	CUTV
3	1	Front headlamp stay	slack/bent	\$ 35.00	\$ 35.00	} NNX
4	1	Front right signal lamp	slack/bent	\$ 55.00	\$ 55.00	
5	1	Front right wing mirror	bent	\$ 45.00	\$ 45.00	CUTV
6	1	Front handle bar	bent	\$ 195.00	\$ 195.00	BTU
7	1	Front right handle balancer	necessary	\$ 28.00	\$ 28.00	CUTV
8	1	Front right brake lever	broken	\$ 65.00	\$ 65.00	BRV
9	1	Front fender	grazed/cut	\$ 105.00	\$ 105.00	✓
10	1	Front right fairing	grazed/cut	\$ 255.00	\$ 255.00	XNN
11	1 set	Front fork assy	malfunction/leaking	\$ 672.00	\$ 672.00	NNX
12	1 set	Front fork bearing assy	necessary	\$ 45.00	\$ 45.00	} NNX
13	1 set	Front fork stem	necessary	\$ 65.00	\$ 65.00	
14	1	Front wheel rim	bent	\$ 450.00	\$ 450.00	} NNX
15	1 set	Front centre cover	grazed/cut	\$ 95.00	\$ 95.00	
16	1	Front basket	bent	\$ 80.00	\$ 80.00	✓ CUT
17	1 set	Rear fairing complete assy	bent/warped	\$ 295.00	\$ 295.00	NNX
18	1	Rear right brake pedal	bent	\$ 65.00	\$ 65.00	✓
19	1	Rear right brake foot rest	bent	\$ 55.00	\$ 55.00	BTU
20	1	Rear right pillion foot rest	bent	\$ 55.00	\$ 55.00	BTU
21	1	Rear exhaust muffler assy	bent/grazed	\$ 850.00	\$ 850.00	✓
22	1	Rear right pillion side peg	bent	\$ 95.00	\$ 95.00	✓
				\$ 3,875.00	\$ 3,875.00	
		Less 10%		\$ 387.50	\$ 387.50	
				\$ 3,487.50	\$ 3,487.50	
		<u>Special Nett Items</u>				
1	1	Front no plate	bent	\$ 25.00	\$ 25.00	BTU
2	1	ERP IU	malfunction	\$ 156.00	\$ 156.00	XNN
3	1	ERP IU bracket	necessary	\$ 25.00	\$ 25.00	BTU
4	1	Rear box carrier assy	bent	\$ 150.00	\$ 150.00	RX
5	1	Rear box assy	necessary	\$ 180.00	\$ 180.00	SCRV
6	1	Rear no plate	bent	\$ 25.00	\$ 25.00	BTU
7	1	Front fork oil	necessary	\$ 40.00	\$ 40.00	NNX
				\$ 601.00	\$ 601.00	
		Total parts		\$ 4,088.50	\$ 4,088.50	

ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount
1	Labour to replace accident affected area.	\$ 500.00	\$ 450.00 ^{300.00}
2	To putty and spray paint affected area.	\$ 500.00	\$ 450.00 ^{200.00}
3	To conduct chassis alignment.	\$ 140.00	\$ 120.00 ^{100.00}
4	To check wheel alignment	\$ 60.00	\$ 40.00 X
5	To transport bike to workshop.	\$ 80.00	\$ 60.00
6	To balance front wheel.	\$ 30.00	\$ 20.00
7	To remove and install rear box assy.	\$ 50.00	\$ 30.00 X
8	To check wiring and lighting.	\$ 30.00	\$ 20.00
Total labour :		\$ 1,390.00	\$ 1,190.00

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 4,088.50	\$ 4,088.50
Total labour :	\$ 1,390.00	\$ 1,190.00
Total repair cost :	\$ 5,478.50	\$ 5,278.50

Adjusted Repair Cost (Lump Sum Repair)

\$ 4,200.00

Repair days 4

TG Caw
 Mui
 22/11/18



**SINGAPORE
POLICE FORCE**



T/20180605/7010

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180605/7010

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/06/2018 18:00	Video Report No.:	Station Diary No.:
--	-------------------	--------------------

Informant's Particulars			
Name of Informant: MUHAMMAD RIZAL BIN TASRAN		Address: APT BLK 547D SEGAR ROAD #15-29 SINGAPORE 674547	
ID Type / ID No.: NRIC NO / S8320706Z		Contact No.: Home/Office: Mobile: 82668992	
Nationality: SINGAPORE CITIZEN		Email: mrtasran@gmail.com	
Sex: Male	Age: 34	Date of Birth: 09/07/1983	Type of Informant: Rider
Race: Malay		Language: English	Institution / School Name:
Occupation: FOOD RIDER		Driving Licence Information: Class: 2B,2A,2,3,4	Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 04/06/2018 11:40	Type of Location: Roundabout
Location: HILLVIEW AVENUE Roundabout before hillview avenue exit				
Weather: Sunny		Road Surface: Dry	Road Speed Limit: 40 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBC2957L	Motorcycle	HONDA	ANF 125MSS A	Red		0
SGG2741L	Car	HONDA	STREAM	Black		0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBC2957L	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MC/00278394/02	05/12/2015	15/01/2019



**SINGAPORE
POLICE FORCE**



T/20180605/7010

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20180605/7010

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MUHAMMAD RIZAL BIN TASRAN	ID No.	S8320706Z
Related Vehicle	FBC2957L (Motorcycle)	Contact No.	82668992
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4 Date of Expiry: NIL
Date Treatment	04/06/2018	Date Discharge	05/06/2018
No. of Days granted Medical Leave	07	Degree of Injury	Serious

Brief Details.

On 04/06/2018 @ 1140HRS, I was travelling on Hillview Road on my motorcycle (FBC2957L) towards the road-about of Hillview Road and Hillview Avenue. I was riding along this place during the course of my work which is delivering food orders for Food Panda. My intended destination is Glendale Park Condominium. When I am in the roundabout facing Hillview Ave towards Glendale Park, suddenly I felt an impact from my rear and caused me to lose control of my bike and fell off. I then realised that a car bearing (SGG2741L) had failed to give way when he was entering the roundabout and collided to the rear of my motorcycle. I quickly took photos and then he came to helped me move my vehicle. Passerby have called an ambulance and I was conveyed to Ng Teng Fong General Hospital for treatment. I was then warded for a night and was given (7) days of MC.



**SINGAPORE
POLICE FORCE**



T/20180605/7010

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20180605/7010

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 05/06/2018 18:00
Officer In Charge Of Case: TP / TP1B / YUS MASTARI I KHAZALI Contact No.: 65476214	Classification Of Case:

Authentication Stamp
NP166

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/06/2018 14:16
Date Of Accident	04/06/2018 11:40
Exact Location Of Accident	HILLVIEW RD ROUNDABOUT NEAR TO HILLVIEW V2 S/M
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGG2741L
Insured/Policyholder	
Name Of Registered Owner	SOH BENG TECK
NRIC No	S1216539J
Email Address	MICHAL_SOH@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-97820525
Alternative Phone No	OTHERS-97820525

Vehicle Particulars

Manufacturer	HONDA
Model	EDIX-1.7 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	Z18VP05018134
Cover Note Number	

Driver

Name of Driver	SOH BENG TECK
NRIC No	S1216539J
Date Of Birth	08/11/1955
Occupation	INDOOR
Date Of Driving Pass	08/08/1977
Driving Experience	40 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97820525
Fax Number	
Contact Number	OTHERS-97820525
EMail Address	MICHAL_SOH@YAHOO.COM.SG

Address	BLK 201 BUKIT BATOK STREET 21 #15-162
Postcode	650201
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO MOTORCYCLIST
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	QUEENSTOWN N.P.C
Police Station Address	ROAD: 3 QUEENSWAY #01-03 , POSTCODE: 149073 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO. 1800-4719999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20180605/2066

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBC2957L
Vehicle Make/Model/Colour	HONDA ANF125 MSS
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	UNKNOWN
Approximate Age	
Injuries Sustain	SLIGHT INJURY
Injured person in which vehicle?	FBC2957L
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"); the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) My Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (c) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature
Date & Time

PL 5/6/18


Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Person's Signature
Name:
NIC/FIN No:

05/06/2018
PEKIA WATSON

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLS REFER TO POLICE REPORT
1/20/2005/2066

DECLARATION

(We declare the foregoing particulars are true in every respect)

AL 4/6/18
Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

15/06/2018
Name: [Signature]
NIC/IN No: [Signature]

POLICE REPORT



SINGAPORE
POLICE FORCE



T201806052066

Police Station Of Origin
Queenstown N P C
3 Queensway #01-03 SINGAPORE 149073
Tel No. 1800-4719990

1 of 3
Report No. T201806052066

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 05/06/2018 13:52	Video Report No.	Station Diary No 52
---	------------------	------------------------

Informant's Particulars			
Name of Informant SOH BENG TECK		Address APT BLK 201 BUKIT BATOK STREET 21 #15-162 SINGAPORE 650201	
ID Type / ID No NRIC NO / S1216539J		Contact No Home/Office Mobile 97820525	
Nationality SINGAPORE CITIZEN		Email	
Sex Male	Age 62	Date of Birth 08/11/1955	Type of Informant Driver
Race Chinese		Language	Institution / School Name
Occupation Retiree		Driving Licence Information Class 3 Date of Expiry	

General Information of the Accident				
Type of Accident	Injury Conveyed By Ambulance	Drink Drive No	Date/Time of Accident 04/06/2018 11:40	Type of Location Roundabout
Location Along Road 1 HILLVIEW ROAD Hillview Rd roundabout near to Hillview V2 Shopping Mall				
Weather Clear		Road Surface Dry	Road Speed Limit 50 Km/h	
Traffic Flow One Way		Traffic Control Not Controlled	Traffic Volume Light	
Type of Collision Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBC2957L	Motorcycle	HONDA	ANF 125MSS A	Red	Slightly Damaged	0
SGG2741L	Car	HONDA	EDIX 1.7 A	Black	Slightly Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGG2741L	LONPAC INSURANCE BHD.	Z18VP05018134	08/05/2018	07/05/2019

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20180605/2066

Police Station Of Origin:
Queenstown N P C
3 Queensway #01-03 SINGAPORE 149073
Tel No 1800-4719999

2 of 3
Report No: T/20180605/2066

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	SOH BENG TECK	ID No.	S1216539J
Related Vehicle	SGG2741L (Car)	Contact No	97820525
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details

On 04/06/2018 at about 1140hrs. I driving along Hillview Rd roundabout and out of sudden a motorbike (FBC2957L) cut into roundabout which led into soft collision. The motorbike lose balance and fell on the right side. Immediately I alight from my car(SGG2741L) to render assistance to the Malay rider. I noticed the Malay rider had bruises and slight bleeding on his palm. I pushed his motorbike to the side. He informed that he need to do delivery (Food Panda) and I drove him the delivery locations. Both of us went back to the scene and the rider need to collect his personal belongings. While the rider taking his personal belongings, an ambulance came to the scene. Paramedic check on the rider and subsequently conveyed to the nearest hospital. The rider gave me his motorbike keys. I have gave him my contact number and till now the rider have yet to call me.

POLICE REPORT



SINGAPORE
POLICE FORCE



T201806052066

Police Station Of Origin
Queenstown N P C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

3 of 3
Report No: T201806052066

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT - Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report D / Sr Staff Sgt MOHAMMAD ASRI BIN MAZLAN	Signature Of Informant
Signature Of Interpreter Not applicable	Date/Time 05/06/2018 13:52
Officer In Charge Of Case TP / GIT / Sr Staff Sgt YUS MASTARI I KHAZALI Contact No: 65476214	Classification Of Case

Authentication Stamp
NP186

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS3/LPC18010797/T1rd3e2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 27-11-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGG 2741L	Veh. Inspected	FBC 2957L
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020653	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	21/11/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA WAVE 125	c.c	125
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	NF125MM5000736	Colour	RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	70/90 R17	MICHELIN	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	60/90 R17	MICHELIN	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/06/2018	Inspection Date	14/06/2018
Survey held at	SS MOTORING 1084 SERANGOON ROAD SINGAPORE 328186		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBC 2957L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT HEADLAMP	NOT NECESSARY	185.00	-
1	SET FRONT HEADLAMP SIDE COVER	CUT	85.00	85.00
1	FRONT HEADLAMP STAY	NOT NECESSARY	35.00	-
1	FRONT RIGHT SIGNAL LAMP	NOT NECESSARY	55.00	-
1	FRONT RIGHT WING MIRROR	CUT	45.00	45.00
1	FRONT HANDLE BAR	BENT	195.00	195.00
1	FRONT RIGHT HANDLE BALANCER	CUT	28.00	28.00
1	FRONT RIGHT BRAKE LEVER	BROKEN	65.00	65.00
1	FRONT FENDER	GRAZED / CUT	105.00	105.00
1	FRONT RIGHT FAIRING	NOT NECESSARY	255.00	-
1	SET FRONT FORK ASSY	NOT NECESSARY	672.00	-
1	SET FRONT FORK BEARING ASSY	NOT NECESSARY	45.00	-
1	SET FRONT FORK STEM	NOT NECESSARY	65.00	-
1	FRONT WHEEL RIM	NOT NECESSARY	450.00	-
1	SET FRONT CENTRE COVER	NOT NECESSARY	95.00	-
1	FRONT BASKET	CUT	80.00	80.00
1	SET REAR FAIRING COMPLETE ASSY	NOT NECESSARY	295.00	-
1	REAR RIGHT BRAKE PEDAL	BENT	65.00	65.00
1	REAR RIGHT BRAKE FOOT REST	BENT	55.00	55.00
1	REAR RIGHT PILLION FOOT REST	BENT	55.00	55.00
1	REAR EXHAUST MUFFLER ASSY	BENT / GRAZED	850.00	850.00
1	REAR RIGHT PILLION SIDE PEG	BENT	95.00	95.00
	LESS 10% DISCOUNT		-387.50	-172.30
			3,487.50	1,550.70
SPECIAL NETT ITEMS				
1	FRONT NO PLATE (SN)	BENT	25.00	25.00
1	ERP IU (SN)	NOT NECESSARY	156.00	-
1	ERP IU BRACKET (SN)	BENT	25.00	25.00
1	REAR BOX CARRIER ASSY (SN)	TO REPAIR SEE LABOUR	150.00	-
1	REAR BOX ASSY (SN)	SCRATCHED	180.00	180.00

Report Ref No. CS3/LPC18010797/T1rd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NO PLATE (SN)	BENT	25.00	25.00
1	FRONT FORK OIL (SN)	NOT NECESSARY	40.00	-
			601.00	255.00
	LABOUR			
	LABOUR TO REPLACE ACCIDENT AFFECTED AREA, INCLUSIVE OF THE REPAIR OF REAR BOX CARRIER ASSY.		500.00	300.00
	TO PUTTY AND SPRAY PAINT AFFECTED AREA.		500.00	200.00
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	140.00	-
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
	TO TRANSPORT BIKE TO WORKSHOP.		80.00	60.00
	TO BALANCE FRONT WHEEL.		30.00	20.00
	TO REMOVE AND INSTALL REAR BOX ASSY.	NOT NECESSARY	50.00	-
	TO CHECK WIRING AND LIGHTING.		30.00	20.00
			1,390.00	600.00
	GRAND TOTAL		5,478.50	2,405.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00

Report Ref No. CS3/LPC18010797/T1rd3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.