

000 Front View Left



001 Front View Right



002 Rear View Right




003 Rear View Left




004 Photographs of Damaged Parts



005 Photographs of Damaged Parts









015 Photographs of Damaged Parts



016 Photographs of Damaged Parts




017 Photographs of Damaged Parts




018 Photographs of Damaged Parts



019 Photographs of Damaged Parts



020 Photographs of Damaged Parts



021 Photographs of Damaged Parts



022 Photographs of Damaged Parts



023 Photographs of Damaged Parts







028 Photographs of Damaged Parts



029 Photographs of Damaged Parts



030 Photographs of Damaged Parts



031 Photographs of Damaged Parts



032 Photographs of Damaged Parts



033 Photographs of Damaged Parts



034 Photographs of Damaged Parts



035 Photographs of Damaged Parts



X

Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JPT2593)

036 Photographs of Damaged Parts



037 Photographs of Damaged Parts







041 Photographs of Damaged Parts



042 Photographs of Damaged Parts



✓



044 Photographs of Damaged Parts



045 Photographs of Damaged Parts



Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JPT2593)

046 Photographs of Damaged Parts



047 Photographs of Damaged Parts



048 Photographs of Damaged Parts





Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JPT2593)

052 Photographs of Damaged Parts



053 Photographs of Damaged Parts



054 Photographs of Damaged Parts



055 Photographs of Damaged Parts



056 Photographs of Damaged Parts



057 Photographs of Damaged Parts





fender



right fender

061 Photographs of Damaged Parts



062 Photographs of Damaged Parts



063 Photographs of Damaged Parts



Tailgate



bumper



reverse
sensor




bumper side

Submitted by: City Adjusters & Investigators Sdn. Bhd. (Vehicle Reg. No JPT2593)
067 Photographs of Damaged Parts



panel

068 Photographs of Damaged Parts



069 Photographs of Damaged Parts





073 Photographs of Damaged Parts



074 Photographs of Damaged Parts



075 Photographs of Damaged Parts







080 Photographs of Damaged Parts



081 Photographs of Damaged Parts





083 Photographs of Damaged Parts



084 Photographs of Damaged Parts



085 Photographs of Damaged Parts



086 Photographs of Damaged Parts



087 Photographs of Damaged Parts





089 Photographs of Damaged Parts



090 Photographs of Damaged Parts



091 Photographs of Damaged Parts



092 Photographs of Damaged Parts



093 Odometer Reading



Submitted by: City Adjusters & Investigators Sdn. Bhd.(Vehicle Reg. No JPT2593)

094 Chassis Number



095 Engine Compartment.JPG



096 Road Tax.JPG

