

22/03/2002

ASS. REC. BY:

REF:

CS/TML18021054/Asbnz

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

Marmen

From (Person): Dillen Senthilan

of

TMJ

Date/Time: 21.11.2018 2.01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJZ 7293U

Insured:

SKE 3311B

at Workshop m/s

Flying High

Tel:

6749 2997

of

Blk 7 Kaki Bukit Ave 6 #01-29

Policy No:

MVD10510

Claim No:

M1805900

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19.11.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

21.11.2018 2.01pm

Person Contacted:

Dean

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJZ 7293U - x

SKE 3311B - X

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJ27293U Yr Regn: 2010 / DecType: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Juke C.C. 1598Colour: Silver A/C: Insured / Std / NI / NASp.Reading: / T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1FBAF1520000015Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 215 / 55 R17R: /

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 21/11/18Survey held at Flying HighDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP: Tokio MarineResurvey No of Tpr E 1MV: 33KPV: 23KNett: 10K

RECEIVED 07 DEC 2018

07/12/18 Confirmed HS \$9,500/- @ 15 days with Adrian.
(\$24,035.83 Red. - 72%)

Date/Time, File Pass to?

07/12/18

Date/Time, File Return to?

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

* S + RS, SI

Photos

Others

TOTAL

550105601)
2)
3)
4)
5)Typst2)
4)
6)

Prel. Report:

Final Report:

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Nov 2018		21 Nov 2018 14:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	CHAY YEW CHOU (3/3), ID: S1429219E								
Main Claimant:	POON SIEW LAY, ID: S7977162G								
Vehicle Reg. No.:	SJZ7293U	Date of Loss:	19/11/2018 08:00 - :59						
Claim Type:	TP / M1805900	Policy/Cover Note No.:	MV010910 (Comprehensive) Coverage: 21/11/2017 - 20/11/2018						
Vehicle Reg. No. (Insured):	SKE3311B	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Flying High Spray Painting (HQ) BLK 1 Kaki Bukit Ave 6, #01-29 Auto Bay, 417883 Kaki Bukit - Tel: 67492997								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/11/2018]								
Driver/Custodian (Insured):	CHAY JIA XING, GORDON (), NRIC: S9718116, Tel: +6581681138								
Adj Asg. Remarks:	PLS. CHECK CONSISTENCY OF THE DAMAGE & PARTS PRICE. THKS								
Claimant's Solicitor:	VISION LAW LLC - Tel: 65342811								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
<div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7162G
Vehicle Details	
Vehicle No.:	SJZ7293U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Nov 2018
Vehicle Make:	NISSAN
Vehicle Model:	JUKE 1.6 A/T ABS D/AIRBAG 2WD 5DR
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	HR16016636C
Chassis No.:	JN1FBAF15Z0000015
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$21,882.00
Original Registration Date:	23 Dec 2010
First Registration Date:	23 Dec 2010
Transfer Count:	3
Actual ARF Paid:	\$21,882.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Dec 2020
PARF Rebate Amount:	\$13,129.00
Intended COE Rebate Details	
COE Expiry Date:	22 Dec 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$47,604.00
COE Rebate Amount:	\$9,930.00
Total Rebate Amount:	\$23,059.00

The information contained herein is correct as at 21 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/11/2018 16:06
Date Of Accident	19/11/2018 08:35
Exact Location Of Accident	KPE TWDS MCE AT 4.6KM MARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ7293U
Insured/Policyholder	
Name Of Registered Owner	POON SIEW LAY
NRIC No	S7977162G
Email Address	FION_POON@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97667798
Alternative Phone No	OFFICE-97667798

Vehicle Particulars

Manufacturer	NISSAN
Model	JUKE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093183875
Cover Note Number	

Driver

Name of Driver	POON SIEW LAY
NRIC No	S7977162G
Date Of Birth	06/08/1979
Occupation	INDOOR
Date Of Driving Pass	12/08/2002
Driving Experience	16 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97667798
Fax Number	
Contact Number	OFFICE-97667798
Email Address	FION_POON@HOTMAIL.COM

Address	BLK 638A PUNGGOL DRIVE #06-435
Postcode	821638
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : CHOW KUAI TENG GENDER: : FEMALE
Passenger 2	NAME: : TAN SHI HUAN FAITH GENDER: : FEMALE
Passenger 3	NAME: : TAN SHI EN GRACE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PUNGGOL N.P.C
Police Station Address	ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20181120/2063.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKE3311B
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B

Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKD7500B
Vehicle Make/Model/Colour
Details Of Properties VEHICLE C
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name GRACE TAN SHI EN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJZ7293U
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name CHOW KUAI TENG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJZ7293U
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 3

Name POON SIEW LAY
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJZ7293U
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?

Address

Postcode


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which ~~could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages~~); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

20/11/18 2:30pm f

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20181120/2063

1 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20181120/2063

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/11/2018 13:24	Vide Report No.:	Station Diary No.: 22
--	------------------	--------------------------

Informant's Particulars

Name of Informant: POON SIEW LAY			Address: APT BLK 638A PUNGGOL DRIVE #06-435 SINGAPORE 821638		
ID Type / ID No.: NRIC NO / S7977162G			Contact No.: Home/Office: Mobile: 97667798		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 39	Date of Birth: 06/08/1979	Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: LOGISTICS OFFICER			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 19/11/2018 08:35	Type of Location:
Location: Along Road 1 Traveling Toward Road 2 KALLANG PAYA LEBAR EXPRESSWAY travelling towards MCE at 4.6km mark				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJZ7293U	Car	NISSAN	JUKE 1.6 A/T ABS D/AIRBAG 2WD 5DR	Silver		3
SKD7500B	Car					0
SKE3311B	Car					0



**SINGAPORE
POLICE FORCE**



T/20181120/2063

2 of 4

Police Station Of Origin:
Punggol N.P.C.
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20181120/2063

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJZ7293U	NTUC Income Insurance Co-Operative Limited	5093183875	07/08/2017	22/12/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA		
Passenger				
Name	GRACE TAN SHI EN	ID No.	T1014070B	
Related Vehicle	SJZ7293U (Car)	Contact No.	NIL	
Hospital/Clinic	KK WOMEN'S AND CHILDREN'S HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	19/11/2018	Date Discharge	19/11/2018	
No. of Days granted Medical Leave	08	Degree of Injury	Serious	
Passenger				
Name	CHOW KUAI TENG	ID No.	S2536162H	
Related Vehicle	SJZ7293U (Car)	Contact No.	NIL	
Hospital/Clinic	RAFFLES HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	19/11/2018	Date Discharge	19/11/2018	
No. of Days granted Medical Leave	03	Degree of Injury	Slight	
Driver				
Name	POON SIEW LAY	ID No.	S7977162G	
Related Vehicle	SJZ7293U (Car)	Contact No.	97667798	
Hospital/Clinic	RAFFLES HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL	
Date Treatment	19/11/2018	Date Discharge	19/11/2018	
No. of Days granted Medical Leave	07	Degree of Injury	Slight	



**SINGAPORE
POLICE FORCE**



T/20181120/2063

3 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20181120/2063

CONTINUATION OF REPORT

Driver			
Name	ANG SOR PUI		ID No. S6813476E
Related Vehicle	SKD7500B (Car)		Contact No. 98341232
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	CHAY JIA XING GORDON		ID No. S9718116J
Related Vehicle	SKE3311B (Car)		Contact No. 81681132
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 19/11/2018 at about 0835hrs, I was travelling along KPE towards MCE on the right most lane of the three lanes, when the vehicle in front of me (A) SKD7500B had jammed braked and thus I had followed suit. However, a moment later, I felt an impact from the rear which caused my vehicle to move forwards and hit the rear bumper of vehicle A. The vehicle travelling on my rear is (B) SKE3311B. Traffic Police and Ambulance came and we were conveyed to Hospital. I and my mother were given 7 days and 3 days MC respectively, whilst my daughter who sustained a hairline fracture on her right arm was given 8 days of MC. That is all.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999



T/20181120/2063

4 of 4



Report No. T/20181120/2063

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Staff Sgt MOHAMAD RADZIF BIN MOHAMAD SALEH	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 20/11/2018 13:24
Officer In Charge Of Case: TP / GIT / Staff Sgt MOHAMED HUSNUL TAUFIQ BIN MD YUSOF Contact No.: 65476358	Classification Of Case: SN 085
Authentication Stamp NP168	Signature:  Singapore Police Force

flying High.

SJZ 72S34.

TP Tokio Marine.

Nissan Juke.

Shirley.

JN1FBAF1520000015

	30(SN) +
Rear Number Plate	30(SN) +
Rear Number Plate Holder. <i>new</i>	608.20 ✓
Rear Bumper <i>Distorted</i>	30 ✓
Rear Bumper Clips. <i>new</i>	$38.2 \times 2 = 76.40$ ✓
Rear Bumper Side Holders $\times 02$ <i>new</i>	$42.6 \times 2 = 85.20$ ✓
Rear Bumper Reflector $\times 02$ <i>crushed</i>	364.90 ✓
Rear Bumper Lower Garnish. <i>Distorted</i>	$45.8 \times 2 = 91.60$ ✓
Rear Bumper Impact Bracket $\times 02$ <i>crushed</i>	189.50 ✓
Rear Bumper Sponge <i>crushed</i>	111.20 ✓
Rear Bumper Inner Garnish. <i>new</i>	280(SN) 200(SN)
Reverse Sensor <i>Damaged</i>	482 ✓
Rear End Panel. <i>Distorted</i>	65.20 ✓
Rear End Panel Top Garnish. <i>new</i>	60(SN) ✓
Rear End Panel Sealant. <i>new</i>	$375.70 \times 2 = 751.40 \times$
Taillamp $\times 02$. <i>new</i>	1430.60 ✓
Tailgate. <i>Distorted</i>	161.40 ✓
Tailgate Lock <i>Jammed</i>	171.10 ✓
Tailgate Weatherstripe <i>cut</i>	508.70

SI27293U.

Tailgate Outer Garnish.	HP per	315	x
Tailgate Damper x02	HP per	216.9 x 2 = 433.80	x
Tailgate Inner Trim Board.	Carbad	399.	✓
Tailgate Inner Trim Board clips.	per	30	✓
Tailgate Glass Moulding.	per	173.20.	✓
Tailgate Glass Sealant.	per	60(SN)	✓
Nissan Logo	2	35.20	✓
Juke Wording	per	56.20	✓
Xtronic Emblem.		45.60	✓
Rear Fenders x02	Repairs	1129.3 x 2 = 2258.60	x
Rear Fenders Inner Trim Board x02	Delhd	352.1 x 2 = 704.20	✓
Rear Fenders Inner Trim Board clips.	per	60.	✓
Rear Fender Protector x02	Delhd	152.2 x 2 = 304.40	✓
Spare Tyre Panel.	Distorted	998.10.	✓
Spare Tyre Panel Top cover	HP per	331.50	x
Tools Tray.	Delhd	351.50	✓
Rear Exhaust Pipe	Bent	538.80.	✓
Rear Exhaust Mounting.	HP per	34.70.	x
Centre Exhaust Pipe.	Bent	589.40.	✓
		7719.2	

SJ2 7293U.

Rees Passenger Seat LH

Rees Passenger Seat RH.

Rees Axle

Rees Shock Absorber x 02

Rees Wheel Hub c/w Bearing x 02

1800(SN) +

1200(SN) +

1285 +

$240.4 \times 2 = 480.8$ +

$301 \times 2 = 602$ +

5367.8

SJ27293U.

Front Number Plate.	Bent	30(SN)	✓
Front Number Plate Holder	Del'd	30(SN)	✓
Front Number Plate Garnish.	Del'd	96.50	✓
Front Bumper	Del'd	572	✓
Front Bumper Lips.	per	30	✓
Front Bumper Side Holder x 02	per	$24.3 \times 2 = 48.60$	✓
Front Bumper Sponge.	each	289.10	✓
Front Bumper Reinforcement.	Bent	538.50	✓
Front Bumper Lower Garnish.	per	343.20	+
Front Bumper Tow Covers.	per	28.50	+
Front Bumper Fog Lamp x 02	each	$327.2 \times 2 = 654.60$	✓
Front Bumper Centre Grille	each	519.80	✓
Front Bumper Centre Grille Logo.	per	52.50	✓
Front Bumper Side Grille x 02	each	$197.9 \times 2 = 395.80$	✓
Headlamps x 02	each	$1496.6 \times 2 = 2993.20$	✓
Air Con Condenser.	Bent	501.10	✓
Radiator	Not per	685.70	+
Front Support Panel.	Repair	333.90	+

8143

STZ7293U.

Panel Beating

~~3800~~ 2000

Spray Painting.

~~3500~~ 1600

Wiring.

~~150~~ 60

To undersent.

~~180~~ 80

To remove reverse sensor.

~~100~~ 50

To remove upholstery.

~~150~~ 80

To remove rear seat.

~~280~~ 180

To transfer tailgate fittings.

~~150~~ 80

To remove tailgate glass

~~180~~ 120

To remove rear and centre exhaust pipes.

~~300~~ 180

To remove rear undercarriage.

380 +

To perform wheel alignment.

150 +

LKK Auto Consultants henceforth the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts price agreed to confirmation
- Third party survey on a "no prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Nett: 14842.60

Less 10%: 13358.34

STW: 320

35808-70.

To remove Condenser, radiator and to regas. 180 120

33535-83

60. ✓ 9560

Labour: 4610

total: 18288.34

2/s: 9.51C.
150up.

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI18021054/ASBN2

Date: 17/12/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MV010910
Claimant Vehicle No :	SJZ7293U	Insured Vehicle No :	SKE3311B
Date of Loss:	19/11/2018	Nature of Claim:	TP
		Claim No:	M1805900

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ7293U	Engine No:	HR16016636C
Make & Model:	NISSAN JUKE, 1.6 (A)	Chassis No:	JN1FBAF15Z0000015
Reg. Date:	23/12/2010 (Man. Year: 2010)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,248.70	13,740.14	12,508.56	47.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,560.00	4,610.00	4,950.00	51.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	35,808.70	18,350.14	17,458.56	48.76
Approved Total (Overridden) (\$\$)		9,500.00		
Nett Amount (\$\$)	35,808.70	9,500.00	26,308.70	73.47

INSPECTION

Date of Assignment:	21/11/2018	
Date Inspected:	21/11/2018	Inspected At:
		Flying High Spray Painting (HQ) BLK 1 Kaki Bukit Ave 6, #01-29 Auto Bay Singapore 417883
Estimated Period of Repair:	15.0 days	

Adjuster: ADRIAN LING**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2018)
Parts:	M1-SUV	NISSAN JUKE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ7293U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	608.20 F	*608.20 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER	Necessary	76.40 F	*76.40 FL
4	2		*REAR BUMPER REFLECTOR	Cracked	85.20 F	*85.20 FL
5	1		*REAR BUMPER LOWER GARNISH	Distorted	364.90 F	*364.90 FL
6	2		*REAR BUMPER IMPACT BRACKET	Dented	91.60 F	*91.60 FL
7	1		*REAR BUMPER SPONGE	Cracked	189.50 F	*189.50 FL
8	1		*REAR BUMPER INNER GARNISH	Torn	111.20 F	*111.20 FL
9	1		*REAR END PANEL	Distorted	482.00 F	*482.00 FL
10	1		*REAR END PANEL TOP GARNISH	Deformed	65.20 F	*65.20 FL
11	2		*TAILLAMP	Not Necessary	751.40 F	*- FL
12	1		*TAILGATE	Distorted	1,430.60 F	*1,430.60 FL
13	1		*TAILGATE LOCK	Jammed	161.40 F	*161.40 FL
14	1		*TAILGATE WEATHERSTRIPE	Cut	171.10 F	*171.10 FL
15	1		*TAILGATE OUTER GARNISH	Not Necessary	315.00 F	*- FL
16	2		*TAILGATE DAMPER	Not Necessary	433.80 F	*- FL
17	1		*TAILGATE INNER TRIM BOARD	Cracked	399.00 F	*399.00 FL
18	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 F	*30.00 FL
19	1		*TAILGATE GLASS MOULDING	Necessary	173.20 F	*173.20 FL
20	1		*NISSAN LOGO	Necessary	35.20 F	*35.20 FL
21	1		*JUKE WORDING	Necessary	56.20 F	*56.20 FL
22	1		*XTRONIC EMBLEM	Necessary	45.60 F	*45.60 FL
23	2		*REAR FENDER	Repair	2,258.60 F	*- FL
24	2		*REAR FENDER INNER TRIM BOARD	Deformed	704.20 F	*704.20 FL
25	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 F	*60.00 FL
26	2		*REAR FENDER PROTECTOR	Deformed	304.40 F	*304.40 FL
27	1		*SPARE TYRE PANEL	Distorted	998.10 F	*998.10 FL
28	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	331.50 F	*- FL
29	1		*TOOLS TRAY	Deformed	351.50 F	*351.50 FL
30	1		*REAR EXHAUST PIPE	Bent	538.80 F	*538.80 FL
31	1		*REAR EXHAUST MOUNTING	Not Necessary	34.70 F	*- FL
32	1		*CENTRE EXHAUST PIPE	Bent	589.40 F	*589.40 FL
33	1		*REAR AXLE	Not Necessary	1,285.00 F	*- FL
34	2		*REAR SHOCK ABSORBER	Not Necessary	480.80 F	*- FL
35	2		*REAR WHEEL HUB C/W BEARING	Not Necessary	602.00 F	*- FL
36	1		*FRONT NUMBER PLATE GARNISH	Deformed	96.50 F	*96.50 FL
37	1		*FRONT BUMPER	Deformed	572.00 F	*572.00 FL
38	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
39	2		*FRONT BUMPER SIDE HOLDER	Necessary	48.60 F	*48.60 FL
40	1		*FRONT BUMPER SPONGE	Cracked	289.10 F	*289.10 FL
41	1		*FRONT BUMPER REINFORCEMENT	Bent	538.50 F	*538.50 FL
42	1		*FRONT BUMPER LOWER GARNISH	Not Necessary	343.20 F	*- FL
43	1		*FRONT BUMPER TOW COVER	Not Necessary	28.50 F	*- FL
44	2		*FRONT BUMPER FOG LAMP	Cracked	654.60 F	*654.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*FRONT BUMPER CENTRE GRILLE	Cracked	519.80 F	*519.80 FL
46	1		*FRONT BUMPER CENTRE GRILLE LOGO	Necessary	52.50 F	*52.50 FL
47	2		*FRONT BUMPER SIDE GRILLE	Cracked	395.80 F	*395.80 FL
48	2		*HEADLAMP	Cracked	2,993.20 F	*2,993.20 FL
49	1		*AIR CON CONDENSER	Bent	501.10 F	*501.10 FL
50	1		*RADIATOR	Not Necessary	685.70 F	*- FL
51	1		*FRONT SUPPORT PANEL	Repair	333.90 F	*- FL
52	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
53	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
54	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
55	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
56	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
57	1		*REAR PASSENGER SEAT LH	Not Necessary	1,800.00 FS	*- FS
58	1		*REAR PASSENGER SEAT RH	Not Necessary	1,200.00 FS	*- FS
59	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
60	1		*FRONT NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,248.70	15,224.60
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,484.46
Total Parts (\$\$)	26,248.70	13,740.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	3,800.00	2,000.00
2	SPRAY PAINTING	New	3,500.00	1,600.00
3	WIRING	New	150.00	60.00
4	TO UNDERSEAL	New	180.00	80.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	80.00
7	TO REMOVE REAR SEAT	New	280.00	180.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO REMOVE REAR AND CENTRE EXHAUST PIPES	New	300.00	180.00
11	TO REMOVE REAR UNDERCARRIAGE	New	380.00	-
12	TO PERFORM WHEEL ALIGNMENT	New	150.00	-
13	TO REMOVE CONDENSER,RADIATOR AND TO REGAS	New	180.00	120.00
14	TOWING FEES	New	60.00	60.00
Gross Labour Cost (S\$)			9,560.00	4,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >