

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: PC59777 Yr Regn: 2017, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Mini BusMake: Mercedes Benz Vito C.C. 2143Colour: Black A/C: Insured / Std / NI / NASp. Reading: 43456 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDF44770523262498Gen. Cond: Good Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17R: 225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 18/07/19Survey held at Cycle and Carriage (Ubi)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front n/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAXA

MV:

PV:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report: