

AS, REC, BY:

REF:

REF: CS/CT18021091/Tlgbez

Special Instruction:

SURVEYOR

maximen

From (Person):

Elaine Cheong

ASSIGNMENT (Office)

Of

CT

Date/Time: 21.11.2018 3:54pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN 5492K

Insured:

YP 9188C

at Workshop m/s

Ryder Auto

Tel:

9090 8277

Arson

of

2 Kaki Bukit Ave 2 #02-19

Policy No:

DMCVSN 3045541800

Claim No:

SNM18D05365602

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12.11.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (wp)

Blk 3 Pioneer Rd North #01-16

30.11.2018 @ 9.30am

H.O.D. Endorsement:

Date/Time:

21.11.2018 4:34 PM

Person Contacted:

Orsun

Vehicle IN/OUT


Date/Time	Action/Instruction (✓) Estimate
	YN 5492K - X
	YP 9188C - X

Taufikh

REF:

CTI

From: _____ Date: _____
 Estimated Cost: _____
 OD (TP / WS / TP RES / OD RES / EVA / INV / MV)
 To Inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: \$50K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: YN5492K Yr Regn: 20/4 July
 Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: 15434. NPR85 C.C. 2499
 Colour: Blue A/C Insured / Std / NI / NA
 Sp. Reading: 197141 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JAANPR85HE7100205
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: NP / S/Rim / STD A/Rim or
 Tyre Size: F: 7.00 R16
 R: 1.2 (D)
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Firestone
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6/6 mm
 L/Bal. 6 mm L/Bal. 6/6 mm
 D.O.A. _____ D.O.I. 30/11/82 930
 Survey held at Ph Ryder Auto Repair
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/5 \$4700, 4 days. (Red \$ 6374.74, 57%) 1979 00006K

RECEIVED 21 JAN 2019

Date/Time File Pass to? ☐ : Preli. Report
21/1. 1979 ☐ : Final Report
 Date/Time File Return to? _____

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee: 220
 Transportation: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

_____ \$ + P.S. \$
 _____ Photos
 _____ Others

Report Format: MER-7P
 Lump Sum / L.B.I. (\$ 4700)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Nov 2018		21 Nov 2018 15:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS <div style="float: right;">[Created by insurer]</div>																								
Insured:	C/O DE CHENG XIN XING PTE LTD, Co. Reg. No.: 198901553R																							
Main Claimant:	YEE LEE OILS & FOODSTUFFS (S) PTE LTD																							
Vehicle Reg. No.:	YN5492K	Date of Loss:	12/11/2018 16:00 - :59																					
Claim Type:	TP / SNM18D05365C02	Policy/Cover Note No.:	DMCVSN3045541800 (Comprehensive)																					
Vehicle Reg. No. (Insured):	YP9188C	Policy No. (Claimant):																						
		Excess:	S\$0.00																					
Repairer:	Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, 417921 Kaki Bukit - Tel:																							
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/11/2018]																							
Adj Asg. Remarks:	NO EST, CASE WITH SJE.																							
ASSOCIATED MAIL RECEIVED <div style="float: right;"> View All Compose Case Mail </div>																								
There are no mail for this case.																								
<div> </div> ALL ASSOCIATED TASKS <div style="float: right;"> View All Search Tasks Create New Task Complete </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

ESTIMATE OF REPAIR

YN5492K Pg 1/2

Veh # : YN5492K Model : ISUZU NPR85UH5AK (1/7/2014)

Date Of Accident: 12/11/2018 3P : YP9188C (CHINA TAIPING)

Location : NO. 101 KALLANG AVE, VICTORIA WAREHOUSE (LOADING/UNLOADING)

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
	<u>List Items</u>				
1 pc	Front n/s door	bt ✓	2200	2,420.80	
1 pc	Front n/s door weather-strip	bt ✓	220	361.10	
1 pc	Front n/s door vertical seal arch.	de ✓		221.10	
6 pcs	Front n/s door vertical seal clips	ne ✓		71.40	
1 pc	Front n/s door inner board	Xiam		701.75	
8 pcs	Front n/s door inner board clips	X nm		103.20	
2 pcs	Front n/s door hinges (Upper & Lower)	bt ✓	300	363.40	
1 pc	Front n/s door lock (Inner)	X nm		482.75	
1 pc	Front o/s door checker	bt ✓	231	281.20	
1 pc	Front o/s door window seal (Outer)	ae ✓		226.40	
1 pc	Front o/s door window channel	ae ✓		248.40	
1 pc	Front o/s door window channel bracket	ae ✓		108.20	
1 pc	Front o/s door lock handle (Outer)	dis ✓	278.70	328.70	
1 pc	Front n/s door pillar (Outer) x R	Ry		789.20	
1 pc	Front n/s door pillar (Inner) x R	Rx		731.10	
1 pc	Front n/s door pillar panel (Outer) H cover	de ✓		383.70	
2 pcs	Front n/s door pillar panel clips	ne ✓		25.80	
1 pc	Door horizontal garnish stick on	ae ✓		86.20	
	Sub-Total		5006.40	7,934.40	
	After -15%			6,744.24	

4600.90

3910.77

Auto Pte Ltd

Email: ryderautoworkshop@gmail.com

YN5492K Pg 2/2

Repair bumper & pillar.

Page - 3910.77.

SN - 350

Lahore - 1580

5840.77

1584700

Man

Director

DipCE, AAE MIMI, MSAE(Aust)

8,819.39

Taufik 7249549.

up

30/11/180945

Reserve after repair.

4 days.

Lumpsum

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date:

SKETCH PLAN

VEHICLE NO.: YN 5492 K
INSURER : NTUC
DATE & TIME: 12/11/18 @ 16:00

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: (YS)
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No: T/20181113/2071

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

13/11/18

(YS)

GIATMC Sketch Plan Form V3 () Claim Own Policy () Claim Third Party () Reporting Only
(✓) Claim OD/TP at other workshop (by own workshop)



SINGAPORE POLICE FORCE



T/20181113/2071

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

1 of 3

Report No. T/20181113/2071

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/11/2018 13:38	Vide Report No.:	Station Diary No.: 39
--	------------------	--------------------------

Informant's Particulars

Name of Informant: IZWAN BIN IDRIS			Address: 1 Jalan Berlian 13 Taman Nora 81800 Ulu Tiram	
ID Type / ID No.: FIN NO / G6784010R			Contact No.: Home/Office: Mobile: 83005891	
Nationality: MALAYSIAN			Email:	
Sex: Male	Age: 26	Date of Birth: 25/07/1992	Type of Informant: Driver	
Race: Malay			Language:	Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 12/11/2018 16:00	Type of Location:
Location: KALLANG AVENUE No. 101 Kallang Avenue, Victoria Warehouse (loading/unloading)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
YN5492K	Lorry				Slightly Damaged	1
YP9188C	Lorry				Slightly Damaged	2

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20181113/2071

2 of 3

Report No. T/20181113/2071

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

CONTINUATION OF REPORT

Pedestrian			
Name	Wong Yok Peng	ID No.	F0337135L
Related Vehicle	YN5492K (Lorry)	Contact No.	81705322
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	12/11/2018	Date Discharge	NIL
No. of Days granted Medical Leave	07	Degree of Injury	Slight

Brief Details.

On 12/11/2018 at about 1600hrs, I parked my vehicle YN5492K at the loading and unloading bay of the said location. My colleague, Wong Yok Peng and myself then did the unloading. After the unloading, I started my engine and waited for my colleague to go in to the passenger. While he was about to enter the passenger door. A vehicle YP9188C honked from the rear my vehicle and tried to squeeze on the left side of my vehicle. The vehicle then squeeze pass my left side and I saw my colleague roll over to the front.

I made a checked and discovered that my left side door was damaged and my colleague left hand area was hit. My colleague was then brought to Tan Tock Seng and given 7 days MC.



**SINGAPORE
POLICE FORCE**



T/20181113/2071

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

3 of 3

Report No. T/20181113/2071

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Staff Sgt ISZAD BIN ISHAK

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SI ANG YI TING, STEPHANIE

Contact No.: 65476414

Signature Of Informant:

Date/Time:

13/11/2018 13:38

Classification Of Case:

Authentication Stamp

NP168



Signature:

Singapore Police Force

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Nov 2018		21 Nov 2018 15:54 Edit Adj Rpt	S\$4,700.00 Edit Estimates	S\$4,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: C/O DE CHENG XIN XING PTE LTD , Co. Reg. No.: 198901553R									
Main Claimant: YEE LEE OILS & FOODSTUFFS (S) PTE LTD									
Vehicle Reg. No.: YN5492K		Date of Loss: 12/11/2018 16:00 - :59	[52 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type: TP / SNM18D05365C02		Policy/Cover Note No.:	DMCVSN3045541800 (Comprehensive)						
Vehicle Reg. No. (Insured): YP9188C		Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer: Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, 417921 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/11/2018]									
Adj Asg. Remarks: NO EST, CASE WITH SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*YN5492K (SNM18D05365C02)

[YP9188C]

TP















































YEE LEE OILS & FOODSTUFFS (S) PTE LTD



Nov 12 2018 4:00PM

[C/O DE CHENG XIN XING PTE LTD]











Ryder Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View In Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)						Thumbnail	Print
1	13/11/18 16:11	Accident Statement						Load HTM	
Photos/Images							3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)						Thumbnail	Print
1	13/11/18 16:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>
2	13/11/18 16:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>
3	13/11/18 16:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>
4	13/11/18 16:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>
5	13/11/18 16:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>
6	13/11/18 16:10	CHASSIS NUMBER [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print
1	21/01/19 15:45	Odometer Reading						Load JPG	<input checked="" type="checkbox"/>
2	21/01/19 15:45	Chassis Number						Load JPG	<input checked="" type="checkbox"/>
3	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
4	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
5	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
6	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
7	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
8	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
9	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
10	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
11	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
12	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
13	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
14	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
15	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
16	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
17	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
18	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
19	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
20	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
21	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
22	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
23	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
24	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>
25	21/01/19 15:45	General View						Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
26	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
27	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
28	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
29	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
30	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
31	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
32	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
33	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
34	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
35	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
36	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
37	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
38	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
40	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
41	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
42	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
43	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
44	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
45	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
46	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
47	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
48	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
49	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
50	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
51	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
52	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
53	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
54	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
55	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
56	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
57	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
58	21/01/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
59	21/01/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	21/01/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	21/01/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	21/01/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	21/01/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	21/01/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	21/01/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	21/01/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	21/01/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	21/01/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	13/11/18 16:07	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	13/11/18 16:07	POLICE REPORT [Linked Accident Report Documents]	 Load TIF	
3	13/11/18 16:08	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]	 Load TIF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
4	13/11/18 16:08	DRIVER'S NRIC + DRIVING LICENCE [Linked Accident Report Documents]	 Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/11/18 15:53	PRI	 Load PDF	
2	21/11/18 15:54	OI GIA	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print	
1	13/11/18 16:11	Accident Statement	 Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print	
1	13/11/18 16:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
2	13/11/18 16:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
3	13/11/18 16:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
4	13/11/18 16:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
5	13/11/18 16:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
6	13/11/18 16:10	CHASSIS NUMBER	 Load JPG	<input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print	
1	13/11/18 16:07	Sketch Plan	 Load TIF		
2	13/11/18 16:07	POLICE REPORT	 Load TIF		
3	13/11/18 16:08	CERTIFICATE OF INSURANCE	 Load TIF		
4	13/11/18 16:08	DRIVER'S NRIC + DRIVING LICENCE	 Load TIF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18021091/T1QBE2

Date: 22/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3045541800

Claimant Vehicle
No : YN5492KInsured Vehicle
No : YP9188C

Date of Loss: 12/11/2018

Nature of Claim: TP

Claim
No: SNM18D05365C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YN5492K

Make & Model: ISUZU NPR85LU5Y, 3.0 D (M)

Reg. Date: 01/07/2014 (Man. Year: 2013)

Colour: Blue

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 4JJ11D2411

Chassis No: JAANPR85HE7100205

Odometer: 197141 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.00 R16

Rear Tyre Size: 7.00 R16 (D)

Front Left Side: Firestone 6 mm

Rear Left Side: Firestone 6/6 mm

Front Right Side: Firestone 6 mm

Rear Right Side: Firestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,344.24	4,260.76	3,083.48	41.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,680.00	1,580.00	2,100.00	57.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,024.24	5,840.76	5,183.48	47.02
Approved Total (Overridden) (S\$)		4,700.00		
Nett Amount (S\$)	11,024.24	4,700.00	6,324.24	57.37

INSPECTION

Date of Assignment: 21/11/2018

Date Inspected: 30/11/2018 Inspected At:

 Ryder Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2, #02-19 AutoHub @
 Kaki Bukit
 Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Jan 2019)	
Parts:	N/A	ISUZU NPR85LU5Y 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN5492K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S DOOR	Bent	2,420.80 FL	*2,200.00 FL
2	1		*FRONT N/S DOOR WEATHER-STRIP	Necessary	361.10 FL	*220.00 FL
3	1		*FRONT N/S DOOR VERTICAL SEAL	Deformed	221.10 FL	*221.10 FL
4	6		*FRONT N/S DOOR VERTICAL SEAL CLIPS	Necessary	71.40 FL	*71.40 FL
5	1		*FRONT N/S DOOR INNER BOARD	Not Necessary	701.75 FL	*- FL
6	8		*FRONT N/S DOOR INNER BOARD CLIPS	Not Necessary	103.20 FL	*- FL
7	2		*FRONT N/S DOOR HINGES (UPPER & LOWER)	Bent	363.40 FL	*300.00 FL
8	1		*FRONT N/S DOOR LOCK (INNER)	Not Necessary	482.75 FL	*- FL
9	1		*FRONT O/S DOOR CHECKER	Bent	281.20 FL	*231.00 FL
10	1		*FRONT O/S DOOR WINDOW SEAL (OUTER)	Necessary	226.40 FL	*226.40 FL
11	1		*FRONT O/S DOOR WINDOW CHANNEL	Necessary	248.40 FL	*248.40 FL
12	1		*FRONT O/S DOOR WINDOW CHANNEL BRACKET	Necessary	108.20 FL	*108.20 FL
13	1		*FRONT O/S DOOR LOCK HANDLE (OUTER)	Distorted	328.70 FL	*278.70 FL
14	1		*FRONT N/S DOOR PILLAR (OUTER)	Repair	789.20 FL	*- FL
15	1		*FRONT N/S DOOR PILLAR (INNER)	Repair	731.10 FL	*- FL
16	1		*FRONT N/S DOOR PILLAR PANEL (OUTER)	Deformed	383.70 FL	*383.70 FL
17	2		*FRONT N/S DOOR PILLAR PANEL CLIPS	Necessary	25.80 FL	*25.80 FL
18	1		*DOOR HORIZONTAL GARNISH	Necessary	86.20 FL	*86.20 FL
19	1		*FRONT O/S DOOR YL LOGO AND ADDRESS STICKER	Necessary	600.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,534.40	4,950.90
- List Item Discount on L Items 15.00/15.00% (S\$)	1,190.16	690.14
Total Parts (S\$)	7,344.24	4,260.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE, STRAIGHTEN AND WELDING	New	1,800.00	800.00
2	TO SPRAY PAINTING	New	1,500.00	750.00
3	TO RE-SEAL ANTI-RUST	New	380.00	30.00
Gross Labour Cost (S\$)			3,680.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >